

47003/0002

ASS. REC. BY:

REF: C3/MSG 19005876 / 653<sup>02</sup>-1 | Special Instruction:

Surveyor: Chia ASSIGNMENT (Office)  
Marimex

From (Person): Christina Wong of MSI 9 Date/Time: 3.4.19 10:17 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SJE 7632L Insured: GBC 517A

at Workshop m/s Em-1 Auto Tel: 64523298

of BK 8 Sin ming Industrial Estate Sector C # 01-68

Policy No: 28604428 Claim No: 529249

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 31.3.2019  
 (Client's Record)

CA / REV / REP. / REV 24 HRS "Wf"

H.O.D. Endorsement:

Date/Time: 12:12pm 3/4/19 Person Contacted: Mr. Chieh Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJE 7632L - SA/INC 110/102/9/41</u>
	<u>GBC 517A - X</u>
	<u>\$1100 - 12 Days.</u>
	<u>10480</u>
	<u>10500 - 10.600/-</u>
	<u>( \$12,000.00 Red - 54% )</u>

14/5/2020

Singapore

PKS  
602

REF:

MSG

79248

## ASSIGNMENT

(-2023)

From:

Date:

Veh No:

SJE7623L

Yr Regn:

07 May 2008

Estimated Cost:

Type: ☒ M/Car ☐ M/Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

Truck / Trailer or

To inspect Vehicle No:

Make:

Honda Fit

C.C.

1339

at Workshop m/s

EM-1

Colour:

Black

A/C

Insured / Std / NI / NA

of

Sp Reading

146688

TiRadio: Insured / Std / NI / NA

Insured

chia

Eng/No:

Policy No

C/No

6E61048288

Claims No

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt

Sum Insured

Excess:

Steering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

(Client's Record)

Brake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Make of Veh

Modi: Nil ☒ STD A/Rim or

(Policy Condition)

Tyre Size:

F:

195/55 R15

R:

11

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KUMHO

Bal. on Market Value:

\$20K

IDAC Accident Report:

Consistent? Yes or No

Front

Rear

GIA / PR Seen:

Consistent? Yes or No

R/Bal

5

mm

R/Bal

5

mm

Est. Repairs

10

days

Res:

Yes or No

L/Bal

5

mm

L/Bal

5

mm

Lum Sum:

%

3 Val:

Yes or No

D.O.A.

D.O.I.

03-04-19

Survey held at

w/s

1pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The ☒ U/C ☐ Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

COC: 15625

\$5000 - \$6000

4/4/2019

03/4 chia said he won't call LKK for 2nd dismantle. resurvey and 3rd After repair resurvey. He will take photos by himself.

Date/Time, Fee Paid to?

☐

Prel. Report

Days Of Repair:

10

1)

☐

Final Report

Resurvey No. of Trip:

-

Survey Fee

Date/Time, Fee Return to?

Transportation

120

2)

Add Fee:

☐

Site Insp (\$

3 - RS, 5)

☐

Interview (\$

) Photo

☐

Tech Insp (\$

) Other

☐

Weekend (\$

)

10

TOTAL

130

Report Format:

PRC

Lump Sum / I.B.I. (\$

## Summer Lee (LKK Auto)

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Monday, 16 December, 2019 7:41 AM  
**To:** Christina Wong; assignments  
**Subject:** RE: Our ref:M589249 TP Paper survey-SJE7623L

Dear Christina,

Thank you for the email.

**Dear Assignment Team,**

**FYNA**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Christina Wong <Christina\_Wong@sg.msig-asia.com>  
**Sent:** Saturday, 14 December 2019 3:00 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Our ref:M589249 TP Paper survey-SJE7623L

Dear Veron

Please do Urgent paper survey. Thanks

Best Regards





**Christina Wong**

Senior Executive, Claims Services (Motor)

Direct line +65 6643 1311 | Direct fax +65 6225 7402 | [christina\\_wong@sg.msig-asia.com](mailto:christina_wong@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

# TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169878  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: [ihling@tcmg.com.sg](mailto:ihling@tcmg.com.sg)

Our Ref : LLH/r/1621/1119/EM1

Your Ref: GBC 5117 A

20 NOV 2019

PFM Engineering Pte Ltd  
21 Bukit Batok Crescent  
#20-79 WCEGA Tower  
Singapore 658065

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay #24-01  
Hong Leong Building  
Singapore 048581

## Attn: Motor Claims Department

Dear Sirs,


### ACCIDENT INVOLVING SJE 7623 L AND GBC 5117 A ON 31 MARCH 2019 ALONG BANGKIT ROAD TO SENJA ROAD BEFORE FAJAR ROAD

We are instructed by **Nurhuda Binte Mohamed Said**, to claim damages against you or your insured, the owner/driver of motor vehicle no. GBC 5117 A in connection with a road traffic accident on 31<sup>st</sup> day of March, 2019 at about 13:20 hours along Bangkit Road towards Senja Road before Fajar Road, involving our client's motor vehicle no. SJE 7623 L and motor vehicle no. GBC 5117 A driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1	Costs of Repair (as recommended)	\$ 24,182.00 (incl. GST)
2	Rental (\$95 x 13 days)	\$ 1,321.45 (incl. GST)
3	GIA / LTA insurance enquiry	\$ 36.45
4	Survey fee	\$ 1,530.00
5	Disbursement (at this stage)	\$ 100.00
6	Legal Cost (at this stage)	\$ 900.00
		<u>\$ 28,069.90</u>

589249.



CW

IBn,

- Scan & upload.
- ACK to TP.
- COP to OI.
- Passed file to CW.

By Certificate of Posting  
(For your attention; without enclosures)

21  
3/12/19

BY PDX NO. 8173

PDX Intercompany Exchange Pte Ltd



010808852232

FROM TOMMY CHOO, MARK GO LL  
PDX Box No 8141

A copy each of the following supporting documents is enclosed:

1. Copy of accident report and LTA insurance enquiry;
2. Copy of accident report of GBC 5117 A;
3. Copy of Certificate of Insurance and PARF/COE particulars;
4. Copy of rental invoice and vehicle rental agreement no. 22171;
5. Copy of survey report and invoice and repair bill;
6. Colour photographs pertaining to our client's motor vehicle for your perusal.

Our clients had on 1<sup>st</sup> April 2019 notified your insurer, M/s MSIG Insurance (Singapore) Pte Ltd about the accident and the pre-repair inspection was conducted.

Please note that if you are insured and you wish to claim your insurance policy, you should immediately pass this letter to your insurer.

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



**LING LEONG HUI (MR)**

enc.  
cc. clients

## TAX INVOICE

Our Ref No: GR-19-062721  
Date of Request: 22/04/2019

Your Ref No: WALK IN CHIA

EM1 AUTO PTE LTD  
BLK 8 #01-68 SIN MING INDUSTRIAL ESTATE SECTOR C  
SINGAPORE 575643

Dear Sir/Madam,

Date of Accident: 31/03/2019  
Vehicle No: SJE7623L  
Place of Accident: BANGKIT RD TO SINJA RD BEFORE FAJAR RD  
Involving Vehicle No: GBC5117A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBC5117A	BANGKIT RD TO SINJA RD BEFORE FAJAR RD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

## TAX INVOICE

Our Ref No: GR-19-062719  
Date of Request: 22/04/2019

Your Ref No: WALK IN CHIA

EM1 AUTO PTE LTD  
BLK 8 #01-68 SIN MING INDUSTRIAL ESTATE SECTOR C  
SINGAPORE 575643

Dear Sir/Madam,

Your Vehicle No: SJE7623L  
Date of Accident: 31/03/2019  
Place of Accident: BANGKIT RD  
Involving Vehicle No: SJZ3012R,GBC5117A

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	
GST Amount	14.02
Total Amount Due (GST Inclusive)	0.98
	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 01 Apr 2019 / 11:46:19

Receipt Date/Time : 01 Apr 2019 / 11:46:19

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-190401-001072

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBC5117A				
As at 31 Mar 2019/13:20:00				
Insurance Co: MSIG INSURANCE (SINGAPORE) PTE LTD				
1	Insurance Enquiry - GBC5117A Enquiry Fee 20190401114357221754	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20190401114446517	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 7924Z

### Vehicle Details

Vehicle No.: SJE7623L  
Vehicle to be Exported: No  
Intended Deregistration Date: 01 Apr 2019  
Vehicle Make: HONDA  
Vehicle Model: FIT 1.3G A  
Primary Colour: Black  
Manufacturing Year: 2008  
Engine No.: L13A4054149  
Chassis No.: GE61048288  
Maximum Power: 73.0 kW (97 bhp)

Output:  
Open Market Value: \$11,389.00  
Original Registration Date: 07 May 2008  
First Registration Date: 07 May 2008  
Transfer Count: 1  
Actual ARF Paid: \$7,529.00

### OPC Cash Rebate Details

OPC Cash Rebate: No  
Eligibility:  
OPC Cash Rebate: -  
Eligibility Expiry Date:  
OPC Cash Rebate: -  
Amount:

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date:  
Date:  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 06 May 2023  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$19,096.00  
COE Rebate Amount: \$15,646.00  
Total Rebate Amount: \$15,646.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Apr 2019

OK

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY/GST REG. NO: 201316380R

## INVOICE

M/S NURHUDA BINTE MOHAMED SAID

MSIG INSURANCE (S) PTE LTD  
MOTOR CLAIMS DEPARTMENT  
16 RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref No. 19/SJE 76231./5417TP  
Date 12/11/2019

Date of Accident 31/03/2019  
Our Vehicle Number SJE 7623L  
Model HONDA FIT  
Your Insured XB 9610K

Lump Sum Repair Cost (Incl GST 7%) \$ 24,182.00

Total Amount \$ 24,182.00

Singapore Dollars : Twenty Four thousand One hundred and Eighty Two only.



友立旅遊服務私人有限公司  
**UNIQUE TOURIST SERVICE (PTE) LTD**

1, Rochor Road, #02-574,  
Rochor Centre Singapore 180001  
Tel: 6292 7656 Fax: (65) 6293 9720  
E-mail: unigtour@singnet.com.sg  
STB LIC TA/00076

Co. Reg. No.: 197401067R  
GST Reg. No.: M2-0019671-6

**TAX INVOICE**

NO. WP2017620

Miss Nurhuda Binte Mohamed Said  
Blk 235 Bukit Panjang Ring Road  
#08-21  
Singapore 670235

20, Sin Ming Lane,  
#08-51, Midview City  
Singapore 573968  
Tel: 6292 7656

15.04.2019

Singapore, \_\_\_\_\_ 20

DATE	PARTICULARS	€	\$	cts
------	-------------	---	----	-----

Rental of one unit Honda Jazz 1.3 Auto  
Registration no. SJU 4383 P self driven as from  
01.04.2019 at 1030 hrs to 13.04.2019 at 1735 hrs.

13 days at \$95.00 per day

\$ 1235.00

Add GST at 7%  
Amount Due

\$ 1235.00

\$ 86.45

\$ 1321.45

( SIN DOLLARS: ONE THOUSAND THREE HUNDRED TWENTY ONE AND FORTY FIVE  
CENTS ONLY )

Standard Rated Supplies:\$ 1235.00  
Total Amount of GST:\$ 86.45

  
AUTHORISED SIGNATURE



# UNIQUE TOURIST SERVICE (PTE) LTD.

20, Sin Ming Lane, #08-51, Midview City, Singapore 573968

TEL: 6292 7656 EMAIL: uniqtour@singnet.com.sg

COMPANY REG NO: 197401067R

GST REG NO: M2-0019671-6

CAR RENTAL AGREEMENT

RA No. 22171

VEHICLE NO.

SJU4283P

MAKE/MODEL

HONDA JAZZ

NAME OF HIRER Nurhuda Binte Mohamed Said

ADDRESS Blk 235 Bukit Panjang Ring Road  
#08-21 SINGAPORE 670235

OFFICE TEL \_\_\_\_\_ RES TEL \_\_\_\_\_ HP 87182887

NAMED DRIVER Nurhuda Binte Mohamed Said

OCCUPATION Educator NATIONALITY \_\_\_\_\_

PASSPORT / NRIC S8307924Z DATE OF BIRTH 15/3/1983

DRIVING LIC NO. S8307924Z

PLACE OF ISSUE \_\_\_\_\_ DATE PASS/EXPIRY 6/10/2006

ADDITIONAL NAMED DRIVER \_\_\_\_\_

ADDRESS \_\_\_\_\_  
SINGAPORE \_\_\_\_\_

OFFICE TEL \_\_\_\_\_ RES TEL \_\_\_\_\_ HP \_\_\_\_\_

OCCUPATION \_\_\_\_\_ NATIONALITY \_\_\_\_\_

PASSPORT / NRIC \_\_\_\_\_ DATE OF BIRTH \_\_\_\_\_

DRIVING LIC NO. \_\_\_\_\_

PLACE OF ISSUE \_\_\_\_\_ DATE PASS/EXPIRY \_\_\_\_\_

BY INITIATING MARK "X" HIRER AGREE TO PAY THE FOLLOWINGS

A. COLLISION DAMAGE WAIVER (CDW) AT \$ \_\_\_\_\_ PER DAY / WEEK / MONTH "X"

B. SURCHARGE OF \$ \_\_\_\_\_ FOR USE IN MALAYSIA FROM

\_\_\_\_\_ TO \_\_\_\_\_ "X"

\* THE HIRER IS RESPONSIBLE FOR ANY DAMAGES UP TO THE EXTENT OF TOTAL LOSS OF CAR, LOSS OF INCOME AND COST OF RECOVERY OF VEHICLE IF THE CAR IS DRIVEN INTO MALAYSIA WITHOUT PRIOR CONSENT FROM THE COMPANY

COMPULSORY EXCESS, DOLLAR

\$ 1200

NOTE

HIRER IS LIABLE FOR ALL PARKING & TRAFFIC VIOLATIONS.

YOUR ATTENTION IS DRAWN TO TERMS & CONDITIONS

PRINTED OVERLEAF

FOR SINGAPORE DRIVE ONLY

DATE: \_\_\_\_\_

SIGNATURE OF HIRER

DATE OUT 11/4/19 TIME OUT 1030 AM

PETROL OUT E 1/4 1/2 3/4 F

DATE IN 13/4/19 TIME IN 17 35

PETROL IN E 1/4 1/2 3/4 F

RENTAL RATES: \$ \_\_\_\_\_

MONTHLY \$ \_\_\_\_\_

WEEKLY \$ \_\_\_\_\_

DAILY 13 \$ 95 = 1235 00

C.D.W. FEE \_\_\_\_\_

PETROL CONSUMPTION \_\_\_\_\_

DELIVERY CHARGE \_\_\_\_\_

COLLECTION CHARGE \_\_\_\_\_

SUB-TOTAL \_\_\_\_\_

GST 7% 86 45

RENTAL DEPOSIT \_\_\_\_\_

TOTAL: 1321 45

DEPOSIT REFUND

PAYMENT BY: BILL CO / CREDIT CARD / CASH

ATTENDED BY: \_\_\_\_\_

OF UNIQUE TOURIST SERVICE (PTE) LTD

## DECLARATION

I HEREBY DECLARE THAT NO MOTOR ACCIDENT HAD OCCURED DURING MY HIRE OF YOUR MOTOR VEHICLE AS STATED IN THE ABOVE MENTIONED SCHEDULE \* OR TO ANY SUBSTITUTED VEHICLE AS STATED IN THE MEMORANDUM DATED

REPLACEMENT VEHICLE NO:

1. \_\_\_\_\_ ON \_\_\_\_\_ TIME \_\_\_\_\_

2. \_\_\_\_\_ ON \_\_\_\_\_ TIME \_\_\_\_\_

3. \_\_\_\_\_ ON \_\_\_\_\_ TIME \_\_\_\_\_

DATE: \_\_\_\_\_

SIGNATURE OF HIRER

## CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009  
Fax: 62874788 Tel: 62856178

## INVOICE

Nurhuda Binte Mohamed Said  
C/o Blk 8, Sin Ming Industrial Estate Sector C  
#01-68  
Singapore 575643

Invoice No: CL 12080 TP  
Our Ref: CL 12080 SJE 7623 L  
Date: 3th November 2019

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: SJE 7623 L</u> Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (Photographs - 355 copies)			\$1,530.00
			<b>Total:</b>	<b>\$1,530.00</b>

We thank you for the opportunity to serve you and assure you of our best at all times

  
PATRICK NG  
Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI ETC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

**CARLINK CONSULTANCY**


60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

**ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

Our Ref: CL 12080 SJE 7623 L

<b>1 REFERENCE</b>			
Date of request	:	3rd April 2019	
Requested by	:	Nurhuda Binte Mohamed Said C/o Blk 8 Sin Ming Road Industrial Estate Sector C, #01-68 SE 575643	
Type of claim	:	Third party	
Workshop	:	M/S EM-1 Auto Pte Ltd Blk 8 Sin Ming Road Industrial Estate Sector C, #01-68 Singapore 575643	
Date of survey	:	3rd April 2019	
Accident date	:	31st March 2019	
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	:	SJE 7623 L	
Make & Model	:	Honda Fit 1.3G A	
Date of registration	:	7th May 2008	
Engine No.	:	L13A4D54149	
Chassis No.	:	GE61048288	
Speedometer reading	:	148688 Km	
Transmission	:	Automatic	
Colour	:	Black	
<b>3 STATIC CHECK</b>			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
<b>4 TYRE CONDITION</b>			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	6mm/Falken	6mm/Falken : 195/55 R15
Rear tyre	:	6mm/Falken	6mm/Falken : 195/55 R15
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

## Annex A : Assesement / Adjustment on Spare Parts

SJE 7023 L

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Tailgate assy	Buckled/cut	1	\$796.60	20%	\$637.28
2	Tailgate badge	Necessary	1	\$42.00	20%	\$33.60
3	Tailgate emblem FIT	Necessary	1	\$48.00	20%	\$38.40
4	Tailgate outer garnish	Bent/cut	1	\$195.60	20%	\$157.28
5	Tailgate outer garnish clips	Necessary	1set	\$40.00	20%	\$32.00
6	Tailgate outer handle	Distorted/	1	\$92.70	20%	\$74.16
7	Tailgate number plate lamps	Distorted/chipped	2	\$84.00	20%	\$67.20
8	Tailgate wiper motor	Distorted/faulty	1	\$453.00	20%	\$362.40
9	Tailgate inner lock	Bent/jammed	1	\$272.10	20%	\$217.68
10	Tailgate auto lock actuator	Faulty	1	\$178.50	20%	\$143.60
11	Tailgate lock catch	Bent/slack	1	\$48.20	20%	\$38.56
12	Tailgate weatherstrip	Deformed/cut	1	\$159.20	20%	\$127.36
13	Tailgate stopper	Necessary	2	\$38.00	20%	\$30.40
14	Tailgate hinges	Repair	2	\$112.00	100%	\$0.00
15	Tailgate absorber	Bent/leaked	2	\$344.00	20%	\$275.20
16	Tailgate inner trim	Dented/cut	1	\$192.30	20%	\$153.84
17	Tailgate inner trim clips	Necessary	1set	\$30.00	20%	\$24.00
18	Tailgate windscreen inner seal	Necessary	1	\$50.00	20%	\$40.00
19	Tailgate windscreen moulding	Necessary	2	\$170.00	20%	\$136.00
20	End panel assy	Buckled	1	\$492.50	20%	\$394.00
21	End panel top trim	Bent/cut	1	\$95.30	20%	\$76.24
22	End panel top trim clips	Necessary	1set	\$30.00	20%	\$24.00
23	Spare tyre panel	Crumpled	1	\$872.00	20%	\$697.60
24	Spare tyre panel top board	Bent/cut	1	\$282.10	20%	\$225.68
25	Spare tyre top side panel	Bent	2	\$342.20	20%	\$273.76
26	Spare tyre top sponge	Deformed/cut	1	\$278.10	20%	\$222.48
27	Rear chassis frame member	Dented/bent	1	\$587.60	20%	\$470.08
28	Tailamps assy	Cracked	2	\$544.20	20%	\$435.36
29	Tailamps inner sealer	Necessary	2	\$76.00	20%	\$60.80
30	Tailamps clips	Necessary	2set	\$50.00	20%	\$40.00
31	Tailamp lower retainer	Necessary	2	\$84.00	20%	\$67.20
32	Tailamp panel	Dented/bent	2	\$312.60	20%	\$250.08
33	Rear fenders	Dented/crumpled	2	\$1,424.40	20%	\$1,139.52
34	Rear fender glass inner seal	Necessary	2	\$100.00	20%	\$80.00
35	Rear fender inner housing RH	Dented/bent	2	\$526.60	20%	\$421.28
36	Rear fender inner trim (black)	Distorted/cut	2	\$582.40	20%	\$465.92
37	Rear fender inner trim cover	Slack/cut	2	\$124.00	20%	\$99.20
38	Rear fender inner trim clips	Necessary	2set	\$60.00	20%	\$48.00
39	Rear fender inner top trim (white) RH	Bent/cut	1	\$115.00	20%	\$92.00
40	Rear fender inner shield	Grazed/cut	2	\$98.80	20%	\$79.04
41	Rear fender inner shield clips	Necessary	2set	\$50.00	20%	\$40.00
42	Rear fender air vent	Cut/slack	2	\$92.40	20%	\$73.92
43	Rear bumper assy	Buckled	1	\$495.50	20%	\$396.40
44	Rear bumper side retainers	Necessary	2	\$76.00	20%	\$60.80
45	Rear bumper clips	Necessary	1set	\$50.00	20%	\$40.00
46	Rear bumper damper RH	Crumpled	1	\$59.00	20%	\$47.20
47	Rear bumper tow cover	Distorted/cut	1	\$32.00	20%	\$25.60



SJE 7623 L

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
48	Rear exhaust silencer	Dented/bent/rattle	1	\$519.20	20%	\$415.36
49	Rear exhaust mountings	Distorted/cut	2	\$76.00	20%	\$60.80
50	Rear exhaust gasket	Necessary	1	\$49.20	20%	\$39.36
51	Rear exhaust heat plate	Crumpled	1	\$92.30	20%	\$73.84
52	Rear door RH	Dented/bent	1	\$712.50	20%	\$570.00
53	Rear door inner lock RH	Distorted/jammed	1	\$279.50	20%	\$223.60
54	Rear door lock catch RH	Bent	1	\$38.20	20%	\$30.56
55	Rear door weatherstrip RH	Deformed/cut	1	\$158.20	20%	\$126.56
56	Rear door black sticker RH	Necessary	1	\$48.00	20%	\$38.40
57	Rear door inner trim RH	Distorted/cut	1	\$480.00	20%	\$384.00
58	Rear door inner board clips	Necessary	1set	\$40.00	20%	\$32.00
59	Rear shock absorber RH	Bent/leaked	1	\$162.20	20%	\$129.76
60	Front bumper	Grazed/cut	1	\$573.70	20%	\$458.96
61	Front bumper reinforcement	Dented/bent	1	\$392.20	20%	\$313.76
62	Front bumper side retainers	Necessary	2	\$76.00	20%	\$60.80
63	Front bumper clips	Necessary	1set	\$50.00	20%	\$40.00
64	Front bumper lower grille	Cut	1	\$162.50	20%	\$130.00
65	Headlamps LH	Grazed/cracked	1	\$692.30	20%	\$553.84
66	Headlamp lower retainer LH	Cut/slack	1	\$49.20	20%	\$39.36
67	Headlamps clips	Necessary	1set	\$20.00	20%	\$16.00
68	Front fender LH	Grazed/dented	1	\$412.00	20%	\$329.60
69	Front fender inner shield LH	Grazed/cut	1	\$96.20	20%	\$76.96
70	Front fender inner shield clips	Necessary	1set	\$30.00	20%	\$24.00
71	Support panel extent panel LH	Dented/bent	1	\$157.20	20%	\$125.76
72	Front absorber LH	Leaked	1	\$469.50	20%	\$375.60
73	Front lower arm LH	Bent	1	\$258.50	20%	\$206.80
74	Front knuckle arm LH	Distorted	1	\$352.80	20%	\$282.24
75	Front wheel bearing LH	Distorted/cracking sound	1	\$163.20	20%	\$130.56
76	Front driver seat RH	Bent/slack	1	\$1,453.50	20%	\$1,162.80
<b>S/Nett Items</b>						
77	Rear bumper lower skirt	Grazed/cut	1	\$900.00		\$900.00
78	Tailgate spoiler	Bent/cut	1	\$750.00		\$750.00
79	Rear windscreen sealant	Necessary	1	\$60.00		\$60.00
80	Rear fender glass sealant	Necessary	2	\$120.00		\$120.00
81	Reverse sensor	Cut/faulty	1set	\$250.00		\$250.00
82	Reverse camera	Faulty	1set	\$450.00		\$450.00
83	Rear number plate with holder (Red plate)	Dented/bent	1	\$70.00		\$70.00
84	Body panel joint sealant	Necessary	1set	\$120.00		\$120.00
85	Rear floor panel insulator pad	Necessary	1set	\$150.00		\$150.00
86	Door sun visor	Necessary	1set	\$280.00		\$280.00
87	Front sport rim RH	Chipped/warped	1	\$550.00		\$550.00
88	Front sport rim tyre RH	Grazed/bulge	1	\$380.00		\$380.00
89	Front bumper lower skirt	Grazed/cut	1	\$900.00		\$900.00
90	Front number plate with holder (Red plate)	Necessary	1set	\$70.00		\$70.00

Total for Spare Parts : \$24,388.90 \$20,431.52

9596  
20%: 7676.8

## Annex B : Adjustment on Labour and Spray Painting

SJE 7623 L

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	Panel beating	\$2,800.00	\$2,400.00
2	Spray painting	\$2,600.00	\$2,100.00
3	Check wiring	\$120.00	\$80.00
4	Anti rust	\$280.00	\$180.00
5	Remove and install rear windscreen	\$140.00	\$120.00
6	Remove and install both rear fender glass	\$240.00	\$160.00
7	Remove and install rear door parts	\$90.00	\$80.00
8	Remove and install tailgate parts	\$90.00	\$80.00
9	Remove and install carpet and seat	\$250.00	\$150.00
10	Remove and install reverse sensor	\$90.00	\$80.00
11	To jack and alignment chassis frame member	\$350.00	\$280.00
12	Remove and install rear exhaust silencer	\$150.00	\$120.00
13	Remove and install front undercarriage	\$280.00	\$180.00
14	To perform computerize wheel alignment	\$90.00	\$80.00
15	To send vehicle to seat red plate pin	\$150.00	\$120.00
TOTAL FOR LABOUR & SPRAY PAINTING :		\$7,720.00	\$6,210.00

### Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$24,388.90	\$20,431.52
TOTAL FOR LABOUR & SPRAY PAINTING :	\$7,720.00	\$6,210.00
TOTAL REPAIR COSTS :	\$32,108.90	\$26,641.52

17,096.8  
20% 10450

## CARLINK CONSULTANCY

SJE 7623 L

### Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S EM-1 Auto Pte Ltd estimated repair cost is **S\$32,108.90** and we have adjusted it to **S\$26,641.52** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$22,600.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of **14** working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,  
CARLINK CONSULTANCY



Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/04/2019 17:11
Date Of Accident	31/03/2019 13:20
Exact Location Of Accident	BANGKIT RD TO SINJA RD BEFORE FAJAR RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE7623L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NURHUDA BINTE MOHAMED SAID
NRIC No	S8307924Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87182887
Alternative Phone No	OTHERS-NOPHONE

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT102139
Cover Note Number	

### Driver

Name of Driver	NURHUDA BINTE MOHAMED SAID
NRIC No	S8307924Z
Date Of Birth	15/03/1983
Occupation	INDOOR
Date Of Driving Pass	06/10/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87182887
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	NOEMAIL

Address	APT BLK 235 BUKIT PANJANG RING ROAD #08-21
Postcode	670235
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC5117A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RIDDUAN BIN IMAM
NRIC/Passport Number	S1803067E
Contact Number	98621596
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJZ3012R
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NG KIT SIANG

NRIC/Passport Number

S8138103H

Contact Number

90477974

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

CITY AUTO PTE LTD  
81k & Sin Ming Road  
#01-55/60/62 Sin Ming Ind Est  
Singapore 575643  
Tel: 6453 2222 Fax: 6453 7944  
(Claims Section)  
  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Bangkit Rd towards Senja Road before Fajar Road on lane 2 before SPC Petrol Kiosk. There was long queue before Petrol Station, front vehicle slowed down to stop. I follow suit (stationary). Suddenly vehicle B hit onto my rear portion and due to the impact, caused my vehicle to move forward and hit onto vehicle C.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

CITY AUTO PTE LTD  
818 Sin Ming Road  
#01-586082 Singapore 505543  
Tel: 6453 1234 Fax: 6453 7966  
(Claims Section)  
Reporting Centre Personnel's Signature  
Name:  
NIC/PIN No.:



## Tokio Marine Insurance (Singapore) Ltd

20 Robinson Road, #20-01/02 Robinson Centre, Singapore 069046  
 Tel: 65 6221 4111 / 65 6221 4355 / 65 6224 0886 / www.tokiomarine.com.sg / www.tokiomarine.com

Company No. 112019001  
 U.S. No. 112019001



TOKIO MARINE  
INSURANCE GROUP

## Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MT102139 (Private Car)

- |  |  |                         |
|--|--|-------------------------|
| 1. Index Mark and Registration Number of Vehicle                               | SJC7523L   | Chassis No.: G851048288 |
| 2. Name of Policyholder  | NURHUDA BINTE MOHAMED SAID   |                         |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 04/05/2018 (14:48:11)  |                         |
| 4. Date of Expiry of Insurance   | 06/05/2019   |                         |
| 5. Persons or Class of Persons entitled to drive*                              | (a) The Policyholder.<br>(b) Any other person who is driving on the Policyholder's order or with his permission. |                         |

\* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any endorsement or suspension in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

## 6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 35 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy is valid and the Certificate is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

## IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd within 7 days thereof or, if the Certificate has been not returned, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189).

## ADDITIONAL INFORMATION

Account No: 253800A

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Privatizing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess: SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	Windscreen Excess	SGD 100.00	
Financial Interest:	TOKYO CENTURY LEASING (S) PTE LTD		

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorized Signature

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/04/2019 17:11
Date Of Accident	31/03/2019 13:20
Exact Location Of Accident	BANGKIT RD TO SINJA RD BEFORE FAJAR RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE7623L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NURHUDA BINTE MOHAMED SAID
NRIC No	S8307924Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87182887
Alternative Phone No	OTHERS-NOPHONE

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT102139
Cover Note Number	

### Driver

Name of Driver	NURHUDA BINTE MOHAMED SAID
NRIC No	S8307924Z
Date Of Birth	15/03/1983
Occupation	INDOOR
Date Of Driving Pass	06/10/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87182887
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	NOEMAIL

Address	APT BLK 235 BUKIT PANJANG RING ROAD #08-21
Postcode	670235
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC5117A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RIDDUAN BIN IMAM
NRIC/Passport Number	S1803067E
Contact Number	98621596
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJZ3012R
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NG KIT SIANG

NRIC/Passport Number

S8138103H

Contact Number

90477974

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


CITY AUTO PTE LTD  
81k 8 Sin Ming Road  
#01-55/56/57 Sin Ming Ind Est  
Singapore 505643  
Tel: 6453 7944 Fax: 6453 7944  
(Claims Section)

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Bangkai Rd towards Sanja Road Before Fajar Road on lane 2 before SPC Petrol Kiosk. There was long queue before Petrol Station, front vehicle slowed down to stop. I follow suit (stationary). Suddenly vehicle B hit onto my rear portion and due to the impact, caused my vehicle to move forward and hit onto vehicle C.

a

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

CITY AUTO PTE LTD  
818 8 Sin Ming Road  
#01-55/56/57/58/59 Ind Est  
Singapore 50543  
Tel: 6453 1234 Fax: 6453 7944  
(Claims Section)  
Reporting Centre Personnel's Signature  
Name:  
NIC/PIN No.



Tokio Marine Insurance (Singapore) Ltd.

Company Reg. No. 1420001900 N.C.T Reg. No. 801000011 E

20 McCabum Street #09-01 Tokio Marine Centre Singapore 069044

Tel: 6221 6111 / 6221 4355 / 6224 0855 / tme@tokiomarine.com.sg / www.tokiomarine.com

Incorporated in  
SingaporeTOKIO MARINE  
INSURANCE GROUP

## Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1969

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

Policy No.: MT102139 (Private Car)

- |  |  |                         |
|--|--|-------------------------|
| 1. Index Mark and Registration Number of Vehicle                               | SJC7623L   | Chassis No.: GR61048268 |
| 2. Name of Policyholder  | NURHUDA BINTE MOHAMED SAID   |                         |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 04/05/2018 (14:48:11)  |                         |
| 4. Date of Expiry of Insurance   | 06/05/2019   |                         |
| 5. Persons or Class of Persons entitled to drive*                              | (a) The Policyholder.<br>(b) Any other person who is driving on the Policyholder's order or with his permission. |                         |

\* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not requested by order of a Court of law or by reason of any enactment or regulation to that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident, loss or damage.

## 6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered operative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 36 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Rules thereunder (Road Transport Act, 1987 (Malaysia)).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

## IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been not destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

## ADDITIONAL INFORMATION

Account No: 2538DDA

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess: SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	
	Financial Interest:	TOKYO CENTURY LEASING (S) PTE LTD	

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorized Signature

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/04/2019 14:56
Date Of Accident	31/03/2019 13:30
Exact Location Of Accident	BEFORE SPC BUKIT PANJANG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC5117A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PFM ENGINEERING PTE LTD
Co Reg No	197600505C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98621596

### Vehicle Particulars

Manufacturer	PEUGEOT
Model	PARTNER 1.6 HDI LWB EURO 4
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	RIDDUAN BIN IMAM
NRIC No	S1803067E
Date Of Birth	22/08/1967
Occupation	OUTDOOR
Date Of Driving Pass	23/07/1997
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98621596
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	502 JELAPANG ROAD #03-392
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 31/03/2019 AT 1329HRS, I WAS TRAVEILLING ALONG BUKIT PANJANG VEHICLE B(SJE7623L), I JAMMED ON THE BRAKES BUT MY VEHICLE WAS NOT ABLE TO STOPPED IN TIME AND HITS TO VEHICLE B

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
    - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:




  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



  
Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

# Sketch Plan #2

## SKETCH PLAN



A- G8C5117A



B- SJE4623L

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/03/2019 at 1329 hours, I was travelling along Bukit Panjang Ring Road. Vehicle B stopped the vehicle before SPE, I jammed on the brakes but my vehicle was not able to stop in time and hit vehicle B.

## DECLARATION

(We declare the foregoing statements are true in every respect.)

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:

Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



# Driving License





Chasis














































## ...CLAIM SUBFOLDER...(Pending for Survey Report)























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2019		03 Apr 2019 10:17 <a href="#">Edit Adj Rpt</a>	<b>S\$10,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$10,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	PFM ENGINEERING PTE LTD, Co. Reg. No.: NA								
Main Claimant:	NURHUDA BINTE MOHAMED SAID, ID: S8307924Z								
Vehicle Reg. No.:	SJE7623L	Date of Loss:	31/03/2019 00:00 - :59 [130 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 589249	Policy/Cover Note No.:	28604428 (Comprehensive) Coverage: 14/09/2018 - 13/09/2019						
Vehicle Reg. No. (Insured):	GBC5117A	Policy No. (Claimant):							
		Excess:							
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Hiew May Fung] ... [Final Rpt due 17/12/2019]								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE, CONTACT:KAREN 9666 6556/6452 3298. on WP.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (14/12/2019): Report Send Back Alerts - SJE7623L (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJE7623L (589249)  
[GBC5117A]  
TP  
NURHUDA BINTE MOHAMED SAID  
Mar 31 2019 12:00AM  
[PFM ENGINEERING PTE LTD]  
Em-1 Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
2	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
3	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
4	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
5	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
6	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
7	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
8	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
9	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
10	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
11	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
12	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
13	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
14	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
15	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
16	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
17	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
18	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
19	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
20	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
21	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
22	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
23	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
24	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
25	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
26	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
27	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
28	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
29	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
30	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
31	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
32	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
33	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
34	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
35	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
36	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
37	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
38	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
39	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
40	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
41	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
42	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					
43	05/04/19 08:52	General View		 Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
59	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
60	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
61	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
62	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
63	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
64	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
65	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
66	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
67	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
68	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
69	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
70	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
71	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
72	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
73	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
74	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
75	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
76	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
77	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
78	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
79	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
80	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
81	05/04/19 08:52	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/04/19 17:55	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	 Load PDF	
2	02/04/19 18:01	SJE7623L TP E-FILE REPORT	 Load PDF	
3	02/04/19 18:05	PRI - EM-1 AUTO PTE LTD	 Load PDF	
4	03/04/19 09:35	GIA report of GBC5117A	 Load PDF	
5	11/12/19 18:02	TPD SJE7623L - SURVEY REPORT & INVOICE	 Load PDF	
6	11/12/19 18:02	LOD with supporting documents - SJE7623L	 Load PDF	
7	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
8	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
9	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
10	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
11	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
12	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
13	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
14	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
15	11/12/19 18:02	TPD SJE7623L - COLOUR PHOTO	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 10:02	PRS Invoice	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005876/GSF3E2-1

Date: 15/01/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28604428

Claimant: SJE7623L

Insured Vehicle No: GBC5117A

Vehicle No: SJE7623L

Date of Loss: 31/03/2019

Nature of Claim: TP

Claim No: 589249

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE7623L

Make &amp; Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4054149

Reg. Date: 07/05/2008 (Man. Year: 2008)

Chassis No: GE61048288

Colour: Black

Odometer: 146688 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,388.90	9,486.80	14,902.10	61.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,720.00	3,790.00	3,930.00	50.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>32,108.90</b>	<b>13,276.80</b>	<b>18,832.10</b>	<b>58.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,600.00</b>		
<b>(S\$)</b>	32,108.90	10,600.00	21,508.90	66.99
<b>+ GST 7.00/7.00% (S\$)</b>	2,247.62	742.00	1,505.62	66.99
<b>Nett Amount (S\$)</b>	<b>34,356.52</b>	<b>11,342.00</b>	<b>23,014.52</b>	<b>66.99</b>

### INSPECTION

Date of Assignment: 03/04/2019

Date Inspected: 03/04/2019 Inspected At:

Em-1 Auto Pte Ltd (HQ)  
Blk 8 Sin Ming Industrial Estate Sector  
C, #01-68  
Singapore 575643

Estimated Period of Repair: 12.0 days

Adjuster: Hiew May Fung

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2020)
<b>Parts:</b>	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJE7623L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ASSY	Buckled / Cut	796.60 F	*796.60 FL
2	1		*TAILGATE BADGE	Necessary	42.00 F	*42.00 FL
3	1		*TAILGATE EMBLEM FIT	Necessary	48.00 F	*48.00 FL
4	1		*TAILGATE OUTER GARNISH	Bent / Cut	196.60 F	*120.60 FL
5	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	40.00 F	*40.00 FL
6	1		*TAILGATE OUTER HANDLE	Serviceable	92.70 F	*- FL
7	2		*TAILGATE NUMBER PLATE LAMPS	Serviceable	84.00 F	*- FL
8	1		*TAILGATE WIPER MOTOR	Serviceable	453.00 F	*- FL
9	1		*TAILGATE INNER LOCK	Bent / Jammed	272.10 F	*232.40 FL
10	1		*TAILGATE AUTO LOCK ACTUATOR	Serviceable	179.50 F	*- FL
11	1		*TAILGATE LOCK CATCH	Bent / Slack	46.20 F	*46.20 FL
12	1		*TAILGATE WEATHERSTRIP	Deformed / Cut	159.20 F	*159.20 FL
13	2		*TAILGATE STOPPER	Serviceable	36.00 F	*- FL
14	2		*TAILGATE HINGES	Repair	112.00 F	*- FL
15	2		*TAILGATE ABSORBER	Serviceable	344.00 F	*- FL
16	1		*TAILGATE INNER TRIM	Dented / Cut	192.30 F	*192.30 FL
17	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	30.00 F	*30.00 FL
18	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	50.00 F	*50.00 FL
19	2		*TAILGATE WINDSCREEN MOULDING	Necessary	170.00 F	*170.00 FL
20	1		*END PANEL ASSY	Buckled	492.50 F	*492.50 FL
21	1		*END PANEL TOP TRIM	Bent / Cut	95.30 F	*95.30 FL
22	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 F	*30.00 FL
23	1		*SPARE TYRE PANEL	Crumpled	872.00 F	*637.40 FL
24	1		*SPARE TYRE PANEL TOP BOARD	Bent / Cut	282.10 F	*282.10 FL
25	2		*SPARE TYRE TOP SIDE PANEL	Bent	342.20 F	*342.20 FL
26	1		*SPARE TYRE TOP SPONGE	Deformed / Cut	279.10 F	*220.00 FL
27	1		*REAR CHASSIS FRAME MEMBER	Dented / Bent	587.60 F	*587.60 FL
28	2		*TAILLAMP ASSY	Cracked	544.20 F	*544.20 FL
29	2		*TAILLAMP INNER SEALER	Necessary	76.00 F	*76.00 FL
30	2		*SET TAILLAMPS CLIPS	Necessary	50.00 F	*50.00 FL
31	2		*TAILLAMP LOWER RETAINER	Necessary	84.00 F	*84.00 FL
32	2		*TAILLAMP PANEL	Repair	312.60 F	*- FL
33	2		*REAR FENDERS	Repair	1,424.40 F	*- FL
34	2		*REAR FENDER GLASS INNER SEAL	Serviceable	100.00 F	*- FL
35	2		*REAR FENDER INNER HOUSING RH	Serviceable	526.50 F	*- FL
36	2		*REAR FENDER INNER TRIM (BLACK)	Distorted / Cut	582.40 F	*582.40 FL
37	2		*REAR FENDER INNER TRIM COVER	Serviceable	124.00 F	*- FL
38	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 F	*60.00 FL
39	1		*REAR FENDER INNER TOP TRIM (WHITE) RH	Serviceable	115.00 F	*- FL
40	2		*REAR FENDER INNER SHIELD	Grazed / Cut	98.80 F	*98.80 FL
41	2		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
42	2		*REAR FENDER AIR VENT	Cut / Slack	92.40 F	*92.40 FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR BUMPER ASSY	Buckled	495.50 F	*495.50 FL
44	2		*REAR BUMPER SIDE RETAINERS	Necessary	76.00 F	*76.00 FL
45	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
46	1		*REAR BUMPER DAMPER RH	Crumpled	59.00 F	*59.00 FL
47	1		*REAR BUMPER TOW COVER	Distorted / Cut	32.00 F	*32.00 FL
48	1		*REAR EXHAUST SILENCER	Dented / Bent / Rattle	519.20 F	*519.20 FL
49	2		*REAR EXHAUST MOUNTINGS	Distorted / Cut	76.00 F	*76.00 FL
50	1		*REAR EXHAUST GASKET	Necessary	49.20 F	*49.20 FL
51	1		*REAR EXHAUST HEAT PLATE	Crumpled	92.30 F	*92.30 FL
52	1		*REAR DOOR RH	Repair	712.50 F	*- FL
53	1		*REAR DOOR INNER LOCK RH	Serviceable	279.50 F	*- FL
54	1		*REAR DOOR LOCK CATCH RH	Serviceable	36.20 F	*- FL
55	1		*REAR DOOR WEATHERSTRIP RH	Serviceable	159.20 F	*- FL
56	1		*REAR DOOR BLACK STICKER RH	Serviceable	48.00 F	*- FL
57	1		*REAR DOOR INNER TRIM RH	Serviceable	480.00 F	*- FL
58	1		*SET REAR DOOR INNER BOARD CLIPS	Serviceable	40.00 F	*- FL
59	1		*REAR SHOCK ABSORBER RH	Serviceable	162.20 F	*- FL
60	1		*FRONT BUMPER	Grazed / Cut	573.70 F	*484.00 FL
61	1		*FRONT BUMPER REINFORCEMENT	Dented / Bent	392.20 F	*351.00 FL
62	2		*FRONT BUMPER SIDE RETAINERS	Necessary	76.00 F	*76.00 FL
63	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
64	1		*FRONT BUMPER LOWER GRILLE	Serviceable	162.50 F	*- FL
65	1		*HEADLAMPS LH	Grazed / Cracked	692.30 F	*575.00 FL
66	1		*HEADLAMP LOWER RETAINER LH	Cut / Slack	49.20 F	*49.20 FL
67	1		*SET HEADLAMPS CLIPS	Necessary	20.00 F	*20.00 FL
68	1		*FRONT FENDER LH	Repair	412.00 F	*- FL
69	1		*FRONT FENDER INNER SHIELD LH	Grazed / Cut	96.20 F	*96.20 FL
70	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 F	*30.00 FL
71	1		*SUPPORT PANEL EXTENT PANEL LH	Serviceable	157.20 F	*- FL
72	1		*FRONT ABSORBER LH	Serviceable	469.50 F	*- FL
73	1		*FRONT LOWER ARM LH	Serviceable	256.50 F	*- FL
74	1		*FRONT KNUCKLE ARM LH	Serviceable	352.80 F	*- FL
75	1		*FRONT WHEEL BEARING LH	Distorted / Cracking sound	163.20 F	*163.20 FL
76	1		*FRONT DRIVER SEAT RH (LOCAL REPAIR)	Bent / Slack	1,453.50 FS	*200.00 FS
77	1		*REAR BUMPER LOWER SKIRT	Grazed / Cut	900.00 FS	*400.00 FS
78	1		*TAILGATE SPOILER	Serviceable	750.00 FS	*- FS
79	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
80	2		*REAR FENDER GLASS SEALANT	Serviceable	120.00 FS	*- FS
81	1		*SET REVERSE SENSOR	Cut / Faulty	250.00 FS	*200.00 FS
82	1		*SET REVERSE CAMERA	Serviceable	450.00 FS	*- FS
83	1		*REAR NUMBER PLATE WITH HOLDER (RED PLATE)	Dented / Bent	70.00 FS	*40.00 FS
84	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*40.00 FS
85	1		*SET REAR FLOOR PANEL INSULATOR PAD	Necessary	150.00 FS	*150.00 FS
86	1		*SET DOOR SUN VISOR	Serviceable	280.00 FS	*- FS
87	1		*FRONT SPORT RIM LH	Chipped / Warped	550.00 FS	*300.00 FS
88	1		*FRONT SPORT RIM TYRE LH	Serviceable	380.00 FS	*- FS
89	1		*FRONT BUMPER LOWER SKIRT	Grazed / Cut	900.00 FS	*400.00 FS
90	1		*SET FRONT NUMBER PLATE WITH HOLDER (RED PLATE)	Necessary	70.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **24,388.90**    **11,406.00**  
 - List Item Discount on L Items 0.00/20.00% (\$\$)    0.00    1,919.20

Total Parts (\$\$) **24,388.90**    **9,486.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,800.00	1,600.00
2	SPRAY PAINTING	New	2,600.00	1,600.00
3	CHECK WIRING	New	120.00	30.00
4	ANTI RUST	New	280.00	80.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL BOTH REAR FENDER GLASS	New	240.00	0.00
7	REMOVE AND INSTALL REAR DOOR PARTS	New	90.00	0.00
8	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
9	REMOVE AND INSTALL CARPET AND SEAT	New	250.00	60.00
10	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	40.00
11	TO JACK AND ALIGNMENT CHASSIS FRAME MEMBER	New	350.00	0.00
12	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	150.00	60.00
13	REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	280.00	0.00
14	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	90.00	60.00
15	TO SEND VEHICLE TO SEAT RED PLATE PIN	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,720.00</b>	<b>3,790.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;