

Room

NS/INC 1902062/Pvf302

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: **SLK 1839R**  
 Policy No: \_\_\_\_\_  
 Claims No: **MT/1075564-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SHC 2598T** Regn: **13/12/2018**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **TOYOTA PRIUS (54)** CC: **1798**  
 Colour: **blue** A/C: Insured / Std / NI / NA  
 Sp. Reading: **162687** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **JTDKB3FU303077698**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: **175/65 R15**  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **DAVANTI**

Front	Rear
R/Bal. <b>6</b> mm	R/Bal. <b>7</b> mm
L/Bal. <b>6</b> mm	L/Bal. <b>7</b> mm
D.O.A. <b>11/12/19</b>	D.O.I. <b>12/12/19</b>

\*Survey held at **comfort delgro (Loyang)**  
 Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or  
**O/S rear & rear**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO Policy
	SHC 2598T - NS/INC 1902062/Pvf302 D.O.A - 21/12/19
	SLK 1839R - X
	P/P: \$1696.82 / = with 2 repair days (Red 858.03, 33%)
	confirm on 30/12/19 with chang-

Date/Time: File Pass to? ☐ : Prel. Report  
☐ : Final Report

Date/Time: File Return to?

2/1 - typist

Report Form: TP  
 Long Form: P/P \$1696.82

RECEIVED 02 JAN 2020

Days Of Repair: **2**

Resurvey No. of Trip: **1**

And Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Master (\$)

Survey Fee:	<b>160</b>
Transportation:	
\$ + PS: \$	
Fines:	
Other:	
TOTAL	<b>160</b>

TP Claims against NTUC Income: Follow-Through Survey

Date : 31/12/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate
1	MT/1075788-002	COMFORTDELGRO ENGINEERING PTE LTD	SHC8084U	SHC6228K	14/12/2019	\$4,366.00
2	MT/1075792-002	COMFORTDELGRO ENGINEERING PTE LTD	SH6184X	F8H2812U	14/12/2019	\$1,837.15
3	MT/1076043-002	COMFORTDELGRO ENGINEERING PTE LTD	SHC8437K	F8D7783H	14/12/2019	\$4,762.04
4	MT/1076556-002	COMFORTDELGRO ENGINEERING PTE LTD	SHA3897J	PC2602U	18/12/2019	\$4,438.18
5	MT/1076543-002	COMFORTDELGRO ENGINEERING PTE LTD	SHC3149A	SHD1402B	20/12/2019	\$5,189.00
6	MT/1078050-001	COMFORTDELGRO ENGINEERING PTE LTD	SHC1158L	SMP5854G	13/12/2019	\$2,487.55
7	MT/1075564-002	COMFORTDELGRO ENGINEERING PTE LTD	SHC2598T	SLK1839R	11/12/2019	\$2,554.85
8	MT/1076964-002	CITYCAB PTE LTD	SHB3268U	SJR8984E	21/12/2019	\$6,096.10
9	MT/1078051-001	CITYCAB PTE LTD	SHC7563K	GBH2718J	21/12/2019	\$1,815.06
10	MT/1076710-002	COMFORTDELGRO ENGINEERING PTE LTD	SHD3025T	SGE3956M	20/12/2019	\$2,169.06
11	MT/1076220-002	COMFORTDELGRO ENGINEERING PTE LTD	SHD3025T	SLX9236J	16/12/2019	\$2,532.48

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC2598T
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	2ZR2B83850
Chassis No.:	JTDKB3FU303077698
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	13 Dec 2018
First Registration Date:	13 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$19,266.00
<b>Total Rebate Amount:</b>	<b>\$29,951.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Dec 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/12/2019 14:27
Date Of Accident	11/12/2019 10:15
Exact Location Of Accident	MAXWELL RD TWDS MCE X ROBINSON ROAD /ANSON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2598T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	QUAK CHEN TEE(GUO ZHENGZHI)
NRIC No	S7539549C
Date Of Birth	31/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	30/09/1994
Driving Experience	25 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91813127
Fax Number	
Contact Number	
Email Address	J_QUAK@HOTMAIL.COM

Address	BLK 596D ANG MO KIO STREET 52 #26-309
Postcode	564596
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK1839R
Vehicle Make/Model/Colour	MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

LH FRONT

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Date & Time: 11/DEC/2019  
@ 1255 hrs

Reporting Centre Personnel's Signature  
Name: Loke Vvai Yieng  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

11 DEC 2019 @ 1015 HRS

(A) I was waiting for cars in front to clear the yellow box.

Vehicle (B) was on my right, trying to squeeze into my lane

As vehicles in front of me cleared, I move forward slowly and was hit by vehicle B.

A lady passenger was in my vehicle at time of accident

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 11/DEC/2019

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Loke Wei Yeng

@ 1255hrs

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305366572

TOMER

VS COMFORT TRANSPORTATION PTE LTD

TOMER NO. 7010045

RESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

(R) 65508755 (O)

(P)

OUNT CARD NO.

REGN NO.:

SHC2598T

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)12.12.2019 10:15

DATE/TIME IN

YR OF MANU.

13.12.2018

TARGET DATE

CHASSIS CODE

JTDKB3FU303077698


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 11.12.2019

NATURE: 3P 11.12.2019

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHC2598T CHIANG

Vehicle No.: SHC2598T

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 2598T

12/12/2019 10:50

MAKE :

MODEL : TOYOTA PRIUS

Advice

Chong

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <del>1ea</del> <i>cha</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>cut</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>xnn</i>			\$ 112.70
REAR BUMPER CLIPS <del>2ea</del> <i>nee</i> <i>xnn</i>			\$ 22.00
TAIL LAMP ASSY (UPPER) (RH) <i>cha</i>			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) <i>xnn</i>			\$ 548.40
SUB TOTAL			\$ 2,252.20
LESS 25%			\$ 563.05
DISCOUNTED TOTAL			\$ 1,689.15
			<i>\$1193.32</i>
REAR BUMPER REVERSE SENSOR <i>xnn</i>			\$ 135.70
NETT			
<div> LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div>			
LABOUR CHARGE			
Panel Beating			\$ 350.00 <i>\$320</i>
Spray Painting Charge			\$ 250.00 <i>\$200</i>
Wiring Charge			\$ 50.00 <i>xnn</i>
Remove/Refix Reverse Sensor <i>x</i>		<i>\$30</i>	\$ 80.00 <i>xxx</i>
TOTAL LABOUR			\$ 730.00
ESTIMATE TOTAL			\$ 2,554.85

*Ram (LKK)*  
*12/12/19 1350hrs*  
*Parasuram@LKKauto.com*  
*58622778*  
*(2) repair days*  
*part by part*

*add paint + photo*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305366572

Date : 13/12/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : PARAM

: SHC2598T

11/12/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC SLK1839R

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost**

~~\$1193.32~~  
\$1176.82  
\$1,176.82  
\$520.00  
\$1696.82  
\$1,696.82  
~~\$1113.32~~  
PIC signed

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name : Ram

Date : 30/12/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 13.12.2019

Time: 10:23:02

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305366572  
REGN NO : SHC2598T  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 13.12.2018  
DATE/TIME IN : 12.12.2019 10:15  
ACCIDENT DATE : 11.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45	cut
0002 04-01-0302-0585-A	PRIG4 LENS & BODY RR COMB	1	557.90	25.00	418.42	cre
0003 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95	cre
					SUB-TOTAL	: 1,176.82

JOB NATURE

0000 PB	PANEL BEATING	320.00	
0001 SP	SPRAYPAINT CHARGE	200.00	
		SUB-TOTAL	: 520.00

TOTAL : 1,696.82

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

*[Handwritten Signature]*


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19022062/Fvf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 07-01-2020	
			Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLK 1839R	Veh. Inspected	SHC 2598T	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1075564-002	Excess (\$)	0.00	
Assign From		Assign Date	12/12/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU303077698	Colour	BLUE	
Odometer	162687	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	6 mm	
L/H Front Tyre	195/65 R15	DAVANTI	6 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	7 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/12/2019	Inspection Date	12/12/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2598T**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CRACKED	458.60	458.60
1	REAR BUMPER UNDER COVER	CUT	552.60	552.60
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	TAIL LAMP ASSY (UPPER) (RH)	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER) (RH)	NOT NECESSARY	548.40	-
	LESS 25% DISCOUNT		-563.05	-392.28
			1,689.15	1,176.82
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			135.70	-
<b><u>LABOUR</u></b>				
	PANEL BEATING.		350.00	320.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	80.00	-
			730.00	520.00
<b>GRAND TOTAL</b>			<b>2,554.85</b>	<b>1,696.82</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,696.82</b>
--	--	--	-----------------

Report Ref No. NS/INC19022062/Fvf3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.