

ASS. REC. BY:

REF:

CS / AIG 19022071 / Gtf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Winnie Fan

of

AIG

Date/Time:

16/12/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN 96600

Insured:

GBJ 39480

at Workshop m/s

KING'S AUTO

Tel:

6457 8629

of

126 S/M Drive #02 RD S/M Autocare

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Veh's Record)

D.O.A.

12/12/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

16/12/19 @ 16.24h

Person Contacted:

Amie

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimated (X)

SGN 96600 - X

GBJ 39480 - X

Pending estimate by Monday.

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Precise Auto Service [<mailto:Support@preciseauto.sg>]

Sent: Monday, October 14, 2019 12:52 PM

To: Motor Claims SG - SG Common

Subject: (Urgent!!!) Fwd: Pre-repair inspection for SJV 9236T (You Insured vehicle no : SLV 8205)

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for SJV 9236T in our workshop ASAP.

Thank You!

Best Regards
Arine

GRL. | ALG.

ASSIGNMENT

(C-2021)

From _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s King's Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

3	
N/S	O/S

Bal. or Market Value: \$23K.
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 56N9660D Yr Regn: 29 Nov 2011
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: chevrolet cruze 1-6 c.c 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 22609 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KLISA69E9ck 599503
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 16-12-19
 Survey held at w/s 3:15 pm
 Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	CoE: 18157
16/12	Estimate give later.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Inve (\$)
☐ Meal etc (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Other:

TOTAL

Report Format:

Drawn: _____

Summer Lee (LKK Auto)

From: Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Sent: Monday, 16 December, 2019 8:40 AM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt Oref: L19.1498.cj - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ3948U AND SGN9660D ON 12/12/2019

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Kuru & Co <kurulegal@yahoo.com.sg>
Sent: Friday, December 13, 2019 10:41 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: [EXTERNAL] Oref: L19.1498.cj - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ3948U AND SGN9660D ON 12/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

KING'S AUTO REPAIR & SERVICE PTE LTD
Blk 176 Sin Ming Drive
#02-10 Sin Ming Autocare
Singapore 575721
Contact: 6457 8629

Annie
~~KEA~~ ✓
veh in
16/12/19 @ 10.24a
Kenne th

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards

Irene

Kuru & Co


150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	822C
Vehicle No.:	SGN9660D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	F16D4296754KA
Chassis No.:	KL1JA69E9CK599503
Maximum Power Output:	91.0 kW (122 bhp)
Open Market Value:	\$13,556.00
Original Registration Date:	29 Nov 2011
First Registration Date:	29 Nov 2011
Transfer Count:	2
Actual ARF Paid:	\$13,556.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2021
PARF Rebate Amount:	\$7,455.00
COE Expiry Date:	28 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$54,887.00
COE Rebate Amount:	\$10,702.00
Total Rebate Amount:	\$18,157.00

The information contained herein is correct as at 16 Dec 2019

OK

Active

PRI

Keng's Auto

Accident Report – Data Collection – TP/OD/

Insurance Co : DMPPH 19-007403

Vehicle No. : 54N 9660 D

Policy Holder Name : WK Contractor

Model : Chevrolet Cruze 1.6

Nric No.

Date Of Accident : 12-12-2019

Relation :

Time Of Accident : 14:00-10

Location : 339 Ang Mo Kio St 31 (Car park).

HP No. 91048128

Email : Kent.9117@hotmail.com

Weather : Clear/Dry - Drizzling / Wet - Raining / WetOccupation : Indoor or Outdoor

Driver & Passenger : 2 pax

Video Footage : Yes / No1) Passenger Name : Liew weng kwai
Gender : Male / ~~Female~~Injury : Yes / No2) Passenger Name : Kwan Foo Ling
Gender : ~~Male~~ / Female3) Passenger Name :
Gender : Male / Female

Third Party's Particulars :


Vehicle No. : GBJ 3948U Vehicle No. :

Name : Ng leong Hy Name :

Nric : S1247071A Nric :

HP No. : 83497291 HP No. :

SKETCH PLAN



I was waiting behind GBJ 3948U for him to clear the corporate gate. With out any warning, he rev. his lorry & hit onto the front part of my car.

AH LIM MOTOR COMPANY

KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721

TEL: 6457-8629 FAX: 6451-7651

DATE 13th Mar 2020
 OUR REF SGN 9660 D
 Liew Weng Kwai
 TO 319 Ang Mo Kio Avenue 1
 #12-1489
 Singapore 560319

13th Mar 2020
for Liew Kwai
Fax 6451-7651

16/03/2020

RE QUOTATION FOR CHEV Cruze SGN 9660 D

Quantity	Item	Unit Price (S\$)	Amount (S\$)
1	Front Bonnet		1,354.00
2	Front Head Lamp	721.00	1,442.00
1	Front Panel Top Garnish		120.00
1	Front Bumper		920.00
set	Front Bumper Clips		35.00
1	Front Bumper Reinforcement		860.00
2	Front Bumper Side Retainers	6.60	13.20
1	Front Bumper Lower Lip		66.00
1	Front Bumper Sponge		77.00
1	Front Grille Top		183.00
1	Front Grille Casing		283.00
1	Emblem		112.00
1	Front License Plate		35.00
SUB-TOTAL			5,500.20
LESS 10% DISCOUNT			550.02
TOTAL			4,950.18

FOR LABOUR CHARGES

Item	Amount (S\$)
Panel Beating	600.00
Spray Painting	800.00
Wiring	50.00
Rustproof	80.00
TOTAL	1,530.00

GRAND TOTAL FOR THIS QUOTATION 6,480.18

