

ASS. REC. BY:

REF: CS/MSG 19022077/ Evf3n2 Special Instruction: ✓

Survivor: JPRV

ASSIGNMENT (Office)

From (Person): Jasmine Lok King hus of MSG Date/Time: 12.12.19 11.014.m

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PBE 7418H Insured: 4P2064Yat Workshop m/s HKL Lim Tel: 92423895of Blk 1006 #01-24 Bukit Merah Lane 3Policy No: 28913521 Claim No: 587373

Sum Insured: Excess:

Make of Veh: D.O.A. 8.3.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 16.12.19 12.58a.m Person Contacted: James H.O.D. Endorsement:Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>PBE 7418H - NBA / INCL 19/12/2019 / Y Don - 08/03/2019</u>
	<u>4P 2064Y - NBA / INCL 19/12/2019 / Y Don - 08/03/2019</u>
<u>17/12/19</u>	<u>Send preli revised via merimen</u>
<u>21/12/20</u>	<u>@ 240pm James said vehicle not repair yet, pending liability</u>

Surveyor **Steve**

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OO / TP / WS / TP RES / OO RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR. Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **FBE 7418H** Yr Regn: **2010**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Yamaha RX 2135** c.c. **133**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp. Reading: **72888** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **PMYSPY190A9032907**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Locked / Burnt or
 Brake: In order / Jammed / Locked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **70/80-17**
 R: **80/90-17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. **5** mm R/Bal. **5** mm
 L/Bal. _____ mm L/Bal. _____ mm
 O.O.A. **8/3/19** O.O.I. **16/12/19**
 Survey held at **HKL Lim**
 Des. of Damages **Frnt** / Rear / **O/S** / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/12/19	Inform HKL Lim James, get log card. (PART value cannot check)
30/5/20	Final: \$2000 (LS), 5 days (James) (Red 5705, 7490)

RECEIVED 31 MAR 2020

Date/Time, File Pks to? ☐ : Procl. Report
☐ : Final Report

1) _____ Date/Time, File Return to?

2) 31/3 - typist

Report Format: **Merimen**
 Lump Sum / L.B.I: (\$) **2000**

Days Of Repair: **5**
 Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech Insp (\$) ☐ : Weekend (\$)

Survey Fee:

Transportation:

_____ S - RS - SI

_____ P/Bal

_____ Others

TOTAL

150
11

161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jasmine Lok Kheng Kwei	Date: 17 Dec 2019
<u>Preliminary Advice</u>	

Insured Vehicle No : YP2064Y	
TP Vehicle No : FBE7418H	Accident Date : 08/03/2019
Make : YAMAHA RXZ135	Assignment Date : 16/12/2019
Date of Inspection : 16/12/2019	Est. Duration of Repair : 5
Inspection At : HKL LIM TEAM MOTORSPORT	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,705.00
Revised Amount	:S\$	4,399.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,399.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Dis Auth'd	Status
Main	13 Mar 2019		16 Dec 2019 11:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HUA SIAH CONSTRUCTION PTE LTD, Co. Reg. No.: 198105429E								
Main Claimant:	NORIZAM BIN JUMAAD, ID: S86204781								
Vehicle Reg. No.:	FBE7418H	Date of Loss:	08/03/2019 18:00 - :59 [102 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 587373	Policy/Cover Note No.:	28913529 (Comprehensive) Coverage: 04/04/2018 - 03/04/2019						
Vehicle Reg. No. (Insured):	YP2064Y	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Hkl Lim Team Motorsport (HQ) BLK 100B #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/12/2019]								
Driver/Custodian (Insured):	NG WU TECK (), NRIC: S0210747C, Tel: +6598833959 Email:								
Adj Asg. Remarks:	on WP. (Manual Assign) Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: James @ 9242 3895 / 6275 6656.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Vehicle No.
FBE7418H

Make / Model
YAMAHA / RXZ

Vehicle Type:

P00 - Passenger Motorcycle/Autocycle/Moped

Vehicle Attachment 1:

No Attachment

Vehicle Scheme:

Normal

Chassis No.:

PMY5PV100A0032907

Propellant:

Petrol

Engine No.:

5PV032907

Motor No.:

-

Engine Capacity:

133 cc

Power Rating:

-

Maximum Power Output:

-

Maximum Laden Weight:

-

Unladen Weight:

106 kg

Year Of Manufacture:

2010

Original Registration Date:

25 Aug 2010

Lifespan Expiry Date:

-

COE Category:

D - Motorcycle

Quota Premium:

\$1,251.00

COE Expiry Date:

24 Aug 2020

Road Tax Expiry Date:

-

PARF Eligibility Expiry Date:

-

Lay-up Expiry Date:

24 Aug 2020

Inspection Due Date:

03 Dec 2020

Intended Transfer Date:

30 Mar 2020

CO2 Emission:

CPV/VES Rebate/Filled Amount:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/12/2019 16:03
Date Of Accident 06/03/2019 18:00
Exact Location Of Accident SENCKO SOUTH ROAD TOWARDS WOODLANDS AVENUE 8
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBE7418H
Insured/Policyholder
Name Of Registered Owner NORIZAM BIN JUMAAD
NRIC No S86204781
Email Address NOR_ZAYIE@YAHOO.COM.SG
Mobile Phone No (LOCAL) +65-93272600
Alternative Phone No OTHERS-93272600

Vehicle Particulars

Manufacturer YAMAHA
Model RXZ135-133CC (M)
Exact Purpose for which vehicle was being used at time of accident ON THE WAY HOME

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5071272524-03
Cover Note Number

Driver

Name of Driver JUMAAD BIN MALEK
NRIC No S0519326E
Date Of Birth 13/09/1947
Occupation INDOOR
Date Of Driving Pass 14/03/1999
Driving Experience 49 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-93272600
Fax Number
Contact Number OTHERS-93272600
Email Address NOR_ZAYIE@YAHOO.COM.SG

Page 1 of 26

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name

Page 2 of 26

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name JUMAAD BIN MALEK

Approximate Age

Injuries Sustain DIED AT THE SCENE

Injured person in which vehicle? FBE741BH

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

15/12/14
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

06/07/15
Reporting Center Personnel's Signature
Name: Resh
NRIC/FIN No: 123456789

SKETCH PLAN

REFER TO ATTACH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT
1/20/19/206/2100

DECLARATION

I/We declare the foregoing particulars are true in every respect.


1542ms 6/2/19

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

06/4/2019
Reporting Centre Person's Signature
Name:
NRIC/TIN No:

8.3.2019



06/12/2018
Road Works



**SINGAPORE
POLICE FORCE**



T/20191206/2100

1 of 3

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20191206/2100

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/12/2019 15:19		Vide Report No.:		Station Diary No.: 49	
Informant's Particulars					
Name of Informant: NORIZAM BIN JUMAAD			Address: APT BLK 540 WOODLANDS DRIVE 16 #06-77 SINGAPORE 730540		
ID Type / ID No.: NRIC NO / S85204781			Contact No.: Home/Office:		Mobile: 93272600
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 25/07/1988	Type of Informant: Vehicle Owner		
Race: Boyanese			Language:		Institution / School Name:
Occupation: TRACK RIDER			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Fatal Others	Drink Drive: No	Date/Time of Accident: 08/03/2019 18:00	Type of Location:
Location: Along Road 1 Traveling Toward Road 2 SENOKO SOUTH ROAD WOODLANDS AVENUE 8 ALONG SENOKO SOUTH ROAD TOWARDS WOODLANDS AVENUE 8 IN FRONT OF UNIT: 23 NEAR LP 10				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBE7418H	Motorcycle					0
YP2064Y	Lorry					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191208/2100

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

3 of 3

Report No. T/20191208/2100

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan



IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 3 DAMIEN LEONG JUN SIAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
06/12/2019 15:19

Officer In Charge Of Case:
TP / FAIT /
SI DZUL HAIRIE BIN RAMLI
Contact No.: 65476220

Classification Of Case:

Authentication Stamp
NP168



**SINGAPORE
POLICE FORCE**



T/20191206/2100

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

2 of 3
Report No: T/20191206/2100

CONTINUATION OF REPORT

Rider			
Name	JUMAAD BIN MALEK	ID No.	S0519326E
Related Vehicle	FBE7418H (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Fatal
Vehicle Owner			
Name	NORIZAM BIN JUMAAD	ID No.	S8620478I
Related Vehicle	NIL	Contact No.	93272600
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I am the vehicle owner of FBE7418H and I share the bike with my father.

On the 8th March 2019, my father had used my bike to travel to work. At about 1802hrs, my father was travelling along Senoko South Road towards Woodlands Avenue 6, on the way back home. However, he met with a fatal accident in front of unit 23, near LP 10 along that road.

My sister contacted me that day to inform me that my father was pronounced dead at the scene itself due to multiple injuries. The IO namely Dzul Hairie Bin Ramli, Senior Investigation Officer from Traffic Police had also contacted me and my family for follow up. I am lodging this report as my bike workshop required a police report from me. I wish to inform that my bike was badly damaged. The reference number to the case is TP/IP/13815/2019 & CI-000779-2019-TA



HKL LIM
TEAM MOTORSPORT

Blok 100B #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklmteam.com.sg Website: www.hklmteam.com.sg

FBE7418H

1 LAMP STAY / OT	\$ 60.00 ✓
2 METER ASSY / OR	\$ 450.00 350 ✓
3 FRONT FORK ASSY LH/RH / OR	\$ 400.00 ✓
4 FRONT FORK UNDER BRACKET / OT	\$ 150.00 ✓
5 STEERING CONE BEARING / MC	\$ 60.00 ✓
6 BODY FRAME ALIGNMENT x (total repair)	\$ 550.00 300 ✓ (labor)
7 FRONT FENDER / OR	\$ 55.00 ✓
8 FRONT WHEEL RIM / OT	\$ 180.00 ✓
9 FRONT WHEEL SHALF / OT	\$ 45.00 ✓
10 FRONT WHEEL BEARING 2PCS / MC	\$ 40.00 ✓
11 FRONT WHEEL BEARING OIL SEAL / MC	\$ 10.00 ✓
12 FRONT BRAKE DISC / OT	\$ 150.00 ✓
13 FRONT BRAKE CALIPER / CAT	\$ 250.00 ✓
14 HEAD COWLING / OR	\$ 150.00 ✓
15 FRONT SIGNALS LH / RH / OR	\$ 90.00 ✓
16 IU UNIT / OR	\$ 170.00 ✓
17 IU BRACKET / OT	\$ 25.00 ✓
18 HANDLE BAR / OT	\$ 150.00 135 ✓
19 HANDLE BAR GRIP x N/A	\$ 20.00 x
20 HANDLE BAR BALANCER x N/A	\$ 40.00 x
21 WINDSHIELD / OR	\$ 35.00 ✓
22 FRONT NO PLATE / OR	\$ 10.00 ✓
23 BRAKE LEVER x N/A	\$ 20.00 x
24 CLUTCH LEVER x N/A	\$ 20.00 x
25 SIDE MIRROR / OR	\$ 35.00 ✓
26 HEAD LIGHT / OR	\$ 120.00 ✓
27 BRAKE PEDAL / OT	\$ 80.00 ✓
28 FRONT FOOT REST / OT	\$ 60.00 ✓
29 FRONT BRAKE HOSE / TN	\$ 150.00 ✓
30 FUEL TANK x N/A	\$ 2,320.00 x
31 EXHAUST PIPE / OT	\$ 580.00 ✓
32 SPEEDER CABLE TN	\$ 30.00 ✓
33 RPM CABLE x N/A	\$ 30.00 x
34 TAIL BOARD / CAT	\$ 120.00 ✓
35 TOP BOX / OR	\$ 150.00 ✓
36 TOP BOX BRACKET / OT	\$ 150.00 ✓
37 TOWING / MC	\$ 50.00 40 ✓ (100)
38 LABOUR	\$ 700.00 500 ✓ (100)
TOTAL	\$ 7,705.00 840

P- 3456

L- 840

4296

L15- 3436.80

= 3450

3840

-10%

3456

17/12/19

STERN (LKK)

8333 8813

WOL M/L

16/12/19, 2:30pm

5 days

L/S

By Mr. Jy

limit repair 2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve Chen (LKK Auto)

From: HKL Lim Team Motorsport <hklteam@gmail.com>
Sent: Monday, March 30, 2020 9:52 AM
To: Steve Chen (LKK Auto)
Subject: Re: FBE7418H Repair Limit

okay agree

On Mon, 30 Mar 2020, 9:27 am Steve Chen (LKK Auto), <SteveChen@lkkauto.com> wrote:

Dear James,

Kindly confirm the finalize \$2000 (L/S, before GST). 5 repair days.

Thanks.

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19022077/EVF3N2

Date: 02/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28913529

Claimant Vehicle No : FBE7418H

Insured Vehicle No : YP2064Y

Date of Loss: 08/03/2019

Nature of Claim: TP Claim No: 587373

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE7418H

Make & Model: YAMAHA RXZ135, 133cc (M)

Engine No: 5PV032907

Reg. Date: 25/08/2010 (Man. Year: 2010)

Chassis No: PMY5PV100A0032907

Colour: Black

Odometer: 72888 km

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/80-17

Rear Tyre Size: 80/90-17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,405.00	3,456.00	2,949.00	46.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	840.00	460.00	35.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,705.00	4,296.00	3,409.00	44.24
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	7,705.00	2,000.00	5,705.00	74.04

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 16/12/2019 Inspected At:

Hkl Lim Team Motorsport (HQ)
BLK 1008 #01-24 BUKIT MERAH LANE 3
Singapore 159722

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Apr 2020)	
Parts:	N/A	YAMAHA RXZ135 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE7418H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP STAY	Bent	60.00 F	*60.00 FL
2	1		*METER ASSY	Broken	450.00 F	*350.00 FL
3	2		*FRONT FORK ASSY LH/RH	Broken	400.00 F	*400.00 FL
4	1		*FRONT FORK UNDER BRACKET	Bent	150.00 F	*150.00 FL
5	1		*STEERING CONE BEARING	Necessary	60.00 F	*60.00 FL
6	1		*FRONT FENDER	Broken	55.00 F	*55.00 FL
7	1		*FRONT WHEEL RIM	Bent	180.00 F	*180.00 FL
8	1		*FRONT WHEEL SHALF	Bent	45.00 F	*45.00 FL
9	1		*FRONT WHEEL BEARING 2PCS	Necessary	40.00 F	*40.00 FL
10	1		*FRONT WHEEL BEARING OIL SEAL	Necessary	10.00 F	*10.00 FL
11	1		*FRONT BRAKE DISC	Bent	150.00 F	*150.00 FL
12	1		*FRONT BRAKE CALIPER	Cut	250.00 F	*250.00 FL
13	1		*HEAD COWLING	Broken	150.00 F	*150.00 FL
14	2		*FRONT SIGNALS LH/RH	Broken	90.00 F	*90.00 FL
15	1		*IU UNIT	Broken	170.00 F	*170.00 FL
16	1		*IU BRACKET	Bent	25.00 F	*25.00 FL
17	1		*HANDLE BAR	Bent	150.00 F	*135.00 FL
18	1		*HANDLE BAR GRIP	Not Necessary	20.00 F	*- FL
19	1		*HANDLE BAR BALANCER	Not Necessary	40.00 F	*- FL
20	1		*WINDSHIELD	Broken	35.00 F	*35.00 FL
21	1		*FRONT NO PLATE	Broken	10.00 F	*10.00 FL
22	1		*BRAKE LEVER	Not Necessary	20.00 F	*- FL
23	1		*CLUTCH LEVER	Not Necessary	20.00 F	*- FL
24	1		*SIDE MIRROR	Broken	35.00 F	*35.00 FL
25	1		*HEAD LIGHT	Broken	120.00 F	*120.00 FL
26	1		*BRAKE PEDAL	Bent	80.00 F	*80.00 FL
27	1		*FRONT FOOT REST	Bent	60.00 F	*60.00 FL
28	1		*FRONT BRAKE HOSE	Torn	150.00 F	*150.00 FL
29	1		*FUEL TANK	Not Necessary	2,320.00 F	*- FL
30	1		*EXHAUST PIPE	Bent	580.00 F	*580.00 FL
31	1		*SPEEDER CABLE	Torn	30.00 F	*30.00 FL
32	1		*RPM CABLE	Not Necessary	30.00 F	*- FL
33	1		*TAIL BOARD	Cut	120.00 F	*120.00 FL
34	1		*TOP BOX	Broken	150.00 F	*150.00 FL
35	1		*TOP BOX BRACKET	Bent	150.00 F	*150.00 FL

F=Franchise part, L=ListitemDisc.

Sub Total (\$\$)	6,405.00	3,840.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	384.00
Total Parts (\$\$)	6,405.00	3,456.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY FRAME ALIGNMENT	New	550.00	300.00
2	TOWING	New	50.00	40.00
3	LABOUR	New	700.00	500.00
Gross Labour Cost (S\$)			1,300.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >