

ASS. REC. BY:

REF: CS/A1G 1022/19/H S 1321 Special Instruction:

SURVEYOR:

Hock Ann

## ASSIGNMENT (Office)

From (Person): Winnie Fan of A1G Date/Time: 16.12.19 3.49p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 6935T Insured: SMM 6761A

at Workshop m/s Green Star Spray Tel: 65463092

of BIK 3011 Bator North Brix 4 #01-2004

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 5.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 16.12.19 4.20p.m. Person Contacted: Jan H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SGH 6935T - X
	SMM 6761A - X
	17/12/19 - survey taken
	18/12/19 - Re-survey taken
	- pending workshop involved (after part photo)

ASS-REC. BY:

REF: AIG

PRS

## ASSIGNMENT

From: \_\_\_\_\_ Date: 17.12.2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGH 6933T

at Workshop m/s Green star spray  
of BIK 3011 Belok Mah Awi 4 101-2004

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGH 6933T Yr Regn: 19/06/2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: T. wish C.C. 1794

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 245746 km T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 2NE100306176

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 215/45/R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 77 mm mm R/Bal. 77 mm

L/Bal. 77 mm mm L/Bal. 77 mm

D.O.A. 5/12/19 D.O.I. 18/12/19

Survey held at Green star spray

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \*

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

DAR - 10h

Days → 5

MV - 39000

PV - 29696

NV - 9300

RECEIVED 27 DEC 2019

Date/Time, File Pass to?

27/12/19

1) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 180

Transportation: S + RS. SI

Photos

Others 11

TOTAL 191

Report Format: PRS

Lump Sum / L.B. / C:

## PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMM6761A AND SGH6933T ON 05/12/2019

From: Fan, Winnie-LW  
 To: Admin A, assignments  
 Cc: Fong, Andy-SY  
 Sent: Monday, 16 December, 2019 3:49:26 PM

---

Hi LKK,

Kindly assist to survey.

Winnie Fan  
 AIG  
 Claims Service Associate  
 Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** [jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg) <[jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg)>  
**Sent:** Monday, December 16, 2019 11:16 AM  
**To:** AIG SGP, Claims-Survey <[AIGSGP\\_ClaimsSurvey@aig.com](mailto:AIGSGP_ClaimsSurvey@aig.com)>  
**Cc:** 'Jerdine' <[jerline.wang@alt.sg](mailto:jerline.wang@alt.sg)>; [vincent@alt.sg](mailto:vincent@alt.sg); [allister@alt.sg](mailto:allister@alt.sg); [sales@greenstarsp.com](mailto:sales@greenstarsp.com)  
**Subject:** [EXTERNAL] PRI - SGH 6933 T

This message is from an external sender; be cautious with links and attachments.

Your Ref: SMM 6761 A

Our Ref: AL.INS.2019.SGH6933T

16 December 2019

AIGASIA PACIFIC INSURANCE PTE. LTD. **BY EMAIL ONLY**  
 78 Shenton Way  
 Tower 2 #07-16  
 Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING SGH 6933 T & SMM 6761 A ALONG GEYLANG LORONG 16 ON 5 DECEMBER 2019 AT ABOUT 2110 HOURS**

We act for the owner of vehicle no. SGH 6933 T.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

**GREEN STAR SPRAY PAINTING**  
 Blk 3011 Bedok North Avenue 4  
 #01-2004 Bedok Industrial Park E  
 Singapore 489977  
 Person In-Charge: Jane  
 Mobile Number: 6546 3092

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at [jjiamin.mak@alt.sg](mailto:jjiamin.mak@alt.sg) / [jerdine.wang@alt.sg](mailto:jerdine.wang@alt.sg) for future correspondences.

*\* Kindly be reminded of the change of our address as stated below.*

Best Regards,

**Jiamin**

For and on behalf of  
Allister Lim

**ALLISTER LIM & THRUMURGAN  
ADVOCATES & SOLICITORS**

1 Coleman Street  
#05-01, The Adelphi  
Singapore 179803  
Telephone : 6422 2187  
Facsimile : 6438 1211

*Email Confidentiality Warning:*

*This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at [mail@alt.sg](mailto:mail@alt.sg) and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	049B
<b>Vehicle Details</b>	
Vehicle No.:	SGH6933T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1ZZ2569668
Chassis No.:	ZNE100306176
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,674.00
Original Registration Date:	19 Jun 2006
First Registration Date:	19 Jun 2006
Transfer Count:	3
Actual ARF Paid:	\$20,542.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$29,696.00
<b>Total Rebate Amount:</b>	<b>\$29,696.00</b>

The information contained herein is correct as at 19 Dec 2019

OK



## CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

### New 5 Years Renewal COE Toyota Wish 1.8A



2.88% P.A., \$0 Admin, Monthly  
From \$688, 7 Years Warranty  
Engine And Gearbox  
GV Credit StarAd



VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND

HOTLINE: 6741 9997

[view our](#)
[Browse by Category](#)

52 vehicles

Search Selection



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Toyota	Wish 1.8A (New 10-yr COE)	Any	Any	Any	Any	Any	Any	

Toyota Wish 1.8A (New 10-yr COE)

\$64,800

\$6,470 /yr

23-Dec-2009

1,797 cc

125,000 km

MPV

Av

1 Year In House Warranty (Official Certificate), Full Loan Available, Free 2 x Servicing, Price Stated Above Is Actual Selling Price, Accident Free, STA Or VICOM Evaluation Are Welcome, All Refurbished Works Done "Under One Roof", New Paintwork, Bank And In House Loan...

Carway

Posted: 19-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (New 10-yr COE)

\$63,800

\$6,370 /yr

29-Jan-2010

1,797 cc

-

MPV

Av

New Paintwork. No Repair Needed. 100% Accident Free. Most Preferred Choice For COE Renewal MPV. Due To It's Reliability. Low Maintenance. Smooth Engine And Gearbox Transmission. Clean And Tidy Interior. Just View To Believe! Transparent Dealing With Honest...

Posted: 19-Dec-2019 Tags: 2010 Toyota Wish, 2010 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (New 10-yr COE)

\$59,800

\$5,980 /yr

30-Oct-2009

1,797 cc

120,000 km

MPV

Av

Owned This Car With 95% Loan Of The Car Price As Showed, 6 Months Warranty. New Paintwork, Call Now For Viewing.

Posted: 18-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (New 10-yr COE)

\$58,800

\$5,880 /yr

23-Feb-2010

1,797 cc

-

MPV

Av

No More Worries About Transfer Of Ownership, Immediate Transfer Can Be Done When You Collect The Vehicle! Lowest Price In Market, Full Loan Available! Low Drive Away! Phv Loan Available! Inhouse Loan And Bank Loan Available! Monthly \$1k++ Onwards, Call Or What...

Posted: 17-Dec-2019 Tags: 2010 Toyota Wish, 2010 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



### Xenon HID Light (With Slim Ballast)

Super Bright HID Light with Slim Ballast . Warranty Covered ! Grab it Today ! Best Performance !

More info about this product



Toyota Wish 1.8A X (New 10-yr COE)

\$60,800

\$6,080 /yr

18-Dec-2009

1,797 cc

106,730 km

MPV

Av

Smooth Engine, Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.

Posted: 17-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (OPC) (New 10-yr COE)

\$59,888

\$5,980 /yr

18-Aug-2009

1,797 cc

102,000 km

MPV

Av

ving Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! cks! Trade-In Welcome! Not The Cheapest But Definitely The Best Value For Money Drive! Well Maintained, Excellent Conditio...

JDM Cars

Posted: 15-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$62,800****\$6,270 /yr****21-Jan-2010****1,797 cc****128,000 km****MPV****Av**

The Best Coe Loan Packages In Town! Call To Enquire! 1 Owner Only Sporty Red Wish! Well Taken Care By Previous Owner! Regular Servicing And Maintenance Done Without Fail! Most Wear & Tear Parts Changed! STA Strongly Recommend! 100% Loan Approval! Call...



Posted: 14-Dec-2019 Tags: 2010 Toyota Wish, 2010 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$59,800****\$5,980 /yr****02-Dec-2009****1,797 cc****-****MPV****Av**

Full Loan Available At \$1k Plus, We Can Help To Conver To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Wee...



88 Motor Trading

Posted: 14-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$59,300****\$5,930 /yr****24-Aug-2009****1,797 cc****-****MPV****Av**

Accredited Company! New Model! Low Mileage Done! Done 10,800km Per Annum Only! Brand New Paintwork! Upgraded 16" S/Rims With Almost New Tyres x 4! Upgraded Pioneer DVD With R/Camera! Most Reliable, Spacious/Fuel Efficiency MPV For You And Your Family! M...

Fu Yip Motor Trading

Posted: 14-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****-****N.A****29-Dec-2009****1,797 cc****-****MPV****5**

100% Loan Available! Well Kept And Maintained By Previous Owner, Original Paintwork With Clean And Neat Interior! 100% Loan Approval With Our Flexible In House Financing. All Enquiries Are Welcome Thru Call Or WhatsApp!

Posted: 14-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Audio Upgrade for Any Budget**

Enhance your in-car entertainment with a headunit upgrade. Choose from 400+ units. Prices from just \$170!

Find out more!

**Toyota Wish 1.8A X (New 10-yr COE)****\$59,888****\$5,980 /yr****24-Aug-2009****1,797 cc****98,000 km****MPV****Av**

95% Loan Amount As Advertised! Meticulously Well Taken Care Of By Previous Owner With Smooth Running Engine! Very Low Mileage Done! Immaculate Condition Assured! Depreciation Is Even Cheaper Not To Be Miss! Our Company Provide Various Loan Scheme With L...

Creative Auto

Posted: 12-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$59,800****\$5,980 /yr****12-Dec-2009****1,797 cc****-****MPV****Av**

New 10 Years COE! Full Loan Available At \$1k+ Monthly! We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Avail...

88 Motor Trading

Posted: 11-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****-****N.A****15-Aug-2009****1,797 cc****-****MPV****5**

Just Arrived! New 10 Years COE. Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Posted: 10-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****-****N.A****26-Mar-2010****1,797 cc****-****MPV****5**

Only 1 Owner With Low Mileage Done! Full Loan Available! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! Accident-Free Quality Pre-Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexible In House Finan...

Cosmo Automobiles

Posted: 09-Dec-2019 Tags: 2010 Toyota Wish, 2010 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

**Toyota Wish 1.8A X (New 10-yr COE)****\$56,988****\$5,690 /yr****11-Dec-2009****1,797 cc****-****MPV****Av**

7 Seater MPV, Great Fuel Efficient And Reliable, Most Wear And Tear Parts Replaced, No Further Repair Needed, Optional 3rs COE At \$38800, Very Well Maintained, Do Not Miss, Call Now.

Compare

COPIES

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/12/2019 16:16
Date Of Accident	05/12/2019 21:10
Exact Location Of Accident	ALONG GEYLANG LOR 16
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH6933T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMED FADIL BIN ABDUL RAHMAN
NRIC No	S8133049B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84681364
Alternative Phone No	OFFICE-84681364

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MA006025
Cover Note Number	10/10/2019-09/10/2020

### Driver

Name of Driver	MOHAMED FADIL BIN ABDUL RAHMAN
NRIC No	S8133049B
Date Of Birth	07/11/1981
Occupation	INDOOR
Date Of Driving Pass	22/12/2014
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84681364
Fax Number	
Contact Number	OFFICE-84681364
Email Address	NOEMAIL



Address	BLK 52 LORONG 6 TOA PAYOH #05-54
Postcode	310052
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NOR QASRINA GENDER: : FEMALE
Passenger 2	NAME: : NORAINI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGI N.P.C
Police Station Address	ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE 05/12/2019 AT AROUND 9PM, I WAS DRIVING ALONG THE SAID ROAD. THE OTHER VEHICLE WAS ABOUT TO DROP THE PASSENGER AND WAS ON THE LEFT SIDE OF THE ROAD. THE ROAD IS A ONE LANE ONE WAY ROAD WHICH IS WIDE. I MANAGED TO OVERTAKE THE VEHICLE AND WHILE I WAS OVERTAKING, THE PASSENGER OF THE OTHER VEHICLE OPEN THE REAR RIGHT DOOR AND HIT ONTO MY LEFT SIDE AND CAUSE DAMAGES TO MY LEFT SIDE MIRROR, FENDER AND DOOR. DURING THE ACCIDENT, MY 6 YEAR OLD DAUGHTER GOT HURT DUE TO THE E BRAKE I HAD TO APPLY. I WAS ALSO INJURED. I WAS WILL BE GOING TO THE DOCTOR AND HAVE A MEDICAL CHECK UP WITH MY DAUGHTER AS WELL.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM6761A
-----------------------------	----------

Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number 93686128  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1


Name MOHAMED FADIL BIN ABDUL RAHMAN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SGH6933T  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name NOR QASRINA  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SGH6933T  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

Geplung bang 16

Veh B SMM6761A



Refer to GIA report

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

	Reporting Only
	Claim OD
	Claim TP
	Claim OD/TP at other workshop

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_





Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 06/12/2019 17:29	Vide Report No.: G/20191205/0176	Station Diary No.: 46
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: MOHAMED FADIL BIN ABDUL RAHMAN			Address: APT BLK 52 LORONG 6 TOA PAYOH #05-54 SINGAPORE 310052		
ID Type / ID No.: NRIC NO / S8133049B			Contact No.: Home/Office: Mobile: 84681364		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 07/11/1981	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/12/2019 21:00	Type of Location: Straight Road
Location: Along Road 1 LORONG 16 GEYLANG				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGH6933T	Car	TOYOTA	WISH 1.8 A	Silver	Seriously Damaged	3
SMM6761A	Car					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGH6933T	ETIQA INSURANCE BERHAD	MA006025	10/10/2019	09/10/2020



Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	MOHAMED FADIL BIN ABDUL RAHMAN	ID No.	S8133049B
Related Vehicle	SGH6933T (Car)	Contact No.	84681364
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Passenger</b>			
Name	Nor Qasrina Amirah	ID No.	NIL
Related Vehicle	SGH6933T (Car)	Contact No.	84681364
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On the 05/12/2019 at around 9pm, I was driving along the said road. The other vehicle was about to drop the passenger and was on the left side of the road. The road is a one lane one way road which is wide. I managed to overtake the vehicle and while I was overtaking, the passenger of the other vehicle open the rear right door and hit onto my left side and cause damages to my left side mirror, fender and door. During the accident, my 6 year old daughter got hurt due to the e brake I had to apply. I was also injured. I will be going to the doctor and have a medical check up with my daughter as well.



Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

Report No. T/20191206/2145

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sr Staff Sgt DZULHILMI BIN OMAR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

06/12/2019 17:29

Classification Of Case:





Condition (L) (D) (C) (S) (R) (N) (A) (G)

(1) Intact (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(7) Deformed (8) Shattered (9) Broken (10) Missing (11) Non-existent (12) Missing  
(13) Loose (14) Unfastened (15) Not Working

# MOTOR CAR (LH)

ACTION (AG)

(1) Replace (✓) (2) Repair (X) (3) Check (V)  
(4) Not Consistent (NC)

Aug 2005

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror Assy			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar A			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1000	991300	Frt Bumper			
1001	991325	Frt Bumper Bracket			
1002	991462	Frt Bumper Side Retainer			
1003	991433	Frt Bumper Reinforcement			
1004	991468	Frt Bumper Sponge			
1005	991427	Frt Bumper Protector			
1006	991301	Frt Bumper Moulding			
1007	991407	Frt Bumper Lower Spoiler			
1008	995153	Frt LH Headlamp Assy			
1009	995088	Frt LH Side Lamp			
1010	995070	Frt LH Fender			
1011	995147	Frt LH Fender Lamp			
1012	995148	Frt LH Fender Protector			

Vehicle No:

SGH 6933T

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1013	992958	Rear Bumper			
1014	992976	Rear Bumper Bracket			
1015	993068	Rear Bumper Side Retainer			
1016	993045	Rear Bumper Reinforcement			
1017	993077	Rear Bumper Sponge			
1018	993040	Rear Bumper Protector			
1019	993026	Rear Bumper Moulding			
1020	993023	Rear Bumper Lower Spoiler			
1021	993851	Rear LH Taillamp			
1022	993436	Rear LH Fender			
1023	993449	Rear LH Fender Protector			
1024	990247	Sticker			
		Frt quarter Glass LH			
		monkey			

No of Items:

Assessor:

A-ANN



(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary  
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

# MOTOR CAR (UC)

(1)Replace (✓) (2)Repair (X) (3)Check (?)  
(4)Not Consistent (NC)

## Undercarriage

Vehicle No:

SGH 69337

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing	CR	✓	1
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1407	993719	Rear LH Shock Absorber			
1408	993723	Rear LH Shock Absorber Mounting			
1409	993170	Rear LH Coil Spring			
1410	993550	Rear LH Knuckle Arm			
1411	993551	Rear LH Knuckle Arm Bearing			
1412	993597	Rear LH Lower Arm			
1413	993884	Rear LH Upper Arm			
1414	995161	Rear LH Drive Shaft			
1415	995216	Rear LH Control Arm			
1416	993881	Rear LH Trailing Arm			
1417	993573	Rear LH Leaf Spring			
1418	992941	Rear LH Brake Disc Rotor			
1419	992937	Rear LH Brake Caliper Assy			
1420	990434	Rear LH Brake Pipe			
1421	992946	Rear LH Brake Hose			
1422	993819	Rear Sub Frame			
1423	993820	Rear Sub Frame Mounting			
1424	992813	Rear Anti Roll Bar			
1425	990168	Rear Anti Roll Bar Linkage			
1426	990202	Axle Beam			
1427	990170	Rear Axle Panhard Rod			
1428	990810	Differential Assy			
1429	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			
		Frt sport rim 2/H	scr	✓	1

No of Items:

Assessor:

H-ANN

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2019 <a href="#">Edit Reg</a>		16 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$S\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	BIS MOTORING PTE LTD, Co. Reg. No.: 201735055D								
Main Claimant:	MOHAMED FADIL BIN ABDUL RAHMAN								
Vehicle Reg. No.:	SGH6933T	Date of Loss:	05/12/2019 00:00 - :59 [161 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0293692217SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SMM6761A	Policy No. (Claimant):							
		Excess:							
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 26/12/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (17/12/2019): TP GIA report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGH6933T (0293692217SG)  
[SMM6761A]  
TP  
MOHAMED FADIL BIN ABDUL RAHMAN  
Dec 5 2019 12:00AM  
[BIS MOTORING PTE LTD]  
GREEN STAR SPRAY PAINTING

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	27/12/19 15:13	Chassis Number														Load JPG	<input checked="" type="checkbox"/>	
2	27/12/19 15:13	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>	
3	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
4	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
5	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
6	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
7	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
8	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
9	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
10	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
11	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
12	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
13	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
14	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
15	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
16	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
17	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
18	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
19	27/12/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>	
20	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
21	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
22	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
23	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
24	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
25	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
26	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
27	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
28	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
29	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
30	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
31	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
32	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
33	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
34	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
35	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
36	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
37	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
38	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
39	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
40	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
41	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
42	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	
43	27/12/19 15:14	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	27/12/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	27/12/19 15:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/12/19 15:08	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022119/HSF3E2

Date: 30/12/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

#### Claimant

Vehicle No : SGH6933T

Insured Vehicle No : SMM6761A

Date of Loss: 05/12/2019

Nature of Claim: TP

Claim No: 0293692217SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH6933T

Make &amp; Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2569668

Reg. Date: 19/06/2006 (Man. Year: 2006)

Chassis No: ZNE100306176

Colour: Silver

Odometer: 245746 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 18/12/2019 Inspected At:

GREEN STAR SPRAY PAINTING (HQ)

BLK 3011 BEDOK NORTH AVENUE

4 #01-2004 BEDOK INDUSTRIAL

PARK E

Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*SET FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER L/H	Crushed	0.00 F	*- F
4	1		*FRT LH FENDER	Bent	0.00 F	*- F
5	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*- F
6	1		*FRT LH FENDER LAMP	Repair	0.00 F	*- F
7	1		*FRT LH FENDER INNER SHIELD	Crushed	0.00 F	*- F
8	1		*FRT LH DOOR	Bent	0.00 F	*- F
9	2		*FRT LH DOOR HINGE	Crushed	0.00 F	*- F
10	1		*FRT LH DOOR WING MIRROR ASSY	Cracked	0.00 F	*- F
11	1		*FRT LH DOOR GLASS OUTER MOULDING	Scratched	0.00 F	*- F
12	1		*FRT LH DOOR GLASS	Scratched	0.00 F	*- F
13	1		*FRT LH DOOR RUBBER	Necessary	0.00 F	*- F
14	1		*FRT LH DOOR OUTER PILLAR A	Repair	0.00 F	*- F
15	1		*FRT QUARTER GLASS L/H	Scratched	0.00 F	*- F
16	1		*FRT QUARTER GLASS MOULDING L/H	Necessary	0.00 F	*- F
17	1		*FRT LH KNUCKLE ARM BEARING	Crushed	0.00 F	*- F
18	1		*FRT SPORT RIM L/H	Scratched	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >