

2200000

ASS. REC. BY:

REF: CS/12419022122/Huf3/

Special Instruction:

ck

Surveyor: Hock am

## ASSIGNMENT (Office)

From (Person): Winnie Pan

of

MG

Date/Time:

16/12/19 @ 4.05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 6457G

Insured:

GB0 9043Y

at Workshop m/s

MS CAR AUTO

Tel:

6385 1838 June.

of

8 KAKI BUKIT AVE 4 #01-07 PRELUCE @ KAKI BUKIT

Policy No:

1800073282

Claim No:

5731039988SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

16/12/19 @ 4.05pm

Person Contacted:

June

Vehicle:

IN / OUT

Date/Time	Action/Instruction
	Tobago (X)
	SLJ 6457G-X
	GB0 9043Y-X
	Dismantle: 17/12/2019
	after part 20/12/19

\* Noted

views open

non upheld

after part photo

posting upheld

PRO

# ASSIGNMENT

From

Date

17/12/19

Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

SLJ 6457G

at Workshop m/s

MS Car

of

No. 8 Kaki Bukit Ave 4 #04-07

Insured:

Premier @ Kaki Bukit

Policy No.

Claims No.

Sum Insured:

Excess

(Client's Record)

Make of Veh:

before 11a

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? - Yes or No

GIA / PR Seen:

Consistent? - Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ 6457G Regn: 17/12/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. A215

cc 1598

Colour

blue

AC:

Insured / Std / NI / NA

Sp. Reading

57144km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

19053 REH1045 62395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Morder / Jammed / Leaked / Burnt or

Brake: Morder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rip / STD A/Rim or

Tyre Size:

F:

215/45/R17

R:

215/45/R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4 mm

Rear

R/Bal.

4 mm

L/Bal.

4 mm

L/Bal.

4 mm

D.O.A.

11/12/19

D.O.I.

17/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DAR - 10w  
Days → 5 day

\* SLJ 6457G  
PR5 case

MV - 62000

PV - 48596

NV - 13400

6/2/20 Submit DAR

RECEIVED 06 FEB 2020

Date/Time, File Path to:

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Path to:

6/2/20 Typist

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Wheel avo (\$)

Survey Fee:

Transportation

5+RS (\$)

Phone

Other

Total

180

11

191

Report Format:

DAR

Lump Sum / Ref:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iss Auth'd	Status
Main	13 Dec 2019 <a href="#">Edit Reg</a>		16 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	HENG HUP HUAT FOODSTUFFS TRADING PTE LTD, Co. Reg. No.: 201736464Z		
Main Claimant:	KOH TENG MENG, Co. Reg. No.: S1574158I		
Vehicle Reg. No.:	SLJ6457G	Date of Loss:	11/12/2019 22:00 - :59
Claim Type:	TP / 5731039988SG	Policy/Cover Note No.:	1800073282 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD9043Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 26/12/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (17/12/2019): TP GIA report


### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE ...**

From: Fan, Winnie-LW  
To: Admin A, assignments  
Cc: Fong, Andy-SY  
Sent: 12/16/2019 4:05:25 PM  
Attachments:  CCF12019\_0001.pdf

---

Hi LKK,

Kindly assist to survey, vehicle in.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

(1)  
June 16/12/19 @ 4.40p  
Carz Auto.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Chia Jia Rong <[jarong@roypartners.com.sg](mailto:jarong@roypartners.com.sg)>  
**Sent:** Sunday, December 15, 2019 5:06 PM  
**To:** Mithoosingh, Aashweenjeetkaur <[Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)>; Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>  
**Cc:** 'MS Group Office' <[msgrouppoffice@gmail.com](mailto:msgrouppoffice@gmail.com)>  
**Subject:** [EXTERNAL] Pre Repair Inspection

This message is from an external sender; be cautious with links and attachments.

Our Ref: MKR/307/9395/2019/as.jr;

Your Ref: Your insured vehicle no. GBD 9043Y;

Dear Sirs,

**CLAIMANT:** Koh Teng Meng (Owner of SLJ 6457G)

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLJ 6457G AND GBD 9043Y ALONG SEMBAWANG ROAD On 11.12.2019 AT ABOUT 2220 HOURS.**

We refer to the above matter.

We act for Koh Teng Meng, the owner of motor vehicle No. **SLJ 6457G**.

We are instructed by our client to notify you of a road traffic accident on 11.12.2019 at about 2200 hours along Sembawang road involving our client's motor vehicle registration number **SLJ 6457G** and motor vehicle registration number **GBD 9043Y** driven by your insured at the material time. A copy of the Singapore Accident Statement report is attached.

As a result of the accident, our client's motor car **SLJ 6457G** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SLJ 6457G** at our client's repairer workshop, M/s Team AutoPro Pte Ltd change at **No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875**. Your said surveyor may contact **Desmond and June at 6385 1838**. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

With regards,

**Chia Jia Rong**

M/s Roy & Partners

133 New Bridge Road

#08-09

China Town Point

Singapore 059413

Tel : 6536 8466 Fax : 6536 1963

Email : [jiarong@roypartners.com.sg](mailto:jiarong@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	158I
Vehicle Details	
Vehicle No.:	SLJ6457G
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY346826
Chassis No.:	MR053REH104562395
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,995.00
Original Registration Date:	20 Dec 2016
First Registration Date:	20 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$19,995.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2026
PARF Rebate Amount:	\$14,996.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$33,600.00
<b>Total Rebate Amount:</b>	<b>\$48,596.00</b>

The information contained herein is correct as at 19 Dec 2019

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal COE Toyota Vios 1.5A



2.80% P.A., \$0 Down, \$0 Down,  
Monthly From \$438, 3 yrs  
Warranty Engine & Gearbox  
GV Credit



Browse by Category

Sort by Date Posted








100 results

61 vehicles

toyota altis

Advanced Search



Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Val	
<b>Search Selection</b>	toyota altis	Any	Any	2016	Any	Any	Any	Av
	<b>Toyota Corolla Altis 1.6A</b>	<b>\$63,500</b>	<b>\$8,610 /yr</b>	<b>16-Mar-2016</b>	<b>1,598 cc</b>	<b>63,000 km</b>	<b>Sedan</b>	<b>Av</b>
Elegant Black, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In House Loan Available.								
Prime Motor & Leasing								
Posted: 19-Dec-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Classic</b>	<b>\$61,800</b>	<b>\$8,510 /yr</b>	<b>14-Mar-2016</b>	<b>1,598 cc</b>	<b>60,505 km</b>	<b>Sedan</b>	<b>Av</b>
Special Offer Till 31 December Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan/Balloon Scheme Available, No Gimmicks, DVD/Bluetooth, Reverse Camera, Leather Seats, 16" Sport Rims, Low Fuel Consumption, Silver In Colour, Maintained And...								
Posted: 19-Dec-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A</b>	<b>\$65,800</b>	<b>\$8,690 /yr</b>	<b>20-May-2016</b>	<b>1,598 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Av</b>
360 VR Cars								
Posted: 19-Dec-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Classic</b>	<b>\$65,800</b>	<b>\$8,400 /yr</b>	<b>22-Sep-2016</b>	<b>1,598 cc</b>	<b>42,000 km</b>	<b>Sedan</b>	<b>Av</b>
\$0 Downpayment, Agent Maintained.Face Lifted Model! Super Well Kept Condition By Previous Owner. Well Known For The Most Reliable Sedan In The Market! Awesome Fuel Consumption At 15km/l Only! Flexible Financing Schemes Available To Meet Your Needs. High Trad...								
Posted: 18-Dec-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>How the new VES affects you as a car buyer</b>							
More than half the cars in this list face a hike in taxes, no thanks to the new Vehicular Emissions Scheme. Find out how this affects you as a car buyer.								
Read this article								
	<b>Toyota Corolla Altis 1.6A Classic</b>	<b>\$61,300</b>	<b>\$8,410 /yr</b>	<b>08-Mar-2016</b>	<b>1,598 cc</b>	<b>44,999 km</b>	<b>Sedan</b>	<b>Av</b>
"We Assure 100% Genuine Mileage", Free 1 Year Warranty On Engine And Gear Box, Only 1 Owner, New Tyres, 1 Year Warranty, 100% Accident Free, Very Well Maintained. Tip Top Original Condition, Great Deal, Come And View Now.								
Posted: 18-Dec-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Elegance (OPC)</b>	<b>\$58,800</b>	<b>\$7,040 /yr</b>	<b>23-Nov-2016</b>	<b>1,598 cc</b>	<b>48,000 km</b>	<b>Sedan</b>	<b>Av</b>
Perfect Car For Everyday Drive With Low Maintenance Cost! Still Under Agent's Warranty! Fully Agent Serviced By Borneo Motors! Low Mileage! Very Fuel Efficient! Only 1 Previous Owner! Flexible Loan Options Available With Attractive Interest Rates. Welcome All Trade I...								
r Pte Ltd								
id: 17-Dec-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								

Compare


**Toyota Corolla Altis 1.6A Elegance**

\$64,800

\$8,440 /yr

16-Jun-2016

1,598 cc

105,000 km

Sedan

Av

1 Owner Only, Flexible Loan Available, Smooth And Responsive Engine, Honest And Transparent Dealing, No Hidden Prices Or Gimmicks, 100% Accident Free, Contact Us For An Immediate Viewing Now! Thank You!

Ka-Hup Vehicles Trading

Posted: 17-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A**

\$63,800

\$8,710 /yr

01-Mar-2016

1,598 cc

67,044 km

Sedan

Av

Only 1 Owner & Well Maintain, Just Completed Grooming For The Lovely Car, Hurry Make Appointment With Our Sales Person For Viewing, Nice Looking New Facelift With Higher Horsepower & Comfort Yet Providing Low Fuel Consumption, This Is What Everyone Is L...

Ka-Hup Vehicles Trading

Posted: 17-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A Classic**

\$59,800

\$8,230 /yr

23-Feb-2016

1,598 cc

39,000 km

Sedan

Av

Low Monthly From \$5xx Only! Face Lifted Model! Super Well Kept Condition By 1 Previous Owner, Well Known For The Most Reliable Sedan In The Market! Awesome Fuel Consumption At 15km/l Only! Flexible Financing Schemes Available To Meet Your Needs, Warranty...

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A Elegance**

\$65,800

\$8,130 /yr

28-Oct-2016

1,598 cc

45,000 km

Sedan

Av

Agent Maintained, 1 Owner Only, Road Tax Valid Till Oct 2020, 100% Genuine Mileage, PARF Value \$10K, Well Maintained, Call To Arrange A Viewing!

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Free Valuation for your Car**

Find out how much your car is worth today! Protect yourself from lowballing buyers with an accurate Free Valuation.

Find out more!


**Toyota Corolla Altis 1.6A Classic**

\$63,800

\$8,390 /yr

26-Jul-2016

1,598 cc

64,206 km

Sedan

Av

Special Offer Till 31 December Only, Vehicle Viewing At AML Building, Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan/Balloon Scheme Available, No Gimmicks, Leather Seats, 16" Sport Rims, Low Fuel Consumption, Silver In Colour, Maintained...

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A Classic**

\$63,800

\$8,370 /yr

02-Aug-2016

1,598 cc

62,400 km

Sedan

Av

Special Offer Till 31 December Only, Vehicle Viewing At 1094 Lower Delta Road, Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan/Balloon Scheme Available, No Gimmicks, Leather Seats, 16" Sport Rims, Low Fuel Consumption, Silver In Colour,...

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A Elegance**

\$63,000

\$8,370 /yr

26-Apr-2016

1,598 cc

69,000 km

Sedan

Av

Looking For A Workhorse Sedan? This Is One Perfect Car For Everyday Drive With Low Maintenance Cost! Bank And In House Full Loan Available, Contact Our Name Person Now For Viewing.

Ka-Hup Vehicles Trading

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A Classic**

\$61,000

\$8,380 /yr

07-Mar-2016

1,598 cc

93,000 km

Sedan

Av

1 Direct Owner, Non PHV Model! Lowest Maintenance And Famous For Its Fuel Economical, With Flexible Interest Rate From Bank/In-house.

Ka-Hup Vehicles Trading

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A Elegance**

\$70,000

\$9,740 /yr

22-Feb-2016

1,598 cc

-

Sedan

Av

Well Maintained By 1 Lady Owner Only, 100% Accident Free, Low Fuel Consumption And Maintenance, Spacious And Reliable, Interest Rate Bank Loan/In House Loan Available, Call For Viewing Now While It Still Last.

Posted: 16-Dec-2019

Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 12/12/2019 17:42  
 Date Of Accident 11/12/2019 22:20  
 Exact Location Of Accident SEMBAWANG ROAD  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ6457G  
**Insured/Policyholder**  
 Name Of Registered Owner KOH TENG MENG  
 NRIC No S1574158I  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-98201637  
 Alternative Phone No OFFICE-98201637

### Vehicle Particulars

Manufacturer TOYOTA  
 Model ALTIS  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number 5112314356  
 Cover Note Number

### Driver

Name of Driver KOH TENG MENG  
 NRIC No S1574158I  
 Date Of Birth 02/01/1963  
 Occupation INDOOR  
 Date Of Driving Pass 19/01/1983  
 Driving Experience 36 YEARS AND 10 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-98201637  
 Fax Number  
 Contact Number OFFICE-98201637  
 Email Address NOEMAIL

Address	APT BLK 555 WOODLANDS DRIVE 53 #05-33
Postcode	730555
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9043Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# SKETCH PLAN

## IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time :

Driver's Signature  
(If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature  
Name :  
NRIC / Fin No :



SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At mentioned Date and Time, I was stationary waiting for traffic light, suddenly I feel a strong impact from my rear portion.

A: SLJ 64576


B: GBD 9043Y

DECLARATION

(We) Declare the foregoing particulars are true in every respect.

  
Policyholder's Signature Date  
& Time:

Driver's Signature  
(If driver is not the policyholder) Date  
& Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

# MOTORCAR (Rear)

## Rear Portion

NAC	INC	Item	CON	ACQ	Q5
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	64	✓	1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips (set)	2	✓	1
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	2	✓	2
1149	993045	Rear Bumper Reinforcement	64	✓	1
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993020	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	1	✓	1
1159	993327	Rear End Panel	2	✓	1
1160	993339	Rear End Panel Top Garnish	1	✓	1
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	2	✓	1
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	2	✓	1
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	2	✓	1
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	993222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	993243	Bootlid Lock			
1178	990377	Bootlid Rubber	2	✓	1
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SLJ 6457 G

NAC	INC	Item	CON	ACQ	Q5
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Rear Bumper	2	✓	1

No of Items:

Assessor:

H-ANN

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2019 <a href="#">Edit Reg</a>		16 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>HENG HUP HUAT FOODSTUFFS TRADING PTE LTD.</b> Co. Reg. No.: 201736464Z								
Main Claimant:	<b>KOH TENG MENG,</b> Co. Reg. No.: S15741581								
Vehicle Reg. No.:	<b>SLJ6457G</b>	Date of Loss:	11/12/2019 22:00 - :59 [35 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 5731039988SG</b>	Policy/Cover Note No.:	1800073282 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBD9043Y</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ms Car Auto Pte Ltd (HQ)</b> 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 26/12/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (17/12/2019): TP GIA report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLJ6457G (5731039988SG)**

**[GBD9043Y]**






































**TP**

**KOH TENG MENG**















































**Dec 11 2019 10:00PM**






















**[HENG HUP HUAT FOODSTUFFS TRADING PTE LTD]**

**Ms Car Auto Pte Ltd**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<a href="#">View</a>		<a href="#">View in Browser</a>	
<b>Photos/Images</b>															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print	
1	19/12/19 18:47	Chassis Number														Load JPG	<input checked="" type="checkbox"/>	
2	19/12/19 18:47	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>	
3	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
4	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
5	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
6	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
7	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
8	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
9	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
10	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
11	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
12	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
13	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
14	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
15	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
16	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
17	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
18	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
19	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
20	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
21	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
22	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
23	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
24	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
25	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
26	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
27	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
28	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
29	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
30	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
31	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
32	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
33	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
34	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
35	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
36	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	
37	19/12/19 18:48	General View														Load JPG	<input checked="" type="checkbox"/>	



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/12/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/12/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/12/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/12/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/12/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/12/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/12/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/12/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/12/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/12/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/12/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/12/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	19/12/19 18:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	19/12/19 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	19/12/19 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	19/12/19 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	19/12/19 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	19/12/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	06/02/20 15:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	06/02/20 15:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	06/02/20 15:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	06/02/20 15:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	06/02/20 15:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	06/02/20 15:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/12/19 12:27	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022122/HYF3E2

Date: 10/02/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800073282  
 Claimant Vehicle No: SLJ6457G Insured Vehicle No: GBD9043Y  
 Date of Loss: 11/12/2019 Nature of Claim: TP Claim No: 5731039988SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLJ6457G  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY346826  
 Reg. Date: 20/12/2016 (Man. Year: 2016) Chassis No: MR053REH104562395  
 Colour: Blue Odometer: 57144 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17  
 Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm  
 Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 16/12/2019  
 Date Inspected: 17/12/2019 Inspected At: Ms Car Auto Pte Ltd (HQ)  
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @  
 KAKI BUKIT  
 Singapore 415875  
 Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	0.00 F	*- F
2	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*SET REVERSE SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*BOOTLID	Repair	0.00 F	*- F
11	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID LOCK	Jammed	0.00 F	*- F
13	1		*BOOTLID RUBBER	Crumpled	0.00 F	*- F
14	1		*REAR BUMPER SENSOR	Cracked	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >