

2019/12/19

ASS. REC. BY:

REF:

C93/AL1902123/HW f301

Special Instruction:

Surveyor: Hock AnnASSIGNMENT (Office)From (Person): Winnie Tan

of

AKDate/Time: 16/12/19 @ 3:59pm

Estimated Cost: _____

Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SMC 688x

Insured: _____

SDU 1991H

at Workshop m/s _____

TRIPLE-T

Tel: _____

63851171of 79 Kaki Bukit Rd 4 #05-66 Synergy @ KB

Policy No: _____

Claim No: _____

3462512162SG

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. _____

4/12/19

CA / REV / REP. / REV 24 HRS

car in 8/12/19 before 12p

H.O.D. Endorsement: _____

Date/Time: _____

Person Contacted: _____

Vehicle IN/OUT

Date/Time

Action/Instruction

Johnny ()18/12/19 - survey1/12/19 - parking workshop updated other point photo2/1/2020Submit DAR report

ASS. REC. BY: **14-ANN**

REF:

AG**ASSIGNMENT**

From:

Date:

18/12/19

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMC 688X

at Workshop m/s

Triple - T

of

25 Kari Bukit Rd 4 #05-06 Synergy

Insured:

CLB SL417800

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMC 688X

Yr Regn:

28/11/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MIT EVO-10 GSR cc 1998

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

1808/81

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

CZ 4A0004151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

265/35/2R18

R:

265/35/2R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

57 mm

R/Bal.

57 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

4/12/19

D.O.I.

17/12/19

Survey held at

Triple - T

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

**DAN = 10h
mpt days: 3 days***** SMC 688X****PRS case***** shortage police report statement****MV - 118000****PV - 32697****IVU - 85300****RECEIVED 02 JAN 2020**

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) **2/1 - typist**

Report Format:

Lump Sum / L.B.R. G:

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others:

TOTAL

180**11****191**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2019 11:24 Edit Reg		20 Dec 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Irene Tay Ai Nai		
Main Claimant:	LEE WEI MING JEREMIE, ID: S8334165C		
Vehicle Reg. No.:	SMC688X	Date of Loss:	04/12/2019 09:00 - :59
Claim Type:	TP / 3462512162SG	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SJU1999H	Policy No. (Claimant):	
		Excess:	
Repairer:	Triple-t Automotive (HQ) NO.10 KAKI BUKIT ROAD 2 #03-07 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 81856692		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 02/01/2020]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (26/12/2019): NO OI GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Sent: Monday, 16 December 2019 3:59 PM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt 05#SJU1999H#027# FW: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJU1999H AND SMC688X ON 04/12/2019
Attachments: SMC688X NOA.PDF

Hi LKK,

Kindly assist to survey on **18.12.2019 (Wednesday) 10am.**

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Irene <motor@iaconsultingsg.com>
Sent: Monday, December 16, 2019 1:06 PM
To: Hor, Yinrul <Yinrul.Hor@aig.com>; 'Loo Sile' <sile@iaconsultingsg.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chan, Jennifer-WM <Jennifer-WM.Chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; 'Tan Ling Ling (Candy)' <candy@iaconsultingsg.com>; candy@iaconsultingsg.com; sile@iaconsultingsg.com
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJU1999H AND SMC688X ON 04/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Yinrul,

We refer to the above matter.

Kindly arrange for PRI photo taking at 25 Kaki Bukit Road 4 #05-66 Synergy@KB Singapore 417800 on **18.12.2019 (Wednesday) 10am.**

Thank you.

Regards,
Irene Tan

16/12/19 @ 4.32pm
Irene
Wage
8/12/19 re 12r
pts.

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	165C
Vehicle Details	
Vehicle No.:	SMC688X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	EVO-10 GSR 2.0 M
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	4B11BK9954
Chassis No.:	CZ4A0004151
Maximum Power Output:	206.0 kW (276 bhp)
Open Market Value:	\$33,346.00
Original Registration Date:	28 Nov 2008
First Registration Date:	28 Nov 2008
Transfer Count:	2
Actual ARF Paid:	\$33,346.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$38,712.00
COE Rebate Amount:	\$32,697.00
Total Rebate Amount:	\$32,697.00

The information contained herein is correct as at 20 Dec 2019

OK



Here is a car loan that's got
our green light!

Mitsubishi Evolution 10 GSR

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼



Home » Used Cars » Car Guru.Com Pte Ltd » Mitsubishi Evolution 10 GSR SST (COE till 11/2028)

Mitsubishi Evolution 10 GSR SST (COE till 11/2028)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM

Price	\$123,800		
Depreciation ⓘ	\$13,850 /yr	Reg Date	26-Nov-2008 (8yrs 11mths 5days COE left)
Mileage	N.A.	Manufactured ⓘ	2008
Road Tax ⓘ	\$1,331 /yr	Transmission	Auto
Dereg Value ⓘ	\$28,715 as of today (change)	OMV ⓘ	\$41,673
COE ⓘ	\$32,121	ARF ⓘ	\$41,673
Engine Cap	1,998 cc	Power	206.0 kW (276 bhp)
Curb Weight ⓘ	1,540 kg	No. of Owners ⓘ	4
Type of Vehicle	Sports Car		

Features

Powerful And Reliable 2.0 MIVEC 4B11 Turbo Charged Engine. View specs of the Mitsubishi Evolution

Accessories

18" Sports Rims, Carbon Fiber Bonnet, New Paintwork With Full Bodykit, Brake Vent, Lip, Canard And Mirror, Intercooler.

Description

Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Car Guru.Com Pte Ltd

24 vehicles for sale. 33 sold in past 3 mths

210 Turf Club Road Lot A7/A8/A9

Car Mall @ The Grandstand

Tel: 67639595

Search cars nearby

Thomas Lim

98589131

Jimmy Cai

90079944

Posted on:

ated on: 18-Dec-2019

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/12/2019 17:55
Date Of Accident 04/12/2019 09:45
Exact Location Of Accident HOUGANG AVE 8
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC688X
Insured/Policyholder
Name Of Registered Owner LEE WEI MING JEREMIE
NRIC No S8334165C
Email Address JEREMIE_LEE@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-90129158
Alternative Phone No OFFICE-90129158

Vehicle Particulars

Manufacturer MITSUBISHI
Model EVO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company ETIQA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number M0011170
Cover Note Number

Driver

Name of Driver LEE WEI MING JEREMIE
NRIC No S8334165C
Date Of Birth 20/10/1983
Occupation INDOOR
Date Of Driving Pass 20/06/2005
Driving Experience 14 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90129158
Fax Number
Contact Number OFFICE-90129158
Email Address JEREMIE_LEE@HOTMAIL.COM

Address	BLK 452A SENGKANG WEST WAY #17-391
Postcode	791452
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T20191204/2040.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU1999H
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20191204/2040

1 of 3

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20191204/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/12/2019 11:27		Vide Report No.: -		Station Diary No.: 26	
Informant's Particulars					
Name of Informant: LEE WEI MENG, JEREMIE			Address: APT BLK 452A SENGKANG WEST WAY #17-391 SINGAPORE 791452		
ID Type / ID No.: NRIC NO / S8334165C			Contact No.: Home/Office: Mobile: 90129158		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 20/10/1983	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SALES ENGINEER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 04/12/2019 09:45	Type of Location: Car Park
Location: Along Road 1 HOUGANG AVENUE 8 BLK 684, OPEN SPACE CARPARK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU1999H		NISSAN	QASHQAI	White		0
SMC688X		MITSUBISHI	EVO	White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191204/2040

2 of 3

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20191204/2040

CONTINUATION OF REPORT

Vehicle Owner				
Name	LEE WEI MENG, JEREMIE		ID No.	S8334165C
Related Vehicle	SMC688X		Contact No.	90129158
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On the 04/12/19 at about 0945hrs, I parked my vehicle bearing registration number SMC688X, at the open space carpark of Blk 684 Hougang Ave 8, carpark no. HGHG64, in lot no. 19. Everything was in order.

When I came back at about 1020hrs, I discovered damages on the front portion of my vehicle. My front bumper was dislodged and there were scratches.

I viewed my front in-car camera, and discovered that a one white colour vehicle bearing registration number SJU1999H had hit onto my vehicle. The said vehicle which was parked in lot no. 18, parked directly beside my vehicle, was exiting out of the said lot, when the left side of the said vehicle hit onto the front right portion of my vehicle.

The said vehicle stopped momentarily and moved off to the other side of the said carpark. Shortly later, one lady clad in a turquoise top, believed to be the driver, came back and was seen assessing the damages on my vehicle. She did not leave any note behind and left thereafter.

I wish to state that my in-car camera also captured one male passerby who had witnessed the collision. He had snapped a photo of the said vehicle but also did not leave any note behind.

I also wish to state that the said vehicle was already there when I parked my vehicle earlier.

I will be able to provide footage of the incident.



**SINGAPORE
POLICE FORCE**



T/20191204/2040

3 of 3

Report No. T/20191204/2040

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MUHAMMAD AZHAR BIN MISSUAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902
Authentication Stamp NP168
SIGNATURE

Signature Of Informant:
Date/Time: 04/12/2019 11:27
Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2019 11:24 Edit Reg		16 Dec 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Irene Tay Ai Nai, Co. Reg. No.: -								
Main Claimant:	LEE WEI MING JEREMIE, ID: S8334165C								
Vehicle Reg. No.:	SMC688X	Date of Loss:	04/12/2019 09:00 - :59 [132 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3462512162SG	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SJU1999H	Policy No. (Claimant):							
		Excess:							
Repairer:	Triple-t Automotive (HQ) NO.10 KAKI BUKIT ROAD 2 #03-07 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 81856692								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 02/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/12/2019): NO OI GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC688X (3462512162SG)
[SJU1999H]**












































TP











LEE WEI MING JEREMIE

Dec 4 2019 9:00AM

[Irene Tay Ai Nai]

Triple-t Automotive

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser <input type="button" value="v"/>	
Photos/Images														3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print
1	23/12/19 19:36	Chassis Number													Load JPG	<input checked="" type="checkbox"/>
2	23/12/19 19:36	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>
3	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
4	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
5	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
6	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
7	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
8	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
9	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
10	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
11	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
12	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
13	23/12/19 19:37	General View													Load JPG	<input checked="" type="checkbox"/>
14	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
15	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
16	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
17	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
18	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
19	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
20	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
21	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
22	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
23	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
24	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
25	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
26	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
27	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
28	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
29	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
30	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
31	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
32	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
33	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
34	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
35	23/12/19 19:38	General View													Load JPG	<input checked="" type="checkbox"/>
36	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
37	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
38	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
39	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
40	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
41	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
42	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>
43	23/12/19 19:39	General View													Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
45	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
46	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	31/12/19 10:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/19 14:04	TP GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022123/HVF3E2

Date: 08/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMC688X

Insured Vehicle No : SJU1999H

Date of Loss: 04/12/2019

Nature of Claim: TP

Claim No: 3462512162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC688X

Make & Model: MITSUBISHI EVO 10, 2.0 GSR (M)

Engine No: 4B11BK9954

Reg. Date: 28/11/2008 (Man. Year: 2008)

Chassis No: CZ4A0004151

Colour: White

Odometer: 180818 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35Z R18

Rear Tyre Size: 265/35Z R18

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 17/12/2019 Inspected At:

25 KAKI BUKIT RD 4 #05-66

SYNERGY @KB

Repairer : Triple-t Automotive (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*SET FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER R/H	Necessary	0.00 F	*- F
4	1		*SET FRT BUMPER RIVET	Necessary	0.00 F	*- F
5	1		*FRT BUMPER LOWER SPOILER	Repair	0.00 F	*- F
6	1		*FRT RH HEADLAMP ASSY	Scratched	0.00 F	*- F
7	1		*FRT RH FENDER	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >