

11/17/2019

ASS. REC. BY:

REF: C1/TPD19022431P9

Special Instructions:

Surveyor:

ASSIGNMENT (Office)

From (Person): Kamaliah Kamle

of

SPF

Date/Time: 12/12/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 8079K

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPE06000029489/1

Claim No:

TP/ID/73519/2019

Sum Insured:

Excess:

D.O.A. 22/11/19

Make of Veh:

(Client's Record)

H.O.D. Endorsement:


CA / REV / REP. / REV 24 HRS

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ()	Estimate



E1010P

Key-in

Vehicles to be inspected: FBM4089B - Rider (Deceased)

SIO In-Charge: SIO Adrian Lim

- f) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Car, SKE1231L (TP/IP/72425/2019)**
- g) **Case IAFP-IB-20191211 - Mechanical Inspection of Bicycle (TP/IP/72425/2019)**

On 21 November 2019 sometime before 8.13 a.m., the accused was driving his motor car on lane 2 of 2-lanes along Tampines Avenue 3 when he collided onto the Cyclist who was crossing the road from his right to left at the Pedestrian Crossing in front of Block 831. Cyclist was conveyed to CGH where she succumbed to his injuries and was pronounced dead on the same day at 9.27am.

Vehicles to be inspected: SKE1231L - Rider (Accused)
Bicycle - Pedal Cyclist (Deceased)

SIO In-Charge: SIO Adrian Lim

- h) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Taxi, SHA8079X (TP/IP/73519/2019)**

On 27 November 2019 (Wednesday) at about 12.30 a.m, the Potential Defendant was driving motor taxi SHA 8079 X, travelling along lane 3 of 4 lanes along Bukit Timah Road towards the direction of Woodlands Road. Before the non-signalised T-junction of Mayne Road, the signalised pedestrian crossing was showing green signal for the Potential Defendant's direction of travel. As he was approaching the said signalised pedestrian crossing, the Deceased had pushed a trolley across the signalised pedestrian at a fast pace, from the the Potential Defendan's right to left, when he collided into the the Deceased. As a result of the accident, the Deceased sustained serious t injuries. She was conveyed to Tan Tock Seng Hospital (TTSH) by the ambulance. On the same day, the Deceased succumbed to her injuries and was pronounced dead at TTSH at 1.04 a.m.

Vehicles to be inspected: SHA8079X - Driver (Potential Defendant)

SIO In-Charge: SIO Raziz

- i) **Case IAFP-IB-20191211 - Mechanical Inspection of Motorcycle, FX8357X (TP/IP/74937/2019)**

On the 3 December 2019 (Tuesday) sometime around 5.46 p.m., the rider was riding along TPE (SLE) on left of 4 lanes in which he claimed that the piston of his motorcycle was jammed. The rider was unable to control his motorcycle and the motorcycle's rear wheel locked causing his motorcycle to lost control. The said motorcycle then side-swiped onto another motorcycle.

Vehicles to be inspected: FX8357X - Rider (Potential Defendant)

SIO In-Charge: IO Phua Tiak Yee

- 2. These request has been approved by my management.
- 3. Thank you Sirs.

cc: FAIT Team & IO Phua, fyip

Best regards,