

ASS. REC. BY:

REF: CS/CT119022153/E913

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Irro Tan Hui Ping of CT1 Date/Time: 16.12.19 15.06p.m

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 8696J Insured: GBJ 8171J

at Workshop m/s Borneo motors Tel: 66311857 / 66311860

of 2 Pandan Cricut

Policy No: DMCRSR19161219000 Claim No: SNM19020597802

Sum Insured: Excess:

Make of Veh: D.O.A. 13.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 17.12.19 9.46a.m Person Contacted: Thomas H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 8696J - X
	GBJ 8171J - X.

ASS. REG. BY:

Steve

REF: CT1

ASSIGNMENT

From:

Date:

17.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 8696J

at Workshop m/s Borneu Motors

of 2 Pandan Crescent

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Acura 11.00 a.m.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKS 8696J

Yr Regn:

12/5/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A1115

C.C.

1598

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

95733

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MROS3 REH / 04532920

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

13/12/19

D.O.I.

17/12/19

Survey held at

Borneo

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or *

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-59K 24/12/19 Final \$2252.40, 4 days. (Cost \$2080, 48%.)

RECEIVED 24 DEC 2019

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Rep. Format:

MER-TP

Lump Sum / F.B.I. /

7757.40

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Dec 2019		16 Dec 2019 15:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: KANG CHEOK CHOO									
Vehicle Reg. No.:		SKS8696J	Date of Loss:	13/12/2019 10:00 - :59					
Claim Type:		TP / SNM19D205978C02	Policy/Cover Note No.:	DMCVSN19161219000					
Vehicle Reg. No. (Insured):		GBJ8171J	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2019]							
Adj Asg. Remarks:		PLEASE SURVEY & REVERT							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 16 December 2019 3:00 PM
To: Ashlyn.Chng@inchcape.com.sg
Cc: assignments; Admin A
Subject: FW: OUR REF: SNM19D205978/GBJ817J/IRENE - Accident involving SKS8696J & GBJ817J DOA 13/12/2019
Attachments: SKS8696J_EFILE.PDF; SKS8696J_EST INV.pdf; SKS8696J_VID FOOTAGE.mp4

Dear Ashlyn,

Liability is down on our insured.

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to conduct survey.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, December 16, 2019 1:43 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Ashlyn.Chng@inchcape.com.sg
Subject: OUR REF: SNM19D205978/GBJ817J/IRENE - Accident involving SKS8696J & GBJ817J DOA 13/12/2019

Dear Irene,

Please conduct PRS for SKS8696J.

Note : officer in charge – Irene Tay 63896192.

***** Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ashlyn Chng [<mailto:Ashlyn.Chng@inchcape.com.sg>]

Sent: Friday, December 13, 2019 3:50 PM

To: Claims Dept of CTI

Cc: Suraidah B Saidi PTCBC

Subject: RE: Direct Settlement (TP) - Accident involving SKS8696J & GBJ817J DOA 13/12/2019

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos, Accident Scene Video Footage & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **GBJ817J** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$100 per day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Thomas Pang @ 9847 6171/ 6631 1860** is located at **2 Pandan Crescent / Level 4** for an appointment to inspect our client's vehicle (currently vehicle NOT in workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you!

Regards,

Ashlyn Chng

D: 6631 1874 | **F:** 6872 7260 | **E:** Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: Steve Chen (LKK Auto)
Sent: Tuesday, 24 December 2019 9:04 AM
To: Thomas Pang PTCBC
Cc: Shiau Chan (LKKAuto)
Subject: Finalize Report of SKS8696J

Dear Thomas,

We confirm the finalize \$2,252.40 (P/P, before GST). 4 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC [<mailto:Thomas.Pang@borneomotors.com.sg>]
Sent: Tuesday, December 24, 2019 8:37 AM
To: Steve Chen (LKK Auto); SUR; Admin A
Subject: Finalize Report of SKS8696J

Dear Steve,

Attach finalize report for your perusal. 04 working days.

Thank you

Regards

Thomas

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	962D
Vehicle Details	
Vehicle No.:	SKS8696J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1ZRX502583
Chassis No.:	MR053REH104530920
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	12 May 2015
First Registration Date:	12 May 2015
Transfer Count:	0
Actual ARF Paid:	\$14,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2025
PARF Rebate Amount:	\$10,941.00
Intended COE Rebate Details	
COE Expiry Date:	11 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,589.00
COE Rebate Amount:	\$37,031.00
Total Rebate Amount:	\$47,972.00

The information contained herein is correct as at 17 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2019 14:00
Date Of Accident	13/12/2019 10:15
Exact Location Of Accident	BLK 192 PANDAN LOOP PANTECH BUSS HUB
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS8696J
Insured/Policyholder	
Name Of Registered Owner	KANG CHEOK CHOO
NRIC No	S1511962D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96734285
Alternative Phone No	OFFICE-96734285

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29123757ATL
Cover Note Number	

Driver

Name of Driver	KANG CHEOK CHOO
NRIC No	S1511962D
Date Of Birth	24/03/1961
Occupation	INDOOR
Date Of Driving Pass	27/01/1979
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96734285
Fax Number	
Contact Number	OFFICE-96734285
Email Address	NOEMAIL

Address	BLK 47 CHOA CHU KANG LOOP #13-17
Postcode	689680
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ817J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SNG CHYE KIN
NRIC/Passport Number	S1557353H
Contact Number	90307929
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Diagram illustrating the reversal of a stack. A vertical stack of two blocks is shown. The top block is labeled 'B' and has a small triangle on top. The bottom block is labeled 'A' and has a semi-circle on the right side. An arrow points from block B down to block A, with the word 'reversed' written next to it.

A- SFS 8696J B- GBS 817J

My car was stationary along Blk 192 Pardan Loop.
I was waiting for my wife. Suddenly a Van GBJ 817J
reversed and hit onto my car's LH rear portion.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Ms Kang Cheok Choo 47 Choa Chu Kang Loop #13-17 Singapore 689680 Mobile: 96734285
		Document No	
		0	
		Document Date	
		13/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGK2	S2	2RE171R 12/05/2015	SKS8696J	0	51572	72/DS/SKS8696J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH104530920	12RX502583	60	Thomas Pang W T	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:CHINA TAIPING INSURANCE TP VEH:GBJ817J DATE OF ACC:13.12.2019			nec	50 100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 REPLACE ACC DAMAGED PARTS 720 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				2160.00
5	B	BP-RES2 RESPRAY ACC AFFECTED AREAS 590				1180 1770.00

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	4,332.40
		Labour 4,332.40	GST 7.00% 303.27
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 4,635.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

TO SECURITY GUARD on a "Without Prejudice" basis

- No illegal modification(s) is allowed

PLEASE ALLOW THE UNDERMENTIONED is subject to final approval from Insurance Company

VEHICLE TO LEAVE THE COMPANY PREMISES

PLEASE TEAR ALONG PERFORATED LINE

DATE 13/12/2019
TIME 14:42

4136101

4136101

Acknowledged by Repairer
Signature: **SKS8696J**
Date: **CUSTOMER**

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Ms Kang Cheek Choo 47 Choa Chu Kang Loop #13-17 Singapore 689680 Mobile: 96734285
	Document No 0	
	Document Date 19/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	12/05/2015	SKS8696J	0	51572 72/DS/SKS8696J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH104530920	12RX502583	60	Thomas Pang W T	17/12/2019	8.00	19/12/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:CHINA TAIPING INSURANCE TP VEH:GBJ817J DATE OF ACC:13.12.2019 BY:LKK-STEVE @ 17.12.2019 04 WORKING DAYS				50.00
2	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST PO:2 A45 5393				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	18			180.00
4	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS PO:25393	A45			720.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	A45			1180.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	2,252.40
		Labour 230.00	GST 7.00%
		Materials 2,022.40	157.67
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 2,410.07

4130004

4130004

19/12/2019
17:24

SKS8696J

WORKSHOP



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19022153/EQF3N2

Date: 27/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19161219000

Claimant Vehicle No: SKS8696J Insured Vehicle No: GBJ8171J

Date of Loss: 13/12/2019 Nature of Claim: TP Claim No: SNM19D205978C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS8696J

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX502583

Reg. Date: 12/05/2015 (Man. Year: 2015) Chassis No: MR053REH104530920

Colour: White Odometer: 95733 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	100.00	50.00	50.00	50.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,232.40	2,202.40	2,030.00	47.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,332.40	2,252.40	2,080.00	48.01
+ GST 7.00/7.00% (S\$)	303.27	157.67	145.60	48.01
Nett Amount (S\$)	4,635.67	2,410.07	2,225.60	48.01

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 17/12/2019 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 27 Dec 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKS8696J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
Total Parts (\$\$)						100.00 50.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND CONDUCT WATER TEST	New	122.40	122.40
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	2,160.00	720.00
4	RESPRAY ACC AFFECTED AREAS	New	1,770.00	1,180.00
Gross Labour Cost (\$\$)			4,232.40	2,202.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >