

ASS. REC. BY:

REF: CS/CT 1902170 / E/f30 Special Instruction:

**Special Instruction:**

Surveyor: Steve

### ASSIGNMENT (Office)

From (Person): Tan Kah Long

of C71

Date/Time: 17.12.19 10:51 AM

Estimated Cost:

Bill to:

OD( / TP ) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 2070Z

Insured: PA 39662

at Workshop m/s *Performance*

Tel: 63190174

of 303 Alexandra Road

Policy No: DMBISA 30593819000

Claim No: SNM1917 205979002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.12.19 2.17p.m

Person Contacted:

Cashwe

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 24702 - X
	PA 39662 - CCG / AIG

Signature *Steve*


REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: *SKT 20702* Yr Regn: *29/5/17*  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: *BMW X3* c.c. *1997*  
 Colour *Silver* A/C: Insured / Std / NI / NA  
 Sp. Reading *116201* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 Ci/No: *WBAW1920 800X01127*  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rlm / STD A/Rlm or  
 Tyre Size: F: *225/60R18*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or



(Policy Condition)  
 Remark: The veh. had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR. Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front Rear  
 R/Bal. *5* mm R/Bal. *5* mm  
 L/Bal. *5* mm L/Bal. *5* mm  
 D.O.A. *13/12/19* D.O.I. *25/2/20*  
 Survey held at *Performance Motors*  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>5/3/20</i>	<i>MV-130K</i> <i>Findn \$3,792.20, 3 days (Mistoh) (Red: 639.15; 14%)</i>
RECEIVED 5 MAR 2020	

Date/Time, File Pass to? ☐ : Prel. Report

1) *5/3 Typist* ☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) *3702.20*

Days Of Repair: *3*

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp. (\$

☐ : Weekend (\$

Survey Fee: *220*

Transportation:

☐ : S + RS, SI

☐ : Photo

☐ : Others

TOTAL

*220*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Dec 2019		17 Dec 2019 10:51 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:		
Main Claimant:	KANAPATHY SINGINATHAN, ID: S1367211C	
Vehicle Reg. No.:	SKT2070Z	Date of Loss: 13/12/2019 11:00 - :59
Claim Type:	TP / SNM19D205979C02	Policy/Cover Note No.: DMB1SN30593819000
Vehicle Reg. No. (Insured):	PA3966Z	Policy No. (Claimant): P1941308
	Excess:	\$50.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]	
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/12/2019]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results;									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Tuesday, 17 December 2019 10:49 AM  
**To:** PBSP  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D205979/PA3966Z/TKL - REQUEST FOR DIRECT SETTLEMENT - SKT2070Z & PA3966Z ON 13/12/2019

### WITHOUT PREJUDICE

Dear Caroline,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Tuesday, December 17, 2019 9:14 AM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Cc:** assignments <assignments@lkkauto.com>  
**Subject:** Re: OUR REF: SNM19D205979/PA3966Z/TKL - REQUEST FOR DIRECT SETTLEMENT - SKT2070Z & PA3966Z ON 13/12/2019

Dear Sirs,

We are agreeable to use a common surveyor below as the SJE.

5. XING GUO QIANG

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>  
**Sent:** Monday, 16 December 2019 2:37 PM  
**To:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>  
**Subject:** RE: OUR REF: SNM19D205979/PA3966Z/TKL - REQUEST FOR DIRECT SETTLEMENT - SKT2070Z & PA3966Z ON 13/12/2019

[External Mail] This email originated from outside of the organisation; be careful with requests, attachments and links.  
**Without Prejudice**

Dear Caroline,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Monday, December 16, 2019 2:24 PM  
**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>  
**Subject:** OUR REF: SNM19D205979/PA3966Z/TKL - REQUEST FOR DIRECT SETTLEMENT - SKT2070Z & PA3966Z ON 13/12/2019

Dear Kah Leong,

Please conduct PRS for SKT2070Z.

Note: officer in charge – Kah Leong 63896193.

**\*\*\* Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** PBSP [<mailto:pml-pbsp@sime-darby.com.sg>]

**Sent:** Monday, 16 December, 2019 8:30 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** REQUEST FOR DIRECT SETTLEMENT - SKT2070Z & PA3966Z ON 13/12/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/12/2019 08:38
Date Of Accident	13/12/2019 11:35
Exact Location Of Accident	LOK YANG WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT2070Z
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	KANAPATHY SINGINATHAN
NRIC No	S1367211C
Email Address	KXSINGI@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-90183020
Alternative Phone No	OTHERS-90183020

#### Vehicle Particulars

Manufacturer	BMW
Model	X3
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1941308
Cover Note Number	

#### Driver

Name of Driver	KANAPATHY SINGINATHAN
NRIC No	S1367211C
Date Of Birth	04/06/1959
Occupation	INDOOR
Date Of Driving Pass	11/05/1982
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90183020
Fax Number	
Contact Number	OTHERS-90183020
Email Address	KXSINGI@SINGNET.COM.SG

Address	BLK 205A COMPASSVALE LANE #04-49
Postcode	541205
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : LIZZA GENDER: : FEMALE
Passenger 2	NAME: : YI ZI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA3966Z
Vehicle Make/Model/Colour	BUS
Details Of Properties	
Vehicle Category	BUS
Name of Driver	PEERMOHAMED KADER S/O KADER ABDUL
NRIC/Passport Number	S1327554H
Contact Number	94242771
Address	
Postcode	



Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

13/12/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Performance Motors Limited  
303 Alexandra Road  
Sima Darby Performance Centre  
Singapore 159941

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 13th Dec 2019 @ 11:35 my car was parked along Lokyang Way parking lot. I'm still in the car with my colleagues using parking apps for parking. Suddenly, the car jerked and noticed the bus that was parked in front beched into my car. Sounded my car horn and the driver pulled it back to the front. Notice that the bus exhaust which was protruding out had back into my car. Then got out of my car and ~~just~~ notice the damaged the my car front side. <sup>was</sup> Asked the driver. His answer was when I ~~get~~ <sup>was</sup> into the bus there was not car. So he assume and reversed and hit my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time: 13/12/19

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name:

Performance Motors Limited

NRIC/FIN No.: 303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	211C
<b>Vehicle Details</b>	
Vehicle No.:	SKT2070Z
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X3 SDRIVE 20i HID NAV
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	A2301618N20B20A
Chassis No.:	WBAWY920800X01127
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$33,704.00
Original Registration Date:	29 May 2017
First Registration Date:	29 May 2017
Transfer Count:	0
Actual ARF Paid:	\$39,186.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2027
PARF Rebate Amount:	\$29,389.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,414.00
COE Rebate Amount:	\$40,219.00
<b>Total Rebate Amount:</b>	<b>\$69,608.00</b>

The information contained herein is correct as at 25 Feb 2020

OK

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601  
64796624

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company



Acknowledged by Repairer  
(After Sales)  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

GST REG. NO : M2 - 0020081 - X

16 DEC 2019

**E S T I M A T E**

Estimate No. : **b1 53789**  
Date Estimated : **14/12/2019**  
Prepared By : **Joseph Yaguel**

Page No. : 1 of 4

**- ESTIMATE REPAIR FOR -**

**Kanapathy Singinathan**  
**205A Compassvale Lane**  
**#04-49**

Singapore 541205

**- ACCOUNT - 135**

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT2070Z	WBAWY920800X01127	29/05/2017	X3	0

**DESCRIPTION**

Replacing front bumper

850 1,275.00

Spray front bumper

934 1,038.00

To check electrical wiring systems at the front section  
for proper function including adjustments of headlights.

150 177.00

Sundries

81 80.00

Total Labour 1: **2,570.00****DESCRIPTION**

FRT SHOCK ABSORBER ECE

QTY

PRIC

VALUE

FRT BUMPER PANEL PRIMED

1

62.75

62.75

DECOUPLING RING PDC TORQUE CONVERTE

1

1,358.50

1,358.50

4

5.10

20.40

Total Parts : **1,441.65**

*Supp*  
*front bumper lower / cut*  
*[Signature]*  
*28/2/2020*

434135



*Steve (LKK) with [Signature]*  
*8377 8813 25/2/20, 12.00pm*  
*3 days*  
*P/P*  
*Ry Del Ry*

Labour 1	:	<b>2,570.00</b>
Parts	:	<b>1,441.65</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>280.82</b>
Grand Total	:	<b>4,292.47</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 53789**  
Date Estimated : **14/12/2019**  
Prepared By : **Joseph Yaguel**

**- ESTIMATE REPAIR FOR -**  
**Kanapathy Singinathan**  
**205A Compassvale Lane**  
**#04-49**

**Singapore 541205**

**- ACCOUNT - 135**  
**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKT2070Z</b>	<b>WBAWY920800X011</b>	<b>29/05/2017</b>	<b>X3</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BRACKET / <i>OR</i>	33.20	1.00	0	33.20
# CLADDING BUMPER FRT (PDC/SCHWARZ) / <i>CR</i>	268.50	1.00	0	268.50
# EXPANDING RIVET BLACK / <i>PRC</i>	1.40	20.00	0	28.00

### # SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	329.70
Total Labour & Parts :	329.70

4341.35

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 53789**  
Date Estimated : **14/12/2019**  
Prepared By : **Joseph Yaguel**

### - ESTIMATE REPAIR FOR -

**Kanapathy Singinathan**  
**205A Compassvale Lane**  
**#04-49**

**Singapore 541205**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKT2070Z</b>	<b>WBAWY920800X011</b>	<b>29/05/2017</b>	<b>X3</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00 ✓
To respray front bumper.	934.00	0	934.00 ✓
To check electrical wiring systems at the front section for proper function.	150.00	0	150.00 ✓
Sundries.	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BRACKET ✓ <i>QR</i>	33.20	1.00	0	33.20 ✓
# CLADDING BUMPER FRT (PDC/SCHWARZ) ✓ <i>cut</i>	268.50	1.00	0	268.50 ✓
FRT BUMPER PANEL PRIMED ✓ <i>07</i>	1,358.50	1.00	0	1,358.50 ✓
# EXPANDING RIVET BLACK ✓ <i>11</i>	1.40	20.00	0	28.00 ✓

#### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,688.20
Total Labour & Parts :	3,702.20 ✓
GST @7%:	259.15
Grand Total :	3,961.35

CAR RENTAL = \$240.00  
GIA SEARCH FEE - \$2.00

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Dec 2019		17 Dec 2019 10:51 <a href="#">Edit Adj Rpt</a>	<b>S\$3,702.20</b> <a href="#">Edit Estimates</a>	<b>S\$3,702.20</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>KANAPATHY SINGINATHAN</b> , ID: S1367211C								
Vehicle Reg. No.:	<b>SKT2070Z</b>	Date of Loss:	13/12/2019 11:00 - :59 [30 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D205979C02</b>	Policy/Cover Note No.:	DMB1SN30593819000						
Vehicle Reg. No. (Insured):	<b>PA3966Z</b>	Policy No. (Claimant):	P1941308						
		Excess:	S\$0.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6880 4888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 27/12/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents


\*SKT2070Z (SNM19D205979C02)  
[PA3966Z]  
TP  
KANAPATHY SINGINATHAN  
Dec 13 2019 11:00AM  
[-]  
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
2	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
3	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	25/02/20 17:39	Odometer Reading							 Load JPG	<input checked="" type="checkbox"/>	
5	25/02/20 17:39	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>	
6	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	25/02/20 17:39	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	05/03/20 08:52	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
22	05/03/20 08:52	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
23	05/03/20 08:52	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
24	05/03/20 08:52	Reinspection Photo							 Load JPG	<input checked="" type="checkbox"/>	
25	05/03/20 08:52	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	05/03/20 08:52	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	


## Linked Accident Report Documents










View

View in Browser

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)			Thumbnail	Print
1	14/12/19 08:55	Accident Statement			 Load HTM	

Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)			Thumbnail	Print
1	14/12/19 08:47	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
2	14/12/19 08:47	Accident Photo	 Load JPG	✓
3	14/12/19 08:47	Accident Photo	 Load JPG	✓
4	14/12/19 08:47	Accident Photo	 Load JPG	✓
5	14/12/19 08:47	Accident Photo	 Load JPG	✓
6	14/12/19 08:47	Accident Photo	 Load JPG	✓
7	14/12/19 08:47	Accident Photo	 Load JPG	✓
8	14/12/19 08:47	Accident Photo	 Load JPG	✓
9	14/12/19 08:47	Accident Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	14/12/19 08:47	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19022170/ETF3E2

Date: 06/03/2020

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SN30593819000

Claimant Vehicle  
No : SKT2070ZInsured Vehicle  
No : PA3966Z

Date of Loss: 13/12/2019

Nature of Claim: TP

Claim  
No: SNM19D205979C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKT2070Z

Make &amp; Model: BMW X3, 2.0 SDRIVE 20i LED SR NAV (A)

Engine No: A2301618N20B20A

Reg. Date: 29/05/2017 (Man. Year: 2017)

Chassis No: WBAWY920800X01127

Colour: Silver

Odometer: 116201 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/60 R18

Rear Tyre Size: 225/60 R18

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,851.35	1,768.20	83.15	4.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,341.35</b>	<b>3,702.20</b>	<b>639.15</b>	<b>14.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>303.89</b>	<b>259.15</b>	<b>44.74</b>	<b>14.72</b>
<b>Nett Amount (S\$)</b>	<b>4,645.24</b>	<b>3,961.35</b>	<b>683.89</b>	<b>14.72</b>

## INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 25/02/2020 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)	
<b>Parts:</b> M1-SUV	BMW X3 2.0 SDRIVE 20I LED SR NAV (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SKT2070Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT SHOCK ABSORBER ECE	Not Necessary	62.75 FS	*- FS
3	1		*FRT BUMPER PANEL PRIMED	Dented	1,358.50 FS	*1,358.50 FS
4	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.40 FS	*- FS
5	1		*BRACKET	Broken	33.20 FS	*33.20 FS
6	1		*CLADDING BUMPER FRT (PDC/SCHWARZ)	Cut	268.50 FS	*268.50 FS
7	20		*EXPANDING RIVET BLACK	Necessary	28.00 FS	*28.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>1,851.35</b>	<b>1,768.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACING FRONT BUMPER	New	1,275.00	850.00
2	SPRAY FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >