

Steve REF: FCI 222011661

From: Date: 13/01/2020
Estimated Cost:
OD: TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SKL 9005 J
at Workshop m/h: Performance Motor
of: 303 Alexandra Road
Insured:
Policy No:
Claims No:
Sum Insured:
(Client's Record)
Make of Veh: Mr. Chung



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: Consistent?: Yes or No
IDAC Accident Rpt: Consistent?: Yes or No
GIA / PR Seen:
Est. Repairs: 3 days Res: Yes or No
Lum Sum: P/P % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted:

Vehicle No: SKL 9005 J
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW 520i C.C. 1998
Colour: B/W A/C: Insured / Std / NI / NA
Sp Reading: 9871 T/Radio: Insured / Std / NI / NA
Eng No:
C/Nr: WBAJA 120108T82710
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 245/45R18 R: 4

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: R/Bal. 5 mm L/Bal. 5 mm
D.O.A. 15/12/19
Survey held at Performance Motors
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction
MV-89K 200K

(P/P \$ 5,914.10/ RED \$ 4,914.05 / 45%)

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair:
Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation:
S + RS \$
Photos
Others

Report Format:
Lump Sum / LBJ: (%)

TOTAL