

ASS. REC. BY:

REF: CS/INC 19022212/Ksf372

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

Date/Time: 17 December 2019

From (Person): Cynthia Ang of INC

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SLG 2353P

To Inspect Vehicle No: SGT 9693S

Tel: 9695 5547

at Workshop m/s NGS Motorsport Pte Ltd

of 10 Ang Mo Kio Ind Park 2A #02-01

Policy No:

Claim No: MT/1074313-002

Sum Insured:

Excess:

D.O.A. 02/12/2019

Make of Veh:

(Client's Record)

"wp"

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 17/12/2019 @ 04:52pm Person Contacted: Evelyn Ng

Vehicle: IN / OUT

Date/Time	Action/Instruction ( V ) Estimate
	SLG 2353P - X
	SGT 9693S: NA/AIG18023303/24 DOA: 28/12/2018

ASS. REC. BY:

REF:

1NC/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_ NGS

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/24 Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: STT 98935 Yr Regn: 11, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS R414 c.c. 1498

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 204863 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: TN1BAAG1180110356

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Greenlander

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 2/12/19 D.O.I. 12/12/19

Survey held at 1.57 PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

23/12/19 Pp 8 220d email & call from  
C @ 2.060.76 Red - 48%

RECEIVED 24 DEC 2019

Date/Time, File Pass to?

24/12/19

☐ : Prel. Report☒ : Final Report1) Type 4  
Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

250

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$) 2,200/- 45

## **Nivitha (LKK Auto)**

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Tuesday, 17 December 2019 2:50 PM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto); 'SUR'  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 17/12/2019

Dear LKK,

Resend with following details.

With Regards

**Cynthia Ang**  
Admin Assistant  
Operations, Motor & Personal Lines (PL)  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



**in** with  
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Cynthia Ang  
**Sent:** Tuesday, 17 December 2019 9:53 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>  
**Cc:** Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** TP CASES FARMED OUT TO LKK ON 17/12/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Muhammad Airwan	MT/1075799-002	SGP3076U	ELITE AM PTE LTD	280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST @ WOODLANDS	Christy / 63397378		SLU1768J	14/12/2019	
2	Eric Tang	MT/1075914-001	SMJ4939J	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	/ 6909 8882		FM2020P	13/12/2019	
3	Jared Liu	MT/1074906-002	SJR1643A	KENT SENG CAR SERVICES	BLK 1017 YISHUN INDUSTRIAL PARK A #01-240	Susan Lim / 91004390		FBK5001H	07/12/2019	
4	Rajeswary	MT/1075688-002	SLP6569K	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SMA9227U	13/12/2019	
5	Chester Chong	MT/1074313-002	SJT9693S	NGS MOTORSPORT PTE LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047	Evelyn Ng / 9695 5547		SLG2353P	02/12/2019	
6	Cyndie Yong	MT/1075869-001	SH7247S	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SJU7278R	13/12/2019	65425119 or 6542 7162 avoid
7	Cyndie Yong	MT/1075422-002	SHD366D	TRANS-CAB SERVICES PTE LTD	NO 2, ANG MO KIO STREET 63	Kek Zhewei / 62876666		SJK5476B	11/12/2019	12pm - 1pm
8	Charlotte Chew	MT/1075939-002	SLK1647C	VERMOGEN ACE PTE LTD	60 JALAN LAM HUAT #03-35/36	Ezel Tejano / 6904 4596		GBJ7837E	16/12/2019	

9	Alice Low	MT/1067081-002	SMD1124U	VERMOGEN ACE PTE LTD	60 JALAN LAM HUAT #03-35/36 SINGAPORE 737869	SINGAPORE 737869	Ezel Tejano / 6904 4596	SJU1067Y	14/10/2019	
---	-----------	----------------	----------	-------------------------	--	---------------------	-------------------------------	----------	------------	--

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

With Regards

**Cynthia Ang**

Admin Assistant

Operations, Motor & Personal Lines (PL)

T +65 6430 7900

[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	618E
<b>Vehicle Details</b>	
Vehicle No.:	SJT9693S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Dec 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	HR15234999B
Chassis No.:	JN1BAAG11Z0110356
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,793.00
Original Registration Date:	11 Nov 2009
First Registration Date:	11 Nov 2009
Transfer Count:	3
Actual ARF Paid:	\$17,793.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Oct 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,287.00
COE Rebate Amount:	\$14,826.00
<b>Total Rebate Amount:</b>	<b>\$14,826.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Dec 2019

OK

MS110159284 / STA INSPECTION PTE LTD - Sin Ming  
ENTRY DATE & TIME: 03/12/2019 10:27  
SUBMITTED BY: Wong Lip Yang

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/12/2019 10:27
Date Of Accident	02/12/2019 12:05
Exact Location Of Accident	GENTING LANE TOWARDS KALLANG WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT9693S
Insured/Policyholder	
Name Of Registered Owner	ABOI CAR RENTAL
Co Reg No	53378618E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91863702

### Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5113388789
Cover Note Number	

### Driver

Name of Driver	MOHAMED SHAFEI BIN AMIR
NRIC No	S1583185E
Date Of Birth	10/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	14/06/1984
Driving Experience	35 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91863702
Fax Number	
Contact Number	

Address BLK 542 SERANGOON NORTH AVENUE 4  
#02-17 SINGAPORE

Postcode 550542

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) Involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name THOMSON NEIGHBOURHOOD POLICE POST

Police Station Address ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4529999 - FAX NO: 6 5535740

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER POLICE REPORT AND ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG2353P

Vehicle Make/Model/Colour

Details Of Properties REFER POLICE REPORT AND ATTACHED

Vehicle Category PRIVATE CAR

Name of Driver LAU JOI MENG

NRIC/Passport Number S1455735J

Contact Number 91868201

Address

Postcode



## Sketch Plan #2 Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 2/10/19 13:20

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2nd December 2019 at 12:06pm while travelling from Gerling Lane towards the Kallang Way while the traffic light was in green, a vehicle number SLG 2353P accidentally hit my rear vehicle number SJT 96938, when his direction flow of the traffic light was in Red. Result right hand side rear mud guard badly damaged. No injury was reported.

Refer Police Report: T/2019/202/2089

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 2/12/19 1330hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

HP: 9695 5547 Fax: 6481 5772 e-mail : ngsmotorsportpteltd@gmail.com

Reg No: 201812604N

17/12/2019

NTUC Income Ins. Co-op Ltd  
75 Bras Basah Road  
NTUC Income Centre  
Singapore 189557

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 02/12/2019, INVOLVING VEH NO.: SJT9693S & SLG2353P  
CLAIMS AGAINST SLG2353P (NTUC)  
YOUR CLAIM REF: MT/

We submit herewith our direct claim estimate quotation as follow:-

## Replacement parts - Nissan Sylphy

1	Rear Bumper	Nett
1	Side Retainer RH	Nett
1	Rear Bumper Moulding	Nett
1	Rear Fender RH	Nett
10	Clips, Fender Shield @\$4.00	S.Nett
1	Rim- <del>Repair</del>	S.Nett

Bulim	\$	660.60	✓
DIT	\$	36.60	✓
nu	\$	162.80	—
B	\$	996.40	—
		\$ 1,856.40	
Less 10%	\$	185.64	
		\$ 1,670.76	
nu	\$	40.00	✓
su	\$	250.00	X

To remove fuel tank enable to cut & weld, remove all damaged parts with all necessary component/attachment straighten chassis member, cut & weld panel, repair/reshape dented body panel, replace damaged parts, refit into position

\$ 1,400.00 600

Spray painting

\$ 700.00 450

Transfer Door Mechanism

nu \$ 150.00 X

Check Wiring/proper function on lights and etc.

\$ 50.00 20

\$ 4,260.76

Any other parts which necessitate repair or renewal will incur additional charged  
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully,

NGS MOTORSPORT PTE LTD  
EVELYN NG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This quotation is issued on "Without Prejudice" basis  
No financial liability is accepted without the approval of the Insured Party  
This quotation is subject to the terms and conditions of the relevant insurance policy and is subject to the approval of the relevant insurance Company

Authorized by: [Signature]  
Signature: [Signature]  
Date: [Date]



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022212/Ksf3n2  
 73 BRAS BASAH ROAD Date: 27-12-2019  
 #05-01 NTUC TRADE UNION HOUSESINGAPORE  
 189556  
 ATTN: CHESTER CHONG Code: INC



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 2353P	Veh. Inspected	SJT 9693S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1074313-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	17/12/2019

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1BAAG11Z0110356	Colour	METALLIC PEARL WHITE
Odometer	204863 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GRENLANDER	5 mm
L/H Front Tyre	195/65 R15	GRENLANDER	5 mm
R/H Rear Tyre	195/65 R15	GRENLANDER	5 mm
L/H Rear Tyre	195/65 R15	GRENLANDER	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	02/12/2019	Inspect Date / Time	17/12/2019 ( 01:57 PM )
Survey held at	NGS TRADING BLK 10 AMK IND PK 2A #02-01 SINGAPORE 568047		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 9693S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (N)	BUCKLED / CRACKED	660.60	660.60
1	SIDE RETAINER RH (N)	DISTORTED	36.60	36.60
1	REAR BUMPER MOULDING (N)	NECESSARY	162.80	162.80
1	REAR FENDER RH (N)	BENT	996.40	996.40
	LESS 10% DISCOUNT		-185.64	-185.64
			1,670.76	1,670.76
<b>SPECIAL NETT ITEMS</b>				
10	CLIPS,FENDER SHIELD @\$4.00 (SN)	NECESSARY	40.00	40.00
1	RIM (SN)	SERVICEABLE	250.00	-
			290.00	40.00
<b>LABOUR</b>				
	TO REMOVE FUEL TANK ENABLE TO CUT & WELD,REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT STRAIGHTEN CHASSIS MEMBER,CUT & WELD PANEL,REPAIR/RESHAPE DENTED BODY PANEL,REPLACE DAMAGED PARTS,REFIT INTO POSITION.		1,400.00	600.00
	SPRAY PAINTING.		700.00	450.00
	TRANSFER DOOR MECHANISM.	NOT NECESSARY	150.00	-
	CHECK WIRING/PROPER FUNCTION ON LIGHTS AND ETC.		50.00	20.00
			2,300.00	1,070.00
<b>GRAND TOTAL</b>			<b>4,260.76</b>	<b>2,780.76</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,200.00</b>

Report Ref No. CS/INC19022212/Ksf3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.