

ASS. REC. BY:

REF:

CS13MC190222 17/01/2019

Special Instruction:

Surveyor Sun Pin

ASSIGNMENT (Office)

From (Person): Cynthia Ang of INC Date/Time: 17 December 2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLK 1647C Insured: GBJ 7837Eat Workshop m/s: Vermogen Ace Pte Ltd Tel: 6904 4596of 60 Jalan Lam Hwat #03-35/36Policy No: \_\_\_\_\_ Claim No: MT/1075 939-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 16/12/2019

(Client's Record)

"w/p"

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17/12/2019 @ 05:30pm Person Contacted: Ezel Teyano Vehicle  IN  OUT


Date/Time	Action/Instruction (✓) Estimate
	GBJ 7837E NA/3MC 190222/17/12/2019
	SLK 1647C NA/3MC 190222/17/12/2019

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLK 1647C Yr Regn: 06/Jan/2017  
 Type:  M. Car  M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: BMW 116D 5DR Hatch c.c 1496  
 Colour: Blue. A/C:  Insured /  Std /  NI /  NA  
 Sp. Reading: 65953 T/Radio:  Insured /  Std /  NI /  NA  
 Eng/No: \_\_\_\_\_  
 C/No: WB41V72070V725431  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  In order /  Jammed /  Leaked /  Burnt or  
 Braks:  In order /  Jammed /  Leaked /  Burnt or  
 Mod:  Nil /  S/Rim /  STD A/Rim or \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commēnced its repair at the time of inspection.



Tyre Size: F: 205/55 R16  
 R: 205/55 R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front R/Bal. 5 mm Rear R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 16/12/2019 D.O.I. 18/11/2019  
 Survey held at V merger 0302PM  
 Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistant? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistant? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chāssis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV: 74k
	PV: 44,453
	NV: 24,547
23/12	Pending Estimate Price RECEIVED 18 FEB 2020 (confirm with Ezel) Finance \$ 5,600 @ 6 days (L/S) (Red \$13421-84, 70%)

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: 6  
 Resurvey No. of Trip: 2

1) \_\_\_\_\_  
 2) 17/2/20 Typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Wheel and (\$ \_\_\_\_\_)

Survey Fee:	<u>250</u>
Transportation:	_____
S + RS	_____
Photo	_____
Others	_____
TOTAL	<u>250</u>

Report Form: \_\_\_\_\_  
 Lump Sum I.E.I. = \$5600/=

## Oi Sun Pin (LKK Auto)

---

**From:** ezel.t@vermogen-group.com  
**Sent:** Friday, 14 February, 2020 9:04 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Subject:** RE: TP FINALIZE SLK1647C DOA: 16/12/2019

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Hi Sun Pin,

We confirmed the finalize amount \$5,600. Repair day 6 days. (L/S, before gst).

Thank you.

Best Regards,

Ezel Tejano  
Vermogen Ace Pte Ltd  
Operation Address:  
60 Jalan Lam Huat # 03-35/36  
Carros Centre Singapore 737869  
Tel: 6904 4596  
Fax: 6694 4929

Mailing Address:  
1 Bukit Batok Crescent #04-54  
Wcega Plaza Singapore 658064

-----Original Message-----

**From:** Oi Sun Pin (LKK Auto) <[sunpin@lkkauto.com](mailto:sunpin@lkkauto.com)>  
**Sent:** Friday, February 14, 2020 8:57 AM  
**To:** [ezel.t@vermogen-group.com](mailto:ezel.t@vermogen-group.com)  
**Subject:** RE: TP FINALIZE SLK1647C DOA: 16/12/2019

Hi Ezel,

Kindly refer the finalize amount \$5,600. Repair day 6 days. (L/S, before gst).  
If agree please update

Thank you.

Best Regards,  
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** [ezel.t@vermogen-group.com](mailto:ezel.t@vermogen-group.com) [<mailto:ezel.t@vermogen-group.com>]

**Nivitha (LKK Auto)**

---

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Tuesday, 17 December 2019 2:50 PM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto); 'SUR'  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 17/12/2019

Dear LKK,

Resend with following details.

With Regards

**Cynthia Ang**  
Admin Assistant  
Operations, Motor & Personal Lines (PL)  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

**From:** Cynthia Ang  
**Sent:** Tuesday, 17 December 2019 9:53 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>  
**Cc:** Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** TP CASES FARMED OUT TO LKK ON 17/12/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Muhammad Airwan	MT/1075799-002	SGP3076U	ELITE AM PTE LTD	280 WOODLANDS INDUSTRIAL PARK ES #01-17 HARVEST @ WOODLANDS	Christy / 63397378		SLU1768J	14/12/2019	
2	Eric Tang	MT/1075914-001	SMI4939J	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	/ 6909 8882		FM2020P	13/12/2019	
3	Jared Liu	MT/1074906-002	SIR1643A	KENT SENG CAR SERVICES	BLK 1017 YISHUIN INDUSTRIAL PARK A #01-240	Susan Lim / 91004390		FBK5001H	07/12/2019	
4	Rajeswary	MT/1075688-002	SLP6569K	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SMA9227U	13/12/2019	
5	Chester Chong	MT/1074313-002	SIT9693S	NGS MOTORSPORT PTE LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047	Evelyn Ng / 9695 5547		SLG2353P	02/12/2019	
6	Cyndie Yang	MT/1075869-001	SH7247S	SOOH HDCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SJU7278R	13/12/2019	65425119 or 6542 7162 avoid
7	Cyndie Yang	MT/1075422-002	SHD366D	TRANS-CAB SERVICES PTE LTD	NO 2, ANG MO KIO STREET 63	Zhewel / 62876666		SJK5476B	11/12/2019	12pm - 1pm
8	Charlotte Chew	MT/1075939-002	SLK1647C	VERMOGEN ACE PTE LTD	60 JALAN LAM HUAT #03-35/36	Ezel Tejano / 6904 4596		GBJ7837E	16/12/2019	

9	Alice Low	MT/1067081-002	SMD1124U	VERMOGEN ACE PTE LTD	SINGAPORE 737869 60 JALAN LAM HUAT #03-35/36 SINGAPORE 737869	Etel Tejano / 6904 4596	SJU1067Y	14/10/2019	
---	-----------	----------------	----------	----------------------	--	-------------------------	----------	------------	--

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

With Regards

**Cynthia Ang**

Admin Assistant  
Operations, Motor & Personal Lines (PL)  
T +65 6430 7900

[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance. Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL ...

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/12/2019 15:23
Date Of Accident	16/12/2019 10:40
Exact Location Of Accident	BLK 192 PANDAN LOOP LOADING BAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK1647C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROBERT SIU WING CHAN
NRIC No	S2593322B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96638981
Alternative Phone No	OFFICE-96638981
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	116I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096528107-01(PREMIUM)
Cover Note Number	
<b>Driver</b>	
Name of Driver	ROBERT SIU WING CHAN
NRIC No	S2593322B
Date Of Birth	12/12/1951
Occupation	INDOOR
Date Of Driving Pass	12/04/1991
Driving Experience	28 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96638981
Fax Number	
Contact Number	OFFICE-96638981
Email Address	NOEMAIL

Address BLK 342 CHOA CHU KANG LOOP #11-27

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WILL EMAIL IF REQUIRED

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ7837E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver MR WU TIONG GHEE

NRIC/Passport Number S7642945F

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature

Date & Time: 12/16/2019  
3:22 pm.

\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
iDAP SUKMIT PATOK (VAC)

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle


<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	322B
<b>Vehicle Details</b>	
Vehicle No.:	SLK1647C
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCH DSC LED
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	34219747B37D15A
Chassis No.:	WBA1V72070V725431
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$25,133.00
Original Registration Date:	06 Jan 2017
First Registration Date:	06 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$12,187.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2027
PARF Rebate Amount:	\$9,140.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	05 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$35,313.00
<b>Total Rebate Amount:</b>	<b>\$44,453.00</b>

The information contained herein is correct as at 18 Dec 2019

OK



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**



Browse by Category

Sort by Date Posted 20 results/page

17 vehicles

BMW 1

Showing Results

Image	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
	BMW 1 Series 116d	\$74,888 / \$5,980 /yr		20-Jan-2017	1,496 cc	32,000 km	Hatchback	Available
	BMW 1 Series 116d	\$75,555 / \$9,833 /yr		24-Jan-2017	1,496 cc	21,548 km	Hatchback	Available
	BMW 1 Series 116d	\$104,800 / \$14,276 /yr		27-Feb-2017	1,496 cc	72,000 km	Hatchback	Available
	BMW 1 Series 116d	\$85,888 / \$10,412 /yr		27-Mar-2017	1,496 cc	21,500 km	Hatchback	Available
	BMW 1 Series 116d	\$79,800 / \$10,120 /yr		31-Mar-2017	1,496 cc	35,122 km	Hatchback	Available
	BMW 1 Series 116d	\$95,800 / \$10,187 /yr		29-May-2017	1,496 cc	31,000 km	Hatchback	Available
	BMW 1 Series 116d	\$85,000 / \$10,660 /yr		12-Jun-2017	1,496 cc	37,000 km	Hatchback	Available
	BMW 1 Series 116d	\$96,000 / \$10,550 /yr		27-Jun-2017	1,496 cc	18,880 km	Hatchback	Available
	BMW 1 Series 116d	\$78,900 / \$5,370 /yr		19-Jul-2017	1,496 cc	52,000 km	Hatchback	Available



Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLK1647C  
 Vehicle Reg. Date: 1/6/2017  
 Make / Model : B.M.W. 116D 5DR HATCH DSC LED  
 Engine No. : 34219747B37D15A  
 Chassis No. : WBA1V72070V725431

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT FENDER LH		\$ 597.25		
2	1	FRONT FENDER INNER SHIELD LH		\$ 105.40		
3	1SET	FRONT FENDER INNER SHIELD LH CLIPS		\$ 25.00		
4	1	FRONT DOOR LH	DD	\$ 1,082.75		\$ 1,082.75
5	1	FRONT DOOR WEATHERSTRIP LH		\$ 153.25		
6	1	FRONT DOOR OUTER HANDLE LH		\$ 459.20		
7	1	FRONT DOOR OUTER HANDLE CAP LH		\$ 33.10		
8	1	FRONT DOOR CATCH LH		\$ 56.05		
9	1	FRONT DOOR HINGE TOP LH		\$ 56.30		
10	1	FRONT DOOR HINGE BOTTOM LH		\$ 56.30		
11	1	FRONT DOOR INNER TRIM BOARD LH		\$ 1,035.60		
12	1SET	FRONT DOOR INNER TRIM BOARD CLIPS		\$ 25.00		
13	1	FRONT DOOR CHROME MOULDING LH		\$ 117.95		
14	1	FRONT DOOR CHECKER LH		\$ 67.00		
15	1	FRONT DOOR LOCK LH		\$ 246.75		
16	1	FRONT DOOR POWER WINDOW MOTOR LH		\$ 319.85		
17	1	SIDE MIRROR LH		\$ 743.35		
18	1	SIDE MIRROR COVER LH		\$ 122.00		
19	1	ROCKER PANEL LH		\$ 1,263.25		
20	1	REAR DOOR LH	DD	\$ 1,082.75		\$ 1,082.75
21	1	REAR DOOR WEATHERSTRIP LH	CRA	\$ 153.25		\$ 153.25
22	1	REAR DOOR OUTER HANDLE LH		\$ 66.15		
23	1	REAR DOOR OUTER HANDLE CAP LH		\$ 33.10		
24	1	REAR DOOR CATCH LH		\$ 56.05		
25	1	REAR DOOR HINGE TOP LH		\$ 58.90		
26	1	REAR DOOR HINGE BOTTOM LH		\$ 58.90		
27	1	REAR DOOR INNER TRIM BOARD LH		\$ 976.60		
28	1	REAR DOOR INNER TRIM BOARD CLIPS		\$ 25.00		
29	1	REAR DOOR CHROME MOULDING LH		\$ 117.95		
30	1	REAR DOOR CHECKER LH	BT	\$ 67.00		\$ 67.00
31	1	REAR DOOR LOCK LH		\$ 246.75		
32	1	REAR DOOR POWER WINDOW MOTOR LH		\$ 319.85		
33	1	REAR FENDER LH	DD	\$ 1,736.30		\$ 1,736.30
34	1	REAR FENDER INNER SHIELD LH	cut	\$ 131.75		\$ 131.75
35	1SET	REAR FENDER INNER SHIELD CLIPS	REC	\$ 25.00		\$ 25.00
36	1	REAR BUMPER		\$ 1,015.00		
37	1	REAR BUMPER RETAINER LH	CRA	\$ 138.50		\$ 138.50
38	1SET	REAR BUMPER CLIPS		\$ 25.00		
39	1	TAIL LAMP LH		\$ 367.10		
40	1	REAR SHOCK ABSORBER LH		\$ 255.40		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
 60 Jalan Lam Huat #03 - 35/36, Singapore (737869)  
 Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLK1647C  
 Vehicle Reg. Date: 1/6/2017  
 Make / Model : B.M.W. 116D SDR HATCH DSC LED  
 Engine No. : 34219747B37D15A  
 Chassis No. : WBA1V72070V725431

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR WHEEL HUB ASSY LH	BT	\$ 185.55		\$ 185.55
42	1	REAR RIM LH (NPH)	JCH		\$ 650.00	
43	1	REAR TYRE LH	SVL X		\$ 300.00	
44	0	0				
45	0	0				
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

4,607.25





# SLK1647C

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
60 Jalan Lam Huat #03 - 35/36, Singapore (737869)  
Tel : 6358 3031 | Fax No : 6694 4929

## ACCIDENT REPAIR ESTIMATE

TP INSURER :	<u>NTUC</u>	Vehicle Reg. No. :	<u>SLK1647C</u>
OWN INSURER :	<u>NTUC</u>	Vehicle Reg. Date:	<u>6-Jan-2017</u>
CLAIM TYPE :	<u>TP</u>	Make / Model :	<u>B.M.W. 116D 5DR</u>
Date of Accident :	<u>16/12/2019</u>	Engine No. :	<u>34219747B37D15A</u>
		Chassis No. :	<u>WBA1V72070V725431</u>

## COST OF CLAIMS

Parts Cost / List Items :	<u>\$ -</u>
Plus/Less <u>5%</u>	<u>\$ -</u>
Total Cost / List :	<u>\$ -</u>
Special Nett Items :	<u>\$ 950.00</u>
<b>Total Parts Amount :</b>	<u>\$ 950.00</u>
<b>Total Labour Amount :</b>	<u>\$ 5,350.00</u>
<b>Gross Total :</b>	<u>\$ 6,300.00</u>
GST % : <u>7%</u>	<u>\$ 441.00</u>
<b>Nett Amount :</b>	<u>\$ 6,741.00</u>

### Surveyor Name and Company :

Date of survey : \_\_\_\_\_

Part by Part / Lump Sum : \_\_\_\_\_ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : \_\_\_\_\_

Fax No : \_\_\_\_\_

HP No : \_\_\_\_\_

This claim is handled by : PAULO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLK1647C  
 Vehicle Reg. Date: 6/1/2017  
 Make / Model : B.M.W. 116D 5DR HATCH DSC LED  
 Engine No. : 34219747B37D15A  
 Chassis No. : WBA1V72070V725431

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT FENDER LH	X SVC			
2	1	FRONT FENDER INNER SHIELD LH	X SVC			
3	1SET	FRONT FENDER INNER SHIELD LH CLIPS	X SVC			
4	1	FRONT DOOR LH	/DD			
5	1	FRONT DOOR WEATHERSTRIP LH	? X SVC			
6	1	FRONT DOOR OUTER HANDLE LH	X SVC			
7	1	FRONT DOOR OUTER HANDLE CAP LH	X SVC			
8	1	FRONT DOOR CATCH LH	X SVC			
9	1	FRONT DOOR HINGE TOP LH	? X SVC			
10	1	FRONT DOOR HINGE BOTTOM LH	? X SVC			
11	1	FRONT DOOR INNER TRIM BOARD LH	X SVC			
12	1SET	FRONT DOOR INNER TRIM BOARD CLIPS	X SVC			
13	1	FRONT DOOR CHROME MOULDING LH	X SVC			
14	1	FRONT DOOR STICKER LH	? X SVC			
15	1	FRONT DOOR LOCK LH	X SVC			
16	1	FRONT DOOR POWER WINDOW MOTOR LH	X SVC			
17	1	SIDE MIRROR LH	X SVC			
18	1	SIDE MIRROR COVER LH	X SVC			
19	1	ROCKER PANEL LH	X SVC			
20	1	REAR DOOR LH	/DD			
21	1	REAR DOOR WEATHERSTRIP LH	? /CRU.			
22	1	REAR DOOR OUTER HANDLE LH	X SVC			
23	1	REAR DOOR OUTER HANDLE CAP LH	X SVC			
24	1	REAR DOOR CATCH LH	X SVC			
25	1	REAR DOOR HINGE TOP LH	? X SVC			
26	1	REAR DOOR HINGE BOTTOM LH	? X SVC			
27	1	REAR DOOR INNER TRIM BOARD LH	X SVC			
28	1	REAR DOOR INNER TRIM BOARD CLIPS	X SVC			
29	1	REAR DOOR CHROME MOULDING LH	X SVC			
30	1	REAR DOOR STICKER LH	? /BT			
31	1	REAR DOOR LOCK LH	X SVC			
32	1	REAR DOOR POWER WINDOW MOTOR LH	X SVC			
33	1	REAR FENDER LH	/DP			
34	1	REAR FENDER INNER SHIELD LH	? /cut			
35	1SET	REAR FENDER INNER SHIELD CLIPS	X /NEC			
36	1	REAR BUMPER	X R			
37	1	REAR BUMPER RETAINER LH	X /CRA			
38	1SET	REAR BUMPER CLIPS	X SVC			
39	1	TAIL LAMP LH	X SVC			
40	1	REAR SHOCK ABSORBER LH	X SVC			

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLK1647C  
 Vehicle Reg. Date: 6/1/2017  
 Make / Model : B.M.W. 116D SDR HATCH DSC LED  
 Engine No. : 34219747B37D15A  
 Chassis No. : WBA1V72070V725431

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR WHEEL HUB ASSY LH	X 2 / BT			
42	1	REAR RIM LH	BR / SCH		\$ 650.00	
43	1	REAR TYRE LH	X 3vc		\$ 300.00	
44	0	0				
45	0	0				
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022217/Qyf3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 18-02-2020



ATTN : CHARLOTTE CHEW

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 7837E	Veh. Inspected	SLK 1647C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1075939-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	17/12/2019

#### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 116D 5DR HATCH	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA1V72070V725431	Colour	BLUE
Odometer	65953 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	GOODYEAR	5 mm
L/H Front Tyre	205/55 R16	GOODYEAR	5 mm
R/H Rear Tyre	205/55 R16	GOODYEAR	5 mm
L/H Rear Tyre	205/55 R16	GOODYEAR	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	16/12/2019	Inspect Date / Time	17/12/2019 ( 03:02 PM )
Survey held at	60 JALAN LAM HUAT #03-35/36		
Repairer	VERMOGEN ACE PTE LTD		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1647C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT FENDER LH	SERVICEABLE	597.25	-
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	105.40	-
1	SET FRONT FENDER INNER SHIELD LH CLIPS	SERVICEABLE	25.00	-
1	FRONT DOOR LH	DENTED	1,082.75	1,082.75
1	FRONT DOOR WEATHERSTRIP LH	SERVICEABLE	153.25	-
1	FRONT DOOR OUTER HANDLE LH	SERVICEABLE	459.20	-
1	FRONT DOOR OUTER HANDLE CAP LH	SERVICEABLE	33.10	-
1	FRONT DOOR CATCH LH	SERVICEABLE	56.05	-
1	FRONT DOOR HINGE TOP LH	SERVICEABLE	56.30	-
1	FRONT DOOR HINGE BOTTOM LH	SERVICEABLE	56.30	-
1	FRONT DOOR INNER TRIM BOARD LH	SERVICEABLE	1,035.60	-
1	SET FRONT DOOR INNER TRIM BOARD CLIPS	SERVICEABLE	25.00	-
1	FRONT DOOR CHROME MOULDING LH	SERVICEABLE	117.95	-
1	FRONT DOOR CHECKER LH	SERVICEABLE	67.00	-
1	FRONT DOOR LOCK LH	SERVICEABLE	246.75	-
1	FRONT DOOR POWER WINDOW MOTOR LH	SERVICEABLE	319.85	-
1	SIDE MIRROR LH	SERVICEABLE	743.35	-
1	SIDE MIRROR COVER LH	SERVICEABLE	122.00	-
1	ROCKER PANEL LH	SERVICEABLE	1,263.25	-
1	REAR DOOR LH	DENTED	1,082.75	1,082.75
1	REAR DOOR WEATHERSTRIP LH	CRUMPLED	153.25	153.25
1	REAR DOOR OUTER HANDLE LH	SERVICEABLE	66.15	-
1	REAR DOOR OUTER HANDLE CAP LH	SERVICEABLE	33.10	-
1	REAR DOOR CATCH LH	SERVICEABLE	56.05	-
1	REAR DOOR HINGE TOP LH	SERVICEABLE	58.90	-
1	REAR DOOR HINGE BOTTOM LH	SERVICEABLE	58.90	-
1	REAR DOOR INNER TRIM BOARD LH	SERVICEABLE	976.60	-
1	REAR DOOR INNER TRIM BOARD CLIPS	SERVICEABLE	25.00	-
1	REAR DOOR CHROME MOULDING LH	SERVICEABLE	117.95	-
1	REAR DOOR CHECKER LH	BENT	67.00	67.00
1	REAR DOOR LOCK LH	SERVICEABLE	246.75	-

Report Ref No. CS/INC19022217/Qyf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR POWER WINDOW MOTOR LH	SERVICEABLE	319.85	-
1	REAR FENDER LH	DENTED	1,736.30	1,736.30
1	REAR FENDER INNER SHIELD LH	CUT	131.75	131.75
1	SET REAR FENDER INNER SHIELD CLIPS	NECESSARY	25.00	25.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,015.00	-
1	REAR BUMPER RETAINER LH	CRACKED	138.50	138.50
1	SET REAR BUMPER CLIPS	SERVICEABLE	25.00	-
1	TAIL LAMP LH	SERVICEABLE	367.10	-
1	REAR SHOCK ABSORBER LH	SERVICEABLE	255.40	-
1	REAR WHEEL HUB ASSY LH	BENT	185.55	185.55
	LESS 5% DISCOUNT		-685.36	-230.14
			13,021.84	4,372.71
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR RIM LH (SN)	SCRATCHED	650.00	650.00
1	REAR TYRE LH (SN)	SERVICEABLE	300.00	-
			950.00	650.00
	<b><u>LABOUR</u></b>			
	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. REAR RH SIDE PORTION. FRT FENDER LH, FRT DOOR LH, ROCKER PANEL LH, RR DOOR LH, RR FENDER LH, REAR BUMPER. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		2,000.00	800.00
	TO PUTTY & SPRAY PAINTING ACCIDENT AREA. REAR RH SIDE PORTION. FRT FENDER LH, FRT DOOR LH, ROCKER PANEL LH, RR DOOR LH, RR FENDER LH, SIDE MIRROR COVER LH, RR BUMPER.		2,000.00	800.00
	TO REMOVE AND TRANSFER FRONT DOOR LH COMPONENTS.		150.00	60.00
	TO REMOVE AND TRANSFER REAR DOOR LH COMPONENTS.		150.00	60.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		100.00	30.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY PARTS TO GIVE WAY THE REPAIR.		200.00	30.00
	TO RUST PROOF AFFECTED AREAS.		150.00	80.00

Report Ref No. CS/INC19022217/Qyf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE REAR SUSPENSION LH.		350.00	100.00
	TO PERFORM WHEEL ALIGNMENT. BEFORE AND AFTER.		250.00	60.00
			5,350.00	2,020.00
<b>GRAND TOTAL</b>			<b>19,321.84</b>	<b>7,042.71</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>5,600.00</b>

Report Ref No. CS/INC19022217/Qyf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.