

ASS. REC. BY:

REF:

CS3/A2G19022271/HAF307

Special Instruction:

Survivor

Huck Ann

ASSIGNMENT (Office)

From (Person):

Winnifan

of

A2G

Date/Time:

18-12-19 8.48am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMN 48176

Insured:

SDV 3533X

at Workshop m/s

Apex Motoring

Tel:

91690325

of

205 Kaki Bukit Road 4 #01-55 Synergy

Policy No:

Claim No:

5738197008SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15-12-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18.12.19 12.04pm

Person Contacted:

Rei Jie

Vehicle


IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SDV 3533X - CS3/A2G19022238/A2G3 DOA: 15/12/2019
	SMN 48176: X
	Dismantle: 19/12/2019
	After paint / / pending workshop update.

ASSIGNMENT

From: Date:   
 Estimated Cost:   
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV   
 To Inspect Vehicle No: SMN 4817 G   
 at Workshop n/s Apex motoriz   
 of 25 Kaki Bukit rd 4 #01-55   
 Insured: Synergy   
 Policy No.   
 Claims No.   
 Sum Insured: Excess:   
 (Client's Record)   
 Make of Veh:

(Policy Condition)   
 Remark: The veh had commenced its   
 repair at the time of inspection.



Bal. or Market Value:   
 IDAC Accident Rpt: Consistent? : Yes or No   
 GIA / PR Seen: Consistent? : Yes or No   
 Est. Repairs: 5 days Res.: Yes or No   
 Lum Sum: % 3 Val.: Yes or No   
 CA / REV / REP. / 24 HRS   
 Date: Person Contacted:   
 Vehicle: IN / OUT

Veh No: SMN 4817 G Yr Regn: 14/08/2019   
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /   
 Truck / Trailer or   
 Make: H. FREE c.c. 1497   
 Colour: Grey A/C: Insured / Std / NI / NA   
 Sp. Reading: 027753100 T/Radio: Insured / Std / NI / NA   
 Eng/No:   
 C/No: 7B71102214   
 Gen. Cond: Good / Fair / Poor / Burnt   
 Steering: Inorder / Jammed / Leaked / Burnt or   
 Brake: Inorder / Jammed / Leaked / Burnt or   
 Modi: Nil / S/Rim / STD A/Rim or   
 Tyre Size: F: R: 185/65/R15   
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /   
 TOYO / YOKO or   
 Front: 6 Yokohama R/Bal. 67 Yokohama   
 L/Bal. 6 mm L/Bal. 6 mm   
 D.O.A. 15/12/14 D.O.I. 18/12/14   
 Survey held at Apex motoriz   
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	DAN - OK
	Days - 5
	UV - 90000
	PV - 53376
	NV - 36600

RECEIVED 05 MAR 2020

Date/Time, File Pass to?   
 ☐ : Prell. Report   
 ☐ : Final Report

Days Of Repair: 5   
 Resurvey No. of Trip:

5/3/20 Typist

Report Format: PRS   
 Large Print / B&W:

Add Fee:   
 ☐ : Site Insp (\$   
 ☐ : Interview (\$   
 ☐ : Tech. Invs (\$   
 ☐ : Weekend (%)

Survey Fee:	180
Transportation:	
S + PS \$	
Photos	
Glasses	11
TOTAL	191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 <a href="#">Edit Reg</a>		18 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>SEE SOON KEONG</b> , ID: S7271756B									
Main Claimant: <b>ADVANCE CR PTE LTD</b> , Co. Reg. No.: 201320997M									
Vehicle Reg. No.: <b>SMN4817G</b>		Date of Loss: 15/12/2019 00:00 - :59							
Claim Type: <b>TP / 5738197008SG</b>		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SDV3533X</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Apex Motoring ( )</b> 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-WZ.Tan@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 30/12/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (19/12/2019): TP GIA report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Fan, Winnie-LW <Winnie-LW.Fan@aig.com>  
**Sent:** Wednesday, 18 December, 2019 8:48 AM  
**To:** Admin A; assignments  
**Cc:** Fong, Andy-SY  
**Subject:** Aigencypt RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDV3533X AND SMN4817G ON 15/12/2019  
**Attachments:** SMN4817G.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

### -----Original Message-----

**From:** [peijie@expresscar.com.sg](mailto:peijie@expresscar.com.sg) <[peijie@expresscar.com.sg](mailto:peijie@expresscar.com.sg)>  
**Sent:** Monday, December 16, 2019 5:31 PM  
**To:** ClaimsDocManagement <[ClaimsDocManagement@aig.com](mailto:ClaimsDocManagement@aig.com)>  
**Subject:** [EXTERNAL] Accident between Vehicle No. SMN 4817 G and Vehicle No. SDV 3533 X on 15122019 @ 1705Hrs

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Kindly refer to attach for Pre-repair inspection.  
Thanks.

--

Best Regards,  
Peijie  
82 Lorong 23 Geylang  
#03-06 ATRIX  
S(388409)  
DID: 91690825

Veh In.  
PRE



16/12/2019

**AIG Asia Pacific Insurance Pte Ltd**  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120  
Fax : [ClaimsDocManagement@aig.com](mailto:ClaimsDocManagement@aig.com)

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SMN 4817 G AND VEHICLE NO. SDV 3533 X ON 15/12/2019 @ 1705 Hrs**

We are the appointed repair workshop of vehicle no. **SMN 4817 G**.

We understand that you are the insurer of vehicle no. **SDV 3533 X**.

The owner of vehicle number **SMN 4817 G** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800  
Mobile No. 91690825 / [pei jie@expresscar.com.sg](mailto:pei jie@expresscar.com.sg). Ms Lim

Yours faithfully



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/12/2019 16:44
Date Of Accident	15/12/2019 17:05
Exact Location Of Accident	CLEMENTI AVE 02 FILTER LANE TWRDS AYE(TUAS)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN4817G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ADVANCE CR PTE LTD
Co Reg No	201320997M
Email Address	PEIJIE@EXPRESSCAR.COM.SG
Mobile Phone No	(LOCAL) +65-91998131
Alternative Phone No	OFFICE-68424992

### Vehicle Particulars

Manufacturer	HONDA
Model	HONDA / FREED HYBRID 1.5G AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29130960 MCX
Cover Note Number	

### Driver

Name of Driver	LEE YIP MENG
NRIC No	S1228029G
Date Of Birth	24/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	16/01/1980
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96521803
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 706 CLEMENTI WEST STREET 2 #03-383
Postcode	120706
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

STOPPED AT THE STOP LINE AND VEHICLE SDV3553X COLLIDED ONTO MY VEHICLE REAR PORTION

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDV3553X
Vehicle Make/Model/Colour	AUDI / Q7 2.0 TFSI QU (252 BHP)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	LEE YIP MENG
Approximate Age	
Injuries Sustain	-3 DAY MC-
Injured person in which vehicle?	SDV3553X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 706 CLEMENTI WEST STREET 2 #03-383
Postcode	120706



# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renew policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon applications by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my Insurer (collectively, the "Personal Information"), and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government security/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail postmarks and/or
  - (v) complying with applicable laws with administrative, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be effected outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 16/12/19

Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/12/19

Reporting Centre Personnel's Signature

Name:

REC/PM No.:

16 DEC 2019

# Accident Sketch Plan

A-SMN 48176  
B-CDV 3333X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref e-ble

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 16/12/19 12:15PM

Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/12/19 12:15PM

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vac@idac.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: 16 DEC 2019

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	997M
Vehicle Details	
Vehicle No.:	SMN4817G
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	LEB5643580
Chassis No.:	GB71102214
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$26,937.00
Original Registration Date:	14 Aug 2019
First Registration Date:	14 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$19,712.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2029
PARF Rebate Amount:	\$14,784.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$38,592.00
<b>Total Rebate Amount:</b>	<b>\$53,376.00</b>

The information contained herein is correct as at 20 Dec 2019

OK



Honda Min Price to No Max Depreciation Vehicle Type Category

Home » New Cars » New Car Brands » Honda » Honda Freed Hybrid

## Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

## Featured Merchants



## Related Articles



2019's most popular Japanese Parallel Import cars



Honda unveils the Insight Sports Modulo concept



New Honda Freed to arrive in Singapore



## Honda Freed Hybrid (Parallel Imported)

Select Another Make Select The Make

Overview Pricing Photos Research Reviews Specs Features Similar Accessories Prom

Add to Shortlist Submit a Review Report Error Share



USER RATINGS: (3 reviews)

## Details

**Sold by** Parallel Importers | 39 dealers  
**Built in** Japan (launched 2016)  
**Variants** 5 submodel(s) » Show pricelist  
**Predecessor** Honda Freed Hybrid (2014-2015)  
**Promotion** 2020 Facelifted Honda Sensing Model! Guarantee COE Without Up! Full Accessories, CASETRUST SVTA Accredited

» View 1 promotions for Freed Hybrid

Add to Shortlist

We have some dealers currently running very good deals on the Honda Freed Hybrid. Get them to contact you directly with more info.

Name\*

☐ I'm not a robot

reCAPTCHA  
Privacy - Terms

Submit

Contact No\*

Submodel	RRP	Depreciation	ECO	Power	Detailed
<b>1.5 G (A)</b>	\$102,000 Pricelist		25km/L	135bhp	Specs   Fei
<b>1.5 G Honda Sensing (A)</b>	\$104,000 Pricelist		25km/L	135bhp	Specs   Fei
<b>1.5 G Dual Power Sliding Doors (A)</b>	\$106,000 Pricelist		25km/L	135bhp	Specs   Fei
<b>1.5 G Honda Sensing Dual Power Sliding Doors (A)</b>	\$108,000 Pricelist	-	25km/L	135bhp	Specs   Fei
<b>1.5 G Welcab (A)</b>	\$126,000 Pricelist	-	26.6km/L	135bhp	Specs   Fei

Verified Ready Stocks are vehicles that have cleared all LTA paperwork and ready to be registered immediately. This is verified by sgCarMart with the VITAS Approval Code (VAC) issued by LTA.   
 » View all the Honda Freed Hybrid that are Ready Stock.

Showing 9 out of 39 dealers selling this vehicle

**Autopoint Automobile Pte Ltd**  
Tel: 91288877

**Leco Auto**  
Tel: 68460020 / 97846364

**Straits Euro Motors**  
Tel: 64562277 / 90992277

Think One Automobile

Car Pulse

Tan Wei Auto

# MOTORCAR (Rear)

## Rear Portion

NAC	INC	Item	CON	AC	Q5
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CRA	✓	1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	CRA	✓	1
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	CRA	✓	1
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	Shut	✓	1
1159	993327	Rear End Panel	R	✓	1
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	1
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	BT	✓	1
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem	BT	✓	1
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BT	✓	1
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CRA	✓	1
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass	CRA	✓	1
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA	✓	1

Vehicle No: SMN 48174

NAC	INC	Item	CON	AC
1202	993784	Spare Tyre Board		
1203	994328	Spare Tyre Panel		
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender	BT	✓
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel	R	✓
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993471	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		
		tail gate Hybrid logo		
		fuel tank		

No of Items:

Assessor:

H-AN

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2019 <a href="#">Edit Reg</a>		18 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by adjuster]</span>									
Insured: <b>SEE SOON KEONG</b> , ID: S7271756B									
Main Claimant: <b>ADVANCE CR PTE LTD</b> , Co. Reg. No.: 201320997M									
Vehicle Reg. No.:	<b>SMN4817G</b>	Date of Loss:	15/12/2019 00:00 - :59 [4 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 5738197008SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SDV3533X</b>	Policy No. (Claimant):							
		Excess:							
Repairer: <b>Apex Motoring ( )</b> 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Boyogan, Joane</b> ] Joane.Boyogan@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 30/12/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (19/12/2019): TP GIA report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*SMN4817G (5738197008SG)**  
**[SDV3533X]**  
**TP**  
**ADVANCE CR PTE LTD**  
**Dec 15 2019 12:00AM**  
**[SEE SOON KEONG]**  
**Apex Motoring**

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Video											1 per page		<div></div>	<div></div>
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)									Thumbnail	Print	
1	19/12/19 15:41		Video - Accident								<div></div>	Load MP4		
													<div></div>	<div></div>
Photos/Images											3 per page		<div></div>	<div></div>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	23/12/19 19:29		Chassis Number								<div></div>	Load JPG	<div></div>	
2	23/12/19 19:29		Odometer Reading								<div></div>	Load JPG	<div></div>	
3	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
4	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
5	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
6	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
7	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
8	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
9	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
10	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
11	23/12/19 19:29		General View								<div></div>	Load JPG	<div></div>	
12	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
13	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
14	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
15	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
16	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
17	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
18	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
19	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
20	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
21	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
22	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
23	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
24	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
25	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
26	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
27	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
28	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
29	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
30	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
31	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
32	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
33	23/12/19 19:30		General View								<div></div>	Load JPG	<div></div>	
34	23/12/19 19:30		General View								<div></div>	Load JPG		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/12/19 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	23/12/19 19:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	23/12/19 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/19 15:40	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022271/HYF3E2

Date: 06/03/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMN4817G

Insured Vehicle No : SDV3533X

Date of Loss: 15/12/2019

Nature of Claim: TP

Claim No: 5738197008SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN4817G

Make &amp; Model: HONDA FREED HYBRID, 1.5 G (A)

Engine No: LEB5643580

Reg. Date: 14/08/2019 (Man. Year: 2019)

Chassis No: GB71102214

Colour: Grey

Odometer: 27753 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 18/12/2019 Inspected At:

Apex Motoring

25 Kaki Bukit Road 4, #01-55 Synergy @

KB

Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Crumpled	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER R/H	Necessary	0.00 F	*- F
5	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
8	1		*REAR RH TAILLAMP PANEL	Bent	0.00 F	*- F
9	1		*TAILGATE	Bent	0.00 F	*- F
10	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE LAMP R/H	Cracked	0.00 F	*- F
12	1		*TAILGATE GLASS	Cracked	0.00 F	*- F
13	1		*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
16	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
17	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
18	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
19	1		*REAR RH FENDER	Bent	0.00 F	*- F
20	1		*REAR RH FENDER INNER PANEL	Repair	0.00 F	*- F
21	1		*TAIL GATE HYBRID LOGO	Necessary	0.00 F	*- F
22	1		*TAIL GATE FREED LOGO	Necessary	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >