

ASS. REC. BY:

REF: CS/EG1902223/As f3

Special Instruction:

Advisor: Adrain ASSIGNMENT (Office)

From (Person): Pauline Soh of Grpo Date/Time: 18.12.19 10.39a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 7425K Insured: YP 9101C

at Workshop m/s: Fastrich Tel: 6746 5405

of 1 Kaki Bukit me 6 #01-41/48/50

Policy No: _____ Claim No: CDMCG19002391

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12.12.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement: _____

Date/Time: 18.12.19 1.19p.m Person Contacted: Lina Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>YP9101C X</u>
	<u>GBJ 7425K X</u>
<u>19/12/19</u>	<u>at 16:01 pm revert pending estimate from repairer to Pauline Soh via M. Minin.</u>

Minin

Adrian

ASSIGNMENT

GBJ7425K 2019 July

Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To inspect Vehicle No _____
 at Workshop no _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Client's Record)
 Make of Veh: _____

Veh No: GBJ7425K Page _____
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Nissan NU350 Reg: 2488
 Colour: white A/C: Insured / Std / NI / NA
 Sp Reading: 13809 T/Ratio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1MC2E2620081272
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195 R15C
 R: 195 R15C
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt. Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

Front Rear
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. _____ D.O.I. 18/12/19
 Survey held at: Fawlech

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Front w/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Ergo

MV:
 PV:
 Nett:

RECEIVED 05 MAR 2020

Adrian Confirmed 45 ~~45~~ \$1,500/- @ 3 days with Bass
 (\$ 13,419.10 Red - 90%)

Date/Time: File Pass to? 05/03/20
 Type: Preli. Report
 Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 2

Report Refused:
 \$ 1,500/- 45

Artd Fee: Site Insp: 15
 Interview: 15
 Transport: 15
 Other: _____

Survey Fee:	350
Transportation:	11
	361

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Wednesday, 18 December 2019 10:39 AM
To: Ong Shiyong; Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Jason; Lina Pang; Ivy Yong; Phoebe Xie
Subject: RE: Claims ref no. (P) CDMCG19002391 REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 7425K DOA: 12.12.2019

Date Classification : Confidential, C3

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Ong Shiyong [mailto:shiyong.ong@fastechauto.com.sg]
Sent: Wednesday, 18 December 2019 10:01 am
To: ERGO Insurance Pte. Ltd. (Claims Department); Pauline Soh
Cc: Jason; Lina Pang; Ivy Yong; Phoebe Xie
Subject: RE: Claims ref no. (P) CDMCG19002391 REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 7425K DOA: 12.12.2019

Without Prejudice

Dear Sir and Madam,

Please arrange (LKK AUTO CONSULTANTS) to conduct the pre- repair survey.

Thank you.

Regards,
Shiyong
Fastech Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-46/48/50
Autobay Singapore 417883
Tel: 6746 5405
Fax: 6745 8520

From: ERGO Insurance Pte. Ltd. (Claims Department) [<mailto:claims@ergo.com.sg>]
Sent: Wednesday, December 18, 2019 9:54 AM
To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>; Pauline Soh <pauline.soh@ergo.com.sg>
Cc: Jason <jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>
Subject: RE: Claims ref no. (P) CDMCG19002391 REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 7425K DOA: 12.12.2019

Date Classification : Confidential. C3

Dear Shiyong

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05, Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Ong Shiyong [mailto:shiyong.ong@fastechno.com.sg]
Sent: Tuesday, 17 December 2019 11:27 am
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Jason; Lina Pang
Subject: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 7425K DOA: 12.12.2019

Without Prejudice

Dear Sir/Madam

Your insured's vehicle: YP 9101C.

Date of accident: 12/12/2019

Please arrange Pre-repair Inspection for my client's vehicle no: GBJ 7425K.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Regards,
Shiyong
Fastechno Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-46/48/50
Autobay Singapore 417883
Tel: 6746 5405
Fax: 6745 8520

View Sent Message

This mail is associated with :

***GBJ7425K**
[YP9101C]
TP

Dec 12 2019 12:00AM

Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 19/12/2019 16:01 PM.
To claims@ergo.com.sg
CC sur@lkkauto.com
Subject GBJ7425K [YP9101C] TP CLAIM NO - CDMCG19002391

Dear Pauline,

Please be informed that we have inspected the vehicle GBJ 7425K on 18/12/2019.

We are pending estimate from repairer.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2019 16:43
Date Of Accident	12/12/2019 17:55
Exact Location Of Accident	SLE NEAR EXIT OF MANDAI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ7425K
Insured/Policyholder	
Name Of Registered Owner	GRADECOOL AIR-CONDITION PTE.LTD.
Co Reg No	A201538249E
Email Address	ENQUIRY@GRADECOOL.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67479707

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900141744

Cover Note Number

Driver

Name of Driver	TEOH NGAM SENG
NRIC No	S2760326B
Date Of Birth	25/05/1956
Occupation	OUTDOOR
Date Of Driving Pass	23/04/2002
Driving Experience	17 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98635137
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address APT BLK 105 PASIR RIS STREET 12
#08-91

Postcode 510105

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : LEE WEI KEONG
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACHED SKETCH PLAN, PHOTO AND VIDEO

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP9101C

Vehicle Make/Model/Colour HINO

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The **issue and acceptance** of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten Signature]


GRADIENT INDUSTRIAL PTE LTD
19 UBI ROAD
SINGAPORE 408623
TEL: 6450 8888 FAX: 6456 7655

Reporting Centre Personnel's Signature
Name: *[Handwritten Name]*
NRIC/FIN No.: *[Handwritten Number]*

SKETCH PLAN

A - GBJ742SK
B - YP9101C

SLE NEAR EXIT MANDAI



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLS REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

GRAND PACIFIC INDUSTRIAL PTE. LTD.
19 UBI ROAD 4
SINGAPORE 408633
TEL: 670 9277 FAX: 6848 7111

Reporting Centre Personnel's Signature
Name: **EMER ALFONSO**
NIC/FIN No.: **GXXXXXX4L**

[Signature]



**SINGAPORE
POLICE FORCE**



T/20191212/2200

1 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20191212/2200

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/12/2019 21:21	Vide Report No.:	Station Diary No.: 80
--------------------------------------------	------------------	--------------------------

Informant's Particulars

Name of Informant: TEOH NGAM SENG		Address: APT BLK 105 PASIR RIS STREET 12 #08-91 SINGAPORE 510105	
ID Type / ID No.: NRIC NO / S2760326B		Contact No.: Home/Office: Mobile: 98635137	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 63	Date of Birth: 25/05/1956	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Technician		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 12/12/2019 17:55	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY SLE towards exit of Mandai				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBJ7425K	Van	NISSAN	NV350 PANEL VAN 5DR 2.5 5AT	White	Slightly Damaged	1
YP9101C	Lorry	HINO	XZU710R 14FT WIDE CAB 5T	White	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20191212/2200

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5652999

Report No. T/20191212/2200

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEOH NGAM SENG	ID No.	S2760326B
Related Vehicle	GBJ7425K (Van)	Contact No.	98635137
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	VINCENT KUMAR S/O PADRASAN	ID No.	S7145578E
Related Vehicle	YP9101C (Lorry)	Contact No.	96557391
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/12/2019 at about 4.55pm, I was on my way to work at Woodlands. While driving on SLE highway towards Mandai exit on the 2nd lane, I lorry which was driving on the middle lane at the back suddenly took over me by cutting from my left side. After taking over my vehicle, I felt an impact as such I parked my vehicle by the road shoulder to make a check. The vehicle whom took over me also stop. As such, we exchanged contact number on the spot. The other party was not happen and insisted that it was my fault for not giving way. He did not want to settle it privately. As such, I decided to make a police report.

When I returned back to my office, my boss viewed my in car CCTV and found out that the reason why the other party overtook me from the left is because on the middle lane, there was another lorry in front of him. As such, he could not overtake from the right side.

No one was injured during that point of time.



SINGAPORE
POLICE FORCE



T/20191212/2200

3 of 3

Report No. T/20191212/2200

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 JOEL NATHANIEL ZAI JUNJIE 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 12/12/2019 21:21
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 21594

Date : 17.12.2019

Vehicle Num : GBJ 7425K

Make/Model : NISSAN NV 350

Chassis/Engine no :

Accident Date : 12.12.2019

Claim No : 1219-21594

Reference :

Policy No :

TP Ergo
Shirley
JNIMC2E2620031272

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Front bumper <i>toin</i>	\$ 985.20 ✓ ⁶¹²
1 pc	Front bumper side bracket LH <i>Me</i>	\$ 185.60 ⁵⁸
1 pc	Front door LH <i>regr</i>	\$ 1,885.20 +
1 pc	Front door inner board <i>Me</i>	\$ 915.20 +
1 pc	Front door pillar LH <i>regr</i>	\$ 825.20 +
2 pc	Front door hinge @ 98.50 <i>?</i>	\$ 197.00 +
1 pc	Front door inner lock LH <i>regr</i>	\$ 296.60 +
1 pc	Front door wing mirror LH <i>regr</i>	\$ 625.30 +
1 pc	Front step garnish LH <i>regr</i>	\$ 241.20 +
1 pc	Headlamp assy LH <i>combed</i>	\$ 925.20 ⁴⁸¹
1 pc	Front knuckle arm (LH) <i>?</i>	\$ 765.20 +
1 pc	Fog lamp cover LH	\$ 155.20 +
1 pc	Front shock absorber LH <i>Me</i>	\$ 425.20 +
1 pc	Cooler LH <i>Me</i>	\$ 1,950.00 +
1 pc	Front wheel bearing LH	\$ 325.20 +
1 pc	Front lower arm LH <i>?</i>	\$ 596.50 +
	Nett Item Total :	\$ 11,299.00
	Discount 10 % :	\$ 1,129.90
		\$ 10,169.10

1151
1035.90

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 21594

Date : 17.12.2019

Vehicle Num : GBJ 7425K

Make/Model : NISSAN NV 350

Chassis/Engine no :

Accident Date : 12.12.2019

Claim No : 1219-21594

Reference :

Policy No :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

1 pc	Front tyre LH } <i>new</i>	\$ 250.00 +
1 pc	Front rim LH } <i>new</i>	\$ 280.00 +
10pc	Front door inner board clips @ 5.00 <i>new</i>	\$ 50.00 +
1	Front door company name sticker <i>new</i>	\$ 40.00 <i>30</i>
1	Front door sticker <i>new</i>	\$ 60.00 <i>50</i>
Special Nett Total :		\$ 680.00

Labour Charge :

To check wiring	<i>830</i>	\$ 150.00 <i>30</i>
Tuff kote		\$ 150.00 +
Remove and refix door mechanism item		\$ 200.00 +
To check wheel alignment		\$ 120.00 +
Remove and replace front undercarriage		\$ 450.00 +
Panel beating and replace spare part		\$ 1,500.00 <i>400</i>
Spray painting effected area		\$ 1,500.00 <i>400</i>
Labour Charge Total :		\$ 4,070.00

Adrian L
4/3 18/12/19
03 Days

E & O . E Total Amount : \$ 14,919.10

Total: 1945.90

W/S: 15K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19022273/ASF3N2
Date: 06/03/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBJ7425K **Insured Vehicle No :** YP9101C
Date of Loss: 12/12/2019 Nature of Claim: TP Claim No: CDMCG19002391

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7425K**
Make & Model: NISSAN NV350, 2.5 5AT 5DR EURO V (A) Engine No: YD25052174B
Reg. Date: 30/07/2019 (Man. Year: 2019) Chassis No: JN1MC2E26Z0031272
Colour: White Odometer: 13809 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,849.10	1,115.90	9,733.20	89.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	830.00	3,240.00	79.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,919.10	1,945.90	12,973.20	86.96
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	14,919.10	1,500.00	13,419.10	89.95
+ GST 7.00/7.00% (S\$)	1,044.34	105.00	939.34	89.95
Nett Amount (S\$)	15,963.44	1,605.00	14,358.44	89.95

INSPECTION

Date of Assignment: 18/12/2019
Date Inspected: 18/12/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 06 Mar 2020)**Parts:** N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBJ7425K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	985.20 FL	*612.00 FL
2	1		*FRONT BUMPER SIDE BRACKET LH	Necessary	185.60 FL	*58.00 FL
3	1		*FRONT DOOR LH	Repair	1,885.20 FL	*- FL
4	1		*FRONT DOOR INNER BOARD	Not Necessary	915.20 FL	*- FL
5	1		*FRONT DOOR PILLAR LH	Repair	825.20 FL	*- FL
6	2		*FRONT DOOR HINGE	Not Necessary	197.00 FL	*- FL
7	1		*FRONT DOOR INNER LOCK LH	Not Necessary	296.60 FL	*- FL
8	1		*FRONT DOOR WING MIRROR LH	Not Necessary	625.30 FL	*- FL
9	1		*FRONT STEP GARNISH LH	Repair	241.20 FL	*- FL
10	1		*HEADLAMP ASSY LH	Cracked	925.20 FL	*481.00 FL
11	1		*FRONT KNUCKLE ARM (LH)	Not Necessary	765.20 FL	*- FL
12	1		*FOG LAMP COVER LH	Not Necessary	155.20 FL	*- FL
13	1		*FRONT SHOCK ABSORBER LH	Not Necessary	425.20 FL	*- FL
14	1		*COOLER LH	Not Necessary	1,950.00 FL	*- FL
15	1		*FRONT WHEEL BEARING LH	Not Necessary	325.20 FL	*- FL
16	1		*FRONT LOWER ARM LH	Not Necessary	596.50 FL	*- FL
17	1		*FRONT TYRE LH	Not Necessary	250.00 FS	*- FS
18	1		*FRONT RIM LH	Not Necessary	280.00 FS	*- FS
19	1		*FRONT DOOR INNER BOARD CLIPS	Not Necessary	50.00 FS	*- FS
20	1		*DOOR COMPANY NAME STICKER	Necessary	40.00 FS	*30.00 FS
21	1		*DOOR STICKER	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,979.00	1,231.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,129.90	115.10
Total Parts (\$\$)	10,849.10	1,115.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	30.00
2	TUFF KOTE	New	150.00	0.00
3	REMOVE AND REFIX DOOR MECHANISM ITEM	New	200.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	0.00
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE	New	450.00	0.00
6	PANEL BEATING AND REPLACE SPARE PART	New	1,500.00	400.00
7	SPRAY PAINTING EFFECTED AREA	New	1,500.00	400.00
Gross Labour Cost (S\$)			4,070.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >