

ASS. REC. BY:

REF: CS3/A2G19022274/71v-f30 Special Instruction:

u/vajoy

TANSHH

ASSIGNMENT (Office)

From (Person): Winnie Fan of ALG Date/Time: 18.12.19 1.30p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 5748R Insured: SMD 4663K

at Workshop m/s Super modern Tel: 62568830

of 25 Kati Bukit Rd 4 101-21 synergy

Policy No: Claim No: 9590628878 SG

Sum Insured: Excess:

Make of Veh: D.O.A. 14.12.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18.12.19 1.40p.m. Person Contacted: madam Teh H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 4663K X
	SLB 5748R X
19/12/19	@ 238pm Mdm Teh said no est
21/1/2020	Submit DAR report

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB 5748R

Yr Regn:

16

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vozel

c.c.

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

51483

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11115261

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

77

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/12/19 @ 4:10pm

Survey held at

Super Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

25 KR RA4 #01-21

Date / Time	Action / Instruction
1	No GIA, 6 days

RECEIVED 02 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 2/1 - typist

Report Format:

Lump Sum / L.E.R. (%)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

3 + RS, SI

Phone

Others

TOTAL

180

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2019 Edit Reg		18 Dec 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KINETIC ALLIANCE PTE LTD , Co. Reg. No.: 201613074E								
Main Claimant:	LUM YEW KUAN , ID: S0009000Z								
Vehicle Reg. No.:	SLB5748R	Date of Loss:	14/12/2019 00:00 - :59						
Claim Type:	TP / 9590628878SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SMD4663K	Policy No. (Claimant):							
		Excess:							
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4 , # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (19/12/2019): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMD4663K AND SLB5748R ON 14/12/2019

From: Fan, Winnie-LW
To: Admin A, assignments
Cc: Fong, Andy-SY
Sent: Wednesday, 18 December, 2019 1:30:47 PM
Attachments:  9233 - SAS of SLB 5748R 20191217145853.pdf

Hi LKK,

Kindly assist to survey, vehicle in.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Oracle Law Corp <mail@oraclelaw.sg>
Sent: Wednesday, December 18, 2019 12:05 PM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Subject: [EXTERNAL] RE: Our Ref: SB/PO/Acc/2019-9233 Your Ref: Insurer of SMD 4663K (9590628878SG003)

This message is from an external sender; be cautious with links and attachments.

Dear Yinrul,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SLB 5748R & SMD 4663K AT CAUSEWAY INTO JOHOR BAHRU ON 14-12-2019 @ 8.10 A.M.

Please refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11

The Alexier, Singapore 159929

Telephone: 6538 6250 Facsimile: 6538 1860

Super modern
25 Kaki Bukit Rd 4
#01-21 Synnott
Ndm Teoh 91525152 / 62568820

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	000Z
Vehicle Details	
Vehicle No.:	SLB5748R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4035267
Chassis No.:	RU11115261
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,980.00
Original Registration Date:	14 Apr 2016
First Registration Date:	14 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$11,372.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2026
PARF Rebate Amount:	\$8,529.00
Intended COE Rebate Details	
COE Expiry Date:	13 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$29,070.00
Total Rebate Amount:	\$37,599.00

The information contained herein is correct as at 19 Dec 2019

OK

IMPORTANT NOTICE

1. Please report correctly the details of the Accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Helpline Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report at the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT

Date Of Report 16/12/2019 14:17
 Date Of Accident 14/12/2019 08:10
 Exact Location Of Accident CAUSEWAY TWEDS JOHOR BAHRU
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB5748R
Insured/Policyholder
 Name Of Registered Owner LUM YEW KUAN
 NRIC No S00090002
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96333351
 Alternative Phone No OFFICE-06333351
Vehicle Particulars
 Manufacturer HONDA
 Model VEZEL 1.5X CVT ABS DIARBAG 2WD
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 6078182335-03
 Cover Note Number DRIVO CLASSIC
Driver
 Name of Driver LUM NAM CHUAN
 NRIC No S5927393E
 Date Of Birth 05/08/1989
 Occupation INDOOR
 Date Of Driving Pass 02/01/2009
 Driving Experience 10 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97597584
 Fax Number
 Contact Number
 Email Address NOEMAIL

If No, Relationship of the Driver with the Insured

PARENT

Vehicle Registration Number of Driver's Own

-

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions DRIZZLING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance NO

Number of Passengers (including Driver) 4

Passenger 1 NAME: LUM YEW KUAN
GENDER: MALE

Passenger 2 NAME: TAN NGAK TEOW
GENDER: FEMALE

Passenger 3 NAME: TIEW YEN FONG
GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recording? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMX466JK
Vehicle Make/Model/Colour TOYOTA / PRIUS AUTO

Details Of Properties

Vehicle Category PRIVATE CAR
Name of Driver WONG CHANG KIT (WANG ZHENJIE)
NRIC/Passport Number S8229025E
Contact Number 97989497

No. Of Damage
No. Of Passenger (including Driver)
Passenger 1

FRONT PORTION
2

NAME

GENDER

PLEASE NOTICE

WHICH PLAN


1. Please report **immediately** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy benefits**.
4. The issue and acceptance of this form by insurance companies is not an expression of policy liability on the part of the insurance companies.
5. **Any false statement may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the Risk Records Management Centre established for the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you remain consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIAS") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (a) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (b) investigating the accident and/or my claims;
 - (c) carrying out and/or dealing with my instructions or responding to any enquiries to me;
 - (d) administering my claims (including the mailing of correspondence, statements, checks, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as in the external cover of envelopes/mail packages) and/or
 - (e) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are disclosed by any of the insurers and/or (b) to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (b) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, settling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 16/12/19
2:25pm

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/12/19
2:24pm

EMAC KAKI BUKIT (YAC)
25 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416097 Fax: 67482305
Email: yack@emac.com.sg

Reporting Centre Personnel's Signature
Name:
Date/Time: 16 DEC 2019



On 10/31/10 at 8:10 am, my car was stationary at the County Courthouse. I was waiting in a parking lot. I was waiting at the rear of my vehicle when I was struck by a motor vehicle. I was struck by a motor vehicle which was hit the rear of my vehicle.

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Physician's Signature _____
Date & Time 10/07/19 2:28pm

Driver's Signature _____
 Of power is not the policyholder
 Date & Time: 6/12/19
 2:23pm

IDAC KAJI BUKIT (VAC)
 25 Kajai Bukit Ave 4 #02-02
 Singapore 415933
 Tel: 67410697 Fax: 67492309
 Email: vackb@idac.com.sg

Reporting Center Personnel's Signature
Name: _____
DATE/TIME: _____ DEC 2019

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (NC)

Rear Portion

Vehicle No: SLB5748R

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	de	✓	
1142	993085	Rear Bumper side RH	Rx		
1143	993017	Rear Bumper side LH	Rx		
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	nc	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	rw	✓	
1159	993327	Rear End Panel	Rx		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	ht	✓	
1182	991328	Tailgate Emblem	wa	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	nc	✓	
1198	994651	Tailgate Rubber	ht	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2019 Edit Reg		18 Dec 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	KINETIC ALLIANCE PTE LTD, Co. Reg. No.: 201613074E								
Main Claimant:	LUM YEW KUAN, ID: S0009000Z								
Vehicle Reg. No.:	SLB5748R	Date of Loss:	14/12/2019 00:00 - :59 [44 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9590628878SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SMD4663K	Policy No. (Claimant):							
		Excess:							
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4 , # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/12/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
AIG_SG (19/12/2019): TP GIA report									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB5748R (9590628878SG)
[SMD4663K]
TP
LUM YEW KUAN
Dec 14 2019 12:00AM
[KINETIC ALLIANCE PTE LTD]
Super Modern Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	02/01/20 08:40	General View													 Load JPG	☒		
2	02/01/20 08:40	General View													 Load JPG	☒		
3	02/01/20 08:40	General View													 Load JPG	☒		
4	02/01/20 08:40	General View													 Load JPG	☒		
5	02/01/20 08:40	General View													 Load JPG	☒		
6	02/01/20 08:40	General View													 Load JPG	☒		
7	02/01/20 08:40	General View													 Load JPG	☒		
8	02/01/20 08:40	General View													 Load JPG	☒		
9	02/01/20 08:41	General View													 Load JPG	☒		
10	02/01/20 08:41	General View													 Load JPG	☒		
11	02/01/20 08:41	General View													 Load JPG	☒		
12	02/01/20 08:41	General View													 Load JPG	☒		
13	02/01/20 08:41	General View													 Load JPG	☒		
14	02/01/20 08:41	General View													 Load JPG	☒		
15	02/01/20 08:41	General View													 Load JPG	☒		
16	02/01/20 08:41	General View													 Load JPG	☒		
17	02/01/20 08:41	General View													 Load JPG	☒		
18	02/01/20 08:41	General View													 Load JPG	☒		
19	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
20	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
21	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
22	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
23	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
24	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
25	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
26	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
27	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
28	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
29	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
30	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
31	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
32	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
33	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
34	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
35	02/01/20 08:41	Reinspection Photo													 Load JPG	☒		
Documentation															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	19/12/19 15:26	OI GIA REPORT													 Load PDF			
2	08/01/20 14:35	TP GIA													 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022274/T1VF3E2

Date: 08/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLB5748R

Insured Vehicle No : SMD4663K

Date of Loss: 14/12/2019

Nature of Claim: TP

Claim No: 9590628878SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB5748R

Make & Model: HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR (A)

Engine No: L15B4035267

Reg. Date: 14/04/2016 (Man. Year: 2016)

Chassis No: RU11115261

Colour: Blue

Odometer: 51483 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 18/12/2019 Inspected At:

Super Modern Services Pte Ltd (Kaki Bukit)

Synergy @ KB, Kaki Bukit road 4 , # 01-26

Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER SIDE RH	Repair	0.00 F	*- F
3	1		*REAR BUMPER SIDE LH	Repair	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*TAILGATE	Bent	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
10	1		*TAILGATE LOCK	Bent	0.00 F	*- F
				Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >