

ASS. REQ. BY:

REF: CS/C1119022275/Kvf302

Special Instruction:

UNR/DR

Kannun

ASSIGNMENT (Office)

From (Person):

Jen Tay Hui Ping

of

C11

Date/Time:

18.12.19 14.11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YL 291

Insured:

at Workshop m/s

Lai Hual

Tel:

64538110

of

160 St Ming Drive #04-01

Policy No:

DMC(SV303890190)

Claim No:

SNM190706016

Sum Insured:

Excess:

\$ 3550.00

Make of Veh:

D.O.A 16.12.19

(Client's Receipt)

CA

REV

REP. / REV 24 HRS

Date/Time:

18.12.19 2.32p.m

Person Contacted:

Jenny

H.O.D. Endorsement

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) (Signature)

YL 291 - NS/NCT10019214/DY1

DOA - 23/01/2010

19/12/19

Revert via merimen

20/12/19

@1204pm Jenny said OI withdraw claim

20/12/19

Rece approved \$5924 from Alfred by merimen

20/12/19

Informed Jenny c/A ex \$3550 by email

ASS. REC. BY:

REF:

C72/ CS/CTI1902275/Kv43

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

862/c with Box

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YL 29J

Yr Regn:

06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Cante

c.c.

2998

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading:

101.081

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FEB 21 EA 21346

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

1 P5 R15 X8

R:

(D)

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

66

mm

L/Bal.

9

mm

L/Bal.

66

mm

D.O.A.

18/12/19

D.O.I.

18/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S, Br w/Screen cracked

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

21/12/19 Recd email from Jenny, CI cancel the claim

RECEIVED 2019

Date/Time, File Pass to?



Prell. Report



Final Report

1)

Date/Time, File Return to?

23/12 - typist

Report Format:

Lump Sum / I.B.I. (\$) Merimen

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + P.S. \$

F. + J. \$

Others

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 Sendback Est	18 Dec 2019 10:02 S\$6,267.40	18 Dec 2019 14:11 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SING SEE SOON FLORAL & LANDSCAPE PTE LTD, Co. Reg. No.: 20009355G		
Vehicle Reg. No.:	YL29J	Date of Loss:	16/12/2019 14:00 - :59 [30 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D206016/YL29J/IRENE	Policy/Cover Note No.:	DMCVSN3038901901 (Comprehensive)
		Excess:	S\$3,550.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/12/2019]		
Driver/Custodian:	PANG JIANQIANG (36 / Male) , NRIC: G3817015K, Tel: +6588090117 Email: NOEMAIL		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 23 December 2019 9:18 AM
To: Irene Tay (irene.tay@sg.cntaiping.com); Claims Dept of CTI; SUR
Subject: FW: YL 29J-DOA: 16/12/2019 (CHINA TAI PING OD)
Attachments: YL 29J.PDF

Dear Irene,

Refer below email from repairer.

We will submit our report in merimen and bill accordingly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Saturday, 21 December 2019 10:11 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Irene Tay' <irene.tay@sg.cntaiping.com>
Subject: RE: YL 29J-DOA: 16/12/2019 (CHINA TAI PING OD)

Dear Veron / Irene

We refer to the above matter.

Our client's have decided to cancel the claim.

A copy of the amended accident report is enclosed for your kind attention.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 20 December 2019 2:59 pm

To: Jenny Lim <jenny.lim@laihuat.com.sg>; SUR <sur@lkkauto.com>
Subject: YL 29J-DOA: 16/12/2019 (CHINA TAI PING OD)

Dear Jenny,

As instructed by our client , please proceed to repair the **insured vehicle YL 29J, (Excess S\$3550/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Saturday, 21 December 2019 10:11 AM
To: Veron Chen (LKKAUTO)
Cc: 'Irene Tay'
Subject: RE: YL 29J-DOA: 16/12/2019 (CHINA TAI PING OD)
Attachments: YL 29J.PDF

Dear Veron / Irene

We refer to the above matter.

Our client's have decided to cancel the claim.

A copy of the amended accident report is enclosed for your kind attention.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 20 December 2019 2:59 pm
To: Jenny Lim <jenny.lim@laihuat.com.sg>; SUR <sur@lkkauto.com>
Subject: YL 29J-DOA: 16/12/2019 (CHINA TAI PING OD)

Dear Jenny,

As instructed by our client , please proceed to repair the **insured vehicle YL 29J, (Excess S3550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 December 2019 2:59 PM
To: Jenny Lim ; SUR
Subject: YL 29J-DOA: 16/12/2019 (CHINA TAI PING OD)

Dear Jenny,

As instructed by our client , please proceed to repair the **insured vehicle YL 29J, (Excess S3550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

YL29J (SNM19D206016/YL29J/IRENE)
OD
Dec 16 2019 2:00PM
[SING SEE SOON FLORAL & LANDSCAPE PTE LTD]
Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 20/12/2019 12:53 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5924.40) - YL29J - Claim Handler: Irene Tay Hui Ping

Approved:5924.40:Please proceed to authorize repairs at \$5,924.40 BEFORE Excess of \$3,550.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Irene Tay Hui Ping	Date:	19 Dec 2019

Preliminary Advice

Vehicle No	: YL29J	Accident Date	: 16/12/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3038901901
Assignment Date	: 18/12/2019	Excess	: S\$3,550.00
Date of Inspection	: 18/12/2019	Est. Duration of Repair	: 7
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and front windscreen cracked and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,267.40
Revised Amount	:S\$	5,924.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,924.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	14,249.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,751.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	355G
Vehicle Details	
Vehicle No.:	YL29J
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C51403
Chassis No.:	FEB21EA21346
Maximum Power Output:	-
Open Market Value:	\$32,995.00
Original Registration Date:	13 Jun 2017
First Registration Date:	13 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$1,650.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,038.00
COE Rebate Amount:	\$14,249.00
Total Rebate Amount:	\$14,249.00

The information contained herein is correct as at 18 Dec 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	355G

Vehicle Details

Vehicle No.:	YL29J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C51403
Chassis No.:	FEB21EA21346
Maximum Power Output:	-
Open Market Value:	\$32,995.00
Original Registration Date:	13 Jun 2017
First Registration Date:	13 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$1,650.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	12 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,038.00
COE Rebate Amount:	\$14,254.00
Total Rebate Amount:	\$14,254.00

The information contained herein is correct as at 17 Dec 2019

OK



中國太平保險(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
(In Reg. No. 194400101)

HE300/C
R SH
JHD420A
Cov. Type: C

Motor Commercial Vehicle

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169)

ORIGINAL

1. CERTIFICATE No.	00CVSH7038901901	Engine No : 4P10C51403
		Chassis: FEB21E*21346
2. Invoiced and Registered Number of Vehicle	YL293	AUTOSAFE
3. Name of Policy Holder	SING SEE SOON FLORAL & LANDSCAPE PTE LTD	
4. Effective date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment	13 June 2019	Excess Sect 1 S\$550.00 EX. ON WINDSCREEN S\$100.00
5. Date of Expiry of Insurance	12 June 2020	
6. Persons or Classes of Persons entitled to drive*		

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the motor vehicle.

6. Limitations as to use*

- (1) use in connection with the Policyholder's business.
 - (2) use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 - (3) use for social, domestic or pleasure purposes.
- The Policy does not cover:
- (1) use for hire or reward or racing, pace-making, reliability trial or speed testing.
 - (2) use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : ARWIN PTE LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under those headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse



For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: EXPRESS INSURANCE AGENCY PTE LTD
Authorised Officer

Authorised Signatory

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2019 10:48
Date Of Accident	16/12/2019 14:00
Exact Location Of Accident	32 PUNGGOL EAST BIN CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YL29J
Insured/Policyholder	
Name Of Registered Owner	SING SEE SOON FLORAL & LANDSCAPE PTE LTD
Co Reg No	20009355G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87770029
Alternative Phone No	OFFICE-63156825
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCVSN3038901901
Cover Note Number	
Driver	
Name of Driver	PANG JIANQIANG
Passport No/FIN	G3817015K
Date Of Birth	18/06/1983
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2019
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88090117
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	C/O 32 PUNGGOL EAST #01-01
Postcode	628824
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	HEAVY RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time
17 DEC 2019
(V. K. S. Tan)

Director's Signature
(If driver is not the policyholder)
Date & Time
17 DEC 2019
(V. K. S. Tan)

Reporting Centre Personnel's Signature
Name
Poh Kwee Choo
NRC/TFN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2019 10:48
Date Of Accident	16/12/2019 14:00
Exact Location Of Accident	32 PUNGGOL EAST BIN CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YL29J
Insured/Policyholder	
Name Of Registered Owner	SING SEE SOON FLORAL & LANDSCAPE PTE LTD
Co Reg No	2XXXX355G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87770029
Alternative Phone No	OFFICE-63156825

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCVSN3038901901
Cover Note Number	

Driver

Name of Driver	PANG JIANQIANG
Passport No/FIN	GXXXX015K
Date Of Birth	18/06/1983
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2019
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88090117
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	C/O 32 PUNGGOL EAST #01-01
Postcode	828824
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	HEAVY RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 17 DEC 2019

Co: Esan

潘建强

Driver's Signature

(If driver is not the policyholder)

Date & Time:

17 DEC 2019

Co: Esan

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo

NRIC/FIN No.:

工业垃圾站
Garbage Bin Centre
YL 29J
DOA: 16/12/10

DOA: 16/12/19

Time : about 2pm

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along 32 Punggol East and self skidded and knocked onto the Bin Centre, but the Bin Centre is damage. During that time, it's was heavy rain and wet.

DECLARATION

I/We declare that foregoing particulars are true in every respect.



Policyholders' Insurance
Date & Time:

17 DEC 2019

潘建强

Driver's Signature
(If driver is not the policyholder)
Date & Time: 17 DEC 2019



Reporting Centre Personnel's Signature
Name: **Poh Kwee Choo**
NRIC/FIN No.:

CERTIFICATE OF INSURANCE Pg. 1



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg No: 20070430-E

MZ300/C
R SH
AND420A
Cov. Type: C

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1990
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1980 (Singapore)

ORIGINAL

CERTIFICATE No.

DMCVSH3038901901

Engine No : 4P10CS1405
Chassis: FEB21EA21346

1. Index Mark and Registration
Number of Vehicle

YL293

AUTOSAFE

2. Name of Policy Holder

SING SEE SOON FLORAL & LANDSCAPE PTE LTD

3. Effective date of the Commencement of
Insurance for the purposes of the Regulations,
Ordinance or Enactment

13 June 2019

Excess Sect I \$5550.00
EX ON WINDSCREEN \$1100.00

4. Date of Expiry of Insurance

12 June 2020

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or
regulations to drive the motor vehicle or has been so permitted and is not disqualified by order of a
Court of Law or by reason of any enactment or regulation in that behalf from driving the motor vehicle.

6. Limitations as to use*

- (1) Use in connection with the Policyholder's business.
 - (2) Use for the carriage of passengers (other than for hire or reward) in connection with the
Policyholder's business.
 - (3) Use for social, domestic or pleasure purposes.
- The policy does not cover:
- (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.
 - (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : ASWIN PTE LTD AS HIRER/OWNER

* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the
provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road
Transport Act, 1987 (Malaysia).

Please see reverse



For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: INDEPRESS INSURANCE AGENCY PTE LTD
Authorised Officer

Authorised Signatory

Accident Photo




Accident Photo



Accident Photo



CHASSIS NUMBER

 **MITSUBISHI FUSO**
TRUCK & BUS CORPORATION

MODEL FEB21E

CHASSIS
NO.

 FEB21EA21346 

MAX G.V.W. 5000 kg

MAX AXLE LOADS FRONT 2300 kg

REAR 3800 kg



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M600017733

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MLHM19165819 Vehicle Registration No: YL 29J
Sing See Soon Floral & Landscape
Name (as shown in NRIC) : Pte Ltd NRIC/FIN/Passport No : 20009355G
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 32 Punggol East #01-01 Singapore (828824)
Contact (Tel) : _____ Mobile No. : 87770029
Email Address : _____
Date of Accident : 16/12/2019 Time of Accident : 14:00 hours
Place of Accident : 32 Punggol East Bin Centre
Insurance Company: China Taiping Insurance (Singapore) Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I would like to cancel my "Own Damages claim" and amend my report to reporting only.



Police/Driver's Signature
Date: 20/12/2019



Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: _____
Date: 20/12/2019

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference:

Repairer Reference: 71130

Date calculated: 18/12/2019 9:53 AM

Full Report

Registration: YL 29J

Printed: 18/12/2019 9:53 AM


Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:		Date of Incident:	16/12/19
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	FUSO
Model:	CANTER (FB/FE/FG)
Sub Model:	BASE MODEL
Model Sheet Number:	32 87 01
Registration:	YL 29J
VIN number:	
Odometer:	101081
Model Specs	
SINGLE CAB	

Not Authorized
Prods Recovery B4 pain
Ex 8355d
7 days



Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All

Underbody

☐
☐

LKK Auto Consultants hereby notify the Repairer of the following:

- To recovery before/after repair painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications is allowed
- Supplementary RAR(s) must be managed and is subject to final approval from Insurance Company

Administered by Repairer

Signature:

Date:

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT BUMPER INCLUDES: R + R NECESSARY ATTACHED PARTS		11.0	46.20
NO NUMBER	R + R RADIATOR GRILLE		12.0	50.40
NO NUMBER	R + R R/F REPEATER LAMP		4.0	16.80
NO NUMBER	RENEW FRONT MANUFACTURER BADGE		3.0	12.60
NO NUMBER	R + R WINDSCREEN INCLUDES: COWL GRILLE, WIPER ARM AND WIPER LINKAGE REMOVE AND REFIT.		25.0	105.00
NO NUMBER	R + R R/F STEP BOARD		2.0	8.40
NO NUMBER	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		18.0	75.60
NO NUMBER	R + R FRONT FLOOR CARPET		4.0	16.80
NO NUMBER	R + R INSTRUMENT PANEL		25.0	105.00
NO NUMBER	R + R STEERING WHEEL		3.0	12.60
NO NUMBER	ADJUST HEADLAMPS		2.0	8.40
NN	R/F INNER STEP GARN R&R / NEW PARTS		3.0*	✓ 12.60
0900	FRONT PANEL CPL REPAIR	15	20.0*	✓ 84.00
2228	RIGHT A-PILLAR REPAIR	60	80.0*	✓ 336.00
2280	RIGHT B-PILLAR REPAIR	20	30.0*	✓ 126.00
4232	R/SIDE MEMBER REPAIR	15	20.0*	✓ 84.00
4242	R/F WHEELARCH PANEL REPAIR	15	20.0*	✓ 84.00
4252	FRONT FLOOR PANEL REPAIR	30	40.0*	✓ 168.00
4253	FRONT PEDAL FLOOR REPAIR	30	40.0*	✓ 168.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		36.20	362.0	1,520.40
Total of Labour				1,520.40

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	R/F CORNER PANEL NEW PART PAINTING		7.0	
	RIGHT FRONT DOOR NEW PART PAINTING		14.0	
	FRONT PANEL CPL REPAIR PAINTING <50%		14.0	
	FRONT PANEL TRIM REPAIR PAINT PLASTIC		10.0	
	RIGHT A-PILLAR REPAIR PAINTING <50%		7.0	
	RIGHT B-PILLAR REPAIR PAINTING <50%		9.0	
	R/SIDE MEMBER SURFACE PAINT		4.0	
	R/F WHEELARCH PANEL SURFACE PAINT		4.0	
	FRONT PEDAL FLOOR SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
0888	R/F CORNER PANEL NEW PART PAINTING	7.20
1482	RIGHT FRONT DOOR NEW PART PAINTING	30.60
0900	FRONT PANEL CPL REPAIR PAINTING <50%	19.00

Paint Material Per Part

Code	Description	Price SGD
1392	FRONT PANEL TRIM REPAIR PAINT PLASTIC	11.10
2228	RIGHT A-PILLAR REPAIR PAINTING <50%	1.00
2280	RIGHT B-PILLAR REPAIR PAINTING <50%	7.50
4232	R/SIDE MEMBER SURFACE PAINT	3.17
4242	R/F WHEELARCH PANEL SURFACE PAINT	1.76
4253	FRONT PEDAL FLOOR SURFACE PAINT	7.39

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			74.0	
Preparation Main Work Metal		1.70	17.0	71.40
Preparation Comp. Work Plastic		0.60	6.0	25.20
Total	10 WU/h	9.70	97.0	407.40

Material Cost - Paint

	Price SGD
New Part Painting	37.88
Repair Painting	27.50
Repair Painting Plastic	11.10
Surface-/Blend Paint	12.32
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	119.60

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0281	FRONT BUMPER	MC978515		B ₁ ✓	550.00
0284	R/F BUMPER BRACKET	MK617974		R ₁ ✓	110.00
0290	R/F BUMPER CORNER	MK617989		m ₁ ✓	190.00
0432	BADGE	MK546617		m ₂ ✓	85.00
0436	R/BADGE	MK676978			X 0.00
0562	RIGHT HEADLAMP ASSY	MK580526		m ₃ H ₁ ✓	300.00
0678	R/F INDICATOR	MK581220		m ₁ ✓	120.00
0718	R/POSITION LAMP	MK580530		m ₁ ✓	80.00
0888	R/F CORNER PANEL	MC976411		C ₁ ✓	220.00
1401	WINDSCREEN	MK403591		C ₁ ✓	750.00
1410	WINDSCREEN SEAL	MK435031		C ₁ ✓	200.00
1411	WINDSCREEN BOND KIT	Z2156507			X 0.00
1482	RIGHT FRONT DOOR	MK702224		R ₁ ✓	800.00
1578	R/INN DOOR LOCK	MK434990		R ₁ ✓	380.00
2206	R/F STEP	MK677507		C ₁ ✓	250.00
1003	R/F INNER STEP GARN	RENEW		C ₁ ✓	95.00
1004	ARM ROUND COVER	R/F DOOR MIRROR		m ₁ ✓	10.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings

Subtotal

Total

0.00

4,140.00

4,140.00

• Extras

Code	Description		Price SGD
1000	FRONT NUMBER PLATE SN	~ X	20.00
1001	W/S SEALANT SN	~ X	50.00
1002	IU BRACKET SN	~ ✓	10.00
Total Extras			80.00

Final Calculation

	SGD	SGD
Parts	4,140.00	
Total Parts		4,140.00
Labour Time Base 10 WU/h	1,242.40	
Total 362.0 WU X 42.00 SGD/h	1,520.40	
Total of Labour		1,520.40
Total Of Extras		80.00
Paint Work Time Base 10 WU/h		
Labour Cost 97.0 WU X 42.00 SGD/h	407.40	
Material Cost	119.60	
Total Paint Including Material		527.00
Repair Cost Excludes GST		6,267.40
GST (+7.0%)		438.72
Repair Cost Included GST		6,706.12

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants

#01-25 Paya Ubi Industrial Park, 51

Ubi Avenue 1

408933

Insurer Reference: 19/6016/OD

Repairer Reference: 71130

Date calculated: 18/12/2019 5:06 PM

Revert

Full Report

Registration: YL 29J

Printed: 18/12/2019 5:06 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	19/6016/OD	Date of Incident:	16/12/19
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	FUSO
Model:	CANTER (FB/FE/FG)
Sub Model:	BASE MODEL
Model Sheet Number:	32 87 01
Registration:	YL 29J
VIN number:	
Odometer:	101081

Model Specs

SINGLE CAB

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT BUMPER INCLUDES: R + R NECESSARY ATTACHED PARTS	11.0		46.20
NO NUMBER	R + R RADIATOR GRILLE	12.0		50.40
NO NUMBER	R + R R/F REPEATER LAMP	4.0		16.80
NO NUMBER	RENEW FRONT MANUFACTURER BADGE	3.0		12.60
NO NUMBER	R + R WINDSCREEN INCLUDES: COWL GRILLE, WIPER ARM AND WIPER LINKAGE REMOVE AND REFIT.	25.0		105.00
NO NUMBER	R + R R/F STEP BOARD	2.0		8.40
NO NUMBER	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	18.0		75.60
NO NUMBER	R + R FRONT FLOOR CARPET	4.0		16.80
NO NUMBER	R + R INSTRUMENT PANEL	25.0		105.00
NO NUMBER	R + R STEERING WHEEL	3.0		12.60
NO NUMBER	ADJUST HEADLAMPS	2.0		8.40
NN	R/F INNER STEP GARN R&R / NEW PARTS	3.0*		12.60
0900	FRONT PANEL CPL REPAIR	15.0*		63.00
2228	RIGHT A-PILLAR REPAIR	60.0*		252.00
2280	RIGHT B-PILLAR REPAIR	20.0*		84.00
4232	R/SIDE MEMBER REPAIR	15.0*		63.00
4242	R/F WHEELARCH PANEL REPAIR	15.0*		63.00
4252	FRONT FLOOR PANEL REPAIR	30.0*		126.00
4253	FRONT PEDAL FLOOR REPAIR	30.0*		126.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		29.70	297.0	1,247.40
Total of Labour				1,247.40

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	R/F CORNER PANEL NEW PART PAINTING		7.0	
	RIGHT FRONT DOOR NEW PART PAINTING		14.0	
	FRONT PANEL CPL REPAIR PAINTING <50%		14.0	
	FRONT PANEL TRIM REPAIR PAINT PLASTIC		10.0	
	RIGHT A-PILLAR REPAIR PAINTING <50%		7.0	
	RIGHT B-PILLAR REPAIR PAINTING <50%		9.0	
	R/SIDE MEMBER SURFACE PAINT		4.0	
	R/F WHEELARCH PANEL SURFACE PAINT		4.0	
	FRONT PEDAL FLOOR SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
0888	R/F CORNER PANEL NEW PART PAINTING	7.25
1482	RIGHT FRONT DOOR NEW PART PAINTING	30.63
0900	FRONT PANEL CPL REPAIR PAINTING <50%	19.00

Paint Material Per Part

Code	Description	Price SGD
1392	FRONT PANEL TRIM REPAIR PAINT PLASTIC	11.10
2228	RIGHT A-PILLAR REPAIR PAINTING <50%	1.00
2280	RIGHT B-PILLAR REPAIR PAINTING <50%	7.50
4232	R/SIDE MEMBER SURFACE PAINT	3.17
4242	R/F WHEELARCH PANEL SURFACE PAINT	1.76
4253	FRONT PEDAL FLOOR SURFACE PAINT	7.39

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		74.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.60	6.0	25.20
Total	10 WU/h	97.0	407.40

Material Cost - Paint

	Price SGD
New Part Painting	37.88
Repair Painting	27.50
Repair Painting Plastic	11.10
Surface-/Blend Paint	12.32
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	119.60

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	MC978515		550.00
0284	R/F BUMPER BRACKET	MK617974		110.00
0290	R/F BUMPER CORNER	MK617989		190.00
0432	BADGE	MK546617		85.00
0436	R/BADGE	MK676978		0.00
0562	RIGHT HEADLAMP ASSY	MK580526		300.00
0678	R/F INDICATOR	MK581220		120.00
0718	R/POSITION LAMP	MK580530		80.00
0888	R/F CORNER PANEL	MC976411		220.00
1401	WINDSCREEN	MK403591		750.00
1410	WINDSCREEN SEAL	MK435031		200.00
1411	WINDSCREEN BOND KIT	Z2156507		0.00
1482	RIGHT FRONT DOOR	MK702224		800.00
1578	R/INN DOOR LOCK	MK434990		380.00
2206	R/F STEP	MK677507		250.00
1003	R/F INNER STEP GARN	RENEW		95.00
1004	ARM ROUND COVER	R/F DOOR MIRROR		10.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,140.00
u: Used parts	Total			4,140.00

Extras

Code	Description	Price SGD
0900	[I]; FRONT PANEL CPL :	0.00*
1002	IU BRACKET SN	10.00*
Total Extras		10.00

Final Calculation

	SGD	SGD
Parts	4,140.00	
Total Parts		4,140.00
Labour Time Base 10 WU/h		
Total 297.0 WU X 42.00 SGD/h	1,247.40	
Total of Labour		1,247.40
Total Of Extras		10.00
Paint Work Time Base 10 WU/h		
Labour Cost 97.0 WU X 42.00 SGD/h	407.40	
Material Cost	119.60	
Total Paint Including Material		527.00
Repair Cost Excludes GST		5,924.40
GST (+7.0%)		414.71
Repair Cost Included GST		6,339.11

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 Sendback Est	18 Dec 2019 10:02 \$56,267.40	18 Dec 2019 14:11 Edit Adj Rpt	\$55,924.40 Edit Estimates	\$55,924.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SING SEE SOON FLORAL & LANDSCAPE PTE LTD , Co. Reg. No.: 20009355G									
Vehicle Reg. No.: YL29J		Date of Loss: 16/12/2019 14:00 - :59 [30 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D206016/YL29J/IRENE		Policy/Cover Note No.: DMCVSN3038901901 (Comprehensive)							
		Excess: \$43,550.00							
Repairer: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/12/2019]									
Driver/Custodian: PANG JIANQIANG (36 / Male) , NRIC: G3817015K, Tel: +6588090117 Email: NOEMAIL									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (20/12/2019): Alert - Adj Mandate Approved (\$55924.40) - YL29J - Claim Handler: Irene Tay Hui ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YL29J (SNM19D206016/YL29J/IRENE)
 OD
 Dec 16 2019 2:00PM
[SING SEE SOON FLORAL & LANDSCAPE PTE LTD]
 Lai Huat (Meng Kee) Motor Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	18/12/19 10:02	Repairer Estimates		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	19/12/19 13:42	Adjuster Immediate Advice		Load HTM		
Photos/Images				3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	18/12/19 09:57	Front View		Load JPG	<input checked="" type="checkbox"/>	
2	18/12/19 09:57	Front View Right		Load JPG	<input checked="" type="checkbox"/>	
3	18/12/19 09:57	Front View Left		Load JPG	<input checked="" type="checkbox"/>	
4	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
5	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
6	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
7	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
8	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
9	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
10	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
11	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
12	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
13	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
14	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
15	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
16	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
17	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
18	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
19	18/12/19 09:57	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
20	18/12/19 09:57	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>	
21	18/12/19 09:58	Chassis Number		Load JPG	<input checked="" type="checkbox"/>	
22	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
23	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
24	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
25	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
26	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
27	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
28	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
29	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
30	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
31	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
32	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
33	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
34	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
35	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
36	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
37	18/12/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	19/12/19 12:53	General View		Load PDF		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	18/12/19 10:01	E-filed GIA report			Load PDF
2	18/12/19 10:01	Driver's NRIC & Driving Licence			Load PDF
3	18/12/19 10:01	Certificate of Insurance			Load PDF
4	18/12/19 10:01	Enquire PARF / COE Rebate for Registered Vehicle			Load PDF
5	18/12/19 10:01	Audatex Report			Load PDF
Relabel/Reorder				Thumbnail	Print
1	19/12/19 12:53	MARK ESTIMATE			Load PDF
2	19/12/19 12:53	AUDATEX			Load PDF
3	23/12/19 09:09	ADDENDUM GIA REPORT			Load PDF

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	17/12/19 14:33	Accident Statement			Load HTM
2	21/12/19 10:05	Addendum Sheet			Load TIF
3	21/12/19 10:06	Accident Statement Addm. #1			Load HTM
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	17/12/19 14:31	Accident Photo			Load JPG <input checked="" type="checkbox"/>
2	17/12/19 14:31	Accident Photo			Load JPG <input checked="" type="checkbox"/>
3	17/12/19 14:31	Accident Photo			Load JPG <input checked="" type="checkbox"/>
4	17/12/19 14:31	CHASSIS NUMBER			Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	17/12/19 14:29	Sketch Plan			Load TIF
2	17/12/19 14:29	CERTIFICATE OF INSURANCE			Load TIF
3	17/12/19 14:30	Driver's Work Permit & Driving Licence			Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022275/KVF3E2

Date: 27/12/2019

REFERENCE

Insured/Claimant: SING SEE SOON FLORAL & LANDSCAPE PTE LTD Policy No: DMCVSN3038901901

Date of Loss: 16/12/2019

Nature of
Claim: OD

Claim
No: SNM19D206016/YL29J/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YL29J**
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M) Engine No: 4P10C51403
Reg. Date: 13/06/2017 (Man. Year: 2016) Chassis No: FEB21EA21346
Colour: White Odometer: 101081 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8 (D)
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,140.00	4,140.00	0.00	0.00
Miscellaneous Items	80.00	10.00	70.00	87.50
Labour	1,520.40	1,247.40	273.00	17.96
Paintwork Labour	527.00	527.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,267.40	5,924.40	343.00	5.47
- Excess (S\$)	550.00	3,550.00	-3,000.00	-545.45
(S\$)	5,717.40	2,374.40	3,343.00	58.47
+ GST 7.00/7.00% (S\$)	400.22	166.21	234.01	58.47
Nett Amount (S\$)	6,117.62	2,540.61	3,577.01	58.47

INSPECTION

Date of Assignment: 18/12/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 18/12/2019 Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that insured decided to cancel the claim.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YL29J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		4,140.00 F	*4,140.00 F
					Total Parts (S\$)	4,140.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front number plate (SERVICEABLE)	20.00	0.00
2	1	IU bracket (NECESSARY)	10.00	10.00
3	1	W/S Sealant (NOT NECESSARY)	50.00	0.00
Sub Total (S\$)			80.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Including Material	New	527.00	527.00
Labour Items				
2	Total of Labour	New	1,520.40	1,247.40
Gross Labour Cost (S\$)			2,047.40	1,774.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >