

ASS. REC. BY:

REF:

C1/TPDI9022293/Ng

Special interaction:

Surveyor

ASSIGNMENT (Office)

FIELD (Period):

## Kamaliah Kamis

end

SPE

Date/Time: 21/11/2019

Estimated Cost:

Bill No.

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To inspect Vehicle No:

FBH 347J

Insured:

at Workshop m/s

: Tel:

of

Policy No.

MHASPF0600002842

Claim No:

7P/1P/62415/2019

Sum Insured:

Exco35:

Make of Veh:

D.O.A. 05/10/19

(Client's Record)

CA / REV / DEP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

[illegible]

FBH 347 J-X

4501-9

IO In-Charge: IO Clarence Lim

r) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBH347J (TP/IP/62415/2019)

On 5th October 2019 at about 12.48 am, deceased was riding on the left of 3 lanes along Clementi Avenue 6 towards the direction of PIE. A witness saw the deceased's motorcycle skidded on the road for unknown reasons and there were no other vehicles involved. 1. LTA sky cam captured the occurrence of the accident. The footage revealed that the deceased was riding on the left most lane at a relatively slow speed when the motorcycle was seen veering towards the left and colliding into the road kerb. The motorcycle then collided into the lamp post. As a result of the accident, the deceased was conveyed conscious to the hospital. However, whilst under medical treatment, deceased collapsed in the hospital and CPR was conducted. Deceased responded and was brought into operating theatre for laparotomy. Deceased collapsed again and however unable to revive deceased. He succumbed to his injuries and was pronounced dead by Dr Ong Say Yang at 5.09 am.

Vehicles to be inspected: FBH347J - Rider (Deceased)

4128/17 G16 Hk  
got key already

IO In-Charge: IO Clarence Lim

s) Case IAFP-IB-20191115 - Mechanical Inspection of Bicycle [Silver and Black] (TP/IP/61821/2019)

On 01.10.2019 at about 6.17 p.m, the Involved Party, the cyclist was cycling on lane 1 of 4. Lane 1 is occupied by parallel parking lots with parked cars. While approaching the incident location, the cyclist noticed the Deceased jay walking on lane 2 from the cyclist's left side to right side. As such the cyclist sounded his bicycle bells to make known of his presence and slowed down to prevent colliding into the Deceased. However, the Deceased still continued to walk into the travel path of the cyclist and he could not brake in time and collided into Deceased. As a result of the accident, the Deceased was seriously injured where he sustained head injuries. He was conveyed conscious due to altered state of mind to Tan Tock Seng Hospital by ambulance.

Vehicles to be inspected: Bicycle [silver and black] - Pedal Cyclist (Involved Party) —

IO In-Charge: IO Clarence Lim

is scooter?  
location?  
original - 10.  
Incident No.?

2 Ma'am, for your approval please.

3 Thank you.

cc: FAIT Team, IO David Yap & IO Noorhidayah, fyip

Best regards,

Kamaliah Kamis (Miss)  
Senior Investigation Officer | Fatal Accident Investigation Team  
Traffic Police Department | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together