	HOCK Ann	AS	SIGNMEN			
rom (Person)	Richard M	no of	Asm	AXA)	Da	nte/Time: 19.1). 1019
estimated Cos	titi	0	1	Bill to:		
OD TP / WE		RESTEVATING SLF 581			Insured:	GBE 68947
at Workshop i	n/s my Car	Consultant			Tel	8 8 668832
of 53 Ub		Dava ub				
Policy No:				Claim No:	SAMO.	PATS .
Sum Insured:				Excess:		
Make of Veh:					D.	O.A. 12.17.2019
(Client's Record		n	417			
	REP. / REV		J	11 - 01		H.O.D Endorsement:
Date/Time;	9.13.19 10.1	Person	Contacted:	Hui Qin	Vel	ich IN I DUT
Date/Time	Action/Instruct	ion (x)	Estimate			
	SLF 587	E - (C4/	ASM 19104	33 A / Apb	352	Day-07/13/219
	(BE 680					
	Dismantle	1. 20/12/20	019			
		ur: 23/12/2				

Burryan H-ANN REF: ASM (AXA)	CLUMBA I NOT
	SIGNMENT
-ront Date: 19.13. 2019	Veh No. 51F 5877E Yr Regn: 12/93/20
EstimateN Gost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLF 5877E	Make: H- civic c.c 1595
at Workshop m/s My Car Consultant	Colour / Red A/C: Insured / Std / NI / NA
of	Sp.Reading 209246 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: JHMFO 462085 20085
Claims No.	Gen. Cond: Good (Fair/ Poor / Burnt
Sum Insured: Excess:	Steering/Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rjm / STD A/Rim or
· L	Tyre Size: F: 225/45/217
(Policy Condition)	R: -225/45/R17
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear B
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 3 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 12/12/19 D.O.I. 19/12/19
Lum Sum: % 3 Val.: Yes or No	Survey held at my cm 1047 AM
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
2 + 4 54	* SIF 5877E
Raye > 315-415/2 rugar pays > 4 Lays	prs case
-76.0	RECEIVED 1 7 JAN 2020
mv - 53000	
pv - 3229/.	
A/1	
NU- 20700	4.4
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Date/Time, File Pass to? : Preli. Report 1) : Final Report	Resurvey No. of Trip: 2 Survey Fee: 100
Date/Time, File Pass to? : Preli. Report 1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 100 Transportation:
Date/Time, File Pass to? : Preli. Report 1) : Final Report	Resurvey No. of Trip: Survey Fee: 100 Transportation: Site Insp (\$)S+RS,SI
Date/Time, File Pass to? : Preli. Report : Final Report 2) Add Fe	Resurvey No. of Trip: Survey Fee: 100 Transportation: Site Insp (\$)S+RS,SI Interview (\$) Photos
Date/Time, File Pass to? : Preli. Report 1) : Final Report 2) Add Fe	Resurvey No. of Trip: Survey Fee: 100 Transportation: S+RS, SI

Menu



Service Request Details

Claim

S9M02AT3

Reference

CC4/ASM19004338/Apb3s2 🔊

Loss Date

December 12, 2019

Report Date

Dec 20, 2019 11:54:00 AM

Request Date

December 20, 2019

Due Date

December 20, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions	
lext Step	
lext Step inish the work	

Vehicle Information

Incident Vehicle Registration #

SLF5877E

Menu

Model

CIVIC

Service Address

,,,

Primary Contact/Insured

SOON HUAT TYRES PTE LTD 48 TOH GUAN ROAD, #01-102 ENTERPRISE HUB, 608586, Singapore 68966976 SOONHUATTRYES@YAHOO.COM.SG

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

WS: My Car Consultant Pte Ltd

Messages Invoices	History Documents Assessment Metrics Notes
Document Type	Document SubType ▼
+ Upload Documents	
NAME	■ EMAIL FROM WS.msg
TYPE	Letters and Correspondence
SUB-TYPE	Others
AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	December 18, 2019
NAME	SLF5877E TP GIA.pdf
TYPE	Reports & Statement



Service Request Details

Claim

59M02A6S

Reference

None &

Loss Date

December 12, 2019

Report Date

Dec 18, 2019 1:47:00 PM

Request Date

December 18, 2019

Due Date

December 26, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration # SLF5877E

LKK AUTO CONSULTANTS PTE LTD (TP) +

Model

CIVIC

Service Address

Primary Contact/Insured

HO WEI XIONG BLK 924 #07-68, HOUGANG AVENUE 9, 530924, Singapore 90491695

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

WS: My Car Consultant Pte Ltd

Messages Invoices History

Documents

5

Assessment

Metrics

Notes

Menu

New Message

Summer Lee (LKK Auto)

From:

My Car Consultant <admin@mycar.sg>

Sent:

Wednesday, 18 December, 2019 2:49 PM

To:

NIKAM Santosh Pandurang

Subject:

[EXTERNAL] re: SPAM-LOW: Acknowledgement Your ref : SLF5877E

Our ref: S9M02A6SMC/RA

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email on even date.

We disagree to your list of surveyor and propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Lee K.W.
- i. Nicky Seah
- j. Winson Goh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyor

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

+65 88668832

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "NIKAM Santosh Pandurang" <santosh.nikam@axa.com.sg>

Sent: Wednesday, December 18, 2019 2:00 PM **To**: "admin@mycar.sg" <admin@mycar.sg>

Subject: SPAM-LOW: Acknowledgement Your ref : SLF5877E Our ref : S9M02A6SMC/RA

WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir.

We want to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list below to conduct the joint pre-repair survey as a <u>Single Joint Expert</u>.

	List of our motor surveyors:	
1.	LKK Auto Consultants Pte Ltd	
2.	Infiniti Appraisal Services	
3.	Priority Services Pte Ltd	
	AXA in house surveyor	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert. Meanwhile, please furnish us with estimate quotation in order for our surveyor to complete the pre repair survey.

If there be any injury claims by your client, please combine it in one Letter of Demand in light of one cause of action, save as to costs and expenses.

From: My Car Consultant [mailto:admin@mycar.sg]
Sent: Wednesday, December 18, 2019 12:57 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: [EXTERNAL] OUR REF: SLF5877E YOUR REF: GBE6894Y PRE-REPAIR INSPECTION FOR SLF5877E

WITHOUT PREJUDICE

OUR REF: SLF5877E YOUR REF: GBE6894Y

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SLF5877E ACCIDENT INVOLVING SLF5877E AND GBE6894Y

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of Pre-repair Inspection for your attention

Best Regards.

Huigin

Cla	ims My Car Consultant Pte Ltd	
	+65 88668832	
	Admin@mycar.sg	
П	Mycar.sg	

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

----Disclaimer----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 625

To: AXA Insurance Pte Ltd

17/1/2020

Survey details

Date of loss	12-Dec-19
Date of appointment	19-Dec-19
Date of survey	19-Dec-19
Location of survey	My Car Consultant Pte Ltd

Vehicle Details:

Claim Type:	Third Party
Vehicle number	SLF 5877E
Make and Model	HONDA CIVIC 1.6L VTI AUTO
Date of registration	12-Mar-08
Excess	
Market Value	\$53,000
Parf Rebate	\$32,291
Nett Loss	\$20,709

Repair details

Initial Estimate	
Proposed/Revised repair cost:	
Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	
Number of days of repair	4
_	
Remarks:	The estimated repair cost of the
	damaged vehicle is in the region of
	\$3,500.00 - \$4,500.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	tered venicle	
Owner ID Type:	Singapore NRIC	
Owner ID:	737A	
Vehicle Details	737A	
Vehicle No.:	SLF5877E	
Vehicle to be Exported:	No	
Intended Deregistration Date:	20 Dec 2019	
Vehicle Make:	HONDA	
Vehicle Model:	CIVIC 1.6L VTI AUTO	
Primary Colour:	Blue	
Manufacturing Year:	2008	
Engine No.:	R16A13002489	
Chassis No.:	JHMFD462085200850	
Maximum Power Output:	92.0 kW (123 bhp)	
Open Market Value:	\$19.551.00	
Original Registration Date:	12 Mar 2008	
First Registration Date:	12 Mar 2008	
Transfer Count:	2	
Actual ARF Paid:		
Intended PARF Rebate Details	\$21,507.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	·	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details	\$5.55	
COE Expiry Date:	11 Mar 2028	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
PQP Paid:	\$39,274.00	
COE Rebate Amount:	\$32,291.00	
Total Rebate Amount:	\$32,291.00	

The information contained herein is correct as at 20 Dec 2019

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



honda civic

Price Range

▼ Depreciation ▼ Year Reg

Мар

Home » Used Cars » Karz Automobile & Leasing Pte Ltd » Honda Civic 1,6A VTi (COE till 11/2028)

Honda Civic 1.6A VTi (COE till 1/2028)



Features

Type of Vehicle

Powerful 1.6L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, ABS, Reverse Sensors, Knockdown Rear Seats.Immobilizer & Climatic Aircon Control View specs of the Honda Civic (2006-2012)

Accessories

16'Sports Rims, Electrical Retractable Side Mirrors, Premium Black Leather Seats. No Modifications Fully Original Bodykit & Spoiler!Touch Screen Headunit

Sporty White Meticulously Well Maintained By Previous Owner!Low Fuel Consumption Yet Low In Maintenance Cost! Smooth, Powerful & Responsive Engine! The Most Spacious Sedan Among It's Class With Huge Cabin & Boot Space! Various Flexible Bank/In House With LTO Scheme/Loan Available!All Trade In Most Welcome!Don't Miss So Hurry Down Now Before It's Gone! Call Our Friendly Sales For More Info Of Our Loan

Category

DOA = 12/12/19

Mid-Sized Sedan

COE Car

Status Available mv - 53000 pv - 3229/

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

ket value of your existing car for free. Get started

















Shortlist

Compare

Add no

Report Error

More Actions

Seller Information

Karz Automobile & Leasing Pte Lt

36 vehicles for sale, 16 sold in past 3 mths

345 Geylang Road #01-39 Pavilion Square Search cars nearby

*	Ryan
	Sam
	Roy

87775736 88085168 87557531 3

Vince

87429379

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for

	ACCIDENT STATEMENT
Date Of Report	14/12/2019 14:00
Date Of Accident	12/12/2019 19:50
Exact Location Of Accident	PIE TOWARDS TUAS AT KIM KEAT LINK EXIT.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLF5877E
Insured/Policyholder	
Name Of Registered Owner	HO WEI XIONG
NRIC No	S8942737A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90491695
Alternative Phone No	OFFICE-90491695
Vehicle Particulars	

-	200			
V/a	hio	la.	Dan	 lare
V C	ш	т.	P 21	Hare

Manufacturer HONDA Model CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Insurance Company

Vehicle Category

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

GA474867/1

Cover Note Number

Driver

Name of Driver HO WEI JIE NRIC No S9347391D Date Of Birth 09/12/1993 Occupation INDOOR Date Of Driving Pass 12/10/2012

Driving Experience 7 YEARS AND 2 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-83660113

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 924 HOUGANG AVE 9 #07-68

Postcode

530924

1997

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SIBLING

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ES

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

...

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0000

Passenger 1

NAME:

: ONG SHI YUAN

GENDER:

: MALE

Passenger 2

NAME:

: TEH KIAN BENG

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON THE STATED DATE AND TIME, I WAS TRAVELLING ON MY VEHICLE BEARING SLF5877E ALONG PIE TOWARDS TUAS AT KIM KEAT LINK EXIT. WHILE I TRAVELLING STRAIGHT AT MY RIGHT OF MY WAY SUDDENLY VEHICLE BEARING GBE6894Y, SUDDENLY SPEED OUT FROM THE LEFT SLIP ROAD EXIT AND COLLIDED ON MY LEFT FRONT VEHICLE THAT CAUSE SERIOUS DAMAGE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBE6894Y

Vehicle Make/Model/Colour

Details Of Properties

VEH B

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

ONG SHI YUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLF5877E

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address Postcode

DETAILS OF INJURED PERSON 2

Name

TEH KIAN BENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLF5877E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

HO WEI JIE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLF5877E

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 - 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:



JEDME SLAIGHBARFAIR VS

Policyholder's Signature

Date & Time:

Driver's Signature

Date & Time:

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

NRIC/FIN No.:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM19022300/Hcf3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 17-01-2020 068811 Code: ASM ATTN: RICHARD ANG Policy Particulars :- (THIRD PARTY CLAIM) **GBE 6894Y SLF 5877E** Insured Veh. Veh. Inspected 0.00 Policy No. Coverage (\$) S9M02AT3 0.00 Claim No. Excess (\$) 19/12/2019 RICHARD ANG **Assign Date** Assian From 2. Vehicle Particulars & Condition HONDA CIVIC 1595 Make & Model C.C HIDDEN 2008 Year of Reg. Engine No. Chassis No. JHMFD46208S200850 RED Colour 209246 KM IN ORDER Odometer Steering SPORTS RIM IN ORDER Modification Brakes FAIR General **Conditions of Tyres** 3. Size Make Balance 225/45 R17 BRIDGESTONE 5 mm R/H Front Tyre 5 mm L/H Front Tyre 225/45 R17 BRIDGESTONE BRIDGESTONE 5 mm R/H Rear Tyre 225/45 R17 L/H Rear Tyre 225/45 R17 BRIDGESTONE 5 mm **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. 5. **General Information** Inspect Date / Time **Accident Date** 12/12/2019 19/12/2019 (10:47 AM) MY CAR CONSULTANT PTE LTD Survey held at 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500 5b. Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/ASM19022300/Hcf3e2

Inspected By

LEE HOCK ANN

Asst. Automotive Assessor

las

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.