

ASS. REC. BY:

REF: CS/CTE19022306/Gyd3² Special Instruction:

SUNVAIOR: QUO Qiang

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTE Date/Time: 19/12/19 @ 10:09am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 9244C Insured: GIBB 4494Y

at Workshop m/s Comfort Delgro Tel: 68838115

of 205 Brnd dell Road

Policy No: DMCVSN30314219000 Claim No: SNM19D206014C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5/12/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 10:57am @ 19/12/19 Person Contacted: william Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 9244C - X
	GIBB 4494Y - X

ASSIGNED BY: Carl | Gi

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Comfort Braddell
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKP9244e yr Regn: 17 Jan 2012
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or 2.4
Make: Honda odyssey c.c 2354
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 075141 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JHMRB 3850 Ac 201493
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD/A/Rim or
Tyre Size: F: 215/55R17
R: 11

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front _____ Rear _____
R/Bal. 4 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 19-12-19
Survey held at W/S 11:30
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
WA O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 2 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>19/12</u>	<u>Inspected of 153 754 with William. (Red \$0)</u> <u>30/12/2019</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 2
Resurvey No. of Trip: 2

1) _____
2) 30/12/19 Typist

Add Fee: Site Insp (\$) Interview (\$) Tech. Insp (\$) Wheel end (\$)

Survey Fee: _____
Transportation: _____
S + RS, SI _____
Photos _____
Other: _____
TOTAL _____

Report Format: _____
Equip. Serial / LB No: _____
PIP \$754k

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2019		19 Dec 2019 10:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BARTER MAISON PRIVATE LIMITED , Co. Reg. No.: 200923634E		
Main Claimant:	COMFORTDELGRO RENT A CAR PTE LTD , Co. Reg. No.: 198105775H		
Vehicle Reg. No.:	SKD9244C	Date of Loss:	05/12/2019 18:00 - :59
Claim Type:	TP / SNM19D206014C02	Policy/Cover Note No.:	DMCVSN30314219000
Vehicle Reg. No. (Insured):	GBB4494Y	Policy No. (Claimant):	
		Excess:	S\$350.00
Repairer:	Comfortdelgro Engineering Pte Ltd (HQ) 205 BRADDELL ROAD, 579701 Braddell - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 19 December 2019 10:05 AM
To: CDGE Braddell Private Cars Crash Repair Operation; assignments
Subject: RE: OUR REF: SNM19D206014/GBB4494Y/TKL - SKD9244C CLAIMING AGAINST GBB4494Y DOA05122019 CHECK LIABILITY & ARRANGE SURVEY

WITHOUT PREJUDICE

Dear William,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Thursday, December 19, 2019 9:16 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D206014/GBB4494Y/TKL - SKD9244C CLAIMING AGAINST GBB4494Y DOA05122019 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir/Madam,

Kindly arrange Kenneth Kong to survey the vehicle as soon as possible.

William Wang

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767
www.SPARKcarcare.com

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 18 December 2019 11:02 AM
To: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Subject: RE: OUR REF: SNM19D206014/GBB4494Y/TKL - SKD9244C CLAIMING AGAINST GBB4494Y DOA05122019 CHECK LIABILITY & ARRANGE SURVEY

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

Without Prejudice

Dear William,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, December 18, 2019 11:00 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; braddell_operation@sparkcarcare.com
Subject: OUR REF: SNM19D206014/GBB4494Y/TKL - SKD9244C CLAIMING AGAINST GBB4494Y DOA05122019 CHECK LIABILITY & ARRANGE SURVEY

Dear Kah Leong,

Please conduct PRS SKD9244C.

Note : officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]

Sent: Tuesday, 17 December, 2019 5:30 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Patrick Chung Chan Kim <patrickchung@cdge.com.sg>; Denis Teo Chin Chye <denisteo@sparkcarcare.com>

Subject: SKD9244C CLAIMING AGAINST GBB4494Y DOA05122019 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir / Madam,

Please advice on the liability of the accident.

Your insured vehicle number GBB4494Y.

Vehicle is in and ready for survey (PRI) at CDGE Braddell.

Please reply with confirmation.

Thanks

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2019 16:09
Date Of Accident	05/12/2019 18:15
Exact Location Of Accident	BLK13 YORKHILL CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD9244C
Insured/Policyholder	
Name Of Registered Owner	COMFORTDELGRO RENT A CAR PTE.LTD
Co Reg No	198105775H
Email Address	DANNYNG@CDGRENTACAR.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-97858800

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4L AT SR - 97969926
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	M460802
Cover Note Number	

Driver

Name of Driver	WAN JONG FAI
NRIC No	S7249144J
Date Of Birth	30/12/1972
Occupation	INDOOR
Date Of Driving Pass	26/12/1990
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96664980
Fax Number	
Contact Number	

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My car was parked at Block 13 yoke hill open place carpark. I was noticed there was a van GBB4494Y reversing his van and collided onto my car. Damages of my car front right side position. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB4494Y
Vehicle Make/Model/Colour	NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN SIAK HENG
NRIC/Passport Number	S8204761A
Contact Number	97728111
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

6-12-2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

**VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
VOO CHEON YEE**

Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:

Sketch Plan #3

ACCIDENT STATEMENT (2000 characters)

My car was parked at Block 13 yoke hill open place carpark. I was noticed there was a van GBB4494Y reversing his van and collided onto my car. Damages of my car front right side position. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

6 December 2019 at 2:13 PM

Date/Time:

6 December 2019 at 2:13 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	775H
Vehicle No.:	SKD9244C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT SR
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	K24Z21351779
Chassis No.:	JHMRB3850AC201493
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$34,230.00
Original Registration Date:	17 Jan 2012
First Registration Date:	17 Jan 2012
Transfer Count:	0
Actual ARF Paid:	\$34,230.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2022
PARF Rebate Amount:	\$20,538.00
COE Expiry Date:	16 Jan 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$70,003.00
COE Rebate Amount:	\$14,527.00
Total Rebate Amount:	\$35,065.00

The information contained herein is correct as at 19 Dec 2019

OK



ATTENTION : _____ ADDRESS : _____
 TEL : _____
 FAX : _____

VEHICLE NO : SKD9244C CHASSIS NO. : _____
 MAKE / MODEL : _____ ENGINE NO : _____
 DAYS OF REPAIR : _____ YEAR OF MANUF : _____
 PREPARED BY / DATE : _____ SALES ORDER : _____

CASH REPAIR QUOTATION

Cost price

S/N	DESCRIPTION OF REPAIR SCOPE	PROPOSED (S\$)
1	HEADLAMP RH / <i>cut</i>	\$ 492.00
2	FRT BUMPER SIDE RETAINER RH / <i>re.</i>	\$ 12.00
	LABOUR	
	TO REMOVE AND INSTALL HEADLAMP RH	FOC
	TO PUUTY AND RESPRAY FRT BUMPER	\$ ✓ 250.00
	<i>2 Days.</i>	
	<i>part by part.</i>	
	<i>After repair photos.</i>	
	<i>Quo Qian - 82880282</i>	
	<i>19/12/19.</i>	
	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company </div>	
		TOTAL \$754.00 _x
	Acknowledged by Repairer	GST 7% \$52.78
	Signature:	
	Date:	TOTAL WITH GST% \$806.78

Note: Quotation for Cash Repairs/not for Insurance Claims (Valid for 1 month only)

Please sign below if you agree with our quotation and fax to us @ 62815767

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2019		19 Dec 2019 10:09 Edit Adj Rpt	S\$754.00 Edit Estimates	S\$754.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	BARTER MAISON PRIVATE LIMITED , Co. Reg. No.: 200923634E								
Main Claimant:	COMFORTDELGRO RENT A CAR PTE LTD , Co. Reg. No.: 198105775H								
Vehicle Reg. No.:	SKD9244C	Date of Loss:	05/12/2019 18:00 - :59 [94 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D206014C02	Policy/Cover Note No.:	DMCVSN30314219000						
Vehicle Reg. No. (Insured):	GBB4494Y	Policy No. (Claimant):							
		Excess:	S\$350.00						
Repairer:	Comfortdelgro Engineering Pte Ltd (HQ) 205 BRADDELL ROAD, 579701 Braddell - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/12/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date:	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD9244C (SNM19D206014C02)**
[GBB4494Y]
 TP
COMFORTDELGRO RENT A CAR PTE LTD
 Dec 5 2019 6:00PM
[BARTER MAISON PRIVATE LIMITED]
 Comfortdelgro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser ▾	
Photos/Images				3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
2	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
3	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
9	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/01/20 09:33	General View		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022306/GYD3S2

Date: 07/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30314219000

Claimant Vehicle No: SKD9244C Insured Vehicle No: GBB4494Y

Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: SNM19D206014C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD9244C**

Make & Model: HONDA ODYSSEY, 2.4 AT SR (A) Engine No: K24Z21351779

Reg. Date: 17/01/2012 (Man. Year: 2010) Chassis No: JHMRB3850AC201493

Colour: Black Odometer: 75141 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	504.00	504.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	250.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	754.00	754.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	52.78	52.78	0.00	0.00
Nett Amount (S\$)	806.78	806.78	0.00	0.00

INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 19/12/2019 Inspected At: Comfortdelgro Engineering Pte Ltd (HQ)
205 BRADDELL ROAD
Singapore 579701

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)**Parts:** M1-MPV HONDA ODYSSEY 2.4 AT SR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKD9244C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cut	492.00 F	*492.00 F
2	1		*FRT BUMPER SIDE RETAINER RH	Deformed	12.00 F	*12.00 F
Total Parts (S\$)					504.00	504.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL HEADLAMP RH. (FOC)	New	0.00	0.00
2	TO PUTTY AND RESPRAY FRT BUMPER.	New	250.00	250.00
Gross Labour Cost (\$\$)			250.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >