

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Ong Zi Hui

of

MSIA

Date/Time:

18/12/19 @ 5:20pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLT 47684

Insured:

SGE 7692Y

at Workshop in/s

Rico 60 Auto

Tel:

91878064

of

8 kaki Bukit Ave 4 # 02-24 premier

8811 2101

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A

14/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:44am @ 19/12/19

Person Contacted:

Shanelle

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (/) Estimate

SLT 47684 - NA/MSA/19022137/19

D.O.A: 14/12/2019

SGE 7692Y - NA/MSA/01000138/29

D.O.A: 14/12/2019

20/12/19

Email preli revised to Zi Hui, pending parts prices from repairer

29/6/20

Lump Sum \$11,500 confirmed by email (Red 46,828.08, 80%)

30/6/20

Send IA via merimen

Tanpin

MS16

ASSIGNMENT

Car No.

Date: 19/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 47684

at Workshop n/s

Rico 60 Auto

of 8 kaki Bukit Ave 4 # 02-24 premier

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Carlin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

Q68K.

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Val No:

SLT47684

Yr Regd:

2017 Jct

Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

cc 1496

Colour:

Blue

AC: Insured / Std / NI / NA

Sp Reading

74087

T/Radio: Insured / Std / NI / NA

EngNo:

C/No:

GK 81104551

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A

D.O.I

19/12/19

Survey held at

Rico 60

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & Fnt O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

4/5/9.400, 9 days

Tanpin

PLS re-confirm parts prices.

2/3

Date/Time, File Path (a)



Preli. Report

11



Final Report

Date/Time, File Path (a)

30/6/20-Typist

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation

3 + 85 = 9

Phone

1000

1000

1000

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Wind (\$

Report Remarks: Merimen

Lum Sum / U/C: LS \$11,500

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 December 2019 1:42 PM
To: 'Ong Zi Hui'; SUR
Cc: 'Crystal Lee'
Subject: RE: Survey Request - Manual Assigned-SLT 4768U
Attachments: SLT 4768U PRELI REVISED.pdf

Dear Zi Hui,

Enclosed preliminary revised of vehicle SLT 4768U
Date of survey: 19/12/2019
Number of days (estimated) : 9 days

Pending parts prices from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email : sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 19 December 2019 9:49 AM
To: 'Ong Zi Hui' <zihui_ong@sg.msigsig-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Crystal Lee' <crystal_lee@sg.msigsig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Zi Hui [mailto:zihui_ong@sg.msigsig-asia.com]
Sent: Wednesday, 18 December 2019 5:20 PM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>
Subject: Survey Request - Manual Assigned

PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Manual Assigned

Dear LKK,

Refer to the email below, please survey the vehicle.

We'll assign via Merlmen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Wednesday, 18 December 2019 3:14 PM
To: Rico 60 <claims@rico60.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Rico 60 <claims@rico60.com>
Sent: Wednesday, 18 December 2019 10:17 AM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Please have LKK or Kelvin from MSIG in house survey the said vehicle.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Helene Phua
Sent: Wednesday, 18 December 2019 9:53 AM
To: claims@rico60.com
Cc: Winnie Chua
Subject: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

We refer to your email dated 17/12/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd

- 5) Appraisal VP Pte Ltd
6) AutoProbe Consultants
7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msigg-asia.com

Have a great week ahead!


Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msigg-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg



From: Enquiry [<mailto:claims@rico60.com>]
Sent: Tuesday, December 17, 2019 5:14 PM
To: Claims <claims@sg.msigg-asia.com>
Subject: PRI Arrangement for SLT 4768 U

Dear all,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SLT 4768 U
Your Insured – SGE 7692 Y
DOA – 14/12/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



This email has been checked for viruses by AVG antivirus software.

www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Your ref: PLEASE ADVISED

Our ref: CS/MSG19022312/T1vd3

Date: 20/12/2019

The Motor Claims Department
M/s: MSIG INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLT 4768U

We thank you for your instruction on 18/12/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/12/2019 at the premises of M/s RICO 60 AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$24,810.00 (LABOUR ONLY)
Revised Estimate Amount	: S\$4,365.00
"Check" Items Amount	: S\$310.00
Total	: S\$4,675.00 (LABOUR ONLY)
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion and front o/s portion



Comments/Present Status:

Damages Consistent

Pending parts prices from repairer

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Wednesday, 18 December 2019 5:20 PM
To: assignments; Admin-D (LKKAuto)
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: PRI Arrangement.pdf

PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Manual Assigned

Dear LKK,

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Wednesday, 18 December 2019 3:14 PM
To: Rico 60 <claims@rico60.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services


D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Rico 60 <claims@rico60.com>

Sent: Wednesday, 18 December 2019 10:17 AM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>

Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Please have LKK or Kelvin from MSIG in house survey the said vehicle.

Thank you.

Best Regards,

John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Helene Phua

Sent: Wednesday, 18 December 2019 9:53 AM

To: claims@rico60.com

Cc: Winnie Chua

Subject: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

We refer to your email dated 17/12/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua


Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



From: Enquiry [<mailto:claims@rico60.com>]
Sent: Tuesday, December 17, 2019 5:14 PM
To: Claims <claims@sg.msig-asia.com>
Subject: PRI Arrangement for SLT 4768 U

Dear all,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SLT 4768 U
Your Insured – SGE 7692 Y
DOA – 14/12/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24
Singapore 415875 | Email: enquiry@rico60.com
Tel: +65 6286 6060 | Fax: +65 6286 7060

PRI ARRANGEMENT

Date: 17/12/19

To: MSG

ATTN: Motor Claims Department

RE: Accident involving motor vehicle nos. SLT 4768U, SG E7692Y, SGW 892L, SML 2069U, SKC 41K ^{& SG S1912}
along CTE tunnel SLE Before TPE Exit on 14/12/19 @ 19:40hrs.

We refer to the above matter.

We are instructed by John Wei Joo Ong
to notify you of a road traffic accident on 14/12/19 at about 19:40hrs
along CTE tunnel SLE Before TPE Exit
involving our client's vehicle no. SLT 4768U and vehicle no. SG E7692Y
driven by you at the stated time.

Due to the above-mentioned accident, our client's vehicle has been damaged. Before our client/we proceed with the repair(s) of the damaged vehicle, please kindly let us know within 2 working days of your receipt of this notice, whether you or your insurer would like to conduct pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to the repair work(s) of the vehicle without further reference to you.

Thank you.

Signature

Name: Shanelle Lim

Mobile No.: 9187 8064

> Back to OneMotoring

Rupin

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

956Z

Vehicle Details

Vehicle No.:

SLT4768U

Vehicle to be Exported:

No

Intended Deregistration Date:

17 Dec 2019

Vehicle Make:

HONDA

Vehicle Model:

SHUTTLE 1.5 G-CVT

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

L15B5005790

Chassis No.:

GK81104851

Maximum Power Output:

97.0 kW (130 bhp)

Open Market Value:

\$18,847.00

Original Registration Date:

30 Oct 2017

First Registration Date:

30 Oct 2017

Transfer Count:

0

Actual ARF Paid:

\$8,847.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Oct 2027

PARF Rebate Amount:

\$6,635.00

Intended COE Rebate Details

COE Expiry Date:

29 Oct 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$45,201.00

COE Rebate Amount:

\$35,553.00

Total Rebate Amount:

\$42,188.00

The information contained herein is correct as at 17 Dec 2019

OK

NHT = 926812

7-10.5

BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START
SEARCH
NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

BMW 3 Series 523i Sedan 513 BHP



1st Owner, Low Mileage, 11,111 km
Only 1 Previous Owner, 1st Owner
Call For More Info: 020
Direct Owner, 1st Owner



Post an Ad Advertiser Login View of Selling

Sort by Date Posted 20 results/page

11 vehicles

HONDA SHUTTLE

Price: Any price Depre: Any depre Reg Date: 2017 to 2017 Eng Cap: Any Veh Type: All types
Fuel: Any fuel Mileage: Any OMV: Any Gear: Any Gear Past Owners: Any
Category: All categories Scheme: All schemes Dealer: Any Dealer Location: Any Status: Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status



Honda Shuttle 1.5A G

\$66,800

\$8,160 /yr

14-Aug-2017

1,496 cc

48,000 km

Stationwagon

Available

Posted: 16-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$66,800

\$8,110 /yr

14-Aug-2017

1,496 cc

75,000 km

Stationwagon

Available

1 Owner, Not Used Grab / Uber, Full Service Records, No Expenses Spared On Maintenance, Well Maintained By Previous Owner, View This Unit Before You Commit To Others, Flexible Loan Packages Could Be Discussed, Call For Viewing Now!

AMS Motors Pte Ltd

Posted: 16-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$73,800

\$8,890 /yr

22-Dec-2017

1,496 cc

32,000 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Posted: 15-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G (OPC)

\$51,800

\$6,620 /yr

15-Feb-2017

1,496 cc

16,345 km

Stationwagon

Available

100% Loan Available, OPC Cannot Be A Previous Grab Car! Super Low Mileage Done! Like New, Superb Condition, Well Maintained Interior Condition, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now!

Sales

Posted: 12-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Lee Sheng Auto Pte Ltd - Specialist for Honda Car repair, servicing & maintenance

Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting.

More info about this shop



Honda Shuttle 1.5A G

\$66,800

\$8,680 /yr

23-Mar-2017

1,496 cc

38,000 km

Stationwagon

Available

Cheapest In Town! Easy 100% Loan Approval Non-PHV Vehicle, Only 1 Previous Owner! In Excellent Condition, Original Paintwork Since Day 1, Accident-Free, Immaculate Condition, In-House Loan And Bank Loan Available! Sms, Call Or Whatsapp Me For Discussion And View.

Heritage Auto Enterprise Pte Ltd

Posted: 11-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$69,555

\$8,340 /yr

20-Oct-2017

1,496 cc

27,000 km

Stationwagon

Available

1 Owner Only, Low Mileage Done At 27k KM Only Owner 2nd Car Always Park At Shuttle Car Park, Low Interest Rate At 2.28% Only, High Loan Available, Hurry Call Now For Viewing.

Cars Premium

Posted: 09-Dec-2019 Tags: 2017 Honda Shuttle, Honda Shuttle, honda shuttle, Used Honda

Compare

- 

Honda Shuttle Hybrid 1.5A \$70,500 \$8,820 /yr 31-Aug-2017 1,496 cc Stationwagon Available

Fuel Type: Petrol-Electric
Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing
Posted: 06-Dec-2013
Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda Shuttle, shuttle, used honda
- 

Honda Shuttle 1.5A G \$68,800 \$8,400 /yr 02-Aug-2017 1,496 cc Stationwagon Available

Powerful And Fuel Efficient Japanese Station Wagon. Elegance White Exterior With Customized Matching Brown And Black Leather Upholstery. Spacious And Enough Leg Room To Seat 5 Adults Comfortably. Suitable For Family, Sales Or Commercial Usage. Comes With...

Posted: 24-Nov-2013
Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda Shuttle, shuttle, used honda
- 

Honda Shuttle Hybrid 1.5A \$71,000 \$8,800 /yr 27-Sep-2017 1,496 cc Stationwagon Available

Fuel Type: Petrol-Electric
Elegant White, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing
Posted: 24-Nov-2013
Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda Shuttle, shuttle, used honda
- 

Honda Shuttle Hybrid 1.5A \$70,500 \$8,870 /yr 15-Aug-2017 1,496 cc Stationwagon Available

Fuel Type: Petrol-Electric
Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing
Posted: 07-Nov-2013
Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda Shuttle, shuttle, used honda
- 

That's a fine looking car interior
Customize your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more
- 

Honda Shuttle 1.5A G \$67,800 \$8,320 /yr 14-Jul-2017 1,496 cc Stationwagon Available

Guarantee Owner Using.

Posted: 31-Oct-2013
Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda Shuttle, shuttle, used honda

Make & Model Price Description Reg Date Eng Cap Mileage Veh Type Status

20 results/page

For old advertisements, view Expired ads

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car dealership for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used HONDA SHUTTLE, HONDA SHUTTLE Singapore, used HONDA SHUTTLE Singapore, used HONDA SHUTTLE, used vehicles Singapore or even buy used HONDA SHUTTLE Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and listed on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement
©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/12/2019 17:38
Date Of Accident 14/12/2019 19:40
Exact Location Of Accident CTE TWDS SLE B4 TPE EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT4768U
Insured/Policyholder
Name Of Registered Owner TOH WEI SEONG
NRIC No S7925956Z
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-94243095
Alternative Phone No OFFICE-94243095

Vehicle Particulars

Manufacturer HONDA
Model SHUTTLE
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A 80463617 QMX
Cover Note Number

Driver

Name of Driver TOH WEI SEONG
NRIC No S7925956Z
Date Of Birth 30/08/1979
Occupation INDOOR
Date Of Driving Pass 31/07/2003
Driving Experience 16 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-94243095
Fax Number
Contact Number OFFICE-94243095
Email Address NOEMAIL

Address	BLK 34 WOODLANDS DR 16 #10-29
Postcode	737771
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	6
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: RYCHELLE GENDER: FEMALE
Passenger 2	NAME: CHA HUI FANG GENDER: FEMALE
Passenger 3	NAME: SHERELLE GENDER: FEMALE
Passenger 4	NAME: JERRELL GENDER: MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGE7692Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number : SKG2892L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category : PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number : SMC2069U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category : PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number : SKC41K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category : PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number : SGS191Z

Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TOH WEI SEONG
 Approximate Age
 Injuries Sustain NECK N BACK
 Injured person in which vehicle? SLT4768U
 Were seat belts worn? YES
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

DETAILS OF INJURED PERSON 2

Name RYCHELLE
 Approximate Age
 Injuries Sustain NECK N BACK
 Injured person in which vehicle? SLT4768U
 Were seat belts worn? YES
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

DETAILS OF INJURED PERSON 3

Name CHA HUI FANG
 Approximate Age
 Injuries Sustain NECK N BACK
 Injured person in which vehicle? SLT4768U
 Were seat belts worn? YES
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

DETAILS OF INJURED PERSON 4

Name SHERELLE
 Approximate Age
 Injuries Sustain NECK N BACK
 Injured person in which vehicle? SLT4768U
 Were seat belts worn? YES
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

DETAILS OF INJURED PERSON 5

Name	JERRELL
Approximate Age	
Injuries Sustain	NECK N BACK
Injured person in which vehicle?	SLT4758U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

A - SLT 47684

B - SGE 76924

C - SRG 28926

D - SMC 20690

E - SKC 412

F - SCS 1912



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14 DECEMBER 2014 AT AROUND 1440H, I WAS DRIVING ON THE MOST RIGHT LANE ON CTE TOWARD SLE. VEHICLE F SUDDENLY E-BRAKE. I SWERVED TO MY RIGHT TO AVOID COLLIDING INTO VEHICLE F. VEHICLE B COLLIDED INTO MY VEHICLE AND VEHICLE F.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRC File No:



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

ATTN	NO	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING <i>new</i>	1	
	2	REAR TAILGATE <i>bt</i>	1	
	3	REAR TAILGATE LAMP L+R <i>LH-?, RH-X</i>	2	
	4	REAR TAILGATE WIPER ARM <i>X</i>	1	
	5	REAR TAILGATE WIPER MOTOR <i>X</i>	1	
	6	REAR TAILGATE WIPER MOTOR COVER <i>X</i>	1	
	7	REAR TAILGATE LOGO 'HONDA' <i>new</i>	1	
	8	REAR TAILGATE CENTER CHROME <i>?</i>	1	
	9	REAR TAILGATE CENTER CHROME NUMBER PLATE LAMP L+R <i>X</i>	2	
	10	REAR TAILGATE CENTER CHROME SWITCH <i>X</i>	1	
	12	REAR TAILGATE EMBLEM 'SHUTTLE' <i>new</i>	1	
	13	REAR TAILGATE INNER TRIM TOP L+R <i>X</i>	1	
	14	REAR TAILGATE INNER TRIM BTM <i>X</i>	1	
	15	REAR TAILGATE INNER HANDLE <i>X</i>	1	
	16	REAR TAILGATE HINGE L+R <i>X</i>	2	
	17	REAR TAILGATE DAMPER L+R <i>X</i>	2	
	18	REAR TAILGATE WEATHERSTRIP <i>?</i>	1	
	19	TAILLAMP L+R <i>LH-cm, RH-X</i>	2	
	20	TAILLAMP PANEL L+R <i>LH-?, RH-X</i>	2	
	21	REAR BUMPER <i>de</i>	1	
	22	REAR BUMPER RETAINER L+R <i>LH-de, RH-X</i>	2	
	23	REAR BUMPER BRACKET L+R <i>LH-de, RH-X</i>	2	
	24	REAR BUMPER SPONGE <i>X</i>	1	
	25	REAR BUMPER REFLECTOR L+R <i>LH-cm, RH-X</i>	1	
	26	REAR BUMPER BUZZER <i>X</i>	1	
	27	REAR FENDER L+R <i>LH-buc, RH-X</i>	2	
	28	REAR FENDER COWLING L+R <i>LH-de, RH-X</i>	2	
	29	REAR FENDER INNER TRIM TOP L+R <i>LH-X, RH-X</i>	2	
	30	REAR FENDER INNER TRIM BTM L+R <i>LH-?, RH-X</i>	2	
	31	END PANEL <i>bt</i>	1	
	32	END PANEL TOP GARNISH <i>?</i>	1	
	33	SPARE WHEEL PANEL <i>Rsp?</i>	1	
	34	SPARE WHEEL PANEL TOP BOARD <i>X</i>	1	
	35	SPARE WHEEL PANEL ACCESSORIES BOX L+R <i>X</i>	2	
	36	REAR CHASSIS RH <i>R X</i>	1	REPAIR
	37	REAR EXHAUST PIPE <i>X</i>	1	
	38	REAR EXHAUST MOUNTING <i>X</i>	1	
	39	REAR EXHAUST BRACKET <i>X</i>	1	
	40	REAR EXHAUST HEAT SHIELD <i>X</i>	1	
	41	HEADLAMP L+R <i>X</i>	2	



Rico 60 Auto Services Pte Ltd, Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

NO	DESCRIPTION / PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING	1	\$486.90
2	REAR TAILGATE	1	\$1,034.40
3	REAR TAILGATE LAMP L+R @ 340.80	2	\$1,104.40
4	REAR TAILGATE WIPER ARM	1	\$461.30
5	REAR TAILGATE WIPER MOTOR	1	\$296.40
6	REAR TAILGATE WIPER MOTOR COVER	1	\$191.60
7	REAR TAILGATE LOGO 'HONDA'	1	\$99.70
8	REAR TAILGATE CENTER CHROME	1	\$516.30
9	REAR TAILGATE CENTER CHROME NUMBER PLATE LAMP L+R	2	\$246.40
10	REAR TAILGATE CENTER CHROME SWITCH	1	\$193.70
12	REAR TAILGATE EMBLEM 'SHUTTLE'	1	\$124.10
13	REAR TAILGATE INNER TRIM TOP L+R	1	\$416.70
14	REAR TAILGATE INNER TRIM BTM	1	\$670.10
15	REAR TAILGATE INNER HANDLE	1	\$79.40
16	REAR TAILGATE HINGE L+R	2	\$232.60
17	REAR TAILGATE DAMPER L+R	2	\$684.40
18	REAR TAILGATE WEATHERSTRIP	1	\$419.60
19	TAILLAMP L+R	2	\$1,164.40
20	TAILLAMP PANEL L+R	2	\$1,006.80
21	REAR BUMPER	1	\$1,071.20
22	REAR BUMPER RETAINER L+R	2	\$421.40
23	REAR BUMPER BRACKET L+R	2	\$406.80
24	REAR BUMPER SPONGE	1	\$329.70
25	REAR BUMPER REFLECTOR L+R	1	\$874.40
26	REAR BUMPER BUZZER	1	\$679.10
27	REAR FENDER L+R	2	\$4,689.30
28	REAR FENDER COWLING L+R	2	\$492.40
29	REAR FENDER INNER TRIM TOP L+R	2	\$1,240.60
30	REAR FENDER INNER TRIM BTM L+R	2	\$2,466.20
31	END PANEL	1	\$1,045.90
32	END PANEL TOP GARNISH	1	\$324.60
33	SPARE WHEEL PANEL	1	\$2,411.70
34	SPARE WHEEL PANEL TOP BOARD	1	\$643.60
35	SPARE WHEEL PANEL ACCESSORIES BOX L+R	2	\$764.20
36	REAR CHASSIS RH	1	REPAIR
37	REAR EXHAUST PIPE	1	\$1,641.70
38	REAR EXHAUST MOUNTING	1	
39	REAR EXHAUST BRACKET	1	
40	REAR EXHAUST HEAT SHIELD	1	
41	HEADLAMP L+R	2	

29,461.30



SLT 4768 U

HONDA SHUTTLE

TYRE₁

CHASSIS NUM:

PARTS TOTAL = \$17,823.50
 - 20% = \$14,274.80,
 SIN = \$885
 LABOUR = \$3,660
 TOTAL = \$18,819.80
 - 20% = \$15,100

~~Injektion~~ 23/12/19

$$\begin{array}{r} 6507.36 + 1120 \\ 405 \\ 3030 \\ 691.12 \end{array}$$

1175348

LS 9.405

42	HEADLAMP BRACKET L+R	X	2	
43	HEADLAMP CHROME L+R	X	2	
44	FRONT GRILLE	X	1	
45	FRONT GRILLE TOP	X	1	
46	FRONT GRILLE LOGO	X	1	
47	FRONT BUMPER	NC X 1050 del	1	\$1,041.50
48	FRONT BUMPER RETAINER RH	NC X 110. ncl	1	\$368.40
49	FRONT BUMPER BRACKET RH	X	1	
50	FRONT BUMPER FOG LAMP RH	X	1	
51	FRONT BUMPER FOG LAMP GARNISH RH	X	1	
52	FRONT BUMPER FOG LAMP CHROME RH	X	1	
53	FRONT FENDER RH	X	1	
54	FRONT FENDER COWLING RH	X	1	
55	FRONT DOOR RH	X	1	
56	FRONT DOOR SIDE MIRROR RH	X	1	
57	FRONT ABSORBER RH	X	1	
58	FRONT UPPER ARM RH	X	1	
59	FRONT LOWER ARM RH	X	1	
60	FRONT KNUCKLE RH	NC X 353.60. b1?	1	\$619.40
61	FRONT KNUCKLE BEARING RH	NC X 270.85. b1?	1	\$541.70
62	FRONT BEARING HUB RH	X	1	
				8134.20 P= \$14,244.40.
				20% 6507.36.
			SUBTOTAL	\$ -
			LESS 20%	\$ -
			PARTS TOTAL	\$ -
SPECIAL NETT				
1	REAR NUMBER PLATE	wtv 45	1	\$ 120.00
2	REVERSE SENSOR	nw 200	2	\$ 300.00
3	REVERSE CAM	n1 X	1	\$ 1,000.00
4	REAR END PANEL SEALANT	nel 40	1	\$ 120.00
5	SPARE WHEEL PANEL SEALANT	n1 X	1	\$ 120.00
6	REAR BUMPER CLIPS	nel 30	10	\$ 120.00
7	TAILLAMP CLIPS	30 nel 1?	12	\$ 60.00
8	REAR FENDER COWLING CLIPS	nel 10	10	\$ 120.00
9	REAR FENDER INNER TRIM CLIPS	nel 20	10	\$ 120.00
10	BOOTLID INNER TRIM CLIPS	nel 20	10	\$ 120.00
11	REAR END PANEL TOP GARNISH CLIPS	nel 10	10	\$ 120.00
12	FRONT BUMPER CLIPS	NC X nel 30	10	\$ 120.00
13	FRONT FENDER COWLING CLIPS	NC X nel 20	10	\$ 120.00
14	FRONT RIM	NC X del 400	SET	\$ 8,000.00
15	FRONT TYRE	n1 X	SET	\$ 4,000.00
				S/N= 885 405
			SPECIAL NETT TOTAL	\$ 14,560.00
LABOUR				
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1/200	1	\$ 4,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1/200	1	\$ 3,500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	50	1	\$ 120.00

2710.50

4	TO RNR REAR WINDSCREEN	120	1	\$	400.00
5	TO RNR REAR BOOT MECHANISM	60	1	\$	250.00
6	TO RNR REAR LUGGAGE COMPARTMENT	60	1	\$	250.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	30	1	\$	250.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	X	1	\$	250.00
9	TO RNR UNDERCARRIAGE SYSTEM	RCX Photo 120?	1	\$	250.00
10	TO CHECK WHEEL ALIGNMENT	WCX 80	1	\$	120.00
11	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	30	1	\$	120.00
12	TO RNR TYRE AND WHEEL BALANCING	WCX 30	1	\$	120.00
13	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	250	1	\$	500.00
14	TO DO WATER LEAK TEST.	30	1	\$	120.00
		3030 -			
	LABOUR = \$3,660.				
				LABOUR TOTAL	\$ 10,250.00
				GRAND TOTAL COST	\$ 24,810.00
					71,295.48

Taupkin 97495749 # 67495434
 'wp'
 19/12/19 @ 4:15pm
 Lumpsum
 Resurvey after repair.
 09 days
 sure/kaauto.com.

PAGE 1 OF 2

LK Auto Consultants hereby notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

$-20\% = 16,900 \text{ m}$

Customer:

Date:

20/12/2019 7:11 PM

Company:

VIN

License No:

SLT4768U

Technician:

Odometer:

Order No.:

Graphic Alignment Report

HONDA, 2018, FIT SHUTTLE GK8(Custom)

