

ASS. REC. BY:

REF: 08/MSA/1022312/TIV03

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Ong Zi Hui of MSLG Date/Time: 18/12/19 @ 5:20pm

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 47684 Insured: SGE 76924

at Workshop m/s Rico 60 Auto Tel: 9187 8064

of 8 kaki Bukit Ave 4 # 02-24 premier 8811 2101

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 14/12/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:44am @ 19/12/19 Person Contacted: Shanellie Vehicle: IN / OUT

Date/Time	Action/Instruction (—) Estimate
	SLT 47684 - N/A / MSA / 1022312 / 14 DOA: 14/12/2019
	SGE 76924 - N/A / MSA / 1022312 / 24 DOA: 14/12/2019
20/12/19	Email preli revised to Zi Hui, pending parts prices from repairer

REC. BY: Tan JmREP: MS16

ASSIGNMENT

From:

Date: 19/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 47684

at Workshop m/s

Rico 60 Autoof 8 Kaki Bukit Ave 4 # 02-24 premier

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Car In

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

Q68K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLT47684Yr Regn: 2017 OctType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda ShuttleC.C. 1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp.Reading

74087

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

6K 81104851Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19/12/19

Survey held at

Rico 60

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4s \$11,500, 10 days.Tan JmPls re-confirm parts prices.

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Repeat Format:

Lump Sum / L&L: \$

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

2/3

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 20 December 2019 1:42 PM
To: 'Ong Zi Hui'; SUR
Cc: 'Crystal Lee'
Subject: RE: Survey Request - Manual Assigned-SLT 4768U
Attachments: SLT 4768U PRELI REVISED.pdf

Dear Zi Hui,

Enclosed preliminary revised of vehicle SLT 4768U
Date of survey: 19/12/2019
Number of days (estimated) : 9 days

Pending parts prices from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 19 December 2019 9:49 AM
To: 'Ong Zi Hui' <zihui_ong@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Crystal Lee' <crystal_lee@sg.msig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Zi Hui [mailto:zihui_ong@sg.msig-asia.com]
Sent: Wednesday, 18 December 2019 5:20 PM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>
Subject: Survey Request - Manual Assigned

PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Manual Assigned

Dear LKK,

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Wednesday, 18 December 2019 3:14 PM
To: Rico 60 <claims@rico60.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of **MS&AD** INSURANCE GROUP

From: Rico 60 <claims@rico60.com>
Sent: Wednesday, 18 December 2019 10:17 AM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Please have LKK or Kelvin from MSIG in house survey the said vehicle.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: claims@rico60.com

From: Helene Phua
Sent: Wednesday, 18 December 2019 9:53 AM
To: claims@rico60.com
Cc: Winnie Chua
Subject: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

We refer to your email dated 17/12/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd

- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!


Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



From: Enquiry [<mailto:claims@rico60.com>]
Sent: Tuesday, December 17, 2019 5:14 PM
To: Claims <claims@sg.msig-asia.com>
Subject: PRI Arrangement for SLT 4768 U

Dear all,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SLT 4768 U
Your Insured – SGE 7692 Y
DOA – 14/12/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



This email has been checked for viruses by AVG antivirus software.

www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED

Our ref: CS/MSG19022312/T1vd3

Date: 20/12/2019

The Motor Claims Department
M/s: MSIG INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLT 4768U


We thank you for your instruction on 18/12/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/12/2019 at the premises of M/s RICO 60 AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$24,810.00 (LABOUR ONLY)
Revised Estimate Amount	: S\$4,365.00
"Check" Items Amount	: S\$310.00
Total	: S\$4,675.00 (LABOUR ONLY)
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion and front o/s portion



Comments/Present Status:

Damages Consistent

Pending parts prices from repairer

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Wednesday, 18 December 2019 5:20 PM
To: assignments; Admin-D (LKKAuto)
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: PRI Arrangement.pdf

PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Manual Assigned

Dear LKK,

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Wednesday, 18 December 2019 3:14 PM
To: Rico 60 <claims@rico60.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Rico 60 <claims@rico60.com>

Sent: Wednesday, 18 December 2019 10:17 AM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>

Subject: RE: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Please have LKK or Kelvin from MSIG in house survey the said vehicle.

Thank you.

Best Regards,

John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Helene Phua

Sent: Wednesday, 18 December 2019 9:53 AM

To: claims@rico60.com

Cc: Winnie Chua

Subject: RE: PRI Arrangement for SLT4768U DOA: 14/12/19 SGE7692Y (MSIG)

Hi,

We refer to your email dated 17/12/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua


Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



From: Enquiry [<mailto:claims@rico60.com>]
Sent: Tuesday, December 17, 2019 5:14 PM
To: Claims <claims@sg.msig-asia.com>
Subject: PRI Arrangement for SLT 4768 U

Dear all,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SLT 4768 U
Your Insured – SGE 7692 Y
DOA – 14/12/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

100 Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24

Singapore 415875 | Email: enquiry@rico60.com

Tel: +65 6286 6060 | Fax: +65 6286 7060

PRI ARRANGEMENT

Date: 17/12/19

To: mslg

ATTN: Motor Claims Department

RE: Accident involving motor vehicle nos. SLT 4768U, SGE7692Y, SKG892L, SML 2069U, SKC41K ^{& SGE51912}
along CTE towards SLE Before TPE Exit on 14/12/19 @ 19:40hrs.

We refer to the above matter.

We are instructed by Toh Wei Seong
to notify you of a road traffic accident on 14/12/19 at about 19:40hrs
along CTE towards SLE Before TPE Exit
involving our client's vehicle no. SLT 4768U and vehicle no. SGE7692Y
driven by you at the stated time.

Due to the above-mentioned accident, our client's vehicle has been damaged. Before our client/we proceed with the repair(s) of the damaged vehicle, please kindly let us know within 2 working days of your receipt of this notice, whether you or your insurer would like to conduct pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to the repair work(s) of the vehicle without further reference to you.

Thank you.

Signature

Name: Shanelle Lim

Mobile No.: 9187 8064

> Back to OneMotoring

Supu

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	956Z
Vehicle Details	
Vehicle No.:	SLT4768U
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5 G CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	L15B5005790
Chassis No.:	GK81104851
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,847.00
Original Registration Date:	30 Oct 2017
First Registration Date:	30 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$8,847.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2027
PARF Rebate Amount:	\$6,635.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$35,553.00
Total Rebate Amount:	\$42,188.00

The information contained herein is correct as at 17 Dec 2019

OK

Nett ≈ 7268/2

7-10.5

SGC8888M

BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START
SEARCH
NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW 5 Series 535i Sunroof 519 BHP.



Facelift Converted To LCI. All
Parts Changed Brand New OE. V
Good For Renew CCE
Direct Owner Starred



Sort by Date Posted

20 results/page

11 vehicles

HONDA SHUTTLE

Basic Search

Price Any price
Fuel Any fuel
Category All categories
Depre Any depre
Mileage Any
Scheme All schemes
Reg Date 2017 to 2017
OMV Any
Dealer Any Dealer
Eng Cap Any
Gear Any Gear
Location Any
Veh Type All types
Past Owners Any
Status Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status



Honda Shuttle 1.5A G

\$66,800

\$8,160 /yr

14-Aug-2017

1,496 cc

48,000 km

Stationwagon

Available

Posted: 16-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$66,800

\$8,110 /yr

14-Aug-2017

1,496 cc

75,000 km

Stationwagon

Available

1 Owner. Not Used Grab / Uber. Full Service Records. No Expenses Spared On Maintenance. Well Maintained By Previous Owner. View This Unit Before You Commit To Others. Flexible Loan Packages Could Be Discussed. Call For Viewing Now!

AMS Motors Pte Ltd

Posted: 16-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$73,800

\$8,890 /yr

22-Dec-2017

1,496 cc

32,000 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Posted: 15-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

PREMIUM AD



Honda Shuttle 1.5A G (OPC)

\$51,800

\$6,620 /yr

15-Feb-2017

1,496 cc

16,345 km

Stationwagon

Available

100% Loan Available. OPC Cannot Be A Previous Grab Car! Super Low Mileage Done! Like New, Superb Condition, Well Maintained Interior Condition, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now!

Iaxis

Posted: 12-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Lee Sheng Auto Pte Ltd - Specialist for Honda Car repair, servicing & maintenance

Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting.

More info about this shop



Honda Shuttle 1.5A G

\$66,800

\$8,680 /yr

23-Mar-2017

1,496 cc

38,000 km

Stationwagon

Available

Cheapest In Town! Easy 100% Loan Approval Non PHV Vehicle, Only 1 Previous Owner! In Excellent Condition, Original Paintwork Since Day 1, Accident-Free, Immaculate Condition, In House Loan And Bank Loan Available! Sms, Call Or Whatsapp Me For Discussion And Vie...

Heritage Auto Enterprise Pte Ltd

Posted: 11-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$69,555

\$8,340 /yr

20-Oct-2017

1,496 cc

27,000 km

Stationwagon

Available

1 Owner Only. Low Mileage Done At 27k KM Only Owner 2nd Car Always Park At Shuttle Car Park. Low Interest Rate At 2.28% Only. High Loan Available. Hurry Call Now For Viewing.

Cars Premium

Posted: 09-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Compare



Honda Shuttle Hybrid 1.5A \$70,500 \$8,820 /yr 31-Aug-2017 1,496 cc - Stationwagon Available

Fuel Type: Petrol-Electric
Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing
Posted: 06-Dec-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G \$68,800 \$8,400 /yr 02-Aug-2017 1,496 cc - Stationwagon Available

Powerful And Fuel Efficient Japanese Station Wagon. Elegance White Exterior With Customized Matching Brown And Black Leather Upholstery. Spacious And Enough Leg Room To Seat 5 Adults Comfortably. Suitable For Family, Sales Or Commercial Usage. Comes Wit... **PREMIUM AD**

Posted: 24-Nov-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A \$71,000 \$8,800 /yr 27-Sep-2017 1,496 cc - Stationwagon Available

Fuel Type: Petrol-Electric
Elegant White, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing
Posted: 24-Nov-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A \$70,500 \$8,870 /yr 15-Aug-2017 1,496 cc - Stationwagon Available

Fuel Type: Petrol-Electric
Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing
Posted: 07-Nov-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



That's a fine looking car interior
Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.
Find out more!



Honda Shuttle 1.5A G \$67,800 \$8,320 /yr 14-Jul-2017 1,496 cc - Stationwagon Available

Guarantee Owner Using.
Posted: 31-Oct-2019 Tags: 2017 Honda Shuttle, 2017 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used HONDA SHUTTLE, HONDA SHUTTLE Singapore, used HONDA SHUTTLE Singapore, used HONDA SHUTTLE, used vehicles Singapore or even buy used HONDA SHUTTLE Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2019 17:38
Date Of Accident	14/12/2019 19:40
Exact Location Of Accident	CTE TWDS SLE B4 TPE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT4768U
Insured/Policyholder	
Name Of Registered Owner	TOH WEI SEONG
NRIC No	S7925956Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94243095
Alternative Phone No	OFFICE-94243095

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80463617 QMX
Cover Note Number	

Driver

Name of Driver	TOH WEI SEONG
NRIC No	S7925956Z
Date Of Birth	30/08/1979
Occupation	INDOOR
Date Of Driving Pass	31/07/2003
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94243095
Fax Number	
Contact Number	OFFICE-94243095
Email Address	NOEMAIL

Address	BLK 34 WOODLANDS DR 16 #10-29
Postcode	737771
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	6
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : RYCHELLE GENDER: : FEMALE
Passenger 2	NAME: : CHA HUI FANG GENDER: : FEMALE
Passenger 3	NAME: : SHERELLE GENDER: : FEMALE
Passenger 4	NAME: : JERRELL GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGE7692Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKG2892L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SMC2069U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SKC41K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SGS191Z

Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TOH WEI SEONG
Approximate Age
Injuries Sustain NECK N BACK
Injured person in which vehicle? SLT4768U
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name RYCHELLE
Approximate Age
Injuries Sustain NECK N BACK
Injured person in which vehicle? SLT4768U
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 3

Name CHA HUI FANG
Approximate Age
Injuries Sustain NECK N BACK
Injured person in which vehicle? SLT4768U
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 4

Name SHERELLE
Approximate Age
Injuries Sustain NECK N BACK
Injured person in which vehicle? SLT4768U
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 5


Name	JERRELL
Approximate Age	
Injuries Sustain	NECK N BACK
Injured person in which vehicle?	SLT4768U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please fill in correctly the details of the accident. Do not leave any blank space.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. The report must be filled in truthfully and accurately as possible in order to ensure the accuracy of the information and to avoid any dispute over the immediate policy liability.
4. The value and acceptance of the claim by insurance companies must be based upon the accuracy of the information provided.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and its copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or the claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
telIC/PH No:

Accident Sketch Plan

SKETCH PLAN

A-SLT47684

B-SGE 76424

C-SRG 2892L

D-SMC 2069U

E-SRC 41K

F-SGS191Z





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 14 DECEMBER 2019 AT AROUND 1940H, I WAS DRIVING ON THE MOST RIGHT LANE ON CIE TOWARD SLE. VEHICLE F SUDDENLY E-BRAKE. I SWEVED TO MY RIGHT TO AVOID COLLIDING INTO VEHICLE F. VEHICLE B COLLIDED INTO MY VEHICLE AND VEHICLE F.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC/Fin No.



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:

SLT 4768 U

MAKE & MODEL:

HONDA SHUTTLE

MILEAGE:


TYRE:

CHASSIS NUM:

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING <i>nei✓</i>	1	
2	REAR TAILGATE <i>bt✓</i>	1	
3	REAR TAILGATE LAMP L+R <i>LH-?, RH-X</i>	2	
4	REAR TAILGATE WIPER ARM <i>X</i>	1	
5	REAR TAILGATE WIPER MOTOR <i>X</i>	1	
6	REAR TAILGATE WIPER MOTOR COVER <i>X</i>	1	
7	REAR TAILGATE LOGO 'HONDA' <i>nei✓</i>	1	
8	REAR TAILGATE CENTER CHROME <i>?</i>	1	
9	REAR TAILGATE CENTER CHROME NUMBER PLATE LAMP L+R <i>X</i>	2	
10	REAR TAILGATE CENTER CHROME SWITCH <i>X</i>	1	
12	REAR TAILGATE EMBLEM 'SHUTTLE' <i>nei✓</i>	1	
13	REAR TAILGATE INNER TRIM TOP L+R <i>X</i>	1	
14	REAR TAILGATE INNER TRIM BTM <i>X</i>	1	
15	REAR TAILGATE INNER HANDLE <i>X</i>	1	
16	REAR TAILGATE HINGE L+R <i>X</i>	2	
17	REAR TAILGATE DAMPER L+R <i>X</i>	2	
18	REAR TAILGATE WEATHERSTRIP <i>?</i>	1	
19	TAILLAMP L+R <i>LH-cra✓, RH-X</i>	2	
20	TAILLAMP PANEL L+R <i>LH-? RH-X</i>	2	
21	REAR BUMPER <i>de✓</i>	1	
22	REAR BUMPER RETAINER L+R <i>LH-de✓, RH-X</i>	2	
23	REAR BUMPER BRACKET L+R <i>LH-de✓, RH-X</i>	2	
24	REAR BUMPER SPONGE <i>X</i>	1	
25	REAR BUMPER REFLECTOR L+R <i>LH-cra✓, RH-X</i>	1	
26	REAR BUMPER BUZZER <i>X</i>	1	
27	REAR FENDER L+R <i>LH-buc✓, RH-X</i>	2	
28	REAR FENDER COWLING L+R <i>LH-de✓, RH-X</i>	2	
29	REAR FENDER INNER TRIM TOP L+R <i>LH-X, RH-X</i>	2	
30	REAR FENDER INNER TRIM BTM L+R <i>LH-?, RH-X</i>	2	
31	END PANEL <i>bt✓</i>	1	
32	END PANEL TOP GARNISH <i>?</i>	1	
33	SPARE WHEEL PANEL <i>Rp?</i>	1	
34	SPARE WHEEL PANEL TOP BOARD <i>X</i>	1	
35	SPARE WHEEL PANEL ACCESSORIES BOX L+R <i>X</i>	2	
36	REAR CHASSIS RH <i>R X</i>	1	REPAIR
37	REAR EXHAUST PIPE <i>X</i>	1	
38	REAR EXHAUST MOUNTING <i>X</i>	1	
39	REAR EXHAUST BRACKET <i>X</i>	1	
40	REAR EXHAUST HEAT SHIELD <i>X</i>	1	
41	HEADLAMP L+R <i>X</i>	2	

42	HEADLAMP BRACKET L+R	X	2
43	HEADLAMP CHROME L+R	X	2
44	FRONT GRILLE	X	1
45	FRONT GRILLE TOP	X	1
46	FRONT GRILLE LOGO	X	1
47	FRONT BUMPER	del✓	1
48	FRONT BUMPER RETAINER RH	neg✓	1
49	FRONT BUMPER BRACKET RH	X	1
50	FRONT BUMPER FOG LAMP RH	X	1
51	FRONT BUMPER FOG LAMP GARNISH RH	X	1
52	FRONT BUMPER FOG LAMP CHROME RH	X	1
53	FRONT FENDER RH	Rx	1
54	FRONT FENDER COWLING RH	?	1
55	FRONT DOOR RH	X	1
56	FRONT DOOR SIDE MIRROR RH	X	1
57	FRONT ABSORBER RH	x	1
58	FRONT UPPER ARM RH	x	1
59	FRONT LOWER ARM RH	X	1
60	FRONT KNUCKLE RH	?	1
61	FRONT KNUCKLE BEARING RH	?	1
62	FRONT BEARING HUB RH	X	1
	SUBTOTAL		\$ -
	LESS 20%		\$ -
	PARTS TOTAL		\$ -
	SPECIAL NETT	QTY	PRICE
1	REAR NUMBER PLATE cut✓45	1	\$ 120.00
2	REVERSE SENSOR nw✓200	2	\$ 300.00
3	REVERSE CAM X	1	\$ 1,000.00
4	REAR END PANEL SEALANT neg✓40	1	\$ 120.00
5	SPARE WHEEL PANEL SEALANT X	1	\$ 120.00
6	REAR BUMPER CLIPS neg✓30	10	\$ 120.00
7	TAILLAMP CLIPS ? 12	12	\$ 60.00
8	REAR FENDER COWLING CLIPS neg✓10	10	\$ 120.00
9	REAR FENDER INNER TRIM CLIPS neg✓20	10	\$ 120.00
10	BOOTLID INNER TRIM CLIPS neg✓20	10	\$ 120.00
11	REAR END PANEL TOP GARNISH CLIPS neg✓10	10	\$ 120.00
12	FRONT BUMPER CLIPS neg✓30	10	\$ 120.00
13	FRONT FENDER COWLING CLIPS neg✓20	10	\$ 120.00
14	FRONT RIM dd✓400	SET	\$ 8,000.00
15	FRONT TYRE X	SET	\$ 4,000.00
	SPECIAL NETT TOTAL		\$ 14,560.00
	LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 12400	1	\$ 4,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 1400	1	\$ 3,500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 50	1	\$ 120.00



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

ATIN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING 121.30 neu✓	1	\$486.90
	2	REAR TAILGATE 1193.70 bti✓	1	\$1,634.90
	3	REAR TAILGATE LAMP L+R @ 340.80 LH- an RH-X	2	\$1,104.40
	4	REAR TAILGATE WIPER ARM nn X	1	\$461.30
	5	REAR TAILGATE WIPER MOTOR nn X	1	\$296.40
	6	REAR TAILGATE WIPER MOTOR COVER nn X	1	\$191.60
	7	REAR TAILGATE LOGO 'HONDA' neu✓	1	\$99.70
	8	REAR TAILGATE CENTER CHROME 383.10 un ✓?	1	\$516.30
	9	REAR TAILGATE CENTER CHROME NUMBER PLATE LAMP L+R nn X	2	\$246.40
	10	REAR TAILGATE CENTER CHROME SWITCH nn X	1	\$193.70
	12	REAR TAILGATE EMBLEM 'SHUTTLE' neu✓	1	\$124.10
	13	REAR TAILGATE INNER TRIM TOP L+R X	1	\$416.70
	14	REAR TAILGATE INNER TRIM BTM X	1	\$670.10
	15	REAR TAILGATE INNER HANDLE nn X	1	\$79.40
	16	REAR TAILGATE HINGE L+R X	2	\$252.60
	17	REAR TAILGATE DAMPER L+R X	2	\$634.40
	18	REAR TAILGATE WEATHERSTRIP 168.50 twi✓?	1	\$419.60
	19	TAILLAMP L+R 520.50 \$223.20 LH- an RH-X an	2	\$1,646.40
	20	TAILLAMP PANEL L+R 303.40 \$503.40 LH- an RH-X an	2	\$1,006.80
	21	REAR BUMPER 860 de✓	1	\$1,071.20
	22	REAR BUMPER RETAINER L+R 48.20 \$210.70 LH- an RH-X an	2	\$421.40
	23	REAR BUMPER BRACKET L+R 64.50 \$203.40 LH- an RH-X an	2	\$406.80
	24	REAR BUMPER SPONGE X an	1	\$329.70
	25	REAR BUMPER REFLECTOR L+R 47.30 \$187.20 LH- an RH-X an	1	\$374.40
	26	REAR BUMPER BUZZER X an	1	\$679.10
	27	REAR FENDER L+R 2210 \$2232.10 LH- an RH-X an	2	\$4,684.20
	28	REAR FENDER COWLING L+R 180 \$246.20 LH- an RH-X an	2	\$492.40
	29	REAR FENDER INNER TRIM TOP L+R LH- an RH-X an	2	\$1,240.40
	30	REAR FENDER INNER TRIM BTM L+R 658.80 \$1,284.10 LH- an RH-X an	2	\$2,468.20
	31	END PANEL 595.30 bti✓	1	\$1,045.90
	32	END PANEL TOP GARNISH 215 ? de✓	1	\$324.60
	33	SPARE WHEEL PANEL R an R an	1	\$2,411.70
	34	SPARE WHEEL PANEL TOP BOARD X	1	\$643.60
	35	SPARE WHEEL PANEL ACCESSORIES BOX L+R X	2	\$764.20
	36	REAR CHASSIS RH R X	1	REPAIR
	37	REAR EXHAUST PIPE X	1	\$1,641.70
	38	REAR EXHAUST MOUNTING X	1	\$
	39	REAR EXHAUST BRACKET nn X	1	\$
	40	REAR EXHAUST HEAT SHIELD X	1	\$
	41	HEADLAMP L+R X	2	\$

29,461.30



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLT 4768 U
HONDA SHUTTLE

ATTN:		
NO.	DESCRIPTION - PARTS	QTY PRICE
1	FRONT BUMPER LOWER PANEL 475.7266 X	1 \$679.60
2	FRONT BUMPER REINFORCEMENT BAR BRACKET (RH) 66X	1 \$190.70
3	TAILGATE LOCK 289.40 ✓ 66X	1 \$419.80
4	SPAREWHEEL PANEL TOP SIDE BOARD (L+R) 338.10 \$438.10. LH-✓, RH-X	2 \$876.20.
5	SPAREWHEEL PANEL TOOL BOX (L+R) 236.40 \$336.40 LH ✓, RH X	2 \$672.80
6	REAR ABSORBER (LH) x ?	1 \$531.40 X
7	REAR KNUCKLE BEARING (LH) x ?	1 \$499.70 X
8	REAR BEARING HUB (LH) x ?	1 \$803.40 X
9	REAR AXLE x	1 \$2,148.40 X
	Re \$3599.10 863.90	
	20% - 691.12	SUBTOTAL \$ -
		LESS 10% \$ -
		PARTS TOTAL \$ -
SPECIAL NETT		QTY PRICE
	SPECIAL NETT TOTAL	\$ -
LABOUR		QTY PRICE

PARTS TOTAL = \$17,843.50
- 20% = \$14,274.80.
S/N = \$885
LABOUR = \$3,660
TOTAL = \$18,819.80
- 20% = \$15,100

Signature 23/12/19

[illegible]

Customer:
Company:
License No: SLT4768U
Odometer:

Date: 20/12/2019 7:11 PM
VIN
Technician:
Order No.:

Graphic Alignment Report

HONDA, 2018, FIT SHUTTLE GK8(Custom)

