

ASS. REC. BY:

REF: 083/FCI19022313/Hvd3<sup>97</sup>

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Rachel Wu Limci of FCF Date/Time: 5:30 pm @ 18/12/19

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 7069E Insured: SHA 3858Y

at Workshop n/s Mycar consultant Tel: 8866 8832

of 53 Ubi Ave 1 #01-33

Policy No: \_\_\_\_\_ Claim No: D19007978MPSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15/12/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS hp? H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 1000 @ 19/12/19 Person Contacted: Hui Qin Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKD 7069E - NA/INC19022313/24 DOA 15/12/2019
	SHA 3858Y - NA/INC19022313/24 DOA: 15/12/2019
	19/12/19 - survey photo
	20/12/19 - 9 files print photo.

23/12/19 Submit PRS - mv: \$27K (EST) LTA: \$19,754 NV: \$7246

ASS. REC. BY: H-ANV

REF: FCI

PKS

ASSIGNMENT

From: \_\_\_\_\_ Date: 19/12/19

Estimated Cost: \_\_\_\_\_

OD:  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 7069E

at Workshop m/s: My Car Consultant

of: 53 ubi Ave 1 # 01-33

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SKD 7069E Yr Regn: 29/12/2011

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: T. Altis c.c. 1598

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 98122 km T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REE104/27846

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi:  Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65/15  
R: \_\_\_\_\_

	X	X
N/S		O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 57 mm Yoko  
L/Bal. 5 mm  
D.O.A. 15/12/2019

Rear R/Bal. 57 mm Yoko  
L/Bal. 5 mm  
D.O.A. 19/12/19 1:40pm

Survey held at: my car

Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Days = 2 by SKD 7069E PKS case
	MV - 27000
	PV - 19754
	NV - 7200

Date/Time, File Pass to?  Preli. Report  Final Report

1) \_\_\_\_\_

Date/Time, File Return to? 2) 23/12 - typist

Report Format: CWS

Lump Sum / T.R.B. \$ \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Site Insp (\$) \_\_\_\_\_

Interview (\$) \_\_\_\_\_

Tech. Invs (\$) \_\_\_\_\_

Wheel std (\$) \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL: \_\_\_\_\_

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	17-12-2019	<b>Our Ref No.</b> D19007978MFSH
<b>Accident Date</b>	15-12-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA3858Y	<b>Third Party Vehicle.</b> SKD7069E
<b>Survey Location</b>	53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park	
<b>Contact Person.</b>	HUIQIN	
<b>Contact No.</b>	88668832/ 88668832	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	MY CAR CONSULTANT PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	RACHELWU LIMEI	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/12/2019 18:39
Date Of Accident	15/12/2019 04:10
Exact Location Of Accident	SERANGOON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD7069E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FOCUS RENTALS PTE LTD
Co Reg No	201836450G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5106629800
Cover Note Number	

### Driver

Name of Driver	PUAR CHIA YONG (PAN JIARONG)
NRIC No	S7736359I
Date Of Birth	15/12/1977
Occupation	OUTDOOR
Date Of Driving Pass	06/08/2002
Driving Experience	17 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97346670
Fax Number	
Contact Number	OFFICE-97346670
Email Address	NOEMAIL

Address	BLK 147 SERANGOON NORTH AVENUE 1 #04-431
Postcode	550147
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3858T
Vehicle Make/Model/Colour	TOYOTA PRIUS
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time and date,  
I receive a call from dispatch to pick up a client at the bus stop, while I was  
on the way to the bus stop, I saw my client waving at me to go forward as  
it was pouring heavily I inch forward and stop by the side, while there  
was a taxi who was ahead of me, reversed onto my vehicle while  
I was stationary. I have an in car camera that recorded the whole event.

DECLARATION

I hereby declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

PRINTED NAME OF POLICYHOLDER

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	450G
Vehicle Details	
Vehicle No.:	SKD7069E
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	1ZRX161368
Chassis No.:	MR053REE104127846
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$14,432.00
Original Registration Date:	29 Dec 2011
First Registration Date:	29 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$14,432.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2021
PARF Rebate Amount:	\$8,659.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$54,887.00
COE Rebate Amount:	\$11,095.00
<b>Total Rebate Amount:</b>	<b>\$19,754.00</b>

- 7216

The information contained herein is correct as at 20 Dec 2019

OK



Here is a car loan that's got our green light!



**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Honda Freed Hybrid 1.5A G Honda Sensing 7 Seater.



New Condition! One Owner W  
Warranty 5 Yrs,4 Services!  
Superbly Well Maintained.  
Direct Owner StarAd

**P PRIME MOTOR & LEASING**  
ICHENG YONG CREDIT ENTERPRISES PTE.LTD GROUP OF COMPY  
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category ▾

Sort by Date Posted ▾ 100 results

6 vehicles

TOYOTA ALTIS

Advanced Search 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
TOYOTA ALTIS		Any	Any	2011	Any	Any	Any	Av
	<b>Toyota Corolla Altis 1.6A</b>	<b>\$24,800</b>	<b>\$10,280 /yr</b>	<b>17-Aug-2011</b>	<b>1,598 cc</b>	<b>103,911 km</b>	Sedan	Av
Very Well Maintained, Excellent Condition, Smooth Engine And Responsive Gearbox, Accident Free! Trade In Welcome! Call Now For Viewing!								
Posted: 19-Dec-2019		Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						
	<b>Toyota Corolla Altis 1.6A</b>	<b>\$21,800</b>	<b>\$11,240 /yr</b>	<b>21-Mar-2011</b>	<b>1,598 cc</b>	<b>163,765 km</b>	Sedan	Av
Hurry! Suitable For Short Term Drive Or Future COE Renewal. Well Maintained And Very Original Unit. Non PHV Ownership. 100% Accident Free. Regular Serviced. Original Paintwork With Beautiful Interior. Smooth Engine And Responsive Gearbox. Dealing With No Hi...								
Posted: 18-Dec-2019		Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						
	<b>Toyota Corolla Altis 1.6A Elegance</b>	<b>\$23,588</b>	<b>\$10,000 /yr</b>	<b>21-Jul-2011</b>	<b>1,598 cc</b>	<b>187,958 km</b>	Sedan	Av
(1St Owner Unit!) Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. STA Evaluation Friendly For Quality And Assurances. Bank And In-house Loan Supported. (Viewing Available Daily By Appointment.)								
Posted: 16-Dec-2019		Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						
	<b>Toyota Corolla Altis 1.6A</b>	<b>\$29,600</b>	<b>\$11,070 /yr</b>	<b>28-Dec-2011</b>	<b>1,598 cc</b>	<b>128,000 km</b>	Sedan	Av
1Lady Owner, 100% Accident Free, Agent Service, Leather Seats, Sport Rim, Reverse Sensor, Well Maintained, Call Before Coming.								
Posted: 14-Dec-2019		Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota						

**GET YOUR COE RENEWAL LOAN**

**Is your COE expiring? Let us help you renew it!**

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



**Toyota Corolla Altis 1.6A** **\$30,700** **\$11,510 /yr** **29-Dec-2011** **1,598 cc** **127,000 km** Sedan Av

Rare 1 Owner Only. Low Mileage Of 126,000km. Excellent Condition. Beautiful Original Metallic Blue Paintwork. Well Kept By Previous Owner. 3M Solar Film. Act Fast And Call Now To Fix An Appointment Before It's Gone.

Posted: 08-Dec-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



**Toyota Corolla Altis 1.6A** **\$28,800** **\$12,340 /yr** **14-Sep-2011** **1,598 cc** **-** Sedan Av

The Altis Is The Flagship Sedan Of Toyota. Ever Popular With Its Reliability And Efficiency, The Frugal 1.6L Engine Will Assure Responsive Yet Fuel-efficient Rides. This Sleek Silver Unit Is Maintained In Excellent Condition With Only 1 Previous Owner, Making It Perfect For A...

Posted: 05-Dec-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Compare

Save this search criteria, to get email alerts whenever a match is found.

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Stat

For old advertisements, view [Expired ads](#)100  result

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpar insurance. Find buy used TOYOTA ALTIS, TOYOTA ALTIS Singapore, used TOYOTA ALTIS Singapore, used TOYOTA ALTIS, used vehicles Singapore or even buy used TOYOTA ALTI!

We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotion: partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COI

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

### Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

DOA 15/12/19

MV - 27000

PV - 19754

NV - 7200

Balance → 1 year 11 months

Mp → 10500 year

$10500 \div 12 = 875$

$10500 + 9625 + 7216$

$= 27341$




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Ref: CS3/FCI19022313/Hvd3s2 Date: 27-12-2019 Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 3858Y	Veh. Inspected	SKD 7069E
Policy No.		Coverage (\$)	0.00
Claim No.	D19007978MFSH	Excess (\$)	0.00
Assign From	RACHELWU LIMEI	Assign Date	18/12/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	MR053REE104127846	Colour	WHITE
Odometer	98122 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information			
Accident Date	15/12/2019	Inspect Date / Time	19/12/2019 ( 01:40 PM )
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$27,000.00(EST)			

Report Ref No. CS3/FCI19022313/Hvd3s2

Inspected By

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.