

ASS. REC. BY:

REF: CS3/A1A19022322/Hq03<sup>57</sup>

Special Instruction:

Survivor

Hock Ann

ASSIGNMENT (Office)

From (Person):

Winnie Fan

of

A14

Date/Time: 19/12/19 @ 9:49am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 93264

Insured:

SGZ 2877D

at Workshop m/s

Teamwork Garage

Tel:

6844 2475

of

53 Ubi Avenue 1 # 01-24

Policy No:

1700038108

Claim No:

3173091020SG

Sum Insured:

Excess:

Make of Veh:

D.O.A

14/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:32am @ 14/12/19

Person Contacted:

Damen

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKE 93264 - NM / INC 19022088 / 24 DOA: 14/12/2019
	SGZ 2877D - NM / INC 19022088 / 24 DOA: 14/12/2019
	19/12/19 - super tube.
	23/12/19 - arrange tube.
	20/1/20 - after tube.
23/01/20	Submit DAR.

ASS. REQ. BY:

L-ANN

REF:

AIG

## ASSIGNMENT

PRS

From:

Date:

19/12/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 9326U

at Workshop m/s

Teamwork Garage

of

53 Ubi Ave 1 # 01-24

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKE 9326U

Yr Regn:

18/04/2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai ELANTRA

c.c 1591

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

NON check sheet

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHDH 41 cm cu 503856

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

57 mm

R/Bal.

57 mm

L/Bal.

57 mm

L/Bal.

57 mm

D.O.A.

14/12/19

D.O.A.

19/12/19

Survey held at

Teamwork Garage

Des. of Damages

Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DAR - 100

1st day - 9 days

RECEIVED 23 JAN 2020

SKE 9326U

LPRS car

NV - 21000

PV - 16515

NV - 4400

\* partly updated photo  
at E drive\* team vehicle have limit repair already  
let workshop Darren know don't over 4k  
repair, partly insurance

Date/Time, File Pass to?



Prel. Report

11/23/19 transfer



Final Report

Date/Time, File Return to?

29

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS + ST

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)




West end (\$)

Report Format:

DAR.

Lump Sum / LRS (\$)

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE ...**

From: Fan, Winnie-LW  
To: Admin A, assignments  
Cc: Fong, Andy-SY  
Sent: 12/19/2019 9:49:18 AM  
Attachments:  SKE9326U\_14122019[138368].pdf

---

Hi LKK,

Kindly assist to survey.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Darren <[claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)>  
**Sent:** Monday, December 16, 2019 5:17 PM  
**To:** Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)>; Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>; Chin, Lee-Ying <[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com)>; Kaur, Baljit <[Baljit.Kaur@aig.com](mailto:Baljit.Kaur@aig.com)>; Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Azlan, Syazairdina <[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Mithoosingh, Aashweenjeetkaur <[Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)>; Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)>  
**Cc:** Darren <[claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)>  
**Subject:** [EXTERNAL] OUR REF: 1912-27 YOUR REF: SGZ2877D PRE-REPAIR INSPECTION FOR SKE9326U

**This message is from an external sender; be cautious with links and attachments.**

WITHOUT PREJUDICE

OUR REF : 1912-27  
YOUR REF : SGZ2877D

Dear Sir / Madam,  
PRE-REPAIR INSPECTION FOR SKE9326U  
ACCIDENT INVOLVING SKE9326U AND SGZ2877D ON 14.12.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

8100 9370

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Darren  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/12/2019 14:18
Date Of Accident	14/12/2019 02:30
Exact Location Of Accident	JUNC BUKIT BATOK EAST AVE 3 & BUKIT BATOK ST 23
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE9326U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ISMAIL BIN SURDI
NRIC No	S1140854J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81252467
Alternative Phone No	OFFICE-81252467

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5053878493-07
Cover Note Number	

### Driver

Name of Driver	ISMAIL BIN SURDI
NRIC No	S1140854J
Date Of Birth	27/06/1955
Occupation	INDOOR
Date Of Driving Pass	16/03/1978
Driving Experience	41 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81252467
Fax Number	
Contact Number	OFFICE-81252467
Email Address	NOEMAIL

Address	BLK 219 JURONG EAST STREET 21 #02-601
Postcode	600219
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20191214/2128.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGZ2877D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name ISMAIL BIN SURDI

Approximate Age

Injuries Sustain HEAD & NECK

Injured person in which vehicle? SKE9326U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
  - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigations the accident and/or my claims;
  - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
  - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
  - (ii) For complying with requirements under my regulations, laws or court orders.

Policy holder's signature  
Date / time:


Driver's signature  
(if driver is not policy holder)  
Date / time:

reporting centre personnel's Signature  
Date / time:



## Accident Sketch Plan

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to police report

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policy holder's signature  
Date & time:

\_\_\_\_\_  
Driver's signature  
(if driver is not policy holder)  
Date & time:

  
reporting centre personnel's Signature  
NRIC/FIN No.:

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20191214/2128

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

1 of 3

Report No. T/20191214/2128

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/12/2019 16:35		Vide Report No.:		Station Diary No.: 60
<b>Informant's Particulars</b>				
Name of Informant: ISMAIL BIN SURDI		Address: APT BLK 219 JURONG EAST STREET 21 #02-601 SINGAPORE 600219		
ID Type / ID No.: NRIC NO / S1140854J		Contact No.: Home/Office: Mobile: 81252467		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 64	Date of Birth: 27/06/1955	Type of Informant: Driver	
Race: Malay		Language: English	Institution / School Name:	
Occupation: Private security officer		Driving Licence Information: Class: 3		Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 14/12/2019 02:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BUKIT BATOK EAST AVENUE 3 BUKIT BATOK STREET 23				
Weather: Heavy rain		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGZ2877D	Car				Seriously Damaged	0
SKE9326U	Car	HYUNDAI	ELANTRA 1.6 AT ABS D/AB 2WD 4DR	Black	Seriously Damaged	0

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20191214/2128

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

2 of 3

Report No. T/20191214/2128

### CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKE9326U	NTUC Income Insurance Co-Operative Limited	5053878493-07	18/04/2019	17/04/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ISMAIL BIN SURDI	ID No.	S1140854J
Related Vehicle	SKE9326U (Car)	Contact No.	81252467
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/12/2019	Date Discharge	14/12/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight

### Brief Details.

On 14/12/2019 at about 0230hrs, I was driving my vehicle SKE9326U from Toh Tuck along Bukit Batok East Avenue 3. I was passing the cross junction of Bukit Batok East Avenue 3 and Bukit Batok Street 23 as the traffic light was in my favour. While my vehicle was halfway through the junction, one vehicle SGZ2877D from the opposite direction attempted to turn right onto Bukit Batok Street 23 and hit onto my vehicle. The front bumper of the two vehicles were damaged.

I then came out from my vehicle to take photos and also called my son namely Ismady HP: 9855 4340 to inform him of the accident. One ambulance then came to scene. I did not know who call for the ambulance. I felt pain on my head and neck area and was conveyed to hospital. The other driver did not wish to be conveyed. I left the handling of the scene to my son as he came before I was conveyed. I did not have the details of the other driver. However my son was in contact with the Traffic Police with regards to the accident. There was no camera in my vehicle.

Police Report



**SINGAPORE  
POLICE FORCE**



T/20191214/2128

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

3 of 3

Report No. T/20191214/2128

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
D /  
Sgt 3 CHEN MIAOJUN

Signature Of Informant:


Signature Of Interpreter:  
Not applicable

Date/Time:  
14/12/2019 16:35

Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt MOHAMED SUFIAN BIN SUDIN  
Contact No.: 65476395

Classification Of Case:

Authentication Stamp  
NP168



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	854J
<b>Vehicle Details</b>	
Vehicle No.:	SKE9326U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	G4FGCU525580
Chassis No.:	KMHDH41CMCU503856
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$11,433.00
Original Registration Date:	18 Apr 2012
First Registration Date:	18 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$11,433.00
<b>OPC Cash Rebate Details</b>	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2022
PARF Rebate Amount:	\$6,859.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$41,501.00
COE Rebate Amount:	\$9,656.00
<b>Total Rebate Amount:</b>	<b>\$16,515.00</b>

The information contained herein is correct as at 20 Dec 2019

OK



Here is a car loan that's got  
our green light!



Hyundai Elantra

Price Range ▾

Depreciation ▾

2012 ▾

Vehicle Type ▾



Home » Used Cars » Giant Automobile Pte Ltd » Hyundai Elantra 1.6A GLS (OPC)

## Hyundai Elantra 1.6A GLS (OPC)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

<b>Price</b>	\$24,666		
<b>Depreciation</b> ⓘ	\$8,350 /yr View models with similar depre	<b>Reg Date</b>	28-Mar-2012 (2yrs 3mths 7days COE left)
<b>Mileage</b>	71,000 km (9.2k /yr)	<b>Manufactured</b> ⓘ	2012
<b>Road Tax</b> ⓘ	\$238 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$19,699 as of today (change)	<b>OMV</b> ⓘ	\$11,470
<b>COE</b> ⓘ	\$56,501	<b>ARF</b> ⓘ	\$11,470
<b>Engine Cap</b>	1,591 cc	<b>Power</b>	95.6 kW (128 bhp)
<b>Curb Weight</b> ⓘ	1,267 kg	<b>No. of Owners</b> ⓘ	1
<b>Type of Vehicle</b>	Mid-Sized Sedan		
<b>OPC Scheme</b>	Revised OPC scheme (use full day on Sat)		

### Features

1.6L Dual CVT Engine, 125 BHP, CVT Auto Transmission, ABS, Airbags, Cruise Control View specs of the Hyundai Elantra (2011-2014)

### Accessories

Leather Seats, Factory Fitted Audio System With USB/AUX Port, Knockdown Rear Seats.

### Description

Well Maintained At Agent Workshop. Low Depreciation, Flexible Loan And High Trade In. Do Call Us To Arrange For A Test Drive.

### Category

OPC Car, PARF Car, Low Mileage Car

### Status

Available

### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



#### Vehicle Evaluation

? Request to have this car evaluated professionally. Find out more

Compare



Location Map

Shortlist

Compare

Add nc

Report Error

More Actions

### Seller Information

#### Giant Automobile Pte Ltd

10 vehicles for sale, 19 sold in past 3 mths

210 Turf Club Road Lot A48

Car Mall @ The Grandstand

Search cars nearby



KAI

86665457 ⓘ

Ricky

97623411 ⓘ

SUXIN

97683411 ⓘ

DOA 14/12/11

MV - 21000

PV - 16515

NV - 4400

Below 2 yrs 4 months  
12yrs

## Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.

You can read customers' reviews & ratings on their services too.

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

BMW 430i Convertible M-Sport super low mileage.



In House Finance Available!  
High trade in. PML Warranty.  
Price Neg! Call now.  
Speedo Motoring [Shop Ad](#)










Browse by Category ▼

Sort by Date Posted ▼ 100 results

10 vehicles

Hyundai Elantra

Advanced Search 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection	Hyundai Elantra	Any	Any	2012	Any	Any	Any	Av
	<b>Hyundai Elantra 1.6A Elite</b>	<b>\$28,588</b>	<b>\$10,060 /yr</b>	<b>01-Feb-2012</b>	<b>1,591 cc</b>	<b>124,800 km</b>	Sedan	Av
Higher Part Value \$ 7,289. Well Maintain, Full-Service Records, Tip Top Condition With No Repairs Needed, In-house Loan Available With No Guarantors Needed, Viewing By Appointment Only.								
Posted: 20-Dec-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	<b>Hyundai Elantra 1.6A</b>	<b>\$29,500</b>	<b>\$8,870 /yr</b>	<b>28-Aug-2012</b>	<b>1,591 cc</b>	-	Sedan	Av
Beautiful Sports Rims! Very Clean Spacious Interior And Boots Space! Good Fuel Efficiency Above 12Km/L. Easy To Drive And Maintain! Bank Loan Or In House Lian Available! Not To Be Missed! Trade In Welcome! Call/Whatsapp Us Now!								
Monster Motors Pte Ltd								
Posted: 16-Dec-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	<b>Hyundai Elantra 1.6A Elite Sunroof</b>	<b>\$29,800</b>	<b>\$9,560 /yr</b>	<b>04-May-2012</b>	<b>1,591 cc</b>	-	Sedan	Av
Well Maintained, Good Condition, Accident Free, Trade In, Loan Quantum Available. Drop Us A Message For Viewing Appointment.								
Posted: 10-Dec-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	<b>Hyundai Elantra 1.6A Elite</b>	<b>\$27,000</b>	<b>\$9,570 /yr</b>	<b>11-Jan-2012</b>	<b>1,591 cc</b>	<b>115,000 km</b>	Sedan	Av
Genuine Low Mileage! Original Stock Paintwork! Accident Free! Beautiful Sports Rims! Very Clean Spacious Interior And Boots Space! Good Fuel Efficiency Above 12Km/L. Easy To Drive And Maintain! Bank Loan Or Full Loan Available! Not To Be Missed! Trade In Welcom...								
Posted: 09-Dec-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	<b>Harmony Motor Pte Ltd - Tyres &amp; Rims</b>							
Harmony Motor operates a total of two automotive workshops in Singapore which is located at Ang Mo Kio and Jurong.								
More info about this shop								
	<b>Hyundai Elantra 1.6A</b>	<b>\$29,800</b>	<b>\$10,940 /yr</b>	<b>10-Jan-2012</b>	<b>1,591 cc</b>	-	Sedan	Av
Electric Seat, Push Start, Keyless. High OMV Value, Scrap Value \$7k, Used By Lady Owner, In Very Good Condition.								
Posted: 06-Dec-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	<b>Hyundai Elantra 1.6A GLS (OPC)</b>	<b>\$24,666</b>	<b>\$8,350 /yr</b>	<b>28-Mar-2012</b>	<b>1,591 cc</b>	<b>71,000 km</b>	Sedan	Av
Well Maintained At Agent Workshop.Low Depreciation, Flexible Loan And High Trade In. Do Call Us To Arrange For A Test Drive.								
ad: 02-Dec-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								

Compare



Posted on: 02-Dec-2019 | Last Updated on: 10-Dec-2019

## Upfront Payment

[» more Financial info](#)

<b>Transfer Fee</b> ⓘ	\$25	
<b>Down Payment</b> ⓘ	\$7,400 (change)	Maximum 70% Loan
<b>1st Instalment</b> ⓘ	\$682	Based on 2.96% interest rate
<b>Insurance</b>	\$702 onwards (Get a quote) Extra 15% Off for MINDEF, MHA & POGIS policyholders Quote assumes a standard profile. "Get a quote" for exact figure.	
<b>Total Upfront Payment</b> ⓘ	\$8,809	Check with seller for exact figure

Powered by

AVIVA

## Products and Services

[» View All](#)

For all your leasing and rental needs.



Enhances Hyundai Elantra's Interior Look



Wide Fender



Keep Your Car Interior Cool & Safe Drive



Unique Design Sports Front Grille



Bidded Carplate for Sale

[View all 108 suitable items for Hyundai Elantra](#)

Check out the specialist workshop for Hyundai cars: [Pro-Jex V2D Auto Pte Ltd](#)

Tags: Hyundai Elantra, hyundai elantra, 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

## Recommended for you

1-6 of 18



The 2018 Elantra earns highest IIHS rating



Rule change allowed access to bigger loans



Hyundai Tucson - pace, space and grace



How the new VES affects you as a car buyer



The Hyundai Avante is poised and composed

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, ev cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, financial services, low mileage cars car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partner openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)



## Vehicle No:

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	993053	Wiper Washer Tank	CRB	✓	1
1074	993052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy	BT	✓	1
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990948	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member	BT	✓	1
1094	990728	Frt Vertical Cross Member	R	✓	1
1095	991863	Frt Lower Cross Member	R	✓	1
1096	993070	Frt LH Fender	R	✓	1
1097	993072	Frt LH Fender Inner Panel	R	✓	1
1098	993147	Frt LH Fender Lamp	R	✓	1
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	993071	Frt RH Fender	CRB	✓	1
1106	991739	Frt RH Fender Inner Panel	R	✓	1
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CRB	✓	1
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass	CRB	✓	1
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding	me	✓	1
1117	992098	Frt Windscreen Sealant	me	✓	1
1118	991019	ERP Bracket	me	✓	1
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish	CRB	✓	1
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy	Bus	✓	1
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag	Bus	✓	1
1128	994485	Steering Wheel Airbag Sensor	Shop	✓	1
1129	990749	Dashboard Airbag	Bus	✓	1
1130	990750	Dashboard Airbag Sensor	Shop	✓	1
1131	990029	Airbag Control Unit	me	✓	1
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy	me	✓	1
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy	me	✓	1
1136	990247	Stroker			
		Resonator Hose	CRB	✓	1
		Intake manifold Box	CRB	✓	1

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRJ

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 <a href="#">Edit Reg</a>		19 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOH CHENG CHEW, ID: S1214903D		
Main Claimant:	-		
Vehicle Reg. No.:	SKE9326U	Date of Loss:	14/12/2019 00:00 - :59 [91 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3173091020SG	Policy/Cover Note No.:	1700038108 (Comprehensive) Coverage: 22/08/2019 - 21/08/2020
Vehicle Reg. No. (Insured):	SGZ2877D	Policy No. (Claimant):	
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 31/12/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






















































































## Claim Documents

**\*SKE9326U (3173091020SG)  
[SGZ2877D]**










































**TP**

**Dec 14 2019 12:00AM  
[GOH CHENG CHEW]  
Teamwork Garage Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<a href="#">View</a> <a href="#">View in Browser ▼</a>	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/12/19 18:39	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
2	23/12/19 18:40	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
3	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
33	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
34	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
35	23/12/19 18:40	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/12/19 18:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	22/01/20 14:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	22/01/20 14:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	22/01/20 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	22/01/20 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	22/01/20 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	22/01/20 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	22/01/20 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	22/01/20 14:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	22/01/20 14:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
119	22/01/20 14:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
120	22/01/20 14:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
121	22/01/20 14:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
122	22/01/20 14:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
123	22/01/20 14:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/12/19 16:34	OI GIA REPORT	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022322/HQD3S2

Date: 29/01/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700038108
Claimant Vehicle No :	SKE9326U	Insured Vehicle No :	SGZ2877D
Date of Loss:	14/12/2019	Nature of Claim:	TP
		Claim No:	3173091020SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE9326U	Engine No:	G4FGCU525580
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Chassis No:	KMHDH41CMCU503856
Reg. Date:	18/04/2012 (Man. Year: 2012)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	19/12/2019		
Date Inspected:	19/12/2019	Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	9.0 days		

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE GARNISH	Bent	0.00 F	*- F
3	1		*FRT BUMPER	Cut	0.00 F	*- F
4	1		*SET FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
6	2		*FRT BUMPER SIDE RETAINER	Crushed	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
8	1		*FRT BUMPER SPONGE	Cut	0.00 F	*- F
9	1		*FRT GRILLE	Cracked	0.00 F	*- F
10	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
11	1		*FRT GRILLE CHROME MOULDING	Scratched	0.00 F	*- F
12	1		*FRT SUPPORT PANEL	Cut	0.00 F	*- F
13	1		*SUPPORT PANEL SIDE AIR GUIDE	Crushed	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*BONNET	Cut	0.00 F	*- F
17	1		*BONNET LOCK	Jammed	0.00 F	*- F
18	1		*BONNET INSULATOR	Crushed	0.00 F	*- F
19	2		*BONNET HINGE	Bent	0.00 F	*- F
20	1		*BONNET RUBBER	Necessary	0.00 F	*- F
21	1		*BONNET CABLE	Jammed	0.00 F	*- F
22	1		*AIR CON CONDENSER	*Check	0.00 F	*- F
23	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	Bent	0.00 F	*- F
24	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Bent	0.00 F	*- F
25	1		*AIR CON COMPRESSOR ASSY	Crushed	0.00 F	*- F
26	1		*RADIATOR	*Check	0.00 F	*- F
27	1		*RADIATOR COWLING ASSY }	*Check	0.00 F	*- F
28	1		*RADIATOR FAN COWLING ASSY }		0.00 F	*- F
29	1		*AIR DUCT	Crushed	0.00 F	*- F
30	1		*WIPER WASHER TANK	Cracked	0.00 F	*- F
31	1		*ALTERNATOR ASSY	Bent	0.00 F	*- F
32	1		*ENGINE MOUNTING RH	Crushed	0.00 F	*- F
33	1		*FRT RH CHASSIS MEMBER	Bent	0.00 F	*- F
34	1		*FRT VERTICAL CROSS MEMBER	Repair	0.00 F	*- F
35	1		*FRT LOWER CROSS MEMBER	Repair	0.00 F	*- F
36	1		*FRT LH FENDER	Repair	0.00 F	*- F
37	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*- F
38	1		*FRT RH FENDER	Cut	0.00 F	*- F
39	1		*FRT RH FENDER INNER PANEL	Repair	0.00 F	*- F
40	1		*FRT RH FENDER INNERSHIELD	Crushed	0.00 F	*- F
41	1		*FRT WINDSCREEN GLASS	Cracked	0.00 F	*- F
42	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
43	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
44	1		*ERP STICKER	Necessary	0.00 F	*- F
45	1		*WIPER PANEL GARNISH	Cracked	0.00 F	*- F
46	1		*DASHBOARD ASSY	Burst	0.00 F	*- F
47	1		*STEERING WHEEL AIRBAG	Burst	0.00 F	*- F
48	1		*STEERING WHEEL AIRBAG SENSOR	Shorted	0.00 F	*- F
49	1		*DASHBOARD AIRBAG	Burst	0.00 F	*- F
50	1		*DASHBOARD AIRBAG SENSOR	Shorted	0.00 F	*- F
51	1		*AIRBAG CONTROL UNIT	Necessary	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRT RH SEAT BELT ASSY	Jammed	0.00 F	*- F
53	1		*FRT LH SEAT BELT ASSY	Jammed	0.00 F	*- F
54	1		*RESONATOR HOSE	Crushed	0.00 F	*- F
55	1		*INTAKE MANIFOLD ASSY	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >