

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref: CC4/ASM19022352/Apa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date: 03-06-2020 Code: ASM	
1.	Insured Veh.	PC 2792D	<u> </u>	SJW 8996J
		VFX/P2361179	Veh. Inspected	0.00
	Policy No.	S9M02AHF	Coverage (\$)	0.00
		39W02AFIF	Excess (\$) Assign Date	18/12/2019
0	Assign From	Vahiala Dar		10/12/2019
2.	Make & Model	TOYOTA WISH	ticulars & Condition	1987
		HIDDEN	c.c Year of Reg.	2010
	Engine No. Chassis No.	JTDGJ20W005002703	Colour	SILVER
	Odometer	158933	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD	Wodification	SFORTS KIIVI
3. Conditions of Tyres				
Size Make Balance				
	R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	17/12/2019	Inspection Date	18/12/2019
	Survey held at	HUA MENG SPRAY PAINTING	G WORKSHOP	
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			