

Surveyor:


KENNETH

DOI: 19/12/2019

Date / Time : 18/12/2019

Registered in Merimen: 16.12.2019 BY AIG

Pre-assign / CCU / FTE



Insured Vehicle No. : SMP 9273G
 Name of Insured : TAN HWAN CHEONG (CHEN HUANZHANG)
 Insured Tel No. : HP: +65-97601534
 Excess Sec II :S\$ D.O.A : 07/12/2019
 Is driver the owner? (☒ YES / NO) Nature of Accident :

Claim No. : 8482826150SG x
 Policy No. : 1900232547
 Make / Model : MERCEDES-BENZ GLC250
 Place of Accident : PIE TWDS JURONG

If NO, Driver Name / Age :


Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

SMJ 6598X



INSRS:
WSP: Wei Lee Motor
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SMJ 6598X - X	SMP 9273G - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler
			Notification ltr (if non-pickup)	☐
			After call ltr to OI:	☐
			Authorisation To Act:	☐
			Release Voucher:	☐
			Final Repair Bill:	☐
			Car Rental Invoice:	☐
			Towing Invoice	☐
			LTA / GIA :	☐
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☐
			LOD	☐
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:				
FINALIZATION Date/Time: Confirm with: Confirm by: Email ☐ Call ☐				
Repair Cost: S\$ (days) Reduction: %				
FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐				
Final Liability: % (Agreed / Assessed) BOLA S/N No. : If NO or B 28, Ass. Lia :				
Repair Cost: S\$				
Loss of Rental (LOR): S\$ (days)				
Loss of Use (LOU): S\$ (\$ x days)				
Loss of Income (LOI): S\$ (\$ x days)				
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]				
GIA/LTA Search S\$				
Medical: S\$				
Disbursement: S\$ (e.g. Tow/ Independent)				
Legal Cost S\$				
Total: S\$ Global Sum S\$: Email ☐ Call ☐				
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1: S\$ Name 1:				
Payee 2: (Strike if N.A.) S\$ Name 2:				
Payee 3: (Strike if N.A.) S\$ Name 3:				

ASS. REC. BY:

REF:

ALG /

22358 / 1cd

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3-4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / File pass to

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Veh No:

SJH 6598X

Yr Regn:

12, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Stream

c.c

1799

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

230054

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRN68609C200227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Fin 179

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

7/12/19

D.O.I.

19/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

813C

Vehicle Details

Vehicle No.:

SMJ6598X

Vehicle to be Exported:

Yes

Intended Deregistration Date:

26 Dec 2019

Vehicle Make:

HONDA

Vehicle Model:

STREAM 1.8L AT

Primary Colour:

Grey

Manufacturing Year:

2009

Engine No.:

R18A13850235

Chassis No.:

JHMRN68609C200227

Maximum Power Output:

103.0 kW (138 bhp)

Open Market Value:

\$24,970.00

Original Registration Date:

02 Dec 2010

First Registration Date:

02 Dec 2010

Transfer Count:

3

Actual ARF Paid:

\$24,970.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

01 Dec 2020

PARF Rebate Amount:

\$12,485.00

Intended COE Rebate Details

COE Expiry Date:

01 Dec 2020

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$45,501.00

COE Rebate Amount:

\$4,233.00

Total Rebate Amount:**\$16,718.00**

The information contained herein is correct as at 16 Dec 2019

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

16, Dec 2019

AIK Pacific Insurance Pte Ltd
78 She nton Way
#07-16
S 079120

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMP9273G

Accident involving vehicle no: SMJ6598X/SMP9273G/SJK5578R/SJG4337U/SMN2087J

DOA: 07/12/2019 AT PIE (Steven Rd twds Tuas)

Dear officer incharge

Cost of repair for vehicle no: SMJ6598X

To supply—

Description	Qty	Amount
Rear bumper	1	588.50
Rear bumper retainer @27	2	54.00
Rear bumper tow cover	1	22.00
End panel	1	306.70
Tailgate lock	1	198.60
Tailgate H logo	1	25.70
Tailgate stream emblem	1	38.50
Parts		1,234.00
Parts less 20%		246.80
		987.20

reverse sensor ✓

To remove damaged parts n attachments

Cut n weld damaged panel

Repair dented tailgate

Replace/align above parts into position

To spray paint

800.00 ?

700.00 500

2,707.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: