







## Home Team Agency

## SCOPE OF WORK

To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

			· · · · · · · · · · · · · · · · · · ·			. •	
CONTRACTOR:	SMRT	VEH TYPE:	MB	UNIT:	CNB SUP 'G'		Reference No.
VEH NO:	PC3362F	Ξ	REPAIR TYPE:		ACCIDENT		
VEH MAKE/MODEL:	NISSAN UR	VAN	ODOMETER:		58048		iLMS No.

Reference No.	3362/CNB/4W/19/12/03
iI MS No	_

S/N		PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mar Up (\$)		
1	Scope Of Repairs								
1.1	LHS Door Pilla	ır	\$1,450.00	1	19%	1725.50	1725.50		
1.2	LHS Sliding D	oor	\$1,850.00	1	19%	2201.50	2201.50		
1.3	Tyre Rims (Fro	nt LH & Rear RH)	\$350.00	2	19%	416.50	833.00		
1.4	Rim Cover		\$220.00	4	19%	261.80	1047.20		
1.5	Front LH Mud	Guard	\$165.00	1	19%	196.35	196.35		
2	Additional Services								
2.1		NA	\$0.00	0	0%	0.00	0.00		
	Remarks:		Parts Total:	\$ 6,003.55					

S/N	LABOUR DESCRIPTION	Man-Hou	r Rate (\$)	Man-Hour Qty	Tot	al Man-Hour Cost (\$)	
1	Scope Of Repairs						
1.1	Remove, Replace & Spray Paint for LHS Door Pillar	<b>68.00</b> 6				408.00	
1.2	Remove, Replace & Spray Paint for LHS Sliding Door including transferring Window Glass, Outer & Inner Door Lock & Door Handle, Central Locking Assy etc. from damaged Sliding Door onto new Sliding Door	68.	<b>68.00</b> 8			544.00	
1.3	Remove & Replace Front LH & Rear RH Tyre Rims including replacing all Rim Covers	68.	.00	1		68.00	
1.4	4 Replace Front LH Mud Guard 68.00 0.5					34.00	
1.5	Panel Beat & Spray Paint for Rear RH Body Panel	68.	.00	2.5		170.00	
		SUB	-TOTAL	18		1224.00	
2	Additional Services						
2.1	Towing Service From Station to Workshop (SOR 10)	176	.80	1		176.80	
2.2	Return Service From Workshop to Station (SOR 9)	61.	.20	1		61.20	
		SUB	-TOTAL	2		238.00	
			Lab	our Total:	\$	1,462.00	
			GRANI	D TOTAL :	\$	7,465.55	
Total sum billed under SOR only :							
Total sum billed under CVR only:							
	Contractor shall complete the entire repair within 20 working days upon approval date. (Include parts awaiting time)						

	Verification of Scope of Work									
Contractor QC			Vetted By:		Approved By:					
Name:	KONG SEW KUI	Name:		Name:						
Date:	18.12.2019	Date:		Date:						
Sign:	Hot.	Sign:		Sign:						
			Verification of Completed Repairs							
Contractor QC			Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager					
Name:		Name:		Name:						
Date:		Date:		Date:						

Sign:		Sign:		Sign:			
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made							