

ASS. REC. BY:

REF:

CS3/III19022379/Etd3⁵⁴

Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person):

Gabriel wee

of

III

Date/Time: 19/12/19 4:23pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBC 2260M

Insured:

GBH 2831P

at Workshop m/s

Chek Kong Motor

Tel:

6769 8793

of

Blk 1 woodlands Road unit 387B, Yew Tee Ind. Estate

Policy No:

Claim No:

MFL2019 D0001639

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:49am @ 20/12/19

Person Contacted:

Ms. Chen

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

PBC 2260M - X

GBH 2831P - X

Submit PRS Report

Dismantle: 27/12/2019 9.56am

After Repair: 6/1/2020 10.56am


Surveyor Steve

REF: TH

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PP. Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBC 2260 M Yr Regn: 31/12/97
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda CBF150 c.c. 149
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 6630.8 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: LAL KC11A 673006491
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 80/80-18
R: 80/90-18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Nylon
Front S Rear S
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 10/12/19 D.O.I. 20/12/19 10.20am
Survey held at Chok King Motor
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Front RH, LH
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-SR</u>
RECEIVED 17 JAN 2020	

Date/Time, File Pass to? ☐ : Proll. Report
1) PL Typist ☒ : Final Report
Date/Time, File Return to? _____
2) _____
Report Format : _____
Lump Sum / I.B.I. (\$) _____
Days Of Repair: _____
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech Insp (\$) ☐ : Weekend (\$) ☐ : _____
Survey Fee: _____
Transportation: _____
S + RS. - SI _____
P/B/S _____
Others _____
TOTAL _____

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 19 December 2019 4:23 PM
To: Denise Ng; 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: Zuhaidah Samsuri
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBC2260M (Accident involving FBC2260M and GBH2831P (Pan Pac) on 10.12.2019)
Attachments: gbh2831p_20191219115101.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FBC2260M
III INSURED VEHICLE NO. : GBH2831P
DATE OF LOSS : 10.12.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Aida.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Denise Ng [mailto:denise@gohjpwong.com]
Sent: 19 December, 2019 1:09 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBC2260M (Accident involving FBC2260M and GBH2831P (Pan Pac) on 10.12.2019)

Dear Sirs

We refer to your email of even date.

We are not agreeable to your proposed motor surveyors.

Our list of proposed Single Joint Expert is as follows:-

1. Jayson Liaw Leong San of Pro-Option Services
2. Dylan Lee of Lee Appraisal Services
3. Oh Han Cheong of Oh Appraisal
4. Seah Kwang Boon of Absolute Appraisal Services
5. Bok Jee Tan of Prudent Adjustors Services
6. Fong Kok Heng Stanley of Automax Survey
7. Sebastian Lim Yong Tian of Constant Appraiser Services
8. Lek Boon Hwee of Auto Performance Appraisal
9. Louis S C Ng Cae Amimi of Prestige Appraiser Services
10. Richard Wong Ah Kow of R W Automotive Appraiser Services

Kindly let us hear from you within 2 working days.

Please be informed that our office will be closed for the holiday season from 24th to 31st December 2019 (both dates inclusive). Business will resume as usual on 2 January 2020.

Best Regards

Denise Ng

for and on behalf of Goh Teck Wee

GOH JP & WONG LLC

133 New Bridge Road

#16-09 Chinatown Point

Singapore 059413

Tel: 6538 5868

Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential.

If you are not the intended recipient, you are hereby notified that any dissemination,

distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Thu, Dec 19, 2019 at 12:16 PM Mail office <mail@gohjpwong.com> wrote:

Please be informed that our office will be closed for the holiday season from 24 to 31 December 2019 (both dates inclusive). Business will resume as usual on 2 January 2020.

GOH JP & WONG LLC
Advocates & Solicitors
Commissioner for Oaths
133 New Bridge Road #16-09
Chinatown Point
Singapore 059413
Tel : 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

----- Forwarded message -----

From: **Motor Claim - III** <motorclaim@iii.com.sg>

Date: Thu, Dec 19, 2019 at 12:03 PM

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBC2260M (Accident involving FBC2260M and GBH2831P (Pan Pac) on 10.12.2019)

To: mail@gohjpwong.com <mail@gohjpwong.com>

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located

both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Nivitha (LKK Auto)

From: Denise Ng <denise@gohjpwong.com>
Sent: Thursday, 19 December 2019 4:38 PM
To: Motor Claim - III
Cc: sur@lkkauto.com; Nivitha (LKK Auto); Zuhaidah Samsuri
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBC2260M (Accident involving FBC2260M and GBH2831P (Pan Pac) on 10.12.2019)

Dear Sirs

We refer to your email of even date.

Our client's motorcycle FBC 2260M is now at Chek Kong Motor Pte Ltd located at Block 1 Woodlands Road 19Km, Unit 387B Yew Tee Industrial Estate Singapore 677899 (Tel: 6769 8793). Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days.

Kindly advise your surveyor to liaise with the workshop directly to conduct the post-repair inspection (if necessary) and keep us in the loop.

Kindly extend to us a copy of your surveyor's pre-repair inspection report once the report has been completed.

Please be informed that our office will be closed for the holiday season from 24th to 31st December 2019 (both dates inclusive). Business will resume as usual on 2 January 2020.

Best Regards
Denise Ng
for and on behalf of Goh Teck Wee
GOH JP & WONG LLC
133 New Bridge Road
#16-09 Chinatown Point
Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2019 09:49
Date Of Accident	10/12/2019 16:40
Exact Location Of Accident	TOH TUCK LINK JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC2260M
Insured/Policyholder	
Name Of Registered Owner	TAN SEE KAU
NRIC No	S2766465B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81605585
Alternative Phone No	OFFICE-81605585

Vehicle Particulars

Manufacturer	HONDA
Model	CBF150-149CC (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMT/18-392186-VA
Cover Note Number	

Driver

Name of Driver	TAN SEE KAU
NRIC No	S2766465B
Date Of Birth	17/04/1958
Occupation	OUTDOOR
Date Of Driving Pass	08/03/2011
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81605585
Fax Number	
Contact Number	OFFICE-81605585
Email Address	NOEMAIL

Address 548 SERANGOON NORTH AVE 3
#03-09
Postcode S550548
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: NO. 92 BOON LAY WAY, POSTCODE: 609962, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

Attachment(s)


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH2831P
Vehicle Make/Model/Colour VAN
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver DAKSINAMOORTHY RAMESH
NRIC/Passport Number G7606765T
Contact Number 86619635
Address
Postcode
Insurance Company Name

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

↑; ↑ ↓; ↓

[The rest of the section is crossed out with a diagonal line.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

10 DEC 2019 IDAC BUKIT BATOK (VAC)
511 BUKIT BATOK RI 23
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191211/2062

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

2 of 3

Report No. T/20191211/2062

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN SEE KAU	ID No.	S2766465B
Related Vehicle	FBC2260M (Motorcycle)	Contact No.	81605585
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	11/12/2019	Date Discharge	11/12/2019
No. of Days granted Medical Leave	14	Degree of Injury	Slight
Driver			
Name	DAKSHINAMOORTHY RAMESH	ID No.	G7606765T
Related Vehicle	GBH2831P (Van)	Contact No.	86619635
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: 06/10/2023
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10.12.2019 at about 1640hrs, I was riding my motorcycle bearing registration number 'FBC2260M' along Toh Tuck Link towards Toh Tuck Ave, it is a one-laned road. The traffic was heavy, it was drizzling and the road was wet. While approaching the T-Junction of Toh Tuck Link near lamp post number 4, a van bearing registration number 'GBH2831P' had made a right turn into my lane. I was unable to stop to avoid the van hence the van had collided onto my right leg and I had fell on the left side together with my motorcycle. I was conscious and had suffered some abrasions on my right leg at the point of time, thus we did not called for ambulance. We had left after exchanging particulars.

The right side of my oil tank side skirt was damaged, steering handle and signal light were damaged, right side mirror and rear registration plate were damaged due to the collision. The van's left front bumper and left side mirror were damaged.

I had went to Ng Teng Fong Hospital to consult a doctor today as I felt pain on my right leg and it was swollen. I was given Hospitalization Leave from 11.12.2019 to 24.12.2019.



**SINGAPORE
POLICE FORCE**



T/20191211/2062

2 of 3

Report No. T/20191211/2062

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN SEE KAU	ID No.	S2766465B
Related Vehicle	FBC2260M (Motorcycle)	Contact No.	81605585
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	11/12/2019	Date Discharge	11/12/2019
No. of Days granted Medical Leave	14	Degree of Injury	Slight
Driver			
Name	DAKSHINAMOORTHY RAMESH	ID No.	G7606765T
Related Vehicle	GBH2831P (Van)	Contact No.	86619635
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: 06/10/2023
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10.12.2019 at about 1640hrs, I was riding my motorcycle bearing registration number 'FBC2260M' along Toh Tuck Link towards Toh Tuck Ave, it is a one-laned road. The traffic was heavy, it was drizzling and the road was wet. While approaching the T-Junction of Toh Tuck Link near lamp post number 4, a van bearing registration number 'GBH2831P' had made a right turn into my lane. I was unable to stop to avoid the van hence the van had collided onto my right leg and I had fell on the left side together with my motorcycle. I was conscious and had suffered some abrasions on my right leg at the point of time, thus we did not called for ambulance. We had left after exchanging particulars.

The right side of my oil tank side skirt was damaged, steering handle and signal light were damaged, right side mirror and rear registration plate were damaged due to the collision. The van's left front bumper and left side mirror were damaged.

I had went to Ng Teng Fong Hospital to consult a doctor today as I felt pain on my right leg and it was swollen. I was given Hospitalization Leave from 11.12.2019 to 24.12.2019.



**SINGAPORE
POLICE FORCE**



T/20191211/2062

3 of 3

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

Report No. T/20191211/2062

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 3 CATHERINE CHOY CHI CHING

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Signature Of Informant:

Date/Time:

11/12/2019 12:47

Classification Of Case:

Authentication Stamp

NP168

SN 35

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	465B
Vehicle Details	
Vehicle No.:	FBC2260M
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	CBF150
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	KC11E2006468
Chassis No.:	LALKC11A673006491
Maximum Power Output:	-
Open Market Value:	\$1,467.00
Original Registration Date:	31 Dec 2007
First Registration Date:	31 Dec 2007
Transfer Count:	2
Actual ARF Paid:	\$221.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,005.00
COE Rebate Amount:	\$3,976.00
Total Rebate Amount:	\$3,976.00

The information contained herein is correct as at 20 Dec 2019

OK

Home: Motorbikes Motorbikes for Sale Class 2B

jamestai5099
No reviews

Chat

Make Offer

Advertisement

S\$5,500

Share 15

Honda CBF150

Singapore Petrol Chemical Complex

Meetup

Used

Used bike Honda CBF150 for sale. Bike in very good condition. Cee renew 10 years, expire on December 2028.

9 months ago In Class 2B

Honda

Road Bike

Insurance

Meet-up

Singapore Petrol Chemical Complex

Advertisement

Listed by jamestai5099

Verified

Check seller profile



Follow us

Facebook
Twitter
Blog
Carousell College

Cars & Property

Cars
Car Accessories
Property
Motorbikes

Fashion

Men's Fashion
Women's Fashion
Health & Beauty
Lingerie

Home & Living

Furniture
Gardening
Home Appliances
Assistant Devices
Babies & Kids
Books & Stationery

Mobiles & Electronics

Electronics
Mobile Phones & Tablets

Hobbies & Games

Learning & Enrichment
Photography
Pet Supplies
Design & Craft
Food & Drink
Music & Media
Toys & Games
Vintage & Collectibles
Travel
Sports
Entertainment
Bicycles & PMGs

Jobs & Services

Jobs
Lifestyle Services
Business Services
Home Services

Others

Finance
Bulletin Board
Everything Else



(/)

Bike model

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS

Q SEARCH VIEW ALL (/LISTING/USEDBIKES/LISTING/)



REPORT ERROR (/LISTING/LISTING/ERROR/USEDBIKE/14449/) + SHORTLIST

Share (HTTPS://WWW.FACEBOOK.COM/SHARER/SHARER.PHP?U=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CBF150/14449/)
(S) SHARE (WHATSAPP) (SENDTEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CBF150/14449/)

Honda CBF150

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CBF150 (/listing/usedbike/model/honda-cbf150/)
Engine Capacity	149cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	17/07/2009
COE Expiry Date	30/06/2029 (9 years 6 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes (/listing/usedbike/model/motorcycle-for-sale/street-bikes/)

Price: SGD\$5900

DETAILS

Tip Top Condition. Original Parts. Visit us at Aljunied Motor Works. Well maintained condition. Seldom use, Trade in welcome

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2019 Edit Reg		19 Dec 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-	Co. Reg. No.:	-
Main Claimant:	-		
Vehicle Reg. No.:	FBC2260M	Date of Loss:	10/12/2019 00:00 - :59 [143 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MFL2019D0001639	Policy/Cover Note No.:	D19MFL0005549
Vehicle Reg. No. (Insured):	GBH2831P	Policy No. (Claimant):	
		Excess:	
Repairer:	Chek Kong Motor Pte Ltd (HQ) BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL ESTATE, 677948 Woodlands - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 02/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBC2260M (MFL2019D0001639)
[GBH2831P]

TP

-

Dec 10 2019 12:00AM

[-]

Chek Kong Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/19 15:56	General View	 Load JPG	☒
2	20/12/19 15:56	General View	 Load JPG	☒
3	20/12/19 15:56	General View	 Load JPG	☒
4	20/12/19 15:56	General View	 Load JPG	☒
5	20/12/19 15:56	General View	 Load JPG	☒
6	20/12/19 15:56	General View	 Load JPG	☒
7	20/12/19 15:56	General View	 Load JPG	☒
8	20/12/19 15:56	General View	 Load JPG	☒
9	20/12/19 15:56	General View	 Load JPG	☒
10	20/12/19 15:56	General View	 Load JPG	☒
11	20/12/19 15:56	General View	 Load JPG	☒
12	20/12/19 15:56	General View	 Load JPG	☒
13	20/12/19 15:56	General View	 Load JPG	☒
14	20/12/19 15:56	General View	 Load JPG	☒
15	20/12/19 15:56	General View	 Load JPG	☒
16	20/12/19 15:56	General View	 Load JPG	☒
17	20/12/19 15:56	General View	 Load JPG	☒
18	20/12/19 15:56	General View	 Load JPG	☒
19	20/12/19 15:56	General View	 Load JPG	☒
20	20/12/19 15:56	General View	 Load JPG	☒
21	20/12/19 15:56	General View	 Load JPG	☒
22	20/12/19 15:56	General View	 Load JPG	☒
23	20/12/19 15:56	General View	 Load JPG	☒
24	20/12/19 15:56	General View	 Load JPG	☒
25	20/12/19 15:56	General View	 Load JPG	☒
26	20/12/19 15:56	General View	 Load JPG	☒
27	20/12/19 15:56	General View	 Load JPG	☒
28	20/12/19 15:56	General View	 Load JPG	☒
29	20/12/19 15:56	General View	 Load JPG	☒
30	20/12/19 15:56	General View	 Load JPG	☒
31	20/12/19 15:56	General View	 Load JPG	☒
32	20/12/19 15:56	General View	 Load JPG	☒
33	20/12/19 15:56	General View	 Load JPG	☒
34	20/12/19 15:56	General View	 Load JPG	☒
35	20/12/19 15:56	General View	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	20/12/19 15:56	General View	 Load JPG	✓
37	20/12/19 15:56	General View	 Load JPG	✓
38	20/12/19 15:56	General View	 Load JPG	✓
39	20/12/19 15:56	General View	 Load JPG	✓
40	20/12/19 15:56	General View	 Load JPG	✓
41	20/12/19 15:56	General View	 Load JPG	✓
42	20/12/19 15:56	General View	 Load JPG	✓
43	20/12/19 15:56	General View	 Load JPG	✓
44	20/12/19 15:56	General View	 Load JPG	✓
45	20/12/19 15:56	General View	 Load JPG	✓
46	20/12/19 15:56	General View	 Load JPG	✓
47	20/12/19 15:56	General View	 Load JPG	✓
48	20/12/19 15:56	Odometer Reading	 Load JPG	✓
49	20/12/19 15:56	General View	 Load JPG	✓
50	20/12/19 15:56	General View	 Load JPG	✓
51	20/12/19 15:56	General View	 Load JPG	✓
52	20/12/19 15:56	General View	 Load JPG	✓
53	20/12/19 15:56	General View	 Load JPG	✓
54	20/12/19 15:56	General View	 Load JPG	✓
55	20/12/19 15:56	General View	 Load JPG	✓
56	20/12/19 15:56	General View	 Load JPG	✓
57	20/12/19 15:56	General View	 Load JPG	✓
58	20/12/19 15:56	General View	 Load JPG	✓
59	20/12/19 15:56	General View	 Load JPG	✓
60	20/12/19 15:56	General View	 Load JPG	✓
61	20/12/19 15:56	General View	 Load JPG	✓
62	20/12/19 15:56	General View	 Load JPG	✓
63	20/12/19 15:56	General View	 Load JPG	✓
64	20/12/19 15:56	General View	 Load JPG	✓
65	20/12/19 15:56	General View	 Load JPG	✓
66	20/12/19 15:56	General View	 Load JPG	✓
67	20/12/19 15:56	General View	 Load JPG	✓
68	20/12/19 15:56	General View	 Load JPG	✓
69	20/12/19 15:56	General View	 Load JPG	✓
70	20/12/19 15:56	General View	 Load JPG	✓
71	20/12/19 15:56	Chassis Number	 Load JPG	✓
72	20/12/19 15:56	General View	 Load JPG	✓
73	20/12/19 15:56	General View	 Load JPG	✓
74	20/12/19 15:56	General View	 Load JPG	✓
75	20/12/19 15:56	General View	 Load JPG	✓
76	20/12/19 15:56	General View	 Load JPG	✓
77	31/12/19 09:32	Reinspection Photo	 Load JPG	✓
78	31/12/19 09:32	Reinspection Photo	 Load JPG	✓
79	31/12/19 09:32	Reinspection Photo	 Load JPG	✓
80	31/12/19 09:32	Reinspection Photo	 Load JPG	✓
81	31/12/19 09:32	Reinspection Photo	 Load JPG	✓
82	31/12/19 09:32	Reinspection Photo	 Load JPG	✓
83	31/12/19 09:32	Reinspection Photo	Load JPG	✓

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
85	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
86	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
87	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
88	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
89	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
90	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
91	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
92	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
93	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
94	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
95	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
96	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
97	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
98	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
99	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
100	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
101	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
102	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
103	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
104	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
105	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
106	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
107	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
108	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
109	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
110	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
111	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
112	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
113	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
114	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
115	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
116	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
117	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
118	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
119	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
120	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
121	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
122	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
123	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
124	31/12/19 09:32	Reinspection Photo	 Load JPG	☒
125	17/01/20 10:35	After Repair Photo	 Load JPG	☒
126	17/01/20 10:35	After Repair Photo	 Load JPG	☒
127	17/01/20 10:35	After Repair Photo	 Load JPG	☒
128	17/01/20 10:35	After Repair Photo	 Load JPG	☒
129	17/01/20 10:35	After Repair Photo	 Load JPG	☒
130	17/01/20 10:35	After Repair Photo	 Load JPG	☒
131	17/01/20 10:35	After Repair Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	17/01/20 10:35	After Repair Photo	Load JPG	☒
133	17/01/20 10:35	After Repair Photo	Load JPG	☒
134	17/01/20 10:35	After Repair Photo	Load JPG	☒
135	17/01/20 10:35	After Repair Photo	Load JPG	☒
136	17/01/20 10:35	After Repair Photo	Load JPG	☒
137	17/01/20 10:35	After Repair Photo	Load JPG	☒
138	17/01/20 10:35	After Repair Photo	Load JPG	☒
139	17/01/20 10:35	After Repair Photo	Load JPG	☒
140	17/01/20 10:35	After Repair Photo	Load JPG	☒
141	17/01/20 10:35	After Repair Photo	Load JPG	☒
142	17/01/20 10:35	After Repair Photo	Load JPG	☒
143	17/01/20 10:35	After Repair Photo	Load JPG	☒
144	17/01/20 10:35	After Repair Photo	Load JPG	☒
145	17/01/20 10:35	After Repair Photo	Load JPG	☒
146	17/01/20 10:35	After Repair Photo	Load JPG	☒
147	17/01/20 10:35	After Repair Photo	Load JPG	☒
148	17/01/20 10:35	After Repair Photo	Load JPG	☒
149	17/01/20 10:35	After Repair Photo	Load JPG	☒
150	17/01/20 10:35	After Repair Photo	Load JPG	☒
151	17/01/20 10:35	After Repair Photo	Load JPG	☒
152	17/01/20 10:35	After Repair Photo	Load JPG	☒
153	17/01/20 10:35	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/19 12:49	EMAIL FROM III TO ARRANGE FOR SURVEY	Load PDF	
2	20/12/19 12:49	WORKSHOP DETAILS	Load PDF	
3	20/12/19 12:49	Police Report	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/12/19 08:44	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19022379/ETD3S2

Date: 04/02/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	FBC2260M	Insured Vehicle No :	GBH2831P
Date of Loss:	10/12/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001639

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC2260M	Engine No:	KC11E2006468
Make & Model:	HONDA CBF150, 149cc (M)	Chassis No:	LALKC11A673006491
Reg. Date:	31/12/2007 (Man. Year: 2007)	Odometer:	66308 km
Colour:	Blue		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80/80-18	Rear Tyre Size:	80/90-18
Front Left Side:	Nylon 5 mm	Rear Left Side:	Nylon 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 20/12/2019 Inspected At:

Chek Kong Motor Pte Ltd (HQ)
BLK 1 387B WOODLANDS ROAD, YEW TEE
INDUSTRIAL ESTATE
Singapore 677948

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Feb 2020)	
Parts:	N/A	HONDA CBF150 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC2260M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >