

REC. BY: Ram

REF: CS/QW19022382 / Fyd3 s2


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHD 6544S Yr Regn: 13/12/2019
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA PRIUS c.c. 1798
 Colour: blue A/C: Insured / Std / NI / NA
 Sp. Reading: 497 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FU 803090321
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195 / 65 R15
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Dunlop

Front Rear
 R/Bal. 10 mm R/Bal. 10 mm
 L/Bal. 10 mm L/Bal. 10 mm
 D.O.A. 15/12/19 D.O.I. 18/12/19

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at (amforhelsuo (urang))
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S rear & O/S rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	bill to SIMING DON'S
	Submit unsafe to repair Total loss
	2nd opinion
	RECEIVED 31 DEC 2019
	not waiting for book value.
	SHD 6544S-X
	31/12/19 Submit unsafe Total loss
	MV =
	LTA = \$31361-00
	NETT =

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) 31/12/19 Typist

Days Of Repair: _____

Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____ \$ + PS. _____ \$

Photos

Other: _____

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Wash etc (\$)

Report Format: _____

Lump Sum / E.P. / G:

Nivitha (LKK Auto)

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Sent: Wednesday, 18 December 2019 9:42 AM
To: assignments
Subject: FW: DOA.15.12.19 SHD6544S - PRIUS - Seek 2nd opinion
Attachments: 2420_001.pdf

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chiang Liat Choon <chianglc@cdge.com.sg>
Sent: Wednesday, 18 December 2019 9:22 AM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Jumani Bin Masudin <jumanibm@cdge.com.sg>
Subject: Fw: DOA.15.12.19 SHD6544S - PRIUS - Seek 2nd opinion

Dear Bryan,

please assist,

Best Regards

Chiang Liat Choon

Taxi Crash Repair ComfortDelGro Engineering Pte Ltd
Off: 62148314 Fax: 65468156



Think Before Printing

From: Jumani Bin Masudin <jumanibm@cdge.com.sg>
Sent: Wednesday, 18 December 2019 9:15 AM
To: Chiang Liat Choon <chianglc@cdge.com.sg>
Subject: Fw: DOA.15.12.19 SHD6544S - PRIUS - Seek 2nd opinion

FYNA.

Best Regards

YY

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Tel. 6214-8315 / Fax. 6546-8156



Think Before Printing

Subject: Re: DOA.15.12.19 SHD6544S - PRIUS - Seek 2nd opinion

Hi Jumani

Pls appoint LKK for 2nd opinion under our account.



CityCab Members of **COMFORTDELGRO**
383 Sin Ming Drive, Singapore 575717

Follow us on   

ComfortRide | **ComfortPoints**

WIN \$8,888* 1 SEP – 31 DEC 2019
by taking **ComfortRIDE**

* Prizes are in the form of ComfortPoints
Terms and conditions apply



Hi Doris

A/m taxi surveyed by VAC-DIN and recommended for scrap

Please advise

Best Regards

Jumani Masudin

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8315 / Fax. 6546-8156



Think Before Printing

Subject: Scan Image

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a

written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2019 12:14
Date Of Accident	15/12/2019 03:30
Exact Location Of Accident	TERMINAL 3 CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6544S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN CHENG WAH
NRIC No	S0028360F
Date Of Birth	19/10/1949
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1975
Driving Experience	44 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97329533
Fax Number	
Contact Number	
EMail Address	CHENGWAH49@YAHOO.COM.SG

Address	871A #12-31 TAMPINES STREET 84
Postcode	521871
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	BOLLARD
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

NOT SURE

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PAX

Approximate Age

Injuries Sustain

NOT SURE

Injured person in which vehicle?

SHD6544S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode



**SINGAPORE
POLICE FORCE**



T/20191215/2033

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20191215/2033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/12/2019 09:14		Vide Report No.:		Station Diary No.: 38	
Informant's Particulars					
Name of Informant: TAN CHENG WAH			Address: APT BLK 871A TAMPINES STREET 84 #12-31 SINGAPORE 521871		
ID Type / ID No.: NRIC NO / S0028360F			Contact No.:		Mobile: 97329533
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 70	Date of Birth: 19/10/1949	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/12/2019 03:30	Type of Location:
Location: Along Road 1 AIRPORT BOULEVARD CHANGI AIRPORT TERMINAL 3, PICKUP POINT				
Weather: Raining		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD6544S	TAXI					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191215/2033

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3

Report No. T/20191215/2033

CONTINUATION OF REPORT

Driver			
Name	TAN CHENG WAH		ID No. S0028360F
Related Vehicle	SHD6544S (TAXI)		Contact No. 97329533
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 15/12/19, at about 0330hrs, I was at Changi Airport Terminal 3 to pick up a passenger. After picking up the passenger, as my vehicle was in 'N' gear, it started to roll forward. I immediately put the gear to 'R' and stepped on the pedal. As a result of stepping too hard, the vehicle reversed all the way and collided with the bollard of the airport. Soon after, police and ambulance was called in. My passenger was conveyed to hospital by ambulance.

My vehicle have a front inbuilt camera. The SD card have been handed over to the police at scene.



SINGAPORE
POLICE FORCE



T/20191215/2033

3 of 3

Report No. T/20191215/2033


Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 JONATHAN LIM XIONG HAI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 15/12/2019 09:14
Officer In Charge Of Case: TP / GIT / Sgt 2 HO JIEKANG, IVAN Contact No.: 65476170	Classification Of Case: <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Authentication Stamp NP168	<div style="border: 1px solid black; padding: 5px;">   SINGAPORE POLICE FORCE AUTHENTICATION STAMP NP168 </div>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Company

821R

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

SHD6544S

Yes

27 Dec 2019

TOYOTA

PRIUS SDR HATCHBACK (AUTO)

Blue

2019

2ZR2G04499

JTDKB3FUX03090321

90.0 kW (120 bhp)

\$26,807.00

13 Dec 2019

13 Dec 2019

0

\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Yes

12 Dec 2027

\$10,897.00

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

12 Dec 2027

A - Car up to 1600cc & 97kW (130bhp)

8

\$25,581.00

\$20,464.00

Total Rebate Amount:**\$31,361.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Dec 2019

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD65445
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS SDR HATCHBACK (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	2ZR2G04499
Chassis No.:	JTDKB3FUX03090321
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	13 Dec 2019
First Registration Date:	13 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2027
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$20,464.00
Total Rebate Amount:	\$31,361.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Dec 2019.

Bill C+PL DOHS

Simon

OK

REPAIR ESTIMATE

VEHICLE NO: SHD 6544S

16/12/2019 17:11

MAKE :

MODEL : TOYOTA PRIUS

2nd Opinion

JU.

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>BUC</i>			\$ 1,126.60
REAR TRUNK LID LOCK <i>7</i>			\$ 457.90
REAR TRUNK LID COVER TRIM BOARD <i>Br</i>			\$ 254.40
REAR TRUNK LID RUBBER			\$ 365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>nee</i>			\$ 733.50
BOARD ASSY, BACK DOOR TRIM <i>Br</i>			\$ 360.80
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>Br</i>			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) <i>nee</i>			\$ 52.90
REAR TRUNK LID LOGO(HYBRID) <i>nee</i>			\$ 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) <i>nee</i>			\$ 47.00
ROOF TOP MOULDING (CENTRE) <i>xan</i>			\$ 950.00
ROOF TOP GARNISH SUB, LH <i>xan</i>			\$ 72.00
ROOF TOP GARNISH SUB, RH <i>xan</i>			\$ 75.00
MOTOR & PUMP ASSY, REAR WASHER			\$ 240.80
MOTOR ASSY, REAR WIPER			\$ 734.60
LINK ASSY, WINDSHIELD WIPER			\$ 369.00
REAR BUMPER <i>BUC</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>BUC</i>			\$ 318.80
REAR BUMPER UNDER COVER <i>Br</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>nee</i>			\$ 112.70
REAR BUMPER TOWING COVER <i>MIS</i>			\$ 82.70
REAR BUMPER CLIPS <i>nee</i>			\$ 22.00
ARM SUB-ASSY, REAR BUMPER, RH			\$ 139.60
ARM SUB-ASSY, REAR BUMPER, LH			\$ 139.60
RETAINER, REAR BUMPER, UPPER SIDE			\$ 30.70
RETAINER, REAR BUMPER, SIDE, RH			\$ 94.80
RETAINER, REAR BUMPER, SIDE, LH			\$ 94.80
SEAL, REAR BUMPER SIDE, RH			\$ 148.40
SEAL, REAR BUMPER SIDE, LH			\$ 148.40
TAIL LAMP ASSY (UPPER) (LH/RH) <i>crn</i>		\$ 557.90	\$ 1,115.80
TAIL LAMP ASSY (LOWER) (LH/RH) <i>scr</i>		\$ 548.40	\$ 1,096.80
TAIL LAMP QUARTER PANEL <i>?</i>		\$ 99.00	\$ 198.00
REAR END PANEL <i>BUC</i>			\$ 602.10
REAR END PANEL GARNISH <i>Br</i>			\$ 165.80
REAR SPARE TYRE PANEL <i>BUC</i>			\$ 667.70
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>crn</i>			\$ 750.00
REAR EXHAUST PIPE <i>?</i>			\$ 1,163.40
REAR FENDER, LH <i>BUC</i>			\$ 836.70
REAR FENDER, RH <i>DD</i>			\$ 836.70
REAR FENDER SHEILD (LH) <i>?</i>			\$ 134.20
REAR FENDER SHEILD (RH) <i>?</i>			\$ 134.20
REAR CHASSIS MEMBER <i>DD</i>		\$ 1,180.80	\$ 2,361.60
REAR FLOOR PANEL SIDE (LH) <i>?</i>			\$ 276.20
REAR FLOOR PANEL SIDE (RH) <i>?</i>			\$ 276.20
REAR FLOOR BOARD (LH) <i>?</i>			\$ 301.00
REAR FLOOR BOARD (LH) <i>?</i>			\$ 301.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FLOOR UNDER COVER CENTRE			\$ 322.00	
REAR FLOOR UNDER COVER			\$ 334.00	
REAR CROSSMEMBER UNDER COVER			\$ 353.00	
REAR FLOOR PANEL <i>BZ</i>			\$ 2,850.50	
REAR WINDSCREEN GLASS WITH MOULDING <i>BOVA</i>			\$ 1,778.30	
REAR TYRE RIM ,LH/RH		\$ 1,555.00	\$ 3,110.00	
REAR WHEEL HUB CAP ,LH/RH		\$ 177.70	\$ 355.40	
REAR WHEEL BEARING ING & HUB , LH/RH		\$ 610.20	\$ 1,220.40	
REAR CROSS MEMBER <i>BT</i>			\$ 2,200.40	
REAR SHOCK ABSORBER, LH/RH		\$ 118.30	\$ 236.60	
REAR SHOCK ABSORBER MOUNTING, LH/RH		\$ 125.30	\$ 250.60	
REAR LOWER ARM, LH/RH		\$ 497.50	\$ 995.00	
REAR UPPER ARM,LH/RH		\$ 356.80	\$ 713.60	
REAR KNUCKLE ARM, LH/RH		\$ 810.60	\$ 1,621.20	
REAR BRAKE ABS SENSOR (WIRE)		\$ 78.80	\$ 157.60	
REAR STABILIZER BAR		\$ 311.50	\$ 623.00	
REAR STABILIZER LINK, LH/RH		\$ 151.60	\$ 303.20	
REAR TRAILING ARM,LH/RH		\$ 314.20	\$ 628.40	
REAR ASSIST ARM,LH/RH		\$ 342.20	\$ 684.40	
SUB TOTAL			\$ 39,081.00	
LESS 25%			\$ 9,770.25	
DISCOUNTED TOTAL			\$ 29,310.75	
REAR NO. PLATE WITH TRIM COVER <i>inc</i>			\$ 100.00	NETT
REAR TRUNK LID APPS STICKER <i>ncc</i>			\$ 40.00	NETT
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>ncc</i>			\$ 60.00	NETT
REAR BUMPER REVERSE SENSOR <i>sc</i>			\$ 135.70	NETT
REAR BUMPER RUBBER MAT <i>ncc</i>			\$ 50.00	NETT
REAR WINDSCREEN SEALANT <i>vet</i>			\$ 46.00	NETT
REAR TYRE ,LH/RH <i>xun</i>		\$ 216.00	\$ 432.00	NETT
LABOUR CHARGE			\$ 863.70	
Panel Beating			\$ 2,000.00	
Spray Painting Charge			\$ 1,600.00	
Wiring Charge			\$ 50.00	
Tuff Kote			\$ 50.00	
Towing Charge			\$ 60.00	
Rear Chassis Alignment Charge			\$ 400.00	
Remove/Refix Cushion & Upholstery Rear			\$ 150.00	
Remove/Refix Rear Windscreen Glass			\$ 120.00	
Remove/Refix Reverse Sensor			\$ 80.00	
Remove/Refix Undercarriage (RR)			\$ 200.00	
Remove/Refix Exhaust Pipe			\$ 150.00	
Rear Wheel Alignment			\$ 80.00	
Diagnosis & Resetting To Erase Fault Code			\$ 480.00	
TOTAL LABOUR			\$ 5,420.00	
ESTIMATE TOTAL			\$ 35,594.45	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To resurvey damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Date: _____


unsafe to repair
Requesting for Book Value
Remy (LKR)
18/11/19
145hrs
7 days

Team: ARC Repair OD(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305367312
CUSTOMER	REGN NO: SHD6544S	MILEAGE	
MS: COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL	
CUSTOMER NO: 7010045	MODEL: PRIUS HYBRID(G4A15)	E:1/2.....F	
ADDRESS: 383 SIN MING DRIVE	DATE/TIME IN: 15.12.2019 03:30	TARGET DATE	
Singapore SINGAPORE 575717	YR OF MANU: 13.12.2019	COMPLETION DATE/TIME:	
(R) 65508755 (O)	CHASSIS CODE: JTDKB3FUX03090321		
(P)			
COUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 15.12.2019
 NATURE: OD 15.12.19

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

Acknowledgement Slip

Vehicle No.: SHD6544S

Signature/Date: JU

Name of Service Advisor

Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHD6544S

Name of Service Advisor

Date

To be kept by Security Guard

Co. Code : CITYL
 Licence Pl.No : SH6544S
 Old Asset No :
 Veh. Model : Hyundai I40
 Reg. Date : 04.11.2014
 Exp. Date : 04.11.2014
 Accident. Date : 15.12.2019
 Veh. Age : 061

Asset No	SA No	Bal. Dep. Minus	Per. Mth. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Our. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated PUMP Refund
		\$	\$	\$		\$	\$	\$	\$	\$	\$
10031634	0	029	277.77	8,055.33	SH6544S H40 04.11.2014 BASIC COST W AIRCON	25,000.00	13,888.33	1,666.60	15,554.93	9,445.07	1.00
10031634	1	029	42.02	1,218.58	SH6544S H40 04.11.2014 IMPORT DUTY 2010MYS18909	3,781.70	2,100.95	252.12	2,353.07	1,428.63	0.00
10031634	2	029	50.71	1,470.59	SH6544S H40 04.11.2014 ARF 1001KOWS18909-CVS7500	11,403.00	2,535.55	304.27	2,839.82	8,569.18	0.00
10031634	3	029	570.41	16,541.89	SH6544S H40 04.11.2014 COE 80%	51,337.00	28,520.55	3,422.47	31,943.02	19,393.98	6,845.00
10031634	4	000	0.00	0.00	SH6544S H40 04.11.2014 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10031634	5	029	0.00	0.00	SH6544S H40 04.11.2014 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10031634	6	029	0.00	0.00	SH6544S H40 04.11.2014 PRINTER DIGITX IJERML	0.00	0.00	0.00	0.00	0.00	0.00
10031634	7	029	0.00	0.00	SH6544S H40 04.11.2014 TAXIMETER DEUTIX FI	0.00	0.00	0.00	0.00	0.00	0.00
10031634	8	029	1.56	45.24	SH6544S H40 04.11.2014 VEH REG FEE	140.00	77.78	5.34	87.12	52.88	0.00
			942.47	27,331.63		91,667.70	47,123.16	5,654.80	52,777.96	38,889.74	
			570.41	16,541.89	Vehicle : Without T/M & COE	40,330.70	18,602.61	2,232.33	20,834.94	19,495.76	
			372.06	10,789.74	Vehicle : Without T/M, With COE	91,667.70	47,123.16	5,654.80	52,777.96	38,889.74	
			942.47	27,331.63	Taximeter	0.00	0.00	0.00	0.00	0.00	