

ASS. REC. BY:

REF: 08/SMO19022390/T1td3

n2

Special Instructions:

Surveyor

Tau Aich

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

20/12/19 @ 2:08pm

Estimated Cost:

Bill to:

OD//TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLF 7211M

Insured:

GBE 6603X

at Workshop n/s

Focus Auto

Tel:

6844 4620

of

1 Kaki Bukit Ave 6 # 02-48/50 Autobay

Policy No:

Claim No:

CM101905913/AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A

19/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:41pm @ 20/12/19

Person Contacted:

Aidah

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF 7211M-CC1/19012540/U1p3y2
	GBE 6603X-X
23/12-	Revised via email/ preli advise.
11/3-	Repair done, finalize.

ADJ. REG. BY:

Tanph

REF:

Sompo

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF7211M

Regn:

2016 Sep.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

cc 1598

Colour

S/new

A/C: Insured / Std / NI / NA

Sp Reading

152306

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MROS3REH1045.57696

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

u 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CS T

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I

20/12/19

Survey held at

Fong Anti

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 0/5, 4/1

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/5 \$ 2800, 4 days (Red: 2852.01; 5070)

1 Act KB Ave 6 #02-45/0

Date/Time, File Pass to?

30/3 Typist

Date/Time, File Return to?

3)

Rep Form:

Lump Sum H.R.:

TP
2800

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wind and (\$

Survey Fee:

Transportation

S + RS \$

Fixed

Other

TOTAL

250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905913/AGC

Date: 23/12/2019

Our Ref: CS/SMO19022390/T1td3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SLF 7211M.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 20/12/2019 at the premises of M/s Focus Auto and have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,707.10</u>
Revised Estimate Amount	: S\$ <u>3,918.50</u>
"Check" Items Amount	: S\$ <u>740.40</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u> -
Nett Value	: S\$ <u> </u> -

Description of Damage:

The vehicle sustained damages at the front o/s portion and undercarriage parts.



Repair days: 4

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 20 December 2019 2:08 PM
To: claims@focusauto.com.sg; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Chan, Shu Hui Agnes; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1905913/AGC - LKK/ GBE6603X & SLF7211M ACCIDENT ON 19.12.19

Our Reference: CMTD1905913/AGC
Your Reference: SLF7211M

Without Prejudice
EMAIL ONLY

Date: 20/12/2019

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S FOCUS AUTO PTE LTD

Dear Aidah,

ACCIDENT INVOLVING GBE6603X & SLF7211M ON 19.12.2019

We refer to your email reply of today.

We will appoint Mr. Marcus Chua of LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for **SLF7211M** on a without prejudice basis and revert with your report upon completion of survey to my colleague, **Ms. Agnes**.

Thank You.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.
We wish you a Merry Christmas and a Happy New Year!

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: claims@focusauto.com.sg <claims@focusauto.com.sg>

Sent: Friday, December 20, 2019 2:01 PM

To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: Re: CMTD1905913/AGC - PRI(NR)/ GBE6603X & SLF7211M ACCIDENT ON 19.12.19

Dear Ms Grace,

Your message is well noted. We are please to select LKK AUTO CONSUTANTS MR MARCUS CHUA as the surveyor. Do let us know early notice for his arrival to our workshop.

Thank You

Best Regards

Aidah

On 2019-12-20 13:40, Teo, Grace wrote:

Our Reference: CMTD1905913/AGC

Your Reference: SLF7211M

Without Prejudice

Date: 20/12/2019

EMAIL ONLY

Attention:

M/S FOCUS AUTO PTE LTD

Dear Aidah,

ACCIDENT INVOLVING GBE6603X & SLF7211M ON 19.12.2019

We refer to your Notice of Accident dated 20/12/2019.

Please be informed that **Ms. Agnes Chan** is the handler of this case who can be contacted at 63295 327/ agnes.chan@sompo.com.sg.

Please be informed that we have yet to receive our insured's accident report.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: claims@focusauto.com.sg <claims@focusauto.com.sg>
Sent: Friday, December 20, 2019 11:43 AM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: PRE SURVEY REPAIR - SLF7211M & GBE6603X ACCIDENT ON 19.12.19

Dear Officer In-Charge,

Good Day,

Please sent surveyor list to arrange the surveyor down to our workshop as below.

We are instructed by our client to notify you of a road traffic accident on 19/12/2019 at about 0900 hours at Ang Mo Kio Industrial Park 2 involving our client's SLF7211M and GBE6603X driven by your insurer or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at :

Name of workshop : FOCUS AUTO PTE LTD

Address : No. 1 Kaki Bukit Avenue 6

Autobay #02-48/50

Singapore 417883

Telephone No.: 6844620

Best Regards

Aidah

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

Office Hours : Mon ~ Sat, 0900 ~ 1800

--

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

Office Hours : Mon ~ Sat, 0900 ~ 1800

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 23 December 2019 2:23 PM
To: Admin-D (LKKAuto); 'Teo, Grace'; assignments
Cc: 'Chan, Shu Hui Agnes'; 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR
Subject: RE: CMTD1905913/AGC - LKK/ GBE6603X & SLF7211M ACCIDENT ON 19.12.19
Attachments: PRELI ADVISED OF SLF 7211M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLF 7211M**
Number of days (estimated) : 4 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 20 December 2019 2:47 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1905913/AGC - LKK/ GBE6603X & SLF7211M ACCIDENT ON 19.12.19

Resend

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that due to the unavailability of the appointed surveyor Mr. Marcus chua,

Repairer agreed our surveyor Mr. Taufikh to survey this vehicle.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

6DD12 / 67483092

Chassis No.

8 MRO53REH 104557696

PROGRESSIVE / FOCUS (ESTIMATE)

No	Qty	Date	Surveyor	Insurance	Vehicle No.	Model
					SIT 7211M	70707A / ALTI5
1	1		Front fender	RHS	H	606.00
2	1		Front fender	dust cover - RH	de	125.40
3	8		Front fender	dust cover - Clipse	RHS	12.10
4	1		Front fender	emblem	RH new	10.40
5	1		Front headlamp	RH	ad	804.10
6	1		Front headlamp	lower bracket	RH ?	18.40
7	1		Front grille	car		398.40
8	6		Front grille	clipse	new	5.50
9	1		Front fender	lower bracket	RH ?	66.00
10	1		Front bumper	de		555.20
11	1		Front bumper	side return	Red de	65.10
12	1		Front Winker	bank	de	144.20
13	1		Front S/absorb		RH x	208.10
14	1		Front fender	arm	RH ?	435.10
15	1		Front lower arm		RH x	410.10
16	1		Front hub	brake	RH ?	210.40

Labour charge

panel Seating - 950 400

check work - 60 30

rust proof - 60 30

alignment - 50 ✓

to remove & replace front under carriage - 280 120 ?

to spray painting - 750 400

LKK Tayfiah 97495149 / 67418434
20/12/19 @ 430pm
Lumpsum
Resurvey after repair

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sur @ lkhauto.com
04 days

No	Qty	Date	Surveyor	Insurance	Vehicle No.	Model
					SIT 7211 m	TOYOTA / ALTIS.
1	✓ 1		Front fender	RHS	H ✓	606.50 888.10
2	✓ 1		Front fender	dust cover - RH	de ✓	125.40
3	✓ 1		Front fender	dust cover - Clipse RH	de ✓	12.10
4	✓ 1		Front fender	emblem	RH new ✓	10.40
5	✓ 1		Front headlamps	RH	ant ✓	804.10
6	✓ 1		Front headlamps	lower bracket	RH RH ✓	18.40
7	✓ 1		Front grille	new		398.40
8	✓ 6		Front grille	clipse	new ✓	5.50
9	✓ 1		Front fender	lower bracket	RH ? bt ✓	66.00
10	✓ 1		Front bumper	de ✓		555.20
11	✓ 1		Front bumper	side return	RHS de ✓	65.10
12	✓ 1		Front Walker	Shank	de ✓	144.20
13	✓ 1		Front S/shoulder		RH x	408.10
14	✓ 1		Front fender	arm	RH ? bt ✓	435.10
15	✓ 1		Front lower arm		RH x	410.10
16	✓ 1		Front hub bearing		RH ? bt ✓	27/12 210.46

17
 18 Hubon cheng
 19 BR10001078
 20 ✓ panel Seating - 950 400
 21
 22 ✓ check wmm - 60 30
 23 ✓ rust proof - 60 30
 24 ✓ alignment - 50 ✓
 25 ✓ to remove & replace front under carriage - 280 120? plus
 26 ✓ to spray painting - 750 400

27
 28 ~~KTH~~ Tayfah 97475749 / 67418434
 29 20/12/19 @ 430pm
 30 Lumpsun
 31 Restoring after repair
 32
 33 540 @ 1 hour 10 min
 34 04 days
 35
 36
 37
 38
 39
 40

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : SOMPO INSURANCE**Estimate No: EST0001078**

Date: 26 Dec 2019

Veh Reg No: **SLF7211M**

Make/Model: TOYOTA COROLLA

Chassis No: MR053REH104557696

Engine No: 1ZRX592355

Reg. Date: 09/07/2016

ATTN: Motor Claim Department
 Your Reference :SLF7211M TOYOTA
 Claim Type: Third Party
 Accident Date: 19.12.19

Estimate Repair Cost to Vehicle No :SLF7211M

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Front Fender - RH	888.10	1 PC	888.10	656 bt ✓
2 Front Fender Dust Cover - RH	125.40	1 PC	125.40	de ✓
3 Front Fender Dust Cover Clip - RH	12.10	8 PC	96.80	nei ✓
4 Front Fender Emblem - RH	10.40	1 PC	10.40	nei ✓
5 Front Head Lamp - RH	804.10	1 PC	804.10	cut ✓ 520.3x
6 Front Head Lamp Lower Bracket - RH	18.40	1 PC	18.40	cu ✓
7 Front Grille	398.40	1 PC	398.40	cu ✓
8 Front Grille Clipse - RH	5.50	6 PC	33.00	nei ✓
9 Front Fender Lower Bracket	66.50	1 PC	66.50	bt ✓
10 Front Bumper	555.20	1 PC	555.20	de ✓
11 Front Bumper Side Retainer	65.10	1 PC	65.10	de ✓
12 Front Washer Tank	144.20	1 PC	144.20	de ✓
13 Front Shock Absorber - RH	408.10	1 PC	408.10	xm ✓
14 Front Knuckle Arm - RH	435.10	1 PC	435.10	bt ✓
15 Front Lower Arm - RH	410.10	1 PC	410.10	xm ✓
16 Front Hub Bearing	210.40	1 PC	210.40	bt ✓
	3335.30		4,669.30	3501.97
	2501.47	Less 25%	1,167.33	3,502.01
Labour				
17 Panel Beating		1 PC	950.00	400 ✓
18 Check Wiring		1 PC	60.00	30 ✓
19 Rust Proofing		1 PC	60.00	30 ✓
20 Alignment Adjustment		1 PC	50.00	✓

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : SOMPO INSURANCE

ATTN: Motor Claim Department
Your Reference : SLF7211M TOYOTA
Claim Type: Third Party
Accident Date: 19.12.19

Estimate No: EST0001078

Date: 26 Dec 2019

Veh Reg No: SLF7211M

Make/Model: TOYOTA COROLLA

Chassis No: MR053REH104557696

Engine No: 1ZR592355

Reg. Date: 09/07/2016

Estimate Repair Cost to Vehicle No :SLF7211M

PAGE:2/2

Description

U/PriceQuantity List Price Amount
SS SS

Labour Price

21 To Remove & Replace Front Under Carriage	1 PC	280.00	120
22 To Spray Painting	1 PC	750.00	400
		2,150.00	2,150.00
			1030
			Total \$5,652.01
			5651.97

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED FIFTY TWO AND ONE CENTS ONLY

For FOCUS AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

AUTHORISED SIGNATURE

Tan Jia 97495749/6748434 2501.47
20/12/19 0430
LKK Auto Consultants
sure Auto 04 days
1/53 2800 #
04 days
3531.47
1030

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FOCUS AUTO PTE LTD
VIN: SLF 7211 M
Date: 21.12.19 14:06



TOYOTA ALTIS 2014-

Front : Left

Actual	Before	Specified Range
-0°47'	-0°47'	-0°59' 0°31'
2°51'	2°51'	5°08' 6°38'
-0°09'	-0°09'	0°00' 0°11'
10°33'	10°33'	
9°47'	9°47'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°06'	-2°06'	-0°59' 0°31'
3°00'	3°00'	5°08' 6°38'
-0°09'	-0°09'	0°00' 0°11'
14°37'	14°37'	
12°31'	12°31'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
1°19'	1°19'	-0°45' 0°45'
-0°09'	-0°09'	-0°45' 0°45'
-4°04'	-4°04'	
-0°18'	-0°18'	0°00' 0°22'

Rear : Left

Actual	Before	Specified Range
-1°33'	-1°33'	-1°58' -0°58'
0°00'	0°00'	-0°01' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°30'	-1°29'	-1°58' -0°58'
0°08'	0°08'	-0°01' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°03'	-0°04'	-0°30' 0°30'
0°08'	0°08'	-0°01' 0°31'
-0°04'	-0°04'	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022390/T11d3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 02-04-2020	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 6603X	Veh. Inspected	SLF 7211M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905913/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/12/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104557696	Colour	SILVER
Odometer	152306	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	CST	6 mm
L/H Front Tyre	205/55 R16	CST	6 mm
R/H Rear Tyre	205/55 R16	CST	6 mm
L/H Rear Tyre	205/55 R16	CST	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/12/2019	Inspection Date	20/12/2019
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7211M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER-RH	BENT	888.10	656.00
1	FRONT FENDER DUST COVER-RH	DEFORMED	125.40	125.40
8	FRONT FENDER DUST COVER CLIP-RH @\$12.10	NECESSARY	96.80	96.80
1	FRONT FENDER EMBLEM-RH	NECESSARY	10.40	10.40
1	FRONT HEAD LAMP-RH	CUT	804.10	520.30
1	FRONT HEAD LAMP LOWER BRACKET-RH	CRACKED	18.40	18.40
1	FRONT GRILLE	CRACKED	398.40	398.40
6	FRONT GRILLE CLIPSE-RH @\$5.50	NECESSARY	33.00	33.00
1	FRONT FENDER LOWER BRACKET	BENT	66.50	66.50
1	FRONT BUMPER	DEFORMED	555.20	555.20
1	FRONT BUMPER SIDE RETAINER	DEFORMED	65.10	65.10
1	FRONT WASHER TANK	DEFORMED	144.20	144.20
1	FRONT SHOCK ABSORBER-RH	NOT NECESSARY	408.10	-
1	FRONT KNUCKLE ARM-RH	BENT	435.10	435.10
1	FRONT LOWER ARM-RH	NOT NECESSARY	410.10	-
1	FRONT HUB BEARING	BENT	210.40	210.40
	LESS 25% DISCOUNT		-1,167.33	-833.80
			3,501.97	2,501.40
LABOUR				
	PANEL BEATING.		950.00	400.00
	CHECK WIRING.		60.00	30.00
	RUST PROOFING.		60.00	30.00
	ALIGNMENT ADJUSTMENT.		50.00	50.00
	TO REMOVE & REPLACE FRONT UNDER CARRIAGE.		280.00	120.00
	TO SPRAY PAINTING.		750.00	400.00
			2,150.00	1,030.00
GRAND TOTAL			5,651.97	3,531.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00



Report Ref No. CS/SMO19022390/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.