

ASS. REC. BY:

REF:

C83/CTI19022401/71sd30

Special Instruction:

Surveyor

Tau Fikih

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

20/12/19 @ 1.27pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 3813P

Insured:

SJD 620X

at Workshop m/s

Apex Motoring

Tel:

9169 0825

of

25 Kalei Bukit Road 4 #01-55 synergy

Policy No:

Claim No:

SNM19D206049

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:31pm @ 20/12/19

Person Contacted:

peijie

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SMK 3813P - X

SJD 620X - X

23/12/19

@ 15:22 pm checked with Pei Te, ~~pending not~~ no estimate

ASSIGNMENT

From: Date: 21

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 1

at Workshop m/s

of 1

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp - PRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMK 3813P Yr Regn: 2019 April

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Freed Hybrid C.C. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 46539 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 1185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 20/12/19

Survey held at Apex Motoring

Des. of Damages: Frt / Rear / O/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No GHA
	\$6000 - \$7000, 7 days

RECEIVED 10 JAN 2020

Date/Time, File Pass to?

1) 10/01/20 Typ: SP

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

150

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 20 December 2019 4:27 PM
To: peijie@expresscar.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D206049/SJD620X/CBS & YOUR REF: SMK3813P -PRS - Accident between Vehicle No. SMK 3813 P and Vehicle No. SJD 620 X on 15122019 @ 1220Hrs

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.
Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: Claims Dept of CTI
Sent: Friday, December 20, 2019 2:13 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; peijie@expresscar.com.sg
Subject: OUR REF: SNM19D206049/SJD620X/CBS & YOUR REF: SMK3813P -PRS -Accident between Vehicle No. SMK 3813 P and Vehicle No. SJD 620 X on 15122019 @ 1220Hrs

Dear Boon Sen,

Please conduct PRS-SMK3813P soonest possible

File to officer in charge-Chong Boon Sen- DID: 6389 6171

Dear Pei Jie,

*** kindly quote our reference number when replying***

Thank you.
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: peijie@expresscar.com.sg [mailto:peijie@expresscar.com.sg]
Sent: Thursday, December 19, 2019 4:46 PM
To: Claims Dept of CTI
Subject: Accident between Vehicle No. SMK 3813 P and Vehicle No. SJD 620 X on 15122019 @ 1220Hrs

Dear Sir / Mdm,

Please refer to attachment

--

Best Regards,
Peijie
82 Lorong 23 Geylang
#03-06 ATRIX
S(388409)
DID: 91690825

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2019 13:31
Date Of Accident	15/12/2019 12:20
Exact Location Of Accident	EXIT CTE TOWARDS TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK3813P
Insured/Policyholder	
Name Of Registered Owner	ASIA EXPRESS CAR RENTAL PTE LTD
Co Reg No	201116882D
Email Address	PEIJIE@EXPRESSCAR.COM.SG
Mobile Phone No	(LOCAL) +65-96253682
Alternative Phone No	OFFICE-68424992

Vehicle Particulars

Manufacturer	HONDA
Model	FREED 1.5G HYBRID SENSING AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	B 29120056 MCX
Cover Note Number	

Driver

Name of Driver	ALEX TANG TIN WAI
NRIC No	S7304524Z
Date Of Birth	29/01/1973
Occupation	OUTDOOR
Date Of Driving Pass	04/09/1999
Driving Experience	20 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88211114
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 111 EDGEFIELD PLAINS #10-402
Postcode	820111
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/2019125/2116;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD620X
Vehicle Make/Model/Colour	MITSUBISHI / LANCER 1.6 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EFFIA TAY YUXUAN
NRIC/Passport Number	S9807185G
Contact Number	90720640

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be located outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory laws or court orders.



Policyholder's Signature

Date & Time:

16/12/19 12:15pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

16/12/19 12:15pm

TO AC KANTHUR (YAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415935

Tel: 67416697 Fax: 67492305

Email: yachb@yach.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/Fin No.:

SKETCH PLAN

B-57D 620X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____

Date & Time:

16/0/19 12 (PM)

2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 2681, 26

Driver's Signature

(If driver is not the policyholder)

Date & Time:

(6) 2/4 12:15 PM

~~TOAD KAKI BUKIT (VAG)~~

23 Kaki Bukit, Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: varkey@vsnl.com

Reporting Center Personnel's Signature

Name: _____

NRIC/FIN No.:

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191215/2116

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3
Report No: T/20191215/2116

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/12/2019 18:36		Vide Report No.:		Station Diary No.: 69	
Informant's Particulars					
Name of Informant: ALEX TANG TIN WAI			Address: APT BLK 111 EDGEFIELD PLAINS #10-402 SINGAPORE 820111		
ID Type / ID No. NRIC NO / S7304524Z			Contact No. Home/Office		Mobile: 88211114
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 46	Date of Birth: 29/01/1973	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/12/2019 12:20	Type of Location: Bend
Location: Along Road 1 TAMPINES EXPRESSWAY				
Along TPE right after CTE Exit				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJD620X	Car					0
SMK3813P	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191215/2116

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No. T/20191215/2116

CONTINUATION OF REPORT

Driver			
Name	ALEX TANG TIN WAI	ID No	S7304524Z
Related Vehicle	SMK3813P (Car)	Contact No.	88211114
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	15/12/2019	Date Discharge	15/12/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	EFFIA TAY YU XUAN	ID No.	S9807185G
Related Vehicle	NIL	Contact No.	90720640
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 15/12/2019 at around 1226hrs, I was travelling along TPE right after CTE Exit and after the first tunnel, there were few cones at the left and it is merging towards the right lane. There are a total of 2 lanes. I was on the right lane and the lane is a merging lane. The traffic was slow moving and there was a point I came to a gradual stop. After about 2 or 3 seconds later, I felt an impact coming from the rear of my vehicle. As such, I alighted to make a check. I then discovered that a vehicle bearing registration number SJD620X had hit onto my rear of the vehicle. We then drove to the side and exchanged particulars. We also took some photos of the damages. There was no one injured on that particular moment. However, I felt some discomfort and stiffness on the back of my neck and decided to proceed to Sengkang General Hospital for a check. I was told by the doctor that I am suffering from some muscle strains and will be referred to Orthopedic for follow ups. I would like to state that the incident was captured by my front in-car dash camera. That is all.

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191215/2116

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 3
Report No. T/20191215/2116

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Staff Sgt FARHAN BIN ABU

Signature Of Informant

[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
15/12/2019 18:36

Officer In Charge Of Case:
TP / AEIT /
SSI 2 JUREMAH BINTE AHMAD
Contact No: 65476219

Classification Of Case:

SN 065

Authentication Stamp
NP168



Signature

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)































CLAIM SUBFOLDER TRACKING









































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2020		10 Jan 2020 10:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ASIA EXPRESS CAR RENTAL PTE LTD , Co. Reg. No.: 201116882D								
Vehicle Reg. No.:	SMK3813P	Date of Loss:	15/12/2019 12:00 - :59 [8 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D206049C02	Policy/Cover Note No.:	DMPCSN17139019022						
Vehicle Reg. No. (Insured):	SJD620X	Policy No. (Claimant):	B 29120056 MCX						
		Excess:	S\$0.00						
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Claim Documents

*SMK3813P (SNM19D206049C02)
[SJD620X]
TP
ASIA EXPRESS CAR RENTAL PTE LTD
Dec 15 2019 12:00PM
[-]
Apex Motoring

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print
1	16/12/19 13:42	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print
1	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	16/12/19 13:42	Driving License [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
8	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
9	16/12/19 13:42	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
2	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
3	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
4	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
5	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
6	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
7	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
8	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
9	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
10	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
11	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
12	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
13	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
14	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
15	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
16	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
17	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
18	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
19	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
20	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
21	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
22	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
23	10/01/20 10:30	General View								Load JPG	<input checked="" type="checkbox"/>
24	10/01/20 10:30	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>
25	10/01/20 10:30	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>
26	10/01/20 10:30	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>
27	10/01/20 10:30	Reinspection Photo								Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/01/20 10:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	16/12/19 13:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	16/12/19 13:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	16/12/19 13:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	16/12/19 13:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	16/12/19 13:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	16/12/19 13:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	16/12/19 13:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
2	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	16/12/19 13:42	Driving License		Load JPG	<input checked="" type="checkbox"/>
7	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	16/12/19 13:42	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	16/12/19 13:41	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	16/12/19 13:41	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	16/12/19 13:41	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
4	16/12/19 13:41	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
5	16/12/19 13:41	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19022401/T1SD3E2

Date: 14/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN17139019022

Claimant Vehicle No: SMK3813P Insured Vehicle No: SJD620X

Date of Loss: 15/12/2019 Nature of Claim: TP Claim No: SNM19D206049C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK3813P

Make & Model: HONDA FREED HYBRID SENSING, 1.5 G (A) Engine No: LEB5621328

Reg. Date: 08/04/2019 (Man. Year: 2018) Chassis No: GB71084065

Colour: Grey Odometer: 46534 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 20/12/2019 Inspected At:

Apex Motoring
25 Kaki Bukit Road 4, #01-55 Synergy
@ KB
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts:	M1-MPV	HONDA FREED HYBRID SENSING 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK3813P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >