

REF: CS³ AIG 19022435/Hyf302

Special Instruction:

SA/VE/PA ROCK AM

ASSIGNMENT (Office)

From (Person) Winnie Fanof AIGDate/Time 23.12.2019 10:22a.m

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Request Vehicle No.

FBD 3744Y

Insured

SLU 2937Gat Workshop info MS Car Auto

Tel:

63851836of NO 8 Kaki Bukit Ave 4 #01-01 Primor

Policy No.

Claim No.

522511536586

Sum Insured

Excess:

Make of Veh.

D.O.A.

17.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

Date/Time: 23.12.19 10:35a.m

Person Contacted

Juw

H.O.D. / Attachment:

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBD 3744Y - NA / FWD 23/12/19 24

Note 1st

SLU 2937G - NA / FWD 23/12/19 24

Note 1st

23/12/19 → singer trucker.

/ / → party workshop updated

* Note: workshop N/A
 L's make, party
 workshop updated

A

6/2/20

ASS. REC. BY: H-ANNREF: AIG

PRs

ASSIGNMENT

From: _____ Date: 23.12.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBD 3744Y

at Workshop n/s: M/S Car Auto

of NO B Kaki Bukit Ave 4 #01-07 Premier

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBD 3744Y Yr Regn: 12/02/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: H. CBR 1000 C.C. 998

Colour: Green/Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 53966/km T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH25C59AX9K101869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70/17
R: 200/55/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 5-BS mm R/Bal. 5-BS mm

L/Bal. mm L/Bal. mm

D.O.A. 17/12/19 D.O.L. 23/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

DAR - /th
up days → 4 days

6/2/20 Submit DAR

MV - 11000

PV - 2921

NV - 8800

RECEIVED 06 FEB 2020

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

6/2/20 Typist

Rep. Form: _____

DAR

Emp. Sign / H.E. / G.

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 180

Transportation

S + RS: \$

Photos

Others

TOTAL

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2019 Edit Reg		23 Dec 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	DU BO								
Main Claimant:	OOI ZI WEI, ID: S8811403E								
Vehicle Reg. No.:	FBD3744Y	Date of Loss:	17/12/2019 17:00 - :59						
Claim Type:	TP / 5225115365SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLU2937G	Policy No. (Claimant):							
		Excess:							
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 03/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (30/12/2019): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE ...

From: Fan, Winnie-LW
To: Admin A, assignments
Cc: Fong, Andy-SY
Sent: 12/23/2019 10:22:20 AM
Attachments:  20122019161720.pdf

Hi LKK,

Kindly assist to survey, bike in.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Pei Qi <pei qi@roypartners.com.sg>
Sent: Friday, December 20, 2019 4:39 PM
To: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Cc: 'MS Group Office' <msgrouppoffice@gmail.com>
Subject: [EXTERNAL] Pre-Repair Inspection

This message is from an external sender; be cautious with links and attachments.

Our Ref: MKR/307/9412/2019/as.pq;

Your Ref: Your insured vehicle no. SLU 2937G;

Dear Sirs,

CLAIMANT: OOI ZI WEI (Owner of FBD 3744Y)

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. FBD 3744Y AND SLU 2937G ALONG SERANGOON ROAD ON 17.12.2019 AT ABOUT 1720 HOURS

We refer to the above matter.

We act for **Ooi Zi Wei**, the owner of motorcycle No. **FBD 3744Y**.

We are instructed by our client to notify you of a road traffic accident on 17.12.2019 at about 1720 hours along Serangoon Road involving our client's motorcycle registration number **FBD 3744Y** and motor car registration number **SLU 2937G**

driven by your insured at the material time. A copy of the Singapore Accident Statement report is attached.

As a result of the accident, our client's motor car **SLJ 6457G** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SLJ 6457G** at our client's repairer workshop, M/s Car Auto Pte Ltd change at **No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875**. Your said surveyor may contact **Desmond and June at 6385 1838**. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Thanks & regards,

Pei Qi

M/s Roy & Partners

133 New Bridge Road

#08-09 Chinatown Point

Singapore 059413

Tel : 6536 8466 Fax : 6536 1963

Email : peiqi@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	403E
Vehicle Details	
Vehicle No.:	FBD3744Y
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	CBR1000RR
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	SC59E2103413
Chassis No.:	JH2SC59AX9K101869
Maximum Power Output:	-
Open Market Value:	\$18,389.00
Original Registration Date:	12 Feb 2009
First Registration Date:	12 Feb 2009
Transfer Count:	7
Actual ARF Paid:	\$2,759.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$3,198.00
COE Rebate Amount:	\$2,921.00
Total Rebate Amount:	\$2,921.00

The information contained herein is correct as at 24 Dec 2019

OK



99

Bike model: Type Of vehicle: Price From: Price To: Class:

[VIEW QUOTE OFFERS](#) [SEARCH](#) [VIEW ALL \(LISTING/USED BIKES/LISTING\)](#)



[REPORT IMAGE](#) [CONTACT SELLER](#) [SHARE](#) [PRINT](#) [COPY URL](#) [COPY URL](#) [COPY URL](#) [COPY URL](#) [COPY URL](#) [COPY URL](#)

Honda CB1000RA

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB1000RA (/listing/usedbike/model/honda-cb1000ra/)
Engine Capacity	998cc
Classification	Class 2 (/listing/usedbike/model/motorcycle-for-sale/class/2/)
Registration Date	02/08/2012
COE Expiry Date	01/08/2022 (2 years 7 months left)
Mileage	83700km
No. of owners	1
Type of Vehicle	Street Bikes (/listing/usedbike/model/motorcycle-for-sale/street-bikes/)

Price: SGD \$14500

SELLER INFORMATION



[\(Viewed 20 times\)](#) [\(Contacted 1 time\)](#) [\(Favourite 0 times\)](#)

★★★★★

RECOMMENDED DEALER

Dynasty Motor Pte Ltd
 (/directory/company/dynasty-motor-pte-ltd/)
 View all used bikes (21)
 Company: (/listing/usedbikes/listing/?user=13427)
 View all new bikes (3)
 (/listing/newbikes/listing/?user=13427)
 30 Bukit Batok Street 23,
 Midview Building #01-24,
 Singapore 658578
 Address: [http://maps.google.com/?q=30+Bukit+Batok+Street+23,+Midview+Building+01-24,+Singapore+658578](#)
 Phone: 68800805
 Fax: 64612337

Name: Contact:
 Email (Kali): +65 92... Click to view
 Email (Kali): +65 94... Click to view

FORMS TO DOWNLOAD

[Agreement Form](#) [Handing Over Form](#)
[Deposit Receipt](#) [Final Receipt](#)
[Private Settlement Form](#)

SIMILAR BIKES

VIEW ALL (LISTING/USED BIKES/LISTING)



Honda CB1000RA



Honda CB1000RA



Honda CB1000RA



Honda CB1000RA



Honda CB1000RA



Honda CB1000RA

[\(/listing/usedbike/honda-cb1000ra/\)](#) [\(/listing/usedbike/honda-cb1000ra/\)](#) [\(/listing/usedbike/honda-cb1000ra/\)](#) [\(/listing/usedbike/honda-cb1000ra/\)](#) [\(/listing/usedbike/honda-cb1000ra/\)](#) [\(/listing/usedbike/honda-cb1000ra/\)](#)

MV-11000
 PV-2921
 NV-8000

EXPLORE SGBIKEMART

Sgbikemart is the Number One Motorcycle Portal in Singapore for buying Singapore bikes, Sportbikes, Superbikes, Dirtbikes, Scooters, Cruisers, COE bike, Scooters, Cabs, Sport Tourers, Super Mutards, Street bikes, Classic bikes, Three wheelers, Parallel imported bikes and more. Buying & selling from new motorcycle distributors, Used motorcycle dealers, Motorcycle accessories & gadgets, apparel & footwear. Search through our motor directory ([https://www.sgbikemart.com.sg/directory](#)) to find your favourite motorbike shop. Post your used motorcycle ([https://www.sgbikemart.com.sg/listing/usedbikes/](#)) & accessories ([https://www.sgbikemart.com.sg/listing/accessories/](#)) for sale in 3 easy steps.

Want to have a hassle free transaction? Our Motorcycle Auction ([https://www.sgbikemart.com.sg/auction/](#)) has one of the easiest ways to sell off your bike immediately. We have our network of traders/dealers able to buy off your bike, just quote the highest price offered, accept and let us help you settle the paperwork.

Our instant motorcycle insurance ([https://www.sgbikemart.com.sg/motorcycle-insurance/](#)) quote provides the cheapest & more affordable premium to all our SGBike members. Get a motorbike insurance quote for less than 30 secs. When you purchase the motor insurance with us, Your motorcycle certificate of insurance will be stored in our Sgbikemart account member's wallet. No more hassle of bringing out the photocopy of the motorcycle insurance card. All you need to do is flash your Sgbikemart App.

Need to rent a motorcycle ([https://www.sgbikemart.com.sg/rent/](#)) to ride around in Singapore or use it as a commutal bike? Go through our list of motorcycles available for rental.

Feature latest motorcycle news ([https://www.sgbikemart.com.sg/blog/](#)), we have all the updated news on new motorcycles, accessories, motorbike reviews, racing events.

Looking for an antique motorcycle number plate ([https://www.sgbikemart.com.sg/listing/plates/](#)) to register for your new motorcycle? Our number plates for sale section has a wide list for transfer.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/12/2019 11:55
Date Of Accident 17/12/2019 17:20
Exact Location Of Accident SERANGOON RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBD3744Y
Insured/Policyholder
Name Of Registered Owner OOI ZI WEI
NRIC No S8811403E
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97997929
Alternative Phone No OFFICE-97997929

Vehicle Particulars

Manufacturer HONDA
Model CBR1000RR
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company FWD SINGAPORE PTE. LTD.
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number PNMC2018-00000606-01
Cover Note Number

Driver

Name of Driver OOI ZI WEI (HUANG ZIWEI)
NRIC No S8811403E
Date Of Birth 11/04/1988
Occupation INDOOR
Date Of Driving Pass 21/11/2013
Driving Experience 6 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97997929
Fax Number
Contact Number OFFICE-97997929
Email Address NOEMAIL

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name OOI ZI WEI (HUANG ZIWEI)

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? FBD3744Y

Were seat belts worn?


Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

Serangoon Rd.



SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS A Police Report T/2019/218/7011

DECLARATION

/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: Date
& Time:

Driver's Signature
(if driver is not the policyholder) Date
& Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LAAPC SketchForm_v1



SINGAPORE POLICE FORCE



T/20191218/7011

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191218/7011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/12/2019 13:29		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: OOI ZI WEI			Address: 1 YOUNGBERG TERRACE #08-14 SINGAPORE 357741		
ID Type / ID No.: NRIC NO / S8811403E			Contact No.: Home/Office:		Mobile: 97997929
Nationality: SINGAPORE CITIZEN			Email: mattheasianguy@yahoo.com.sg		
Sex: Male	Age: 31	Date of Birth: 11/04/1988	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Manufacturing engineer (general)			Driving Licence Information: Class: 2,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/12/2019 17:20	Type of Location: Bend
Location: SERANGOON ROAD				
Weather: Raining		Road Surface: Wet		Road Speed Limit: 60 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD3744Y	Motorcycle	HONDA	CBR1000RR	White		0
SLU2937G	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBD3744Y	FWD Singapore Pte. Ltd	PNMC2018-00000606-01	11/03/2019	10/03/2020



**SINGAPORE
POLICE FORCE**



T/20191218/7011

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191218/7011

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	OOI ZI WEI	ID No.	S8811403E
Related Vehicle	FBD3744Y (Motorcycle)	Contact No.	97997929
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Serious
Driver			
Name	DU BO	ID No.	S8772128J
Related Vehicle	SLU2937G (Car)	Contact No.	82182200
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was travelling from under woodsville flyover turning right towards upper serangoon road. Suddenly i felt a huge impact on the rear of my motorcycle causing to skid and crashed into the barrier infront of me. I stood up and realised that Vehicle No., SLU2937G actually collided into my motorycle.

I felt uncomfortable throughout my body and sustained bruises and bleeding. I then proceeded to a local GP to get treated and received 3 days of MC.



**SINGAPORE
POLICE FORCE**



T/20191218/7011

3 of 3

Report No. T/20191218/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
18/12/2019 13:29

Classification Of Case:

FOR MOTORCYCLE

4. Hot/C. Lat (M)

Motorcycle

Vehicle No: **FBD 37447**

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate	sur	✓	1
3001	992065	Front Tyre			
3002	992095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	R		1
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			1
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			1
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	sur	✓	1
3015	992337	Front Headlamp Bracket			1
3016	992345	Front Headlamp Fairing	sur	✓	1
3017	992130	Front Windshield	sur	✓	1
3018	992134	Front Wing Mirror	sur	✓	1
3019	995245	Front LH Signal Lamp			1
3020	995246	Front RH Signal Lamp	sur	✓	1
3021	992556	Meter Casing			
3022	992553	Meter Assy			
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			1
3029	994427	Steering Cone			1
3030	992299	Handle Bar			1
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH			
3034	992300	Handle Bar Balancer RH	sur	✓	1
3035	992179	Fuel Tank	sur	✓	1
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever			
3038	992293	Hand Brake Lever	sur	✓	1
3039	991119	Side Fairing	sur	✓	1
3040	994220	Side Fairing Top Garnish			1
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield			
3043	992047	Front Top Fairing Inner Garnish			
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing			
3046	993378	Rear Fairing			
3047	991121	Fairing Stopper			
3048	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
3049	995074	Radiator			
3050	992738	Radiator Cowling			
3051	994146	Seat Assy			
3052	990915	Engine Crash Bar			
3053	990928	Engine Case Assy R/H	sur	✓	1
3054	990219	Battery			
3055	990224	Battery Cover			
3056	990223	Battery Bracket			
3057	991144	Foot Brake			
3058	991154	Front Foot Rest R/H	sur	✓	1
3059	991779	Front Foot Rest Bracket R/H	sur	✓	1
3060	994269	Side Stand			
3061	992549	Main Stand			
3062	990615	Clutch Engine Cover R/H	sur	✓	1
3063	992478	Kick Starter Rubber			
3064	992477	Kick Starter Lever			
3065	991145	Foot Gear Shifter			
3066	993500	Rear Foot Rest			
3067	993501	Rear Foot Rest Bracket			
3068	992581	Exhaust Muffler Heat Shield	sur	✓	1
3069	991058	Exhaust Muffler Assy	sur	✓	1
3070	993719	Rear LH Shock Absorber			
3071	993720	Rear RH Shock Absorber			
3072	995065	Rear Tyre			
3073	991200	Rear Rim			
3074	994872	Rear Tyre Rim Spoke			
3075	993474	Rear Fender Wheel Guard			
3076	993443	Rear Fender Mudflap			
3077	992940	Rear Brake Disc			
3078	992936	Rear Brake Caliper			
3079	995236	Rear Spocket			
3080	990585	Chain			
3081	990580	Chain Guard			
3082	994530	Swing Arm			
3083	993819	Rear Sub frame			
3084	995245	Rear LH Signal Lamp			
3085	995246	Rear RH Signal Lamp			
3086	995251	Rear Taillamp			
3087	993626	Rear Number Plate			
3088	994192	Side Box			
3089	992927	Rear Box			
3090	992928	Rear Box Bracket			
3091	991328	Emblem			
3092	990247	Sticker			
3093		Rear Foot Rest R/H	sur	✓	1
3094		Engine Case Assy R/H	sur	✓	1

Page of THREE

Assessor: **H-ANN**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2019 Edit Reg		23 Dec 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	DU BO, Co. Reg. No.: -								
Main Claimant:	OOI ZI WEI, ID: S8811403E								
Vehicle Reg. No.:	FBD3744Y	Date of Loss:	17/12/2019 17:00 - :59 [130 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5225115365SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLU2937G	Policy No. (Claimant):							
		Excess:							
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 03/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (30/12/2019): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBD3744Y (5225115365SG)
[SLU2937G]
TP
OOI ZI WEI
Dec 17 2019 5:00PM
[DU BO]
Ms Car Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print				
1	30/12/19 11:07		Video - Accident											Load MP4						
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print				
1	13/01/20 16:49		General View											Load JPG		☒				
2	13/01/20 16:49		General View											Load JPG		☒				
3	13/01/20 16:49		General View											Load JPG		☒				
4	13/01/20 16:49		General View											Load JPG		☒				
5	13/01/20 16:49		General View											Load JPG		☒				
6	13/01/20 16:49		General View											Load JPG		☒				
7	13/01/20 16:49		General View											Load JPG		☒				
8	13/01/20 16:49		General View											Load JPG		☒				
9	13/01/20 16:49		General View											Load JPG		☒				
10	13/01/20 16:49		General View											Load JPG		☒				
11	13/01/20 16:49		General View											Load JPG		☒				
12	13/01/20 16:49		General View											Load JPG		☒				
13	13/01/20 16:49		General View											Load JPG		☒				
14	13/01/20 16:49		General View											Load JPG		☒				
15	13/01/20 16:49		General View											Load JPG		☒				
16	13/01/20 16:49		General View											Load JPG		☒				
17	13/01/20 16:49		General View											Load JPG		☒				
18	13/01/20 16:49		General View											Load JPG		☒				
19	13/01/20 16:49		General View											Load JPG		☒				
20	13/01/20 16:49		General View											Load JPG		☒				
21	13/01/20 16:49		General View											Load JPG		☒				
22	13/01/20 16:49		General View											Load JPG		☒				
23	13/01/20 16:49		General View											Load JPG		☒				
24	13/01/20 16:49		General View											Load JPG		☒				
25	13/01/20 16:49		General View											Load JPG		☒				
26	13/01/20 16:49		General View											Load JPG		☒				
27	13/01/20 16:49		General View											Load JPG		☒				
28	13/01/20 16:49		General View											Load JPG		☒				
29	13/01/20 16:49		General View											Load JPG		☒				
30	13/01/20 16:49		General View											Load JPG		☒				
31	13/01/20 16:49		General View											Load JPG		☒				
32	13/01/20 16:49		General View											Load JPG		☒				
33	13/01/20 16:49		General View											Load JPG		☒				
34	13/01/20 16:49		General View											Load JPG		☒				

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				☒
35	13/01/20 16:49	General View	 Load JPG	☒
36	13/01/20 16:49	General View	 Load JPG	☒
37	13/01/20 16:49	General View	 Load JPG	☒
38	13/01/20 16:49	General View	 Load JPG	☒
39	13/01/20 16:49	General View	 Load JPG	☒
40	13/01/20 16:49	General View	 Load JPG	☒
41	13/01/20 16:49	General View	 Load JPG	☒
42	13/01/20 16:49	General View	 Load JPG	☒
43	13/01/20 16:49	General View	 Load JPG	☒
44	13/01/20 16:49	General View	 Load JPG	☒
45	13/01/20 16:49	General View	 Load JPG	☒
46	13/01/20 16:49	General View	 Load JPG	☒
47	13/01/20 16:49	General View	 Load JPG	☒
48	13/01/20 16:49	General View	 Load JPG	☒
49	13/01/20 16:49	General View	 Load JPG	☒
50	13/01/20 16:49	General View	 Load JPG	☒
51	13/01/20 16:49	General View	 Load JPG	☒
52	13/01/20 16:49	General View	 Load JPG	☒
53	13/01/20 16:49	General View	 Load JPG	☒
54	13/01/20 16:49	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/12/19 11:07	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022435/HYF3E2

Date: 10/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBD3744Y

Insured Vehicle No : SLU2937G

Date of Loss: 17/12/2019

Nature of Claim: TP

Claim No: 5225115365SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBD3744Y

Make & Model: HONDA CBR1000RR, 998cc

Engine No: SC59E2103413

Reg. Date: 12/02/2009 (Man. Year: 2008)

Chassis No: JH2SC59AX9K101869

Colour: Green/Yellow

Odometer: 53966 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70/17

Rear Tyre Size: 200/55/17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 23/12/2019 Inspected At:

Ms Car Auto Pte Ltd (HQ)

8 KAKI BUKIT AVE 4 #01-07 PREMIER @

KAKI BUKIT

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Repair	0.00 F	*- F
3	1		*FRONT FORK ASSY	* Check	0.00 F	*- F
4	1		*FRONT FORK BRACKET	* Check	0.00 F	*- F
5	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
6	1		*FRONT HEADLAMP BRACKET	* Check	0.00 F	*- F
7	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
8	1		*FRONT WINDSHIELD	Cracked	0.00 F	*- F
9	1		*FRONT WING MIRROR	Cracked	0.00 F	*- F
10	1		*FRONT LH SIGNAL LAMP	* Check	0.00 F	*- F
11	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
12	1		*STEERING STEM	* Check	0.00 F	*- F
13	1		*STEERING CONE	* Check	0.00 F	*- F
14	1		*HANDLE BAR	* Check	0.00 F	*- F
15	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
16	1		*FUEL TANK	Scratched	0.00 F	*- F
17	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
18	1		*SIDE FAIRING	Scratched	0.00 F	*- F
19	1		*SIDE FAIRING TOP GARNISH	* Check	0.00 F	*- F
20	1		*ENGINE HOUSING R/H	Cracked	0.00 F	*- F
21	1		*FRONT FOOT REST R/H	Scratched	0.00 F	*- F
22	1		*FRONT FOOT REST BRACKET R/H	Scratched	0.00 F	*- F
23	1		*CLUTCH ENGINE COVER L/H	Scratched	0.00 F	*- F
24	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
25	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
26	1		*REAR FOOT REST R/H	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >