

ASS. REC. BY:

REC

CS/CT1 19022459/Ht f3²

Speed Instruction:

Surveyor:

Hock Ann

ASSIGNMENT (Office)

From (Person):

Irene Tay Hui Ping

of

CT1

Date/Time:

23.12.19 11:58 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLU 1200E

Insured:

GBJ 2113T

at Workshop n/s

Precision motorworks

Tel:

87427247

of

68 Kari Bukit Ave 6 A01-02 AREA PB

Policy No:

DMCVSR 3014231900

Claim No:

SVM1911206057602

Sum Insured:

Excess:

Make of Veh:

D.O.A

18.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mpv

H.O.D. Endorsement

Date/Time:

23.12.19 1:57pm

Person Contacted:

John

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLU 1200E - NA / CT1 19022459 / 24 D.O.A - 18/12/2019
	GBJ 2113T - NA / CT1 19022459 / 24 D.O.P - 18/12/2019
	30/12/19 - survey taken
	2/1/20 - Rear view taken.
	6/1/20 - 90 deg port taken.

ASS. REC. BY: H-ANN

REF: CTE

PRS

ASSIGNMENT

From: _____ Date: 20/12/19
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLU 1200E
at Workshop m/s precision Motorworks
of 68 keri Bukit Ave 6 # 01-02 ARK
Insured: @ KB
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: After lunch

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLU 1200E Yr Regn: June / 2013
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: BMW 640 c.c. 2079
Colour: red A/C: Insured / Std / NI / NA
Sp. Reading: 78175/km T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBAZW720800K15343
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 255/35/R20
R: 285/30/R20
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 57 mm R/Bal. 57 mm
L/Bal. 57 mm Rear 57 mm
D.O.A. partly air D.O.I. 30/12/19
Survey held at precision motorworks.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SLU 1200E PRS car
	Range > 6.5 - 7.5k
	repair days > 4 days
	mv - 114000
	pv - 10/128
	nv - 12800

7/1/2020

RECEIVED 08 JAN 2020 John

Date/Time, File Pass to? ☐ : Preli. Report
1) 8/1 Typist ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 4
Resurvey No. of Trip: 2

Report Format: PRS
Lump Sum / LBA: G

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	
3 + RS, SI	
Photos	
Others	
TOTAL	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019		23 Dec 2019 11:58 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	THUM SIN WEE		
Vehicle Reg. No.:	SLU1200E	Date of Loss:	18/12/2019 16:00 - :59
Claim Type:	TP / SNM19D206057C02	Policy/Cover Note No.:	DMCVSN3014251900
Vehicle Reg. No. (Insured):	GBJ2113T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Precision Motorworks Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB, 417896 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/01/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 23 December 2019 11:28 AM
To: Jennifer Guay
Cc: assignments@lkkauto.com; admin-a@lkkauto.com
Subject: Re: OUR REF :SNM19D206057/GBJ2113T/IRENE & YOUR REF: AW-INS-P48-112455-19.jgv -TO CONDUCT PRS-SLU1200E

Dear Sir (LKK),

We refer to the above matter and the email below.

Please liaise with PRECISION MOTORWORKS to conduct PRS.

Regards,

Irene Tay

From: Jennifer Guay <jenniferguay@visionlawllc.com>
Sent: Monday, December 23, 2019 11:22 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF :SNM19D206057/GBJ2113T/IRENE & YOUR REF: AW-INS-P48-112455-19.jgv -TO CONDUCT PRS-SLU1200E

PRE - REPAIR SURVEY

CLAIMANT: THUM SIN WEE

ACCIDENT INVOLVING SLU 1200E & GBJ2113T ON 18 DECEMBER 2019 ALONG 107 SERANGOON NORTH CARPARK

Dear Sirs

Refer to your email of 23 December 2019 informing that you wish to conduct a pre-repair survey and to your list of surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyors for your consideration:-

1.B J Loi (Par Automotive Consultancy)

Please be informed that the pre-repair survey of our clients vehicle can be survey as follows :

Venue : Precision Motorworks
68 Kaki Bukit Ave 6,
ARK @ KB 01-02

Singapore 417896

Contact : John (Tel: 8742 7247)

Please let us hear from you by 10 April 2018 . Thank you.

Regards

Jennifer Guay

(Secretary for Ms Audrey Wong)

VISION LAW LLC

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]

Sent: Monday, 23 December, 2019 10:34 AM

To: Jennifer Guay

Cc: Jennifer Guay

Subject: RE: OUR REF :SNM19D206057/GBJ2113T/IRENE & YOUR REF: AW-INS-P48-SLU1200E-19.jgv -TO CONDUCT PRS-SLU1200E

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING

Kelvin Ang

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

XING QUO QIANG

KENNETH KONG

SIMON HO

CHUA WEIJIE

MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Friday, December 20, 2019 5:42 PM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Jennifer Guay <jenniferguay@visionlawllc.com>

Subject: OUR REF :SNM19D206057/GBJ2113T/IRENE & YOUR REF: AW-INS-P48-SLU1200E-19.jgv -TO CONDUCT PRS-SLU1200E

Dear Irene,

Please conduct PRS –SLU1200E - soonest possible and our Insured has not filed SAS Report

File to officer in charge-Irene Tay- DID: 6389 6192.

Dear Jennifer,

**** kindly quote our reference number when replying****

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]

Sent: Friday, December 20, 2019 10:59 AM

To: Claims Dept of CTI

Cc: Precision Motorworks; johnkhor90@gmail.com; tomlim8050@gmail.com

Subject: OUR REF : AW-INS-P48-SLU1200E-19.jgv & YR REF: GNJ 2113 T

PRE - REPAIR SURVEY

CLAIMANT: THUM SIN WEE

ACCIDENT INVOLVING SLU 1200E & GBJ2113T ON 18 DECEMBER 2019 ALONG 107 SERANGOON NORTH CARPARK

Dear Sirs

We are instructed by **THUM SIN WEE** to notify you of a road accident on **18 DECEMBER 2019** at about 16.25hr **ALONG 107 SERANGOON NORTH CARPARK** involving our client's **SLU 1200E & GBJ2113T** driven by your driver at the material time.

As a result of the accident, our client's vehicle has been damage. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For Surveyor

Please initial here after completion of pre-repair survey.
Thank you.

Appointed Surveyor: _____
Name & Signature

Contact: _____

Date & Time _____

Surveyor during repair: _____

Date & Time: _____

Surveyor after repair: _____

Date & Time: _____

Regards

Jennifer Guay
(Secretary)
VISION LAW LLC
133 New Bridge Road #18-01
Chinatown Point

Regards

Jennifer Guay
(Secretary for Ms Audrey Wong)
VISION LAW LLC
133 New Bridge Road #18-01
Chinatown Point
Singapore 059413
Tel : 6534 2811 (Ext 116)
Fax : 6535 6802

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2019 17:17
Date Of Accident	18/12/2019 16:25
Exact Location Of Accident	107 SERANGOON NORTH CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU1200E
Insured/Policyholder	
Name Of Registered Owner	THUM SIN WEE
NRIC No	SXXXX645D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90904664
Alternative Phone No	OFFICE-90904664

Vehicle Particulars

Manufacturer	BMW
Model	640I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00006804-02
Cover Note Number	

Driver

Name of Driver	THUM SIN WEE
NRIC No	SXXXX645D
Date Of Birth	27/04/1982
Occupation	INDOOR
Date Of Driving Pass	06/09/2003
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90904664
Fax Number	
Contact Number	OFFICE-90904664
Email Address	NOEMAIL

Address	BK 107 SERANGOON NORTH AVE 1 #06-685
Postcode	550107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 18/12/2019 AROUND 4.45PM, MY VEHICLE (SLU1200E) WAS PARKED AT LOT 92 107 SERANGOON NORTH AVE 1 CARPARK. VEHICLE (GBJ2113T) REVERSE AND HIT ONTO THE FRONT LEFT OF MY VEHICLE (SLU1200E).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ2113T
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Plot 92

107 Serangoon North Ave 1 Carpark



A - SKU1200E

B - GBJ 2113T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/12/19 Around 4.45 pm, my vehicle
SKU1200E was parked at lot 92 107 Serangoon
North Ave 1 Carpark.
Vehicle GBJ 2113T reverse and hit onto
the front left of my vehicle SKU1200E.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	645D
Vehicle Details	
Vehicle No.:	SLU1200E
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	640i A
Primary Colour:	Gold
Manufacturing Year:	2011
Engine No.:	14967891N55B30A
Chassis No.:	WBALW72080DK15343
Maximum Power Output:	235.0 kW (315 bhp)
Open Market Value:	\$79,608.00
Original Registration Date:	28 Jun 2013
First Registration Date:	28 Jun 2013
Transfer Count:	1
Actual ARF Paid:	\$115,295.00 — 57647
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2023
PARF Rebate Amount:	\$74,941.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,000.00
COE Rebate Amount:	\$26,187.00
Total Rebate Amount:	\$101,128.00

The information contained herein is correct as at 31 Dec 2019

OK

Get Trade 100 Bonus

Enter New Year in style with FBS. Use Trade 100 Bonus and profit with \$100 gift. Start now FBS

BMW 640i

Price Range

Depreciation

2013

Vehicle Type

Home » Used Cars » Global Carz Pte Ltd » BMW 6 Series 640i Gran Coupe

BMW 6 Series 640i Gran Coupe

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREM



GLOBAL CARZ

Price	\$115,800	Reg Date	06-Jun-2013 (3yrs 4mths 29days COE left)
Depreciation ⓘ	\$19,480 /yr View models with similar depre	Manufactured ⓘ	2013
Mileage	94,000 km (14.3k /yr)	Transmission	Auto
Road Tax ⓘ	\$2,362 /yr	OMV ⓘ	\$70,378
Dereg Value ⓘ	\$83,957 as of today (change)	ARF ⓘ	\$98,681
COE ⓘ	\$58,090	Power	235.0 kW (315 bhp)
Engine Cap	2,979 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,825 kg		
Type of Vehicle	Luxury Sedan		

Features

3.0L Inline 6 Cylinders Twin Power Turbocharged Engine Coupled 8 Speed Transmission Producing 315Bhp And 450Nm Torque, 0-100Km/H 5.4 Seconds. View specs of the BMW 6 Series Coupe (2011-2017)

Description

Excellent Condition, Accident Free, Trade In Are Welcome, Powerful Engine And Smooth Transmission. Perfect Condition! Call Us Today To Book Appointment Before It's Gone. 100% Approval! Don't Miss Out This Golden Opportunity And Bring It Home Today!

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Request to have this car evaluated professionally. Find out more

Compare



Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Global Carz Pte Ltd

4 vehicles for sale. 9 sold in past 3 mths

159 Sin Ming Road #01-03

Amtech Building

Tel: 63851484

Search cars nearby

Aloysius
Marcsen87178787
96917236

DOA: 18/12/13

mv - 114000

pv - 10128

NL - 12800

Behaving 3 yrs 6 mths

Age 17000 yrs

17000 km = 14/6

51000 + 8496 + 57647

= 117143



YOUR CLASSIC CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours or the next working day of the incident
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2017-00006804-02

About this policy

Premium paid	: S\$1,268.07	Coverage start date	: 28/12/2019
(Inclusive of GST)		Coverage end date	: 27/12/2020
Who is insured to drive:	: You and any Authorised Driver		
Policy Type	: CLASSIC		

About you (As the policyholder)

Your name	: THUM SIN WEE		
Address	: 107 Serangoon North Avenue 1 #06-685 Singapore 550107		
Email	: stewardsw@hotmail.com		
NRIC/FIN	: S8272645D	Date of birth	: 27/04/1982
Marital status	: Married	Gender	: Male
Current no claims discount	: 50%	Mobile Number	: 90904664
Years of driving experience	: Three or more	Certificate of merit	: Yes

About your car

Car make and model	: BMW 640I CABRIOLET
Year of first registration	: 2013
Car plate number	: SLU1200E
Issued on:	: 18/11/2019

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions and exclusions of this policy.

Please immediately inform us at +65-6820-8888 or email us to contact.sg@fwd.com if any details in this Car Insurance Summary need to be changed.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019		23 Dec 2019 11:58 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	THUM SIN WEE		
Vehicle Reg. No.:	SLU1200E	Date of Loss:	18/12/2019 16:00 - :59 [77 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D206057C02	Policy/Cover Note No.:	DMCVSN3014251900
Vehicle Reg. No. (Insured):	GBJ2113T	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Precision Motorworks Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB, 417896 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 03/01/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU1200E (SNM19D206057C02)**
[GBJ2113T]

TP








































THUM SIN WEE

Dec 18 2019 4:00PM

[-]

Precision Motorworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/12/19 08:28	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	31/12/19 08:28	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
4	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
5	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
6	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
7	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
8	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
9	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
10	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
11	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
12	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
13	31/12/19 08:28	General View	Load JPG	<input checked="" type="checkbox"/>
14	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
15	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
16	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
17	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
18	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
19	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
20	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
21	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
22	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
23	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
24	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
25	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
26	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
27	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
28	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
29	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
30	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
31	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
32	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
33	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
34	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
35	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
36	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
37	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
38	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
39	31/12/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
40	06/01/20 08:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/01/20 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/01/20 08:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
76	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/01/20 09:55	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119022459/HTF3S2

Date: 16/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSN3014251900

Claimant Vehicle No: SLU1200E

Insured Vehicle No: GBJ2113T

Date of Loss: 18/12/2019

Nature of Claim: TP

Claim No: SNM19D206057C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU1200E

Make & Model: BMW 640I, 3.0 (A)

Reg. Date: 28/06/2013 (Man. Year: 2011)

Colour: Red

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 14967891N55B30A

Chassis No: WBALW72080DK15343

Odometer: 78175 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 255/65 R20

Rear Tyre Size: 285/30 R20

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 30/12/2019 Inspected At:

Precision Motorworks Pte Ltd (HQ)
68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB
Singapore 417896

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

1/16/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500.00 - \$7,500.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >