




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19022466/Ags3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN			Date : 29-06-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 9987C	Veh. Inspected	SLW 33S
	Policy No.	VFX/P1680520	Coverage (\$)	0.00
	Claim No.	S9M02AHN	Excess (\$)	0.00
	Assign From		Assign Date	19/12/2019
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 316I	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBA3A12040J720387	Colour	WHITE
	Odometer	131354	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/35 R19	GOODYEAR	6 mm
	L/H Front Tyre	245/35 R19	GOODYEAR	6 mm
	R/H Rear Tyre	245/35 R19	GOODYEAR	6 mm
	L/H Rear Tyre	245/35 R19	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/12/2019	Inspection Date	19/12/2019
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	