

ASS. REC. BY:

REF:

AG/

msf - K2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Est not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

TOTAL

Veh No:

SKX 00887

Yr Regn:

12, 15

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1318

Colour

M. Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

59.199

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK 38 504 X 216837

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

15/12/19

D.O.I.

4/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Attn Edmund JHMGK3850GX216837
SKX8098J

List/buy

1 pc rear bumper ?

br ————— clips ?

1 pc tail gate BT ✓

emblem "JAZZ" ✓

inner lock. rx

1 pc ————— w/ glass moulding rx

CHENG HQ 67557719

① 1 pc rear w/ls gun

#40/5 ✓

② 1 set reverse sensor

#200/5 ✓ X

① R & R rear w/ls glass

#120/ ✓

② R & R rear bumper assy, tail gate
and attachment, moulding. To R & R
rear end panel and heat the same

#500/ 400

③ Buff & respray on rear bumper,
rear panel, & tail gate

#600/ 400

④ Rust proofing

#20/ ✓

> Back to OneMotoring

SKX 8098J
TP/AIG

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	148F
Vehicle Details	
Vehicle No.:	SKX8098J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT ABS D/AIRBAG 2WD
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	L13B11010092
Chassis No.:	JHMGK3850GX216837
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,382.00
Original Registration Date:	29 Dec 2015
First Registration Date:	29 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$9,382.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$7,036.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$34,331.00
Total Rebate Amount:	\$41,367.00

The information contained herein is correct as at 19 Dec 2019

OK