

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
POH
WEI BENG
(FU WEIMING)
BLK 436 JURONG WEST AVENUE 1
#12-452
SINGAPORE 640436

Document no.
Document date 23-12-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019003101/ 1
Job order date 21-12-2019
Service Advisor EDMUND, HUI HUANG GOH

License plate	Model code	First registration	VIN	Model	Mileage
SMR1604C	7N24MYH0	29-11-2019	WVWZZZ7NZKV016297	Sharan Highline 2.0 TSI 162kW DSG	30

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
7N0807417E GRU	Cover For Bumper Primed / <i>DD</i>	1	pcs.	1,144.79	#1	1,144.79	1,224.93
7N0807521C 9B9	Spoiler Satin Black X <i>?</i>	1	pcs.	252.03	#1	252.03	269.67
7N0807863	Attachment Strip <i>?</i>	1	pcs.	178.03	#1	178.03	190.49
	BUMPER CENTRE BRACKET <i>?</i>						
7N0807251A	Foam Insert <i>?</i>	1	pcs.	126.41	#1	126.41	135.26
7N0807305A	Bumper Bracket <i>?</i>	1	pcs.	754.12	#1	754.12	806.91
	(BUMPER REINFORCEMENT)						
7N0807375	Guide Piece <i>?</i>	1	pcs.	76.72	#1	76.72	82.09
	(BUMPER SIDE BRACKET LH)						
7N0807376	Guide Piece <i>?</i>	1	pcs.	76.72	#1	76.72	82.09
	(BUMPER SIDE BRACKET RH)						
7N0827025H	Rear Trunk Lid / <i>DD</i>	1	pcs.	2,734.69	#1	2,734.69	2,926.12
7N0853687 739	Inscription Chrome <i>RPC</i>	1	pcs.	83.72	#1	83.72	89.58
	(SHARAN)						
7P6853630D FOD	Vw Sign Black High Gloss / <i>RPC</i>	1	pcs.	98.06	#1	98.06	104.92
8D0853419D	Packing Adhesive / <i>RPC</i>	1	pcs.	27.03	#1	27.03	28.92
	REAR NUMBER PLATE PACKING X						
3CN945087	Additional Brake Light Wi 3RD BRAKE LIGHT <i>RPC (Take photo)</i>	1	pcs.	208.66	#1	208.66	223.27
1T0919133C 9B9	Seal Ring Satin Black / <i>RPC</i>	1	pcs.	0.69	#1	0.69	0.74
1S0919275C GRU	Sensor Primed <i>?</i>	1	pcs.	164.62	#1	164.62	176.14
D 169300M2	1k Window Adhesive / <i>RPC</i>	2	pcs.	49.88	#1	99.76	106.74
D 00920002	Primer / <i>RPC</i>	1	pcs.	25.92	#1	25.92	27.73
D 00950025	Applicator / <i>RPC</i>	2	pcs.	9.48	#1	18.96	20.29
D 181802M1	Activator For Precoated W / <i>RPC</i>	1	pcs.	24.00	#1	24.00	25.68
D 00940104	All Purpose Cleaner / <i>RPC</i>	1	pcs.	89.95	#1	89.95	96.25
WHT007341	Rivetted Cap Nut / <i>RPC</i>	2	pcs.	1.88	#1	3.76	4.02
	R&R REAR WINDSCREEN GLASS	1	pcs.	840.00	#1	840.00	898.80
	LABOUR	<i>A2</i>	pcs.	840.00	#1 <i>1680</i>	3,360.00	3,595.20
	Spray Painting	<i>A2</i>	pcs.	800.00	#1 <i>1600</i>	3,200.00	3,424.00
	TRANSFER BOOTLID PARTS	<i>A1/2</i>	pcs.	840.00	#1 <i>420</i>	840.00	898.80
	CHECK REAR WATER LEAK TEST <i>RPC</i>	1	pcs.	150.00	#1	150.00	160.50

Quotation valid till 28-12-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	14,578.64	7%	1,073.70	15,338.64	16,412.34
Total	760.00	14,578.64		1,073.70	15,338.64	16,412.34

aftermarket coating claim

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page	2/2
Document no.	
Document date	23-12-2019
Customer no.	5211043795
Customer GST-ID	201009404M
Dealer	39999
Job order number	2019003101/ 1
Job order date	21-12-2019
Service Advisor	EDMUND, HUI HUANG GOH

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
POH
WEI BENG
(FU WEIMING)
BLK 436 JURONG WEST AVENUE 1
#12-452
SINGAPORE 640436

License plate	Model code	First registration	VIN	Model	Mileage
SMR1604C	7N24MYH0	29-11-2019	WVWZZZ7NZKV016297	Sharan Highline 2.0 TSI 162kW DSG	30

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

Steve CLKK) with Pa
24/12/19, 10.45am
6 days
P/P
By Bel Sky

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: