



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19022532/Aga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-04-2020



ATTN: LYNN KHONG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 1648D	Veh. Inspected	SDJ 9893E
Policy No.	GA453021	Coverage (\$)	0.00
Claim No.	S9M02AVS	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	24/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71200991	Colour	WHITE
Odometer	41263	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	CONTINENTAL	6 mm
L/H Front Tyre	185/60 R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/60 R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/60 R15	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/12/2019	Inspection Date	23/12/2019
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------