

22/02/2019

ASS. REC. BY:

REF

CS3/CTF19022560/Asd3^{SY}

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Tan Kah Kong of CTI Date/Time: 21/12/19 @ 11:49am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 5 R Insured: SKJ 8494Y

at Workshop in/s Y3K AUTO Tel: 9640 2541

of 1 Kaki Bukit Ave 6 # 01-49 Autobay

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 22/12/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:16pm @ 21/12/19 Person Contacted: Danny Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	
	SGL 5R - NBA/CTF19022517/h4	DOA: 22/12/2019
	SKJ 8494Y - NBA/CTF19022517/h4	DOA: 22/12/2019

Page No. / Date

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Person)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

DAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP China. PRS.

MV :

PV :

Nett :

Date/Time File Pass to:

13/01/20

ii) Typ: 4

Date/Time File Return to:



: Prel. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee

Transportation

Site Insp

Interview

Photo

Other

Site Insp

Interview

Photo

Other

PRS

RECEIVED 13 JAN 2020

Repair Range : 5K-6K.
No of Days : 5 Days.

SGLSR.

2018 April

Type of Car / Motorcycle / Bus / Van / Heavy / Taxi / Private / Special

Truck / Trailer

Previa.

Make

Toyota ~~Estima~~

2362

Colour

Silver.

A.C.

Insured / Std / HI / NA

Sp. Reading

54779.

T. Radio

Insured / Std / HI / NA

Eng. No.

C/No.

JTEGDS6M107159880

Gen. Cond: ~~Good~~ Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil / ~~S/Rim~~ / STD A/Rim or

Tyre Size:

F:

215/55R17.

R:

215/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / ~~MIC~~ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

24/12/19.

Survey held at

YSK.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 24 December 2019 11:49 AM
To: Jenny; 'assignments'
Cc: 'Ling Leong Hui'; Rachel Ling; 'tcmg backup'
Subject: RE: NOTICE OF PRE-REPAIR INSPECTION FOR VEHICLE NO. SGL 5 R [CHINA TAIPING ref: SKJ 8494 Y]

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Jenny,

We refer to your email of below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jenny [mailto:jenny@tcmg.com.sg]
Sent: Tuesday, December 24, 2019 11:43 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: 'Ling Leong Hui' <lhlh@tcmg.com.sg>; Rachel Ling <jin@tcmg.com.sg>; 'tcmg backup' <tcmg.backup@gmail.com>
Subject: RE: NOTICE OF PRE-REPAIR INSPECTION FOR VEHICLE NO. SGL 5 R [CHINA TAIPING ref: SKJ 8494 Y]
Importance: High

IMMEDIATE ATTENTION

CHINA TAIPING ref: SKJ 8494 Y

Our ref: TCMG/ SGL 5 R /1219/YSK

Dear Sirs

We refer to the above matter and to your email of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.



Our team wishes you and your staff Merry Christmas and Happy New Year.

(P/S : Please acknowledge receipt of this e-mail. Thank you.)

Regards

Jenny Tham
TOMMY CHOO, MARK GO LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876
Tel: 6532 2455 - Fax: 6538 9850
Email Address: jenny@tcmg.com.sg

From: Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]

Sent: Tuesday, 24 December, 2019 11:21 AM

To: jln@tcmg.com.sg

Subject: RE: PRE REPAIR INSPECTION NOTICE FOR SGL 5 R | YOUR REF: SKJ 8494 Y

Without Prejudice

Dear Rachel,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, December 24, 2019 11:16 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; jlin@tcmg.com.sg

Subject: Fw: PRE REPAIR INSPECTION NOTICE FOR SGL 5 R | YOUR REF: SKJ 8494 Y

Dear Kah Leong,

Please assist to conduct PRS -SGL5R soonest possible

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Rachel Ling <jlin@tcmg.com.sg>

Sent: Monday, December 23, 2019 1:04 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: 'Ling Leong Hui' <lhling@tcmg.com.sg>; 'Jenny' <jenny@tcmg.com.sg>; dannyskyeo@gmail.com
<dannyskyeo@gmail.com>

Subject: PRE REPAIR INSPECTION NOTICE FOR SGL 5 R | YOUR REF: SKJ 8494 Y

Our Ref: TCMG/SGL 5 R/1219/YSK

Your Ref: SKJ 8494 Y

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Woo Mun Keong**, the owner and/or driver of motor vehicle no. **SGL 5 R**, which was involved in an accident along junction Hillside Drive on 22nd December 2019 at 15:25 hrs.

We hereby give you NOTICE that we are claiming against your insured motor vehicle no. **SKJ 8494 Y** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s YSK Auto Workshop, (1 Kaki Bukit Avenue 6 #01-49 Autobay, Singapore 417883– Danny Yeo @ 9640 2541).

If we do not hear from you within the next two (2) working days, we shall deem that you have waived the requirement for the pre-repair inspection.

Regards,
Rachel Ling

TOMMY CHOO, MARK GO LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876

Tel: 6532 2455
Fax: 6538 9850

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 11:55
Date Of Accident	22/12/2019 15:25
Exact Location Of Accident	JUNC HILLSIDE DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL5R
Insured/Policyholder	
Name Of Registered Owner	WOO MUN KEONG
NRIC No	SXXXX713B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90604978
Alternative Phone No	OFFICE-90604978

Vehicle Particulars

Manufacturer	TOYOTA
Model	PREVIA AERAS 2.4 CVT MR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MS004540
Cover Note Number	

Driver

Name of Driver	GRACE NG AI WOON
NRIC No	SXXXX854I
Date Of Birth	09/07/1976
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1997
Driving Experience	22 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90604978
Fax Number	
Contact Number	OFFICE-90604978
EMail Address	NOEMAIL

Address	41 LEITH ROAD
Postcode	547908
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WOO YIAT CHEUNG (HU RIZHANG), ZEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ8494Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	90258395
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	GRACE NG AI WOON
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SGL5R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	WOO YIAT CHEUNG (HU RIZHANG), ZEN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SGL5R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 2

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement

[A large diagonal line is drawn across the entire section, from the bottom left to the top right.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING STRAIGHT ALONG THE STATED VENUE. SUDDENLY VEHICLE B CAME OUT FROM MINOR ROAD AND HIT ONTO MY VEHICLE FRONT RIGHT PORTION.

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

VIN:
Date

SGL 5 L
28.12.19 11:12



SGL 5 L

Toyota : Previa/Tarago : ACR50 GSR50

Front : Left

Actual	Before	Specified Range
-0°10'	-0°29'	-0°55' 0°35'
5°57'	5°57'	5°00' 6°30'
0°02'	-0°08'	-0°03' 0°08'
8°12'	8°31'	10°37' 12°07'
8°02'	8°02'	9°42' 12°42'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°28'	0°29'	-0°55' 0°35'
5°57'	5°57'	5°00' 6°30'
0°00'	-0°09'	-0°03' 0°08'
5°26'	5°25'	10°37' 12°07'
5°54'	5°54'	9°42' 12°42'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°38'	-0°58'	
0°00'	0°00'	
2°46'	3°06'	
0°02'	-0°17'	-0°05' 0°15'

Rear : Left

Actual	Before	Specified Range
-1°53'	-1°54'	-1°54' -0°54'
0°06'	0°04'	0°01' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°32'	-1°32'	-1°54' -0°54'
0°12'	0°12'	0°01' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°21'	-0°21'	-0°30' 0°30'
0°19'	0°15'	0°02' 0°32'
-0°03'	-0°04'	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019		27 Dec 2019 08:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	WOO MUN KEONG , ID: S7040713B		
Vehicle Reg. No.:	SGL5R	Date of Loss:	22/12/2019 15:00 - :59 [19 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D206105C02	Policy/Cover Note No.:	DMPCSN30204519000
Vehicle Reg. No. (Insured):	SKJ8494Y	Policy No. (Claimant):	MS004540
		Excess:	S\$500.00
Repairer:	Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-71 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































Claim Documents





































***SGL5R (SNM19D206105C02)**
[SKJ8494Y]

TP
WOO MUN KEONG
Dec 22 2019 3:00PM
[-]
Ysk Auto Workshop



Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/01/20 10:19	General View	 Load JPG	✓
2	13/01/20 10:19	General View	 Load JPG	✓
3	13/01/20 10:19	General View	 Load JPG	✓
4	13/01/20 10:19	General View	 Load JPG	✓
5	13/01/20 10:19	General View	 Load JPG	✓
6	13/01/20 10:19	General View	 Load JPG	✓
7	13/01/20 10:19	General View	 Load JPG	✓
8	13/01/20 10:19	General View	 Load JPG	✓
9	13/01/20 10:19	General View	 Load JPG	✓
10	13/01/20 10:19	General View	 Load JPG	✓
11	13/01/20 10:19	General View	 Load JPG	✓
12	13/01/20 10:19	General View	 Load JPG	✓
13	13/01/20 10:19	General View	 Load JPG	✓
14	13/01/20 10:19	General View	 Load JPG	✓
15	13/01/20 10:19	General View	 Load JPG	✓
16	13/01/20 10:19	General View	 Load JPG	✓
17	13/01/20 10:19	General View	 Load JPG	✓
18	13/01/20 10:19	General View	 Load JPG	✓
19	13/01/20 10:19	General View	 Load JPG	✓
20	13/01/20 10:19	General View	 Load JPG	✓
21	13/01/20 10:19	General View	 Load JPG	✓
22	13/01/20 10:19	General View	 Load JPG	✓
23	13/01/20 10:19	General View	 Load JPG	✓
24	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
25	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
26	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
27	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
28	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
29	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
30	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
31	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
32	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
33	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
34	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
35	13/01/20 10:21	Reinspection Photo	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
37	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
38	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
39	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
40	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
41	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
42	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
43	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
44	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
45	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
46	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
47	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
48	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
49	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
50	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
51	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
52	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
53	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
54	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
55	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
56	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
57	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
58	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
59	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
60	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
61	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
62	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
63	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
64	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
65	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
66	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
67	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
68	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
69	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
70	13/01/20 10:21	Reinspection Photo	 Load JPG	✓
71	13/01/20 10:21	Reinspection Photo	 Load JPG	✓

Linked Accident Report Documents

Assessment Reports			View	View In Browser ▼	1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print		
1	23/12/19 12:05	Accident Statement	 Load HTM			
Photos/Images			3 per page ▼	✓		
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print		
1	23/12/19 12:02	Accident Photo	 Load JPG	✓		
2	23/12/19 12:02	Accident Photo	 Load JPG	✓		

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=900549&extid=326929&... 3/3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19022560/ASD3S2
Date: 03/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30204519000	
Claimant Vehicle No :	SGL5R	Insured Vehicle No :	SKJ8494Y	
Date of Loss:	22/12/2019	Nature of Claim:	TP	Claim No: SNM19D206105C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL5R	Engine No:	2AZ1A65504
Make & Model:	TOYOTA PREVIA AERAS, 2.4 CVT MR (A)	Chassis No:	JTEGD56M107159980
Reg. Date:	27/04/2018 (Man. Year: 2018)	Odometer:	54779 km
Colour:	Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/12/2019		
Date Inspected:	24/12/2019	Inspected At:	Ysk Auto Workshop No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2020)
Parts:	M1-MPV	TOYOTA PREVIA AERAS 2.4 CVT MR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL5R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >