

22/03/2011

ASS. REC. BY:

REF: C83

CTI 19022563/PLD3⁵²

Special Instruction:

Survey: Rasul

ASSIGNMENT (Office)

From (Person): Ben Tang

of

CTI

Date/Time: 24/12/19 @ 11:38am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 1155P

Insured:

YM 73324

at Workshop m/s

Ah Sun Trading

Tel:

6266 2236

of

No. 1 SDON (Lee Street) #02-19

Policy No:

Claim No:

SNM19D206061

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/12/19.

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time: 11:52am @ 24/12/19

Person Contacted:

William

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Telephone X

GBH 1155P - X

YM 73324 - NA / CTI 1902235/13

D.O.A: 19/12/2019

REC BY: PRs

612

1954

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 1155P
 at Workshop m/s: AH SAN TRADING
 of: 1,300N LEE ST #02-19
 Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 57K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBH 1155P Yr Regn: 2018 / Jan
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: TOYOTA DYNA 150 5MT C.C. 2582
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTRAT 35490K209566

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R15C
 R: 155R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Honour

Front

Rear

R/Bal. 6 mm R/Bal. 5/5 mmL/Bal. 6 mm L/Bal. 5/5 mmD.O.A. 19/12/19 D.O.I. 24/12/19Survey held at AH SAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range & days - \$11-\$12K / (12 days)

RECEIVED 03 JAN 2020

Date/Time, File Pass to?

03/01/20

1) Typist

Date/Time, File Return to?

2)

Report Format:

PRs

Lump Sum / U/C / S

Days Of Repair: 12Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Wast exp (\$)

Survey Fee:

Transportation:

3 + RS \$

Photos

Other:

TOTAL

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Tuesday, 24 December 2019 11:38 AM
To: 'Accident@kscgp.com'
Cc: Claims Dept of CTI; 'assignments@lkkauto.com'
Subject: RE: 1st Notice to Conduct Pre-repair Survey - Your Ref: YM7332G Our Ref: GBH1155P/AH/ms/hk

Dear Sirs

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Accident@kscgp.com <Accident@kscgp.com>
Sent: Tuesday, December 24, 2019 11:32 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: 1st Notice to Conduct Pre-repair Survey - Your Ref: YM7332G Our Ref: GBH1155P/AH/ms/hk

Dear Sirs,

We refer to the matter above and your email of even date.

Please see enclosed our 2nd Notice to Conduct Pre-Repair Survey. Our client is not agreeable to your proposed motor surveyors as a Single Joint Expert.

The workshop details are as follows:-

Ah San Trading & Services

No. 1 Soon Lee Street

#02-19 Pioneer Centre

Singapore 627605

Contact person: William (6266 2236)

Thank you.

Regards,
Hong Kuin
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Ben Tang [<mailto:Ben.Tang@sg.cntaiping.com>]

To: accident@kscgp.com

Cc: claimsdept@sg.cntaiping.com

Sent: Tue, 24 Dec 2019 03:19:37 +0000

Subject:

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 24 December 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Tuesday, December 24, 2019 10:57 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; accident@kscgp.com
Subject: Fw: 1st Notice to Conduct Pre-repair Survey - Your Ref: YM7332G Our Ref: GBH1155P/AH/ms/hk

OUR REF: SNM19D206061/YM7332G/BEN

Dear Ben,

Please conduct PRS -GBH1155P- soonest possible

File with officer in charge -Ben Tang- 6389 6175

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Accident@kscgp.com <Accident@kscgp.com>

Sent: Monday, December 23, 2019 5:04 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: 1st Notice to Conduct Pre-repair Survey - Your Ref: YM7332G Our Ref: GBH1155P/AH/ms/hk

Dear Sirs,

We refer to the subject matter.

Please find enclosed a Notice to Conduct Pre-repair Survey herewith for your attention.

Thank you.

Regards,

Hong Kuin

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2019 13:05
Date Of Accident	19/12/2019 09:00
Exact Location Of Accident	HOUANG AVE 3 TURNING DEFU LANE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH1155P
Insured/Policyholder	
Name Of Registered Owner	MAPLE VEHICLE LEASING PTE. LTD.
Co Reg No	201634195H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90072867

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPX/P1899466
Cover Note Number	

Driver

Name of Driver	TAN HOE HAI
NRIC No	S1686198G
Date Of Birth	23/05/1965
Occupation	OUTDOOR
Date Of Driving Pass	07/02/1985
Driving Experience	34 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90049097
Fax Number	
Contact Number	
E-Mail Address	YISHAN@MAPLEFRT.COM.SG

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along HOUGANG AVE 3 it was a 4 lane traffic and my vehicle was positioned in the 4th lane and was going straight. suddenly near DEFU LANE 12 third party vehicle which on the opp side making a right turn dashed out and I was not able to stop my vehicle on time. therefore collided onto third party (GBC1225Y) on the front of passenger side. Another third party vehicle also involved, YM7332G.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC1225Y
Vehicle Make/Model/Colour	KIA / K2900 2.9L M/T 2WD 2DR
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ISLAM AMIRUL
NRIC/Passport Number	G2544796X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YM7332G
Vehicle Make/Model/Colour	ISUZU / NPR85LU5Y
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN HOE HAI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBH1155P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


19 Dec 2019

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER

MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature

Stamp

NSIC/TIN No.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	195H
Vehicle Details	
Vehicle No.:	GBH1155P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2766411
Chassis No.:	JTFAT35Y90K209566
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	04 Jan 2018
First Registration Date:	04 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$13,207.00
COE Rebate Amount:	\$10,594.00
Total Rebate Amount:	\$10,594.00

The information contained herein is correct as at 26 Dec 2019

OK

57,000
10,594

46,403

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2019		02 Jan 2020 16:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[\[Created by insurer\]](#)

CLAIM SUBFOLDER DETAILS

Insured:	-, Co. Reg. No.: -			
Main Claimant:	MAPLE VEHICLE LEASING PTE. LTD.			
Vehicle Reg. No.:	GBH1155P	Date of Loss:	19/12/2019 09:00 - :59 [23 Months and 15 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D206061	Policy/Cover Note No.:	DMCVSN15458019033	
Vehicle Reg. No. (Insured):	YM7332G	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Ah San Motor Trading & Repairing (HQ) 1 Soon Lee Street, #02-19 Pioneer Centre, 627605 Pioneer - Tel: 62264771			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/01/2020]			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH1155P (SNM19D206061)
[YM7332G]**

TP

**MAPLE VEHICLE LEASING PTE. LTD.
Dec 19 2019 9:00AM**

[-]

















































Ah San Motor Trading & Repairing

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
2	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
3	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
4	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
5	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
6	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
7	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
8	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
9	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
10	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
11	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
12	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
13	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
14	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
15	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
16	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
17	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
18	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
19	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
20	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
21	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
22	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
23	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
24	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
25	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
26	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
27	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
28	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
29	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
30	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
31	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
32	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
33	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
34	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
35	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
36	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
37	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
38	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
39	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
40	03/01/20 09:31	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
71	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
72	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
73	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
74	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
75	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
76	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
77	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
78	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
79	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
80	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
81	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
82	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
83	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
84	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
85	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
86	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
87	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
88	03/01/20 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19022563/R1SD3S2

Date: 10/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN15458019033
 Claimant Vehicle No: GBH1155P Insured Vehicle No: YM7332G
 Date of Loss: 19/12/2019 Nature of Claim: TP Claim No: SNM19D206061

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH1155P
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)
 Reg. Date: 04/01/2018 (Man. Year: 2017)
 Colour: Grey
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price
 Engine No: 1KD2766411
 Chassis No: JTFAT35Y90K209566
 Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R15C Rear Tyre Size: 155 R12C(D)
 Front Left Side: Honour 6 mm Rear Left Side: Honour 5/5 mm
 Front Right Side: Honour 6 mm Rear Right Side: Honour 5/5 mm
 The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/01/2020
 Date Inspected: 24/12/2019 Inspected At: Ah San Motor Trading & Repairing (HQ)
 1 Soon Lee Street, #02-19 Pioneer Centre
 Singapore 627605
 Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000.00 - \$12,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jan 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1155P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >