

ASS. REF. NO.

REF: CSI/CTI 190225H / Hs ~~602~~

Special Instruction:

SA/Vojna

Hock Ann

ASSIGNMENT (Office)

From (Person)

Tan Kah Loong

of

CTI

Date/Time

24.12.19 10:05a.m

Estimated Cost

Bill to

OD / TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No.

GBH 8713H

Insured

PA 6468A

at Workshop no.

Jm Anso

Tel.

62898126

of

Blk 14 Defn Lane 10 #01-410/412

Policy No.

DM B15N 16591719033

Claim No.

SAMMD706081

Name Insured

Excess:

Make of Veh

(Client's Record)

D.O.A.

20.12.2019

CA / REV / REP. / REV 24 HRS

Imp

Date/Time

24.12.2019 10:40a.m

Person Contacted

Jouis

R.O.D. Endorsement:

Vehicle

IN/OUT

Date/Time

Action/Description (✓) Estimate

- 62898126@Jouis -

GBH 8713H - X

PA 6468A - X

5/2/20 → \* GBH 8713H Finalised about part/part COR \$ 8199.77 DOR P Lys  
 Agree by workshop invoice person (Jouis) @  
 C \$ 823.20 Red - 9%

ASS. REC. BY: ANNREF: C71

## ASSIGNMENT

From: \_\_\_\_\_ Date: 24.12.2019

Estimated Cost: \_\_\_\_\_

OD: TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBH 8713Hat Workshop n/s: Jm Autoof Bik 14 Dafu Lam 10 #01410 / 412

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S                                 | O/S                                 |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GI/A / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBH 8713HVr Regn: 17/19/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: T. HIACEC.C. 2382Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 29553

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTF HT 02 P500245870

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 195/2/150

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 67 mmR/Bal. 67 mmL/Bal. 67 mmL/Bal. 67 mmD.O.A. 22/12/19D.O.L. 24/12/19Survey held at Jm AutoDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\* workshop required work to do P/P repair

GBH 8713H No issue  
case by 5/1/2020

RECEIVED 10 FEB 2020

10/2/2020

MV - 56000

PV - 22141

NV - 33800

Jouis - 67898126

Date/Time, File Pass to?

10/02/20

1)

Type St

Date/Time, File Return to?

3)

Rep. Form:

Lump Sum 112 = \$ 8,199.77 P/PDays Of Repair: 8Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Ins (\$)

☐

Wind end (\$)

Survey Fee:

Transportation

B + RS \$

Photos

Colours

TOTAL

220

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                    | Est Submitted                              | Adj Assigned                                   | Adj Rpt | Adj Submitted | Inc Auth'd | Status                                               |
|------|---------------------------------------------|--------------------------------------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 23 Dec 2019<br><a href="#">Sendback Est</a> | 23 Dec 2019<br>15:52<br><b>\$57,410.69</b> | 24 Dec 2019<br>10:05<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

#### CLAIM SUBFOLDER DETAILS

|                             |                                                                                                               |                        |                                                                             |
|-----------------------------|---------------------------------------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------------------------|
| Insured:                    | PA6468A, Co. Reg. No.: -                                                                                      |                        |                                                                             |
| Main Claimant:              | D.I.S AIRCONDITIONING & ELECTRICAL PTE LTD, Co. Reg. No.: 1XXXXX350W                                          |                        |                                                                             |
| Vehicle Reg. No.:           | GBH8713H                                                                                                      | Date of Loss:          | 20/12/2019 09:00 - :59<br>[14 Months and 1 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / SNM19D206081/PA6468A/TKL                                                                                 | Policy/Cover Note No.: | DMB15N16591719033                                                           |
| Vehicle Reg. No. (Insured): | PA6468A                                                                                                       | Policy No. (Claimant): |                                                                             |
|                             |                                                                                                               | Excess:                | S\$1,000.00                                                                 |
| Repairer:                   | Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126          |                        |                                                                             |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193] |                        |                                                                             |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/01/2020]                             |                        |                                                                             |
| Driver/Custodian (Insured): | WAN TAILONG ( / Male) Email:                                                                                  |                        |                                                                             |

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Hock Ann (LKK Auto)

---

**From:** Hock Ann (LKK Auto)  
**Sent:** Wednesday, 5 February, 2020 5:25 PM  
**To:** jous  
**Cc:** Shirley Hiew (LKK Auto)  
**Subject:** RE: GBH 8713H FINALIZED

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear jous ,

Good day, o.k will be process base on finalized total amount COR \$ 8199.77 PART/PART REPAIR and DOR 8 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct china taiping insurance claim dept.

Thanks.

Best Regards,  
**Hock Ann** | Assistant Automotive Assessor  
**LKK Auto Consultants**  
Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** jous [mailto:jous@jinauto.com.sg]  
**Sent:** Tuesday, 4 February, 2020 1:31 PM  
**To:** Hock Ann (LKK Auto)  
**Cc:** Shirley Hiew (LKK Auto)  
**Subject:** RE: GBH 8713H FINALIZED

Dear Hock Ann

Ok PART/ PART amount \$ 8199.77 non including GST \$ 573.98

DOR – 8 DAYS

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** Hock Ann (LKK Auto) [<mailto:HockAnn@lkkauto.com>]  
**Sent:** Tuesday, 4 February 2020 10:56 AM  
**To:** [JOUIS@JINAUTO.COM.SG](mailto:JOUIS@JINAUTO.COM.SG)  
**Cc:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>  
**Subject:** RE: GBH 8713H FINALIZED

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear jouis ,

Good day , Kindly attached refer finalized updated calculate adjustment on 4.2.2020

COR - \$ 8199.77

DOR – 8 DAYS

Please refer adjustment updated total PART/ PART amount \$ 8199.77 non including GST \$ 573.98 if agree total PART/PART amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,  
**Hock Ann** | Assistant Automotive Assessor  
**LKK Auto Consultants**  
Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

Insurer Reference: SNM19D206081  
Repairer Reference: GBH8713H  
Date calculated: 31/01/2020 8:49 AM

**Full Report**  
**Registration: GBH8713H**  
**Printed: 31/01/2020 8:49 AM**

### Summary Information

**Claim**

|                        |                |                   |                                             |
|------------------------|----------------|-------------------|---------------------------------------------|
| Location:              | Singapore (SG) | Work Provider:    | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by:            | KK LAU         | Currency:         | SGD                                         |
| Claim Reference:       | SNM19D206081   | Date of Incident: | 20/12/19                                    |
| Estimated Repair Time: | 8              | Hire Car Start:   |                                             |
| Actual Repair Days:    |                | Hire Car End:     |                                             |

### Vehicle Details

**Vehicle**

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | TOYOTA            |
| Model:              | HIACE             |
| Sub Model:          | COMMUTER BUS      |
| Model Sheet Number: | 70 E4 05          |
| Registration:       | GBH8713H          |
| VIN number:         | JTFHT02P500245890 |
| Odometer:           |                   |

**Model Specs**

|                   |                    |                    |                     |
|-------------------|--------------------|--------------------|---------------------|
| AIR CONDITIONING  | LED HEADLAMP       | L/R SLIDING WINDOW | RR BUMPER WITH STEP |
| RAD GRILLE CHROME | 3.0 LTR 100/106 KW | WHEELBASE 3110MM   | CAB WIDTH 1880MM    |
| R/SLIDING DOOR    | BUS                | TWO COAT METALLIC  | PREPARE OFF VEHICLE |


### Vehicle Condition

**Vehicle Status**

Pre-Accident Damage:  
Date of Inspection:

**Damage Areas**

All ☐  
Underbody ☐



Final price  
Amount → \$8199.77  
GST  
GST → \$573.98

## Labour

| Code                             | Description                                                                                                                                                                                 | Time Base 10 WU/h | Price = 42.00 SGD/h |               |
|----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|---------------------|---------------|
|                                  |                                                                                                                                                                                             |                   | WU                  | Price SGD     |
| B020                             | RENEW FRONT BUMPER<br>(BUMPER REMOVED)<br>INCLUDES: R + R FRONT FOG LAMPS                                                                                                                   | 7.0               |                     | 29.40         |
| NO NUMBER                        | R + R CENTRE LOWER RADIATOR GRILLE                                                                                                                                                          | 2.0               |                     | 8.40          |
| B030                             | R + R RADIATOR GRILLE                                                                                                                                                                       | 2.0               |                     | 8.40          |
| B040                             | R + R HEADLAMPS<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS                                                                                                                           | 4.0               |                     | 16.80         |
| 530051                           | RENEW BONNET<br>INCLUDES: ASS ATTACHED PARTS AND IF NECE<br>RENEW                                                                                                                           | 3.0               |                     | 12.60         |
| B125                             | RENEW FRONT LOCK CARRIER                                                                                                                                                                    | 5.0               |                     | 21.00         |
| NO NUMBER                        | RENEW R/F SIDEMEMBER REINFORCEMENT                                                                                                                                                          | 8.0               |                     | 33.60         |
| B290                             | RENEW REAR END PANEL                                                                                                                                                                        | 36.0              |                     | 151.20        |
| B390                             | RENEW TAILGATE<br>INCLUDES: R + R TAILGATE AND NECESSARY<br>ATTACHED PARTS<br>DOES NOT INCLUDE: R + R REAR WINDOW                                                                           | 30.0              |                     | 126.00        |
| B420                             | RENEW REAR BUMPER<br>INCLUDES: REAR BUMPER AND REQUIRED<br>ATTACHED PARTS R + R                                                                                                             | 5.0               |                     | 21.00         |
| B407                             | R + R RIGHT TAIL LAMP                                                                                                                                                                       | 1.0               |                     | 4.20          |
| M010                             | RENEW RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)<br>INCLUDES: INTERCOOLER, ELECTRIC FAN<br>CPL AND REQUIRD ATTACHED PARTS<br>REMOVE AND REFIT.<br>COOLING SYSTEM REFILL AND<br>BLEED. | 22.0              |                     | 92.40         |
| NO NUMBER                        | R + R PRESSURE HOSE                                                                                                                                                                         | 2.0               |                     | 8.40          |
| NN                               | REAR SCREEN R&R / NEW PARTS                                                                                                                                                                 | 24.0*             |                     | 100.80        |
| 3482                             | R/R SIDE PANEL REPAIR                                                                                                                                                                       | 20.0*             |                     | 84.00         |
| 3578                             | R/R CORNER PILLAR REPAIR                                                                                                                                                                    | 10.0*             |                     | 42.00         |
| <b>Labour Cost</b>               |                                                                                                                                                                                             | <b>Hrs</b>        | <b>WU</b>           |               |
| <b>Panel / Mechanical Labour</b> |                                                                                                                                                                                             | <b>18.10</b>      | <b>181.0</b>        | <b>760.20</b> |
| <b>Total of Labour</b>           |                                                                                                                                                                                             |                   |                     | <b>760.20</b> |

## Paint

| Paint Work |                                        | SYSTEM AZT | Time Basis 10 WU/h |           |
|------------|----------------------------------------|------------|--------------------|-----------|
| Code       | Description - TWO COAT METALLIC        |            | WU                 | Price SGD |
|            | BONNET NEW PART PAINTING               |            | 20.0               |           |
|            | FRT LOCK CARRIER CPL SURFACE PAINT     |            | 5.0                |           |
|            | R/F S-MEMBER REINF SURFACE PAINT       |            | 4.0                |           |
|            | FRONT BUMPER NEW PART PAINT K1N        |            | 18.0               |           |
|            | REAR PANEL REPAIR PAINTING >50%        |            | 14.0               |           |
|            | BOOTLID/TAILGATE REPAIR PAINTING >50%  |            | 48.0               |           |
|            | R/R SIDE PANEL REPAIR PAINTING >50%    |            | 39.0               |           |
|            | R/R CORNER PILLAR REPAIR PAINTING >50% |            | 13.0               |           |

## Paint Work

## SYSTEM AZT

Time Basis 10 WU/h

| Code | Description - TWO COAT METALLIC | WU | Price SGD |
|------|---------------------------------|----|-----------|
|------|---------------------------------|----|-----------|

## Paint Material Per Part

| Code | Description                            | Price SGD |
|------|----------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING               | 62.44     |
| 1015 | FRT LOCK CARRIER CPL SURFACE PAINT     | 6.23      |
| 1328 | R/F S-MEMBER REINF SURFACE PAINT       | 1.00      |
| 0281 | FRONT BUMPER NEW PART PAINT K1N        | 87.11     |
| 2711 | REAR PANEL REPAIR PAINTING >50%        | 11.06     |
| 2931 | BOOTLID/TAILGATE REPAIR PAINTING >50%  | 82.95     |
| 3482 | R/R SIDE PANEL REPAIR PAINTING >50%    | 63.99     |
| 3578 | R/R CORNER PILLAR REPAIR PAINTING >50% | 8.69      |

## Labour Cost - Paint

|                                | Hrs            | WU           | Price SGD     |
|--------------------------------|----------------|--------------|---------------|
| Factor                         | 42.00 SGD/h    |              |               |
| Time Paint                     |                | 161.0        |               |
| Preparation Main Work Metal    | 2.50           | 25.0         | 105.00        |
| Preparation Comp. Work Plastic | 0.80           | 8.0          | 33.60         |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>194.0</b> | <b>814.80</b> |

## Material Cost - Paint

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 62.44         |
| New Part Painting - Plastic K1N     | 87.11         |
| Repair Painting                     | 166.69        |
| Surface-/Blend Paint                | 7.23          |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 12.70         |
| <b>Total</b>                        | <b>364.77</b> |

## Spare Parts

|      |                      |                |          | prices as at 2015-06-01/01 |
|------|----------------------|----------------|----------|----------------------------|
| Code | Description          | Part Number    | Supplier | Price SGD                  |
| 1003 | 70KM/HR              | 70KM/H         |          | 10.00                      |
| 3020 | BADGE MODEL          | 75441 26281    |          | 0.00                       |
| 3015 | BADGE TOYOTA         | 90975 02086    |          | 30.00                      |
| 0471 | BONNET               | 53301 26090    |          | 250.00                     |
| 2977 | BOOT/TAILGATE LOCK   | 69350 26131    |          | 100.00                     |
| 2944 | BOOT/TAILGATE SEAL   | 67881 26103    |          | 120.00                     |
| 2931 | BOOTLID/TAILGATE     | 67005 26R20    |          | 780.00                     |
| 4465 | CONDENSER            | 88450 26120    |          | 480.00                     |
| 1011 | CROSS PANEL          | T58127-26050   |          | 40.00                      |
| 1000 | End Panel Sealant    | End Panel Seal |          | 20.00                      |
| 8405 | EXPANSION TANK       | 16470 75123    |          | 150.00                     |
| 1012 | F/RETAINER           | T52115-26150   |          | 50.00                      |
| 7768 | FAN SHROUD           | 16711 30081    |          | 120.00                     |
| 0281 | FRONT BUMPER         | 52119 26670    |          | 160.00                     |
| 1015 | FRT LOCK CARRIER CPL | 53201 26100    |          | 150.00                     |
| 0413 | GRILLE BACKING       | 53112 26100    |          | 180.00                     |



| Code | Description          | Part Number      | Supplier | Price SGD |
|------|----------------------|------------------|----------|-----------|
| 0431 | GRILLE BADGE         | 90975 02176      |          | 0.00      |
| 1008 | GRILLE CLIP          | GRILLE CLIP      |          | 15.00     |
| 1013 | INNERBOARD           | INNERBOARD       |          | 60.00     |
| 8732 | INTERCOOLER BOOSTER  | AIR CLEANER ASSY |          | 300.00    |
| 0561 | LEFT HEADLAMP ASSY   | 81185 26842      |          | 400.00    |
| 0410 | LWR RADIATOR GRILLE  | 53111 26570      |          | 180.00    |
| 1005 | MUDGUARD ARTWK       | MUDGUARD ARTWK   |          | 200.00    |
| 1009 | R/BOOT GARNISH       | T7681126160      |          | 55.00     |
| 1328 | R/F S-MEMBER REINF   | 57016 26020      |          | 65.00     |
| 3282 | R/R LAMP             | 81551 26201      |          | 115.00    |
| 7761 | RADIATOR             | 16400 30163      |          | 650.00    |
| 2581 | REAR BUMPER          | 52159 26570      |          | 180.00    |
| 2711 | REAR PANEL           | 57069 26170      |          | 155.00    |
| 3151 | REAR SCREEN          | 68105 26211      |          | 360.00    |
| 3160 | REAR SCREEN BOND KIT | PZ49I 00C1131    |          | 0.00      |
| 1002 | Reverse Sensor       | Reverse Sensor   |          | 200.00    |
| 0562 | RIGHT HEADLAMP ASSY  | 81145 26842      |          | 400.00    |
| 1001 | SEALANT              | SEALANT          |          | 25.00     |
| 1006 | TAILGATE ARTWK       | TAILGATE ARTWK   |          | 200.00    |
| 1436 | WASHER CONTAINER     | 85315 26110      |          | 60.00     |

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

|                 |          |
|-----------------|----------|
| <b>Savings</b>  | 0.00     |
| <b>Subtotal</b> | 6,260.00 |
| <b>Total</b>    | 6,260.00 |

## Final Calculation

|                                       | SGD      | SGD      |
|---------------------------------------|----------|----------|
| <b>Parts</b>                          | 6,260.00 |          |
| <b>Total Parts</b>                    |          | 6,260.00 |
| <b>Labour Time Base 10 WU/h</b>       |          |          |
| Total 181.0 WU X 42.00 SGD/h          | 760.20   |          |
| <b>Total of Labour</b>                |          | 760.20   |
| <b>Paint Work Time Base 10 WU/h</b>   |          |          |
| Labour Cost 194.0 WU X 42.00 SGD/h    | 814.80   |          |
| Material Cost                         | 364.77   |          |
| <b>Total Paint Including Material</b> |          | 1,179.57 |
| <b>Repair Cost Excludes GST</b>       |          | 8,199.77 |
| GST (+7.00%)                          |          | 573.98   |
| <b>Repair Cost Included GST</b>       |          | 8,773.75 |

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No assessment notes entered.

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Tuesday, 24 December 2019 10:04 AM  
**To:** jouis; 'assignments'  
**Subject:** RE: OUR REF: SNM19D206081/PA6468A/TKL & YOUR REF: GBH8713H -PRS - ACCIDENT INVOLVING VEHICLE GBH8713H ,PC6161Z AND PA6468A ON 20/12/2019

WITHOUT PREJUDICE

Dear Jouis,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong  
Assistant Executive  
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: jouis [mailto:jouis@jinauto.com.sg]  
Sent: Tuesday, December 24, 2019 10:02 AM  
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
Subject: RE: OUR REF: SNM19D206081/PA6468A/TKL & YOUR REF: GBH8713H -PRS -ACCIDENT INVOLVING VEHICLE GBH8713H ,PC6161Z AND PA6468A ON 20/12/2019

Hi Kah Leong ,

Please appoint Marcus Chua .

Thank you & Best Regards,  
Jouis Séow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : jouis@jinauto.com.sg

-----Original Message-----

From: Tan Kah Leong [mailto:KahLeong.Tan@sg.cntaiping.com]  
Sent: Monday, 23 December 2019 5:24 PM  
To: jouis@jinauto.com.sg  
Subject: RE: OUR REF: SNM19D206081/PA6468A/TKL & YOUR REF: GBH8713H -PRS -ACCIDENT INVOLVING VEHICLE GBH8713H ,PC6161Z AND PA6468A ON 20/12/2019

Without Prejudice

Dear Jouis,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong  
Assistant Executive  
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: Claims Dept of CTI  
Sent: Monday, December 23, 2019 1:32 PM  
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; 'jouis@jinauto.com.sg' <jouis@jinauto.com.sg>  
Subject: OUR REF: SNM19D206081/PA6468A/TKL & YOUR REF: GBH8713H -PRS -ACCIDENT INVOLVING VEHICLE GBH8713H ,PC6161Z AND PA6468A ON 20/12/2019  
Importance: High

Dear Kah Leong,

Please conduct PRS-GBH8713H soonest possible.

File to officer-in -charge: Tan Kah Leong -DID 6389 6193.

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: jous [mailto:jouis@jinauto.com.sg]

Sent: Friday, December 20, 2019 2:05 PM

To: Alfred Toh; Claims Dept of CTI

Subject: ACCIDENT INVOLVING VEHICLE GBH8713H ,PC6161Z AND PA6468A ON 20/12/2019

Importance: High

Without Prejudice

Dear Alfred ,

ACCIDENT INVOLVING VEHICLE GBH8713H ,PC6161Z AND PA6468A ON 20/12/2019

We are assisting owner of GBH8713H handling his third party claim recovery against PA6468A .

Have your insured PA6468A reported

Kindly establish liability for this case.

Thank you & Best Regards,

Jouis Seow

Jin Auto Services Pte Ltd

Blk 14 #01-412 Defu Lane 10

Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : jouis@jinauto.com.sg

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                         |
|-------------------------------|-------------------------|
| Owner ID Type:                | Company                 |
| Owner ID:                     | 350W                    |
| Vehicle Details               |                         |
| Vehicle No.:                  | GBH8713H                |
| Vehicle to be Exported:       | No                      |
| Intended Deregistration Date: | 26 Dec 2019             |
| Vehicle Make:                 | TOYOTA                  |
| Vehicle Model:                | HIACE VAN TURBO 5DR MT  |
| Primary Colour:               | White                   |
| Manufacturing Year:           | 2018                    |
| Engine No.:                   | 1KD2829524              |
| Chassis No.:                  | JTFHT02P500245890       |
| Maximum Power Output:         | -                       |
| Open Market Value:            | \$28,136.00             |
| Original Registration Date:   | 19 Oct 2018             |
| First Registration Date:      | 19 Oct 2018             |
| Transfer Count:               | 0                       |
| Actual ARF Paid:              | \$1,407.00              |
| Intended PARF Rebate Details  |                         |
| PARF Eligibility:             | No                      |
| PARF Eligibility Expiry Date: | -                       |
| PARF Rebate Amount:           | \$0.00                  |
| Intended COE Rebate Details   |                         |
| COE Expiry Date:              | 18 Oct 2028             |
| COE Category:                 | C - Goods Vehicle & Bus |
| COE Period(Years):            | 10                      |
| PQP Paid:                     | \$25,134.00             |
| COE Rebate Amount:            | \$22,141.00             |
| <b>Total Rebate Amount:</b>   | <b>\$22,141.00</b>      |

The information contained herein is correct as at 26 Dec 2019

OK



Here is a car loan that's got  
our green light!

### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

32500kms Low Mileage, Car In Tip Top Condition.



Low Mileage In Near New  
Condition - Formal Off Road  
Car.  
Direct Owner - StarArt



**PRIME MOTOR & LEASING**

SEHANG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Browse by Category

Sort by Date Posted

100 results

9 vehicles

Toyota Hiace

Advanced Search

|                                                                                                                                                                                                                                                                                                                                                                                                                                                      | Make                                                                                                                                                                                             | Model                   | Price    | Depreciation | Reg Date    | Eng Cap  | Mileage   | Veh Type | Stat |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|----------|--------------|-------------|----------|-----------|----------|------|
| <b>Search Selection</b>                                                                                                                                                                                                                                                                                                                                                                                                                              | Toyota Hiace                                                                                                                                                                                     |                         | Any      | Any          | 2018        | Any      | Any       | Any      | Av   |
|                                                                                                                                                                                                                                                                                                                                                                      | Toyota Hiace                                                                                                                                                                                     | Commuter 3.0A High Roof | \$71,800 | \$8,440 /yr  | 28-Jun-2018 | 2,982 cc | 288 km    | Bus      | Av   |
| <b>Fuel Type:</b> Diesel<br>Sliding Auto Door.Brand New, 1 Year Road Tax 14 Seaters Mini Bus For Sales! 100% Loan And High Trade-In. Can Register Excursion, Private Hire, Or Private Bus, Call Our Friendly Sales Executive And Find Out More. Price Inclusive Of GST.<br>Tai Huat Automobile<br>Posted: 26-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota                      |                                                                                                                                                                                                  |                         |          |              |             |          |           |          |      |
|                                                                                                                                                                                                                                                                                                                                                                    | Toyota Hiace                                                                                                                                                                                     | 3.0M                    | \$55,800 | \$6,640 /yr  | 21-May-2018 | 2,982 cc | -         | Van      | Av   |
| <b>Fuel Type:</b> Diesel<br>One Owner, Super Low Mileage, Just Done Regular Servicing At Borneo Service Centre, Original Condition, 100% Loan, In House Loan Available, High Trade In Price Offer, Call Now.<br>ABWIN Bus Pte Ltd<br>Posted: 20-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota                                                                                   |                                                                                                                                                                                                  |                         |          |              |             |          |           |          |      |
|                                                                                                                                                                                                                                                                                                                                                                    | Toyota Hiace                                                                                                                                                                                     | Commuter 2.8A           | \$78,800 | \$8,900 /yr  | 01-Nov-2018 | 2,754 cc | -         | Bus      | Av   |
| <b>Fuel Type:</b> Diesel<br>(Hiace Commuter With Front Sensing) Lots Of Safety Features! Come With Lots Of Accessories, High Loan With Low Interest Rate, High Trade In, Call Now To Find Out More!<br>Posted: 18-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota                                                                                                                 |                                                                                                                                                                                                  |                         |          |              |             |          |           |          |      |
|                                                                                                                                                                                                                                                                                                                                                                    | Toyota Hiace                                                                                                                                                                                     | Commuter 3.0A High Roof | \$78,800 | \$8,790 /yr  | 12-Dec-2018 | 2,982 cc | 6,000 km  | Bus      | Av   |
| <b>Fuel Type:</b> Diesel<br>Do We Need To Say? This Baby Has Just Clocked Less Than 6000 Km! Its A Rare Of A Kind In This Leading Toyota Brand In Singapore With Such Condition. Have No Fear On Loan And Insurance As Our Team Are Here To Assist You Throughout The Whole Journey. Call U...<br>Bell Auto Pte Ltd<br>Posted: 14-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota |                                                                                                                                                                                                  |                         |          |              |             |          |           |          |      |
|                                                                                                                                                                                                                                                                                                                                                                    | <b>The Perfection In Suspension Tuning</b><br>R.Logic Suspension System for Japanese & Korean cars. Call us now for more information or drop by our place today!<br>More info about this product |                         |          |              |             |          |           |          |      |
|                                                                                                                                                                                                                                                                                                                                                                    | Toyota Hiace                                                                                                                                                                                     | 3.0M                    | \$58,800 | \$6,800 /yr  | 15-Aug-2018 | 2,982 cc | 17,000 km | Van      | Av   |
| <b>Fuel Type:</b> Diesel<br>New Arrival! (100% Quality Buy!) Super Low Mileage Done At 17000km Only! 1st Owner! (Borneo Motors Unit!) Cheapest In Town! Very Mint Condition! Interior & Exterior Looks Like New! Driver's Seat Plastic Still Intact! Drives Like A New Vehicle! Durable Euro 5 Engine! U...<br>Posted: 07-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota         |                                                                                                                                                                                                  |                         |          |              |             |          |           |          |      |
| Compare                                                                                                                                                                                                                                                                                                                                                                                                                                              | ta Hiace Commuter 2.8A                                                                                                                                                                           |                         | \$77,777 | \$8,810 /yr  | 22-Oct-2018 | 2,754 cc | -         | Bus      | Av   |



**GL High Roof****Fuel Type:** Diesel

High Roof New 14 Seater Toyota Commuter Model! Cheapest In SG! Full Accessories! Can Register Excursion Private Hire Or Private Bus. No Gimmicks! Call Our Sales Executive And Grab It Before It's Gone! Stock Is Limited. Able To Test Drive!

Net Link Partners Pte Ltd

Posted: 29-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

**Toyota Hiace 2.8A DX****\$59,800****\$6,890 /yr****31-Aug-2018****2,754 cc****32,000 km****Van****Av****Fuel Type:** Diesel

Hiace 5 Door Auto With Rear Aircon. Very Well Maintained.

Posted: 19-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

**Toyota Hiace 3.0A DX****\$61,800****\$7,380 /yr****08-May-2018****2,982 cc****-****Van****Av****Fuel Type:** Diesel

May 2018 Toyota Hiace 3.0 Auto 5 Door / With Original Rear Air Con/ Reverse Camera / LED Head Light, Call Us Now.

Think One Automobile &amp; Trading

Posted: 08-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

**Toyota Hiace Commuter 2.8A GL****\$75,800****\$8,590 /yr****22-Oct-2018****2,754 cc****-****Bus****Av****Fuel Type:** Diesel

10/18 Toyota Hiace Commuter 2.8 GL, 14 Seater, New Model.

Think One Automobile &amp; Trading

Posted: 03-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Sort

For old advertisements, view [Expired ads](#)

100  result

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpar insurance. Find buy used Toyota Hiace, Toyota Hiace Singapore, used Toyota Hiace Singapore, used Toyota Hiace, used vehicles Singapore or even buy used Toyota Hiace Singapore new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE result

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                         |
|----------------------------|-------------------------|
| Date Of Report             | 20/12/2019 13:01        |
| Date Of Accident           | 20/12/2019 09:30        |
| Exact Location Of Accident | PIE TO JURONG DIRECTION |
| Country/State Of Loss      | SINGAPORE               |

### DETAILS OF OWN VEHICLE

|                             |                                            |
|-----------------------------|--------------------------------------------|
| Vehicle Registration Number | GBH8713H                                   |
| <b>Insured/Policyholder</b> |                                            |
| Name Of Registered Owner    | D.I.S AIRCONDITIONING & ELECTRICAL PTE LTD |
| Co Reg No                   | 1XXXXX350W                                 |
| Email Address               | NOEMAIL                                    |
| Mobile Phone No             | (LOCAL) +65-87226733                       |
| Alternative Phone No        | OFFICE-87226733                            |

### Vehicle Particulars

|                                                                              |                    |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer                                                                 | TOYOTA             |
| Model                                                                        | HIACE-3.0 D (M)    |
| Exact Purpose for which vehicle was being used at time of accident           | WORKING            |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                 |
| If No, Please state action to be taken                                       | THIRD PARTY        |
| Vehicle Category                                                             | COMMERCIAL VEHICLE |

### Insurance Company

|                           |                                              |
|---------------------------|----------------------------------------------|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD |
| Type Of Coverage          | COMPREHENSIVE                                |
| Fleet Policy              | NO                                           |
| Policy Number             | DMCVSN3076751900                             |
| Cover Note Number         |                                              |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | KARIM REZAUL         |
| Work Permit No       | 0XXXXX186            |
| Date Of Birth        | 05/05/1992           |
| Occupation           | OUTDOOR              |
| Date Of Driving Pass | 13/02/2018           |
| Driving Experience   | 1 YEAR AND 10 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-82014773 |
| Fax Number           |                      |
| Contact Number       |                      |
| Email Address        | NOEMAIL              |



|                                                     |                                     |
|-----------------------------------------------------|-------------------------------------|
| Address                                             | #04-00 WUI HONG BUILDING (S) 408612 |
| Postcode                                            |                                     |
| Was driver an employee of the Insured's Company     | YES                                 |
| If No, Relationship of the Driver with the Insured  |                                     |
| Vehicle Registration Number of Driver's Own Vehicle | -                                   |
|                                                     | -                                   |
| Insurance Company of Driver's Own Vehicle           | -                                   |
|                                                     | -                                   |
|                                                     | -                                   |

#### General Information of the Accident

|                    |                 |
|--------------------|-----------------|
| Type Of Accident   | CHAIN COLLISION |
| Weather Conditions | CLEAR           |
| Road Surface       | DRY             |

#### Other Information

|                                                                                             |                                     |
|---------------------------------------------------------------------------------------------|-------------------------------------|
| Was any foreign vehicle involved in this accident?                                          | NO                                  |
| Number of vehicles (including own vehicle) involved in the accident                         | 3                                   |
| Was any body injured in the Accident?                                                       | NO                                  |
| Was any injured conveyed to hospital by ambulance?                                          |                                     |
| Was any other material or property damaged?                                                 | YES                                 |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                  |
| Number of Passengers (Including Driver)                                                     | 4                                   |
| Passenger 1                                                                                 | NAME: : COLLEAGUE<br>GENDER: : MALE |
| Passenger 2                                                                                 | NAME: : COLLEAGUE<br>GENDER: : MALE |
| Passenger 3                                                                                 | NAME: : COLLEAGUE<br>GENDER: : MALE |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

I WAS DRIVING GBH8713H BEHIND C, WHEN VEHICLE'S C STOPPED I FOLLOW TO STOP IN TIME, SHORTLY A STRONG IMPACT HIT ONTO MY VAN GBH8713H FROM BEHIND AND MY VAN HAD MOVE AHEAD TO BANG ONTO C. UPON CHECKING I WAS INVOLVED IN A VEHICLE'S CHAIN COLLISION. PA6468A WAS THE BUS THAT HIT ONTO MINE.

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | YES |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |             |
|-----------------------------|-------------|
| Vehicle Registration Number | PA6468A     |
| Vehicle Make/Model/Colour   |             |
| Details Of Properties       |             |
| Vehicle Category            | BUS         |
| Name of Driver              | WAN TAILONG |

NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number PC6161Z  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category BUS  
Name of Driver LIM SOO BAN  
NRIC/Passport Number SXXXX270G  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims/collectively the "Purposes"
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reported Centre Person  
Name:  
NRIC/FIN No.:

SKETCH PLAN

Date: 20/12/19

Time: 0930 AM

Place PIE → JURONG


A: GBH 8713 H

B: PA 6468 A

C: PC 6161 Z

Type of Accident:

Chain Collision



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving GBH 8713 H behind C, when vehicle C stopped I follow to stop in time, Shortly a strong impact hit onto my Van GBH 8713 H from behind and my van had move ahead to bang onto C upon checking I was involved in a 3 vehicle's Chain Collision. PA 6468 A was the bus that hit onto mine.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Signature*  
20/12/19  
Date & Time:  
Michael



*Signature*  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*Signature*  
Reporting Officer's Signature  
Name:  
NRIC/FIN No.:



CERTIFICATE OF INSURANCE

**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

**Insurer Reference: SNM19D206081**  
**Repairer Reference: GBH8713H**  
**Date calculated: 24/12/2019 11:19 AM**

**Full Report**  
**Registration: GBH8713H**  
**Printed: 24/12/2019 11:19 AM**

### Summary Information

|                        |                |                   |                                             |
|------------------------|----------------|-------------------|---------------------------------------------|
| <b>Claim</b>           |                |                   |                                             |
| Location:              | Singapore (SG) | Work Provider:    | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by:            | JOUIS SEOW     | Currency:         | SGD                                         |
| Claim Reference:       | SNM19D206081   | Date of Incident: | 20/12/19                                    |
| Estimated Repair Time: | 14 d           | Hire Car Start:   |                                             |
| Actual Repair Days:    |                | Hire Car End:     |                                             |

### Vehicle Details


|                     |                                                                                           |                    |                     |
|---------------------|-------------------------------------------------------------------------------------------|--------------------|---------------------|
| <b>Vehicle</b>      |                                                                                           |                    |                     |
| Manufacturer:       | TOYOTA (Toyota [70])                                                                      |                    |                     |
| Model:              | HIACE (Hiace - KDH2#/LH2#/TRH2# From 12.2013/GDH201 From 01.2017 [E4]/Hiace Commuter Bus) |                    |                     |
| Sub Model:          | COMMUTER BUS                                                                              |                    |                     |
| Model Sheet Number: | 70 E4 05                                                                                  |                    |                     |
| Registration:       | GBH8713H                                                                                  |                    |                     |
| VIN number:         | JTFHT02P500245890                                                                         |                    |                     |
| Odometer:           |                                                                                           |                    |                     |
| <b>Model Specs</b>  |                                                                                           |                    |                     |
| AIR CONDITIONING    | LED HEADLAMP                                                                              | L/R SLIDING WINDOW | RR BUMPER WITH STEP |
| RAD GRILLE CHROME   | 3.0 LTR 100/106 KW                                                                        | WHEELBASE 3110MM   | CAB WIDTH 1880MM    |
| R/SLIDING DOOR      | BUS                                                                                       | TWO COAT METALLIC  | PREPARE OFF VEHICLE |

### Vehicle Condition

**Vehicle Status**  
Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All ☐  
Underbody ☐



## Labour

| Code                      | Description                                                                                                                                                                                 | Time Base 10 WU/h | Price = 42.00 SGD/h |          |       |
|---------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|---------------------|----------|-------|
|                           |                                                                                                                                                                                             |                   | WU                  | Price SG |       |
| B091                      | R + R RIGHT FRONT WING                                                                                                                                                                      |                   | X 1.0               | 4.2      |       |
| B020                      | RENEW FRONT BUMPER<br>(BUMPER REMOVED)<br>INCLUDES: R + R FRONT FOG LAMPS                                                                                                                   |                   | 7.0                 | 29.4     |       |
| NO NUMBER                 | R + R L/F BUMPER MOUNTING                                                                                                                                                                   |                   | X 1.0               | 4.2      |       |
| NO NUMBER                 | R + R CENTRE LOWER RADIATOR GRILLE                                                                                                                                                          |                   | 2.0                 | 8.4      |       |
| B030                      | R + R RADIATOR GRILLE                                                                                                                                                                       |                   | 2.0                 | 8.4      |       |
| B040                      | R + R HEADLAMPS<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS                                                                                                                           |                   | 4.0                 | 16.8     |       |
| 530051                    | RENEW BONNET<br>INCLUDES: ASS ATTACHED PARTS AND IF NECE<br>RENEW                                                                                                                           |                   | 3.0                 | 12.6     |       |
| B080                      | R + R BONNET HINGE/S                                                                                                                                                                        |                   | X 1.0               | 4.2      |       |
| B125                      | RENEW FRONT LOCK CARRIER                                                                                                                                                                    |                   | 5.0                 | 21.0     |       |
| B290                      | RENEW REAR END PANEL                                                                                                                                                                        |                   | 36.0                | 151.2    |       |
| B390                      | RENEW TAILGATE<br>INCLUDES: R + R TAILGATE AND NECESSARY<br>ATTACHED PARTS<br>DOES NOT INCLUDE: R + R REAR WINDOW                                                                           |                   | 30.0                | 126.0    |       |
| B420                      | RENEW REAR BUMPER<br>INCLUDES: REAR BUMPER AND REQUIRED<br>ATTACHED PARTS R + R                                                                                                             |                   | 5.0                 | 21.0     |       |
| B407                      | R + R RIGHT TAIL LAMP                                                                                                                                                                       |                   | 1.0                 | 4.2      |       |
| M010                      | RENEW RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)<br>INCLUDES: INTERCOOLER, ELECTRIC FAN<br>CPL AND REQUIRD ATTACHED PARTS<br>REMOVE AND REFIT.<br>COOLING SYSTEM REFILL AND<br>BLEED. |                   | 22.0                | 92.4     |       |
| NN                        | REAR SCREEN R&R / NEW PARTS                                                                                                                                                                 |                   | 24                  | 28.0*    | 117.6 |
| 1008                      | remove shelves remove shelves                                                                                                                                                               | ? - photo X (not) |                     |          |       |
| 3482                      | R/R SIDE PANEL REPAIR                                                                                                                                                                       |                   | 30.0*               | 126.0    |       |
| 3578                      | R/R CORNER PILLAR REPAIR                                                                                                                                                                    |                   | 25.0*               | 105.0    |       |
| Labour Cost               |                                                                                                                                                                                             | Hrs               | WU                  |          |       |
| Panel / Mechanical Labour |                                                                                                                                                                                             | 20.30             | 203.0               |          | 852.6 |
| Total of Labour           |                                                                                                                                                                                             |                   |                     |          | 852.6 |

## Paint

| Paint Work |                                       | SYSTEM AZT | Time Basis 10 WU/h |           |
|------------|---------------------------------------|------------|--------------------|-----------|
| Code       | Description - TWO COAT METALLIC       |            | WU                 | Price SGD |
|            | BONNET NEW PART PAINTING              |            | 20.0               |           |
|            | FRT LOCK CARRIER CPL SURFACE PAINT    |            | 5.0                |           |
|            | FRONT BUMPER NEW PART PAINT K1N       |            | 18.0               |           |
|            | REAR PANEL REPAIR PAINTING >50%       |            | 14.0               |           |
|            | BOOTLID/TAILGATE REPAIR PAINTING >50% |            | 48.0               |           |
|            | R/R SIDE PANEL REPAIR PAINTING >50%   |            | 39.0               |           |



| Code   | Description           | Part Number    | Supplier  | Price SGD |
|--------|-----------------------|----------------|-----------|-----------|
| - 3015 | BADGE TOYOTA          | 90975 02086 ✓  | me        | 30.00     |
| 3020   | BADGE MODEL           | 75441 26281    | X NN      | 0.00      |
| - 3151 | REAR SCREEN           | 68105 26211 ✓  | CRA       | 360.00    |
| 3160   | REAR SCREEN BOND KIT  | PZ49I 00C1131  | X NN      | 0.00      |
| - 3282 | R/R LAMP              | 81551 26201 ✓  | CRA       | 115.00    |
| - 4465 | CONDENSER             | 88450 26120    | st        | 500.00    |
| - 7761 | RADIATOR              | 16400 30163    | X (suc) ✓ | 600.00    |
| - 1000 | End Panel Sealant     | End Panel Seal | ✓         | 45.00     |
| - 1001 | SEALANT               | SEALANT        | ✓         | 25.00     |
| - 1002 | Reverse Sensor        | Reverse Sensor | ✓         | 200.00    |
| 1003   | 70KM/HR               | 70KM/H         | ✓         | 10.00     |
| 1004   | HIACE STICKER         | HIACE STICKER  | X NN      | 20.00     |
| - 1005 | MUDGUARD ARTWK        | MUDGUARD ARTWK | ✓         | 350.00    |
| - 1006 | TAILGATE ARTWK        | TAILGATE ARTWK | ✓         | 350.00    |
| 1007   | NO.PLATE LAMP GARNISH | NO.PLATE LAMP  | X NN      | 60.00     |

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**  
**Subtotal**  
**Total**

**0.00**  
**5,560.00**  
**5,560.00**

## Final Calculation

|                                       | SGD      | SGD      |
|---------------------------------------|----------|----------|
| <b>Parts</b>                          |          |          |
| <b>Total Parts</b>                    | 5,560.00 | 5,560.00 |
| <b>Labour Time Base 10 WU/h</b>       |          |          |
| Total 203.0 WU X 42.00 SGD/h          | 852.60   |          |
| <b>Total of Labour</b>                |          | 852.60   |
| <b>Paint Work Time Base 10 WU/h</b>   |          |          |
| Labour Cost 190.0 WU X 42.00 SGD/h    | 798.00   |          |
| Material Cost                         | 363.77   |          |
| <b>Total Paint Including Material</b> |          | 1,161.77 |
| <b>Repair Cost Excludes GST</b>       | 9022.97  | 7,574.37 |
| GST (+7.00%)                          |          | 530.21   |
| <b>Repair Cost Included GST</b>       |          | 8,104.58 |

## Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.

26/12/19 P/P up  
without prejudice  
before paint  
Resurvey  
Hock ANN  
8511883

Hock ANN@lkk-auto.com  
24/12/19  
11:15pm  
Hock

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

| Code | Description - TWO COAT METALLIC        | WU   | Price SGD |
|------|----------------------------------------|------|-----------|
|      | R/R CORNER PILLAR REPAIR PAINTING >50% | 13.0 |           |

## Paint Material Per Part

| Code | Description                            | Price SGD |
|------|----------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING               | 62.44     |
| 1015 | FRT LOCK CARRIER CPL SURFACE PAINT     | 6.23      |
| 0281 | FRONT BUMPER NEW PART PAINT K1N        | 87.11     |
| 2711 | REAR PANEL REPAIR PAINTING >50%        | 11.06     |
| 2931 | BOOTLID/TAILGATE REPAIR PAINTING >50%  | 82.95     |
| 3482 | R/R SIDE PANEL REPAIR PAINTING >50%    | 63.99     |
| 3578 | R/R CORNER PILLAR REPAIR PAINTING >50% | 8.69      |

## Labour Cost - Paint

|                                | Hrs            | WU           | Price SGD    |
|--------------------------------|----------------|--------------|--------------|
| Factor                         | 42.00 SGD/h    |              |              |
| Time Paint                     |                | 157.0        |              |
| Preparation Main Work Metal    | 2.50           | 25.0         | 105.00       |
| Preparation Comp. Work Plastic | 0.80           | 8.0          | 33.60        |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>19.00</b> | <b>190.0</b> |

## Material Cost - Paint

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 62.44         |
| New Part Painting - Plastic K1N     | 87.11         |
| Repair Painting                     | 166.69        |
| Surface-/Blend Paint                | 6.23          |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 12.70         |
| <b>Total</b>                        | <b>363.77</b> |

## Spare Parts

prices as at 2015-06-01/01

| Code   | Description          | Part Number | Supplier   | Price SGD |
|--------|----------------------|-------------|------------|-----------|
| * 0281 | FRONT BUMPER         | 52119 26670 | ✓ cut      | 160.00    |
| 0317   | L/F INNER COVER BRKT | 52116 26170 | X NN       | 65.00     |
| * 0410 | LWR RADIATOR GRILLE  | 53111 26570 | ✓ CRA      | 180.00    |
| 0411   | UPP RADIATOR GRILLE  | 53111 26560 | X (SVC)    | 80.00     |
| * 0413 | GRILLE BACKING       | 53112 26100 | ✓ CRA      | 180.00    |
| 0431   | GRILLE BADGE         | 90975 02176 | X NN       | 25.00     |
| * 0471 | BONNET               | 53301 26090 | ✓ St       | 250.00    |
| 0476   | RIGHT BONNET HINGE   | 53410 26040 | X (K)      | 30.00     |
| * 0562 | RIGHT HEADLAMP ASSY  | 81145 26842 | ✓ CRA      | 400.00    |
| - 1015 | FRT LOCK CARRIER CPL | 53201 26100 | ✓ St       | 150.00    |
| * 2581 | REAR BUMPER          | 52159 26570 | ✓ cut DD   | 180.00    |
| - 2711 | REAR PANEL           | 57069 26170 | ? photo St | 155.00    |
| - 2931 | BOOTLID/TAILGATE     | 67005 26R20 | ✓ St       | 780.00    |
| - 2944 | BOOT/TAILGATE SEAL   | 67881 26103 | ✓ new DI   | 120.00    |
| 2973   | REAR LOCK CATCH      | 69430 95J01 | X (SVC)    | 40.00     |
| - 2977 | BOOT/TAILGATE LOCK   | 69350 26131 | ✓ Jm       | 100.00    |

**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

**Insurer Reference: SNM19D206081**  
**Repairer Reference: GBH8713H**  
**Date calculated: 15/01/2020 2:16 PM**

**Full Report**  
**Registration: GBH8713H**  
**Printed: 15/01/2020 2:19 PM**

### Summary Information

|                        |                |                   |                                             |
|------------------------|----------------|-------------------|---------------------------------------------|
| <b>Claim</b>           |                |                   |                                             |
| Location:              | Singapore (SG) | Work Provider:    | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by:            | KK LAU         | Currency:         | SGD                                         |
| Claim Reference:       | SNM19D206081   | Date of Incident: | 20/12/19                                    |
| Estimated Repair Time: | 14 8           | Hire Car Start:   |                                             |
| Actual Repair Days:    |                | Hire Car End:     |                                             |

### Vehicle Details

|                     |                    |                    |                     |
|---------------------|--------------------|--------------------|---------------------|
| <b>Vehicle</b>      |                    |                    |                     |
| Manufacturer:       | TOYOTA             |                    |                     |
| Model:              | HIACE              |                    |                     |
| Sub Model:          | COMMUTER BUS       |                    |                     |
| Model Sheet Number: | 70 E4 05           |                    |                     |
| Registration:       | GBH8713H           |                    |                     |
| VIN number:         | JTFHT02P500245890  |                    |                     |
| Odometer:           |                    |                    |                     |
| <b>Model Specs</b>  |                    |                    |                     |
| AIR CONDITIONING    | LED HEADLAMP       | L/R SLIDING WINDOW | RR BUMPER WITH STEP |
| RAD GRILLE CHROME   | 3.0 LTR 100/106 KW | WHEELBASE 3110MM   | CAB WIDTH 1880MM    |
| R/SLIDING DOOR      | BUS                | TWO COAT METALLIC  | PREPARE OFF VEHICLE |


### Vehicle Condition

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All ☐  
Underbody ☐



## Labour

| Code                             | Description                                                                                                                                                                                 | Time Base 10 WU/h   | Price = 42.00 SGD/h |               |
|----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|---------------------|---------------|
|                                  |                                                                                                                                                                                             |                     | WU                  | Price SGD     |
| B020                             | RENEW FRONT BUMPER<br>(BUMPER REMOVED)<br>INCLUDES: R + R FRONT FOG LAMPS                                                                                                                   | ✓ 7.0               |                     | 29.40         |
| ✓ NO NUMBER                      | R + R CENTRE LOWER RADIATOR GRILLE                                                                                                                                                          | ✓ 2.0               |                     | 8.40          |
| ✓ B030                           | R + R RADIATOR GRILLE                                                                                                                                                                       | ✓ 2.0               |                     | 8.40          |
| ✓ B040                           | R + R HEADLAMPS<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS                                                                                                                           | ✓ 4.0               |                     | 16.80         |
| 530051                           | RENEW BONNET<br>INCLUDES: ASS ATTACHED PARTS AND IF NECE<br>RENEW                                                                                                                           | ✓ 3.0               |                     | 12.60         |
| ✓ B125                           | RENEW FRONT LOCK CARRIER                                                                                                                                                                    | ✓ 5.0               |                     | 21.00         |
| NO NUMBER                        | RENEW R/F SIDEMEMBER REINFORCEMENT                                                                                                                                                          | ✓ 8.0               |                     | 33.60         |
| ✓ B290                           | RENEW REAR END PANEL                                                                                                                                                                        | ✓ 36.0              |                     | 151.20        |
| ✓ B390                           | RENEW TAILGATE<br>INCLUDES: R + R TAILGATE AND NECESSARY<br>ATTACHED PARTS<br>DOES NOT INCLUDE: R + R REAR WINDOW                                                                           | ✓ 30.0              |                     | 126.00        |
| ✓ B420                           | RENEW REAR BUMPER<br>INCLUDES: REAR BUMPER AND REQUIRED<br>ATTACHED PARTS R + R                                                                                                             | ✓ 5.0               |                     | 21.00         |
| ✓ B407                           | R + R RIGHT TAIL LAMP                                                                                                                                                                       | ✓ 1.0               |                     | 4.20          |
| ✓ M010                           | RENEW RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)<br>INCLUDES: INTERCOOLER, ELECTRIC FAN<br>CPL AND REQUIRD ATTACHED PARTS<br>REMOVE AND REFIT.<br>COOLING SYSTEM REFILL AND<br>BLEED. | ✓ 22.0              |                     | 92.40         |
| NO NUMBER                        | R + R PRESSURE HOSE                                                                                                                                                                         | ✓ 2.0               |                     | 8.40          |
| ✓ NN                             | REAR SCREEN R&R / NEW PARTS                                                                                                                                                                 | ✓ 24 hrs 28.0*100.8 |                     | 117.60        |
| ✓ 3482                           | R/R SIDE PANEL REPAIR                                                                                                                                                                       | 20 hrs 30.0*84      |                     | 126.00        |
| ✓ 3578                           | R/R CORNER PILLAR REPAIR                                                                                                                                                                    | 10 hrs 25.0*142     |                     | 105.00        |
| <b>Labour Cost</b>               |                                                                                                                                                                                             | <b>Hrs</b>          | <b>WU</b>           |               |
| <b>Panel / Mechanical Labour</b> |                                                                                                                                                                                             | <b>21.00</b>        | <b>210.0</b>        | <b>882.00</b> |
| <b>Total of Labour</b>           |                                                                                                                                                                                             |                     |                     | <b>882.00</b> |

## Paint

| Paint Work |                                        | SYSTEM AZT |  | Time Basis 10 WU/h |           |
|------------|----------------------------------------|------------|--|--------------------|-----------|
| Code       | Description - TWO COAT METALLIC        |            |  | WU                 | Price SGD |
|            | BONNET NEW PART PAINTING               |            |  | 20.0               |           |
|            | FRT LOCK CARRIER CPL SURFACE PAINT     |            |  | 5.0                |           |
|            | R/F S-MEMBER REINF SURFACE PAINT       |            |  | 4.0                |           |
|            | FRONT BUMPER NEW PART PAINT K1N        |            |  | 18.0               |           |
|            | REAR PANEL REPAIR PAINTING >50%        |            |  | 14.0               |           |
|            | BOOTLID/TAILGATE REPAIR PAINTING >50%  |            |  | 48.0               |           |
|            | R/R SIDE PANEL REPAIR PAINTING >50%    |            |  | 39.0               |           |
|            | R/R CORNER PILLAR REPAIR PAINTING >50% |            |  | 13.0               |           |

## Code Description - TWO COAT METALLIC

WU Price SGD

## Paint Material Per Part

| Code | Description                            | Price SGD |
|------|----------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING               | 62.44     |
| 1015 | FRT LOCK CARRIER CPL SURFACE PAINT     | 6.23      |
| 1328 | R/F S-MEMBER REINF SURFACE PAINT       | 1.00      |
| 0281 | FRONT BUMPER NEW PART PAINT K1N        | 87.11     |
| 2711 | REAR PANEL REPAIR PAINTING >50%        | 11.06     |
| 2931 | BOOTLID/TAILGATE REPAIR PAINTING >50%  | 82.95     |
| 3482 | R/R SIDE PANEL REPAIR PAINTING >50%    | 63.99     |
| 3578 | R/R CORNER PILLAR REPAIR PAINTING >50% | 8.69      |

## Labour Cost - Paint

|                                | Hrs          | WU           | Price SGD     |
|--------------------------------|--------------|--------------|---------------|
| Factor                         |              |              | 42.00 SGD/h   |
| Time Paint                     |              | 161.0        |               |
| Preparation Main Work Metal    | 2.50         | 25.0         | 105.00        |
| Preparation Comp. Work Plastic | 0.80         | 8.0          | 33.60         |
| <b>Total</b>                   | <b>19.40</b> | <b>194.0</b> | <b>814.80</b> |

## Material Cost - Paint

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 62.44         |
| New Part Painting - Plastic K1N     | 87.11         |
| Repair Painting                     | 166.69        |
| Surface-/Blend Paint                | 7.23          |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 12.70         |
| <b>Total</b>                        | <b>364.77</b> |

## Spare Parts

| Code | Description          | Part Number | Supplier                   | prices as at 2015-06-01/01 | Price SGD |
|------|----------------------|-------------|----------------------------|----------------------------|-----------|
| 0281 | FRONT BUMPER         | 52119 26670 | ✓ conf                     |                            | 160.00    |
| 0410 | LWR RADIATOR GRILLE  | 53111 26570 | ✓ am                       |                            | 180.00    |
| 0413 | GRILLE BACKING       | 53112 26100 | ✓ chm                      |                            | 180.00    |
| 0431 | GRILLE BADGE         | 90975 02176 | x (not used, needs handle) | x NN                       | 0.00      |
| 0471 | BONNET               | 53301 26090 | ✓ st                       |                            | 250.00    |
| 0561 | LEFT HEADLAMP ASSY   | 81185 26842 | ✓ WRA                      | AA                         | 400.00    |
| 0562 | RIGHT HEADLAMP ASSY  | 81145 26842 | ✓ WRA                      | ✓                          | 400.00    |
| 1015 | FRT LOCK CARRIER CPL | 53201 26100 | ✓ st                       |                            | 150.00    |
| 1328 | R/F S-MEMBER REINF   | 57016 26020 | ✓ st                       | (import part)              | AA 65.00  |
| 1436 | WASHER CONTAINER     | 85315 26110 | ✓ CPU                      | (Radiator, tank)           | AA 60.00  |
| 2581 | REAR BUMPER          | 52159 26570 | ✓                          | DO ✓                       | 180.00    |
| 2711 | REAR PANEL           | 57069 26170 | ✓ st                       | ✓                          | 155.00    |
| 2931 | BOOTLID/TAILGATE     | 67005 26R20 | ✓ st                       | ✓                          | 780.00    |
| 2944 | BOOT/TAILGATE SEAL   | 67881 26103 | ✓                          | DO ✓                       | 120.00    |
| 2977 | BOOT/TAILGATE LOCK   | 69350 26131 | ✓ Jm                       | ✓                          | 100.00    |
| 3015 | BADGE TOYOTA         | 90975 02086 | ✓ am                       | ✓                          | 30.00     |

| Code | Description                     | Part Number    | Supplier                 | Price SGD |
|------|---------------------------------|----------------|--------------------------|-----------|
| 3020 | BADGE MODEL                     | 75441 26281    | X NN                     | 0.00      |
| 3151 | REAR SCREEN                     | 68105 26211    | ✓ CRA ✓                  | 360.00    |
| 3160 | REAR SCREEN BOND KIT            | PZ49I 00C1131  | X NN                     | 0.00      |
| 3282 | R/R LAMP                        | 81551 26201    | ✓ CRA ✓                  | 115.00    |
| 4465 | CONDENSER                       | 88450 26120    | ✓ BT ✓                   | 480.00    |
| 7761 | RADIATOR                        | 16400 30163    | ✓ BT ✓                   | 650.00    |
| 7768 | FAN SHROUD                      | 16711 30081    | ✓ CRA (fan shroud) AA    | 120.00    |
| 8405 | EXPANSION TANK                  | 16470 75123    | ✓ CRA (washer tank) AA   | 150.00    |
| 8732 | INTERCOOLER BOOSTER AIR CLEANER | RASSY          | ✓ CRA (Radiator tank) AA | 300.00    |
| 1000 | End Panel Sealant               | End Panel Seal | ✓ CRA 20                 | 45.00     |
| 1001 | SEALANT                         | SEALANT        | ✓ CRA                    | 25.00     |
| 1002 | Reverse Sensor                  | Reverse Sensor | ✓ CRA                    | 200.00    |
| 1003 | 70KM/HR                         | 70KM/H         | ✓ CRA                    | 10.00     |
| 1005 | MUDGUARD ARTWK                  | MUDGUARD ARTWK | ✓ CRA 200                | 350.00    |
| 1006 | TAILGATE ARTWK                  | TAILGATE ARTWK | ✓ CRA 200                | 350.00    |
| 1008 | GRILLE CLIP                     | GRILLE CLIP    | ✓ CRA AA                 | 15.00     |
| 1009 | R/BOOT GARNISH                  | T7681126160    | ✓ CRA AA                 | 55.00     |
| 1010 | PLATE BACKDOOR                  | T6793526190    | X (SVC) AA               | 50.00     |
| 1011 | CROSS PANEL                     | T58127-26050   | ✓ BT AA (SVC 12.4m) AA   | 40.00     |
| 1012 | F/RETAINER                      | T52115-26150   | ✓ CRA AA                 | 50.00     |
| 1013 | INNERBOARD                      | INNERBOARD     | ✓ CRA AA (Car boot)      | 60.00     |

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**  
**Subtotal**

**Total**

0.00  
6,635.00  
6,635.00

## Final Calculation

|                                       | SGD      | SGD      |
|---------------------------------------|----------|----------|
| <b>Parts</b>                          | 6,635.00 |          |
| <b>Total Parts</b>                    |          | 6,635.00 |
| <b>Labour Time Base 10 WU/h</b>       |          |          |
| Total 210.0 WU X 42.00 SGD/h          | 882.00   |          |
| <b>Total of Labour</b>                |          | 882.00   |
| <b>Paint Work Time Base 10 WU/h</b>   |          |          |
| Labour Cost 194.0 WU X 42.00 SGD/h    | 814.80   |          |
| Material Cost                         | 364.77   |          |
| <b>Total Paint Including Material</b> |          | 1,179.57 |
| <b>Repair Cost Excludes GST</b>       |          | 8,696.57 |
| GST (+7.00%)                          |          | 608.76   |
| <b>Repair Cost Included GST</b>       |          | 9,305.33 |

## Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21/1/20 10:00 AM  
checked by H. ANW  
workshop updated  
supplied items  
but for this estimate  
finalised A

GBH 8713 H

Part labor only



total \$ 62 60 #



CREDIT  
COUNSELLING  
SINGAPORE

Cre



f Connect with Facebook

HOME

NEW CARS

USED CARS

COMMERCIAL VEH

RENTAL CARS

SELL CARS

MOTOR DIRECTORY

Home &gt; Used Commercial Veh &gt; Toyota Hiace 3.0M (COE till 11/2021)

## TOYOTA HIACE 3.0M (COE TILL 11/2021)

OVERVIEW

GALLERY

Share



STCARS.SG

SG CAR MART.COM



|                   |                  |  |
|-------------------|------------------|--|
| Price             | \$17,800         |  |
| Registration Date | 22-Dec-2006      |  |
| COE Remaining     | 1yr 10mths 8days |  |
| Manufactured      | 2006             |  |
| Mileage           | -                |  |
| No. of Owners     | 2                |  |
| Transmission      | Manual           |  |
| Engine Capacity   | 2,982 cc         |  |
| Fuel Type         | Diesel           |  |
| COE               | \$24,191         |  |
| Paper Value       | \$4,494          |  |
| Depreciation      | \$9,580 / year   |  |
| Type              | Van              |  |

Recognise For Its Reliability. Buy With A Peace Of Mind As All Wear And Tear Done Up With New Paintwork. Call Our Friendly Sales Person For Viewing And Test Drive.

For full set of photos and payment break-down, <https://www.sgcar mart...=878539&Dl=3494>

Status: Available | Category: COE Vehicles, Diesel Vehicles

Date Posted: 06-Jan-2020 | Date Updated: 06-Jan-2020

## SELLER INFORMATION

## Pan Pac Automobile Pte Ltd

8 Chang Charn Road (map)

68711109

ISSAC

91695221

ALEX

87972000

" SAY YOU SAW THIS AD ON  
STCARS.SG! "



## SIMILAR VEHICLES



Toyota Liteace 2.2M (COE  
till 03/2022)  
21-Nov-2002  
\$16,838



Opel Combo 1.7M (COE till  
12/2024)  
28-Dec-2009  
\$19,800



Suzuki Every (COE till  
11/2023)  
17-Nov-2008  
\$17,800



Fiat Doblo Cargo Maxi 1.9M  
(COE till 07/2024)  
15-Jul-2009  
\$17,800

## SELLING YOUR

Get The Best Price From  
Exclusive List Of Car Dea



Click to find out more!



## USED VEHICLE SEARCH

Vehicle Make / Vehicle Model

Category

Vehicle Type

Transmission

Engine Cap

Min Price

Max Price

Min Depreciation

Max Depre

From Reg Year

To Reg Year

## VEHICLE TOOLS

COE Results

Loan Calc

Post an Ad

Road Tax

Carpark Rates

Car Insur

IS YOUR CAR DUE FOR  
SCRAP  
OR  
EXPORT?



We help you get the  
BEST PRICE for your vehicle!

## LIFESTYLE

Food &amp; Beverage

Health Ci

Home Needs

IT Prod

Men's Fashion

Men's Ho

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                             |                                     |                                      |                               |                         |            |                                          |
|--------------------------|-----------------------------|-------------------------------------|--------------------------------------|-------------------------------|-------------------------|------------|------------------------------------------|
| Case                     | Notified                    | Est Submitted                       | Adj Assigned                         | Adj Rpt                       | Adj Submitted           | Ins Auth'd | Status                                   |
| Main                     | 23 Dec 2019<br>Sendback Est | 23 Dec 2019<br>15:52<br>\$57,410.69 | 24 Dec 2019<br>10:05<br>Edit Adj Rpt | \$58,199.77<br>Edit Estimates | \$58,199.77<br>View Rpt |            | Pending for Survey Report<br>Cancel Case |

| Main                                                                                                                                       | Reference | Claim Details                                                                             | Documents  | Show All |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------------------------------------------------------------------|------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                             |           |                                                                                           |            |          |         |             |              |            |       |
| Insured: PA6468A, Co. Reg. No.: -                                                                                                          |           |                                                                                           |            |          |         |             |              |            |       |
| Main Claimant: D.I.S AIRCONDITIONING & ELECTRICAL PTE LTD, Co. Reg. No.: 1XXXXX350W                                                        |           |                                                                                           |            |          |         |             |              |            |       |
| Vehicle Reg. No.: GBH8713H                                                                                                                 |           | Date of Loss: 20/12/2019 09:00 - :59<br>[14 Months and 1 Days From LTA Reg Date (Man Yr)] |            |          |         |             |              |            |       |
| Claim Type: TP / SNM19D206081/PA6468A/TKL                                                                                                  |           | Policy/Cover Note No.: DMB1SN16591719033                                                  |            |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): PA6468A                                                                                                        |           | Policy No. (Claimant):                                                                    |            |          |         |             |              |            |       |
|                                                                                                                                            |           | Excess: \$51,000.00                                                                       |            |          |         |             |              |            |       |
| Repairer: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126                             |           |                                                                                           |            |          |         |             |              |            |       |
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]            |           |                                                                                           |            |          |         |             |              |            |       |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 06/01/2020]                  |           |                                                                                           |            |          |         |             |              |            |       |
| Driver/Custodian (Insured): WAN TAILONG ( / Male) Email:                                                                                   |           |                                                                                           |            |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>                                                 |           |                                                                                           |            |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                           |           |                                                                                           |            |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |           |                                                                                           |            |          |         |             |              |            |       |
| Due Date                                                                                                                                   | Priority  | Type                                                                                      | Task Group | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                |           |                                                                                           |            |          |         |             |              |            |       |

## Claim Documents

GBH8713H (SNM19D206081/PA6468A/TKL)  
[PA6468A]  
TP  
D.I.S AIRCONDITIONING & ELECTRICAL PTE LTD  
Dec 20 2019 9:00AM  
[PA6468A]  
Jin Auto Services Pte Ltd

|                    |                 |                                   |               |  |                                                                                                |  |                                     |  |                                     |
|--------------------|-----------------|-----------------------------------|---------------|--|------------------------------------------------------------------------------------------------|--|-------------------------------------|--|-------------------------------------|
| Upload Documents   |                 |                                   | Upload Photos |  | Compose New Letter                                                                             |  | View <div>View in Browser</div>     |  |                                     |
| Video              |                 |                                   |               |  |                                                                                                |  | 1 per page                          |  | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | Jin Auto Services Pte Ltd (Defu)  |               |  | Thumbnail                                                                                      |  | Print                               |  |                                     |
| 1                  | 23/12/19 15:51  | Video - Accident                  |               |  |  Load MP4   |  |                                     |  |                                     |
| Assessment Reports |                 |                                   |               |  |                                                                                                |  | 1 per page                          |  | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | Jin Auto Services Pte Ltd (Defu)  |               |  | Thumbnail                                                                                      |  | Print                               |  |                                     |
| 1                  | 23/12/19 15:52  | Repairer Estimates                |               |  |  Load HTM   |  |                                     |  |                                     |
| Photos/Images      |                 |                                   |               |  |                                                                                                |  | 3 per page                          |  | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | Jin Auto Services Pte Ltd (Defu)  |               |  | Thumbnail                                                                                      |  | Print                               |  |                                     |
| 1                  | 16/01/20 12:31  | artwork                           |               |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |                                     |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  | Thumbnail                                                                                      |  | Print                               |  |                                     |
| 1                  | 26/12/19 09:00  | Chassis Number                    |               |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |                                     |
| 2                  | 26/12/19 09:01  | Odometer Reading                  |               |  |  Load JPG  |  | <input checked="" type="checkbox"/> |  |                                     |
| 3                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 4                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 5                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 6                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 7                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 8                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 9                  | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 10                 | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 11                 | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 12                 | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 13                 | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 14                 | 26/12/19 09:01  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 15                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 16                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 17                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 18                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 19                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 20                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 21                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 22                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 23                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 24                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 25                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 26                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 27                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 28                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |
| 29                 | 26/12/19 09:02  | General View                      |               |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |                                     |

| Video |                |                                  | 1 per page                                                                            | <input checked="" type="checkbox"/> |
|-------|----------------|----------------------------------|---------------------------------------------------------------------------------------|-------------------------------------|
| No    | Finalized On   | Jin Auto Services Pte Ltd (Defu) | Thumbnail                                                                             | Print                               |
|       |                |                                  |                                                                                       | <input checked="" type="checkbox"/> |
| 30    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 31    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 32    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 33    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 34    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 35    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 36    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 37    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 38    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 39    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 40    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 41    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 42    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 43    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 44    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 45    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 46    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 47    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 48    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 49    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 50    | 26/12/19 09:02 | General View                     |    | <input checked="" type="checkbox"/> |
| 51    | 26/12/19 09:02 | General View                     |   | <input checked="" type="checkbox"/> |
| 52    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 53    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 54    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 55    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 56    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 57    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 58    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 59    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 60    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 61    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 62    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 63    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 64    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 65    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 66    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 67    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 68    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 69    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 70    | 26/12/19 09:02 | General View                     |  | <input checked="" type="checkbox"/> |
| 71    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 72    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 73    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 74    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 75    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 76    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 77    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |
| 78    | 26/12/19 09:03 | General View                     |  | <input checked="" type="checkbox"/> |

| Video |                |                                  | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------|----------------|----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No    | Finalized On   | Jin Auto Services Pte Ltd (Defu) | Thumbnail                                                                                      | Print                               |
| 79    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 80    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 81    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 82    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 83    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 84    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 85    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 86    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 87    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 88    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 89    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 90    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 91    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 92    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 93    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 94    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 95    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 96    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 97    | 26/12/19 09:03 | General View                     |  Load JPG   | <input checked="" type="checkbox"/> |
| 98    | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 99    | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 100   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 101   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG  | <input checked="" type="checkbox"/> |
| 102   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 103   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 104   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 105   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 106   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 107   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 108   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 109   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 110   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 111   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 112   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 113   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 114   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 115   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 116   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 117   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 118   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 119   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 120   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 121   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 122   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 123   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 124   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 125   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 126   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 127   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 128   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |

| Video |                |                                  | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------|----------------|----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No    | Finalized On   | Jin Auto Services Pte Ltd (Defu) | Thumbnail                                                                                      | Print                               |
| 129   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 130   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 131   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 132   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 133   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 134   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 135   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 136   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 137   | 31/12/19 09:00 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 138   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 139   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 140   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 141   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 142   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 143   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 144   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 145   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 146   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 147   | 31/12/19 09:01 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 148   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 149   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 150   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG   | <input checked="" type="checkbox"/> |
| 151   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG  | <input checked="" type="checkbox"/> |
| 152   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 153   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 154   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 155   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 156   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 157   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 158   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 159   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 160   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 161   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 162   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 163   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 164   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 165   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 166   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 167   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 168   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 169   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 170   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 171   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 172   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 173   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 174   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 175   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 176   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 177   | 31/12/19 09:03 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |
| 178   | 31/12/19 09:04 | Reinspection Photo               |  Load JPG | <input checked="" type="checkbox"/> |



| Video         |                 |                                   | 1 per page |                                     |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Finalized On    | Jin Auto Services Pte Ltd (Defu)  | Thumbnail  | Print                               |
| 179           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 180           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 181           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 182           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 183           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 184           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 185           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 186           | 31/12/19 09:04  | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 187           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 188           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 189           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 190           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 191           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 192           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 193           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 194           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 195           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 196           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 197           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 198           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 199           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 200           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 201           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 202           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 203           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 204           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 205           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 206           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 207           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| 208           | 03/01/20 08:30  | After Repair Photo                |            | <input checked="" type="checkbox"/> |
| Documentation |                 |                                   | 1 per page |                                     |
| No            | Finalized On    | Jin Auto Services Pte Ltd (Defu)  | Thumbnail  | Print                               |
| 1             | 23/12/19 15:51  | AUDATEX                           |            |                                     |
| 2             | 23/12/19 15:51  | E-filed GIA report                |            |                                     |
| 3             | 16/01/20 12:27  | Purchase Invoice                  |            |                                     |
| 4             | 16/01/20 12:28  | Purchase Invoice                  |            | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 11/02/20 16:02  | GBH8713H - AUDATEX .pdf           |            |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                                                  |  | Reset | Save | Print |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------|------|-------|
| There are no document checklists configured.                                                                                                                                         |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>                                         |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |





# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022571/KSF3E2

Date: 12/02/2020

### REFERENCE

|                       |                                               |                      |                   |           |                          |
|-----------------------|-----------------------------------------------|----------------------|-------------------|-----------|--------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMB1SN16591719033 |           |                          |
| Claimant Vehicle No : | GBH8713H                                      | Insured Vehicle No : | PA6468A           |           |                          |
| Date of Loss:         | 20/12/2019                                    | Nature of Claim:     | TP                | Claim No: | SNM19D206081/PA6468A/TKL |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                    |             |                   |
|-----------------------------|------------------------------------|-------------|-------------------|
| Reg No:                     | GBH8713H                           | Engine No:  | 1KD2829524        |
| Make & Model:               | TOYOTA HIACE, 3.0 D TURBO 5 DR (M) | Chassis No: | JTFHT02P500245890 |
| Reg. Date:                  | 19/10/2018 (Man. Year: 2018)       | Odometer:   | 29553 km          |
| Colour:                     | White                              |             |                   |
| Engine Capacity:            | 2982 cc                            |             |                   |
| Market Value/New Car Price: | N/A                                |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price         |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195 R15C         | Rear Tyre Size:  | 195 R15C         |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference     | Diff %        |
|-------------------------------|-----------------|-----------------|----------------|---------------|
| Parts                         | 5,480.00        | 6,260.00        | -780.00        | -14.23        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00           |               |
| Labour                        | 1,930.69        | 1,939.77        | -9.08          | -0.47         |
| Paintwork Labour              | 0.00            | 0.00            | 0.00           |               |
| Towing                        | 0.00            | 0.00            | 0.00           |               |
| <b>Gross Total (S\$)</b>      | <b>7,410.69</b> | <b>8,199.77</b> | <b>-789.08</b> | <b>-10.65</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>518.75</b>   | <b>573.98</b>   | <b>-55.23</b>  | <b>-10.65</b> |
| <b>Nett Amount (S\$)</b>      | <b>7,929.44</b> | <b>8,773.75</b> | <b>-844.31</b> | <b>-10.65</b> |

### INSPECTION

|                             |            |                   |                                                                                          |
|-----------------------------|------------|-------------------|------------------------------------------------------------------------------------------|
| Date of Assignment:         | 24/12/2019 | Present Location: | Jin Auto Services Pte Ltd (Defu)                                                         |
| Date Inspected:             | 24/12/2019 | Inspected At:     | Jin Auto Services Pte Ltd (Defu)<br>Blk 14 Defu Lane 10, #01-410/412<br>Singapore 539195 |
| Estimated Period of Repair: | 8.0 days   |                   |                                                                                          |

Adjuster: LEE HOCK ANN

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                                     |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 12 Feb 2020)                       |
| <b>Parts:</b>        | 213                                                                                                                                                                          | TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                   |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBH8713H)                                                                                                                                    |                                                                     |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                     |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                     |

## Recommended Parts

| No.               | Qty | Part No. | Particulars                           | Condition   | Repairer's | Amount      |
|-------------------|-----|----------|---------------------------------------|-------------|------------|-------------|
| 1                 | 1   |          | *Total parts                          |             | 5,480.00 F | *4,945.00 F |
| 2                 | 1   |          | *LEFT HEADLAMP ASSY                   | Cracked     | -          | *400.00 F   |
| 3                 | 1   |          | *R/F S-MEMBER REINF                   | Bent        | -          | *65.00 F    |
| 4                 | 1   |          | *WASHER CONTAINER                     | Crushed     | -          | *60.00 F    |
| 5                 | 1   |          | *FAN SHROUD                           | Cracked     | -          | *120.00 F   |
| 6                 | 1   |          | *EXPANSION TANK                       | Crushed     | -          | *150.00 F   |
| 7                 | 1   |          | *INTERCOOLER BOOSTER AIR CLEANER ASSY | Cracked     | -          | *300.00 F   |
| 8                 | 1   |          | *GRILLE CLIP                          | Necessary   | -          | *15.00 F    |
| 9                 | 1   |          | *R/BOOT GARNISH                       | Crushed     | -          | *55.00 F    |
| 10                | 1   |          | *CROSS PANEL                          | Bent        | -          | *40.00 F    |
| 11                | 1   |          | *F/RETAINER                           | Necessary   | -          | *50.00 F    |
| 12                | 1   |          | *INNERBOARD                           | Cracked     | -          | *60.00 F    |
| 13                | 1   |          | *PLATE BACKDOOR                       | Serviceable | -          | *- F        |
| Total Parts (S\$) |     |          |                                       |             | 5,480.00   | 6,260.00    |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's | Amount   |
|-------------------------|--------------|----------|------------|----------|
| <u>Labour Items</u>     |              |          |            |          |
| 1                       | total labour | New      | 852.60     | 760.20   |
| 2                       | total paint  | New      | 1,078.09   | 1,179.57 |
| Gross Labour Cost (S\$) |              |          | 1,930.69   | 1,939.77 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >