

2/10/2017

ASS. REC. BY:

REF CS3/ Lp 19019520/ R11B-1

Special Instruction:

Surveyor: Rosa

ASSIGNMENT (Office)

From (Person):

Gerald Bh

of

LP^C

Date/Time:

24.11.2019
5.11.19 12.29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 4460P

Insured:

XE 1865D

at Workshop m/s:

AAK Logistics Services

Tel:

6 6650190 / 66776227

of

4 Penjurah close

Policy No:

Claim No:

191191191 VC06/022587

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/10/2019

CA / REV / REP. / REV 24 HRS

map

H.O.D. Endorsement:

Date/Time:

5.11.19 1.43p.m

Person Contacted:

Pe: Juan

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

return original to LPC.
full set.GY 4460P - XXE1865D - Xlump sum \$4750, 7 days
(Red: 750, 13%)6/- file pass to typist.30/12/2019

RECEIVED 06 JAN 2020

ASS. REQ. BY:

REF: LPC

388t

COE: 2024 / July

ASSIGNMENT

From:

Date:

6.11.2019

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No:

GY 4460P

at Workshop m/s

AAK Logistics Services

of

4 Panjuru Close

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

30k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GY 4460P

Yr Regn: 2005 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HILUX MANUAT C.C. 2494

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

483457

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFH502P300012688

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GIR

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/10/19

D.O.I.

06/11/19 3.05pm

Survey held at

AAK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 NOV 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format:

PR3

Lump Sum / LEI: (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (%)☐ : Weekend (%)

Survey Fee:


Transportation:

S + RS \$

Photos

Others

TOTAL



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 19/19/19/VC06/022587

Your Ref : CS3/LPC19019520/R1cf3s2

13 December 2019

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF GY4460P

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of GY4460P
- b) GIA report GY4460P
- c) GIA report and photos of XE1865D

Kindly study the documents and let us have your report by 27 December 2019.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2019 17:32
Date Of Accident	29/10/2019 13:00
Exact Location Of Accident	TPE EXPRESSWAY BEFORE EXIT 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY4460P
Insured/Policyholder	
Name Of Registered Owner	RHINO RENTAL PTE LTD
Co Reg No	201325388E
Email Address	INFO@RHINORENTAL.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62548858
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE-2.0 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5107952193-000032
Cover Note Number	
Driver	
Name of Driver	VASANTHAN ASHOKKUMAR
NRIC No	G6872388X
Date Of Birth	23/03/1977
Occupation	OUTDOOR
Date Of Driving Pass	25/04/2019
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90366563
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	C/O 26 KAKI BUKIT PLACE
Postcode	416204
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER'S DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1865D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

31/10/19 @ 4.40pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

V. Ashok Kumar

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along TPE before exit 2 around 1pm on 29/10/19. I ~~also~~ changed lane from the third lane to the second lane. After changing lane, the driver of XE1865D did not notice and hit onto the back of my vehicle.

* Third Party claim other workshop - Rhino *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2019 17:32
Date Of Accident	29/10/2019 13:00
Exact Location Of Accident	TPE EXPRESSWAY BEFORE EXIT 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY4460P
Insured/Policyholder	
Name Of Registered Owner	RHINO RENTAL PTE LTD
Co Reg No	201325388E
Email Address	INFO@RHINORENTAL.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62548858

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-2.0 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number 5107952193-000032

Cover Note Number

Driver

Name of Driver VASANTHAN ASHOKKUMAR

NRIC No G6872388X

Date Of Birth 23/03/1977

Occupation OUTDOOR

Date Of Driving Pass 25/04/2019

Driving Experience 0 YEAR AND 6 MONTH

Gender MALE

Mobile Number (LOCAL) +65-90366563

Fax Number

Contact Number

EMail Address NOEMAIL

Address	C/O 26 KAKI BUKIT PLACE
Postcode	416204
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER'S DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1865D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
(Date & Time)

31/10/18 @ 4:40pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

V. Doharaj

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along TPE before exit 2 around 1pm on 29/10/19. I also changed lane from the third lane to the second lane. After changing lane, the driver of XF1865D did not notice and hit onto the back of my vehicle.

* Third Party claim other workshop - Rhino *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time
Company Chop (if applicable)

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	388E
Vehicle No.:	GY4460P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	2KD1242632
Chassis No.:	JTFH502P300012688
Maximum Power Output:	-
Open Market Value:	\$23,804.00
Original Registration Date:	05 Apr 2005
First Registration Date:	05 Apr 2005
Transfer Count:	3
Actual ARF Paid:	\$1,191.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,880.00
COE Rebate Amount:	\$13,133.00
Total Rebate Amount:	\$13,133.00

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 07 Nov 2019

OK

30,000
13,133
16,867

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2019 09:06
Date Of Accident	29/10/2019 12:35
Exact Location Of Accident	TPE TWDS PUNGGOL (LAMP POST 38)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE1865D
Insured/Policyholder	
Name Of Registered Owner	PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD
Co Reg No	200304394R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68583477

Vehicle Particulars

Manufacturer	ISUZU
Model	CYH52S
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/19/VC06/105097
Cover Note Number	

Driver

Name of Driver	MUTHUVEL BALU
Passport No/FIN	G7334196K
Date Of Birth	05/04/1979
Occupation	OUTDOOR
Date Of Driving Pass	05/04/2017
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94232480
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	421 TAGORE INDUSTRIAL AVENUE #04-06/07
Postcode	787815
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY4460P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/HIN No.:



Nabilah

Sketch Plan Pg. 2

SKETCH PLAN

Vehicle A - XE 1865D

Vehicle E = G/4460 P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE:	ACCIDENT DATE & TIME:
CONTACT NUMBER:	E-MAIL ADDRESS:
LOCATION:	
On 29/10/2019 around 1236 hrs, Vehicle A from TPE toward Punggol (lamp post 38) at lane 3 suddenly Vehicle B cut onto lane 3 and emergency slow down therefore Vehicle A collided to Vehicle B rear portion.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy	<input type="checkbox"/> Claim Third Party
<input type="checkbox"/> Claim OD/TP at other workshop	<input type="checkbox"/> Reporting Only

DECLARATION

/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature:
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature
Name: Namalak
NIC/PH No.:



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref : PP/ET/CT.4460.TP.11-19

25 November 2019

M/s Rhino Rental Pte Ltd
c/o 4 Penjuru Close
Singapore 608574

WITHOUT PREJUDICE

Dear Sirs,

**Re : Third Party Claim
Vehicle Registration No. GY 4460 P**

We refer to your instruction to appraise the above-mentioned vehicle on 5 November 2019.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs **AAK Logistics Services Pte Ltd** for **\$12,575.65** as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is **\$6,884.61**. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for **\$5,500.00 NETT** which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of **7 (seven) days**, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,
PRO PLUS AUTOMOBILE ENGINEERS

Errol Tan
Licensed Appraiser & Automobile Engineer
Encls:



The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To: M/s Rhino Rental Pte Ltd
c/o 4 Penjuru Close
Singapore 608574

Insured	:	
Policy Number	:	
Claim Number	:	
Our Reference	:	PP/ET/CT-4460.TP.11-19
Own Damage/Sum Insured	:	
Excess	:	
Third Party/Insce Company	:	
Date	:	25 November 2019

Instructed By	:	Ms Lee Pei Juan
Date of Assignment	:	5 November 2019
Date of Accident	:	29 October 2019
Date of Inspection	:	6 November 2019
Name of Workshop	:	AAK Logistics Services Pte Ltd
Place of Inspection	:	4 Penjuru Close Singapore 608574

PARTICULARS OF DAMAGED VEHICLE

Registration Number	:	GY 4460 P	Odometer Reading	:	483 451 Km
Make/Model	:	Toyota Hiace 2.0	Radio/Cassette/CD	:	Fitted
Year of Manuf/Reg	:	2005	Air Conditioner	:	Fitted
Engine Number	:	2KD1242632	View Mirrors	:	Fitted -O/s & n/s
Chassis Frame Number	:	JTFHS0ZP300012688	Seat Belts	:	Fitted -Front only
Class/Type	:	Panel Van (Goods)	Other Assessories	:	
Colour	:	White	(Specify)	:	

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	:	Good	Any Apparent Engine	:	
Paintwork	:	Good	Modification/s	:	
Footbrakes	:	Serviceable	Market Value	:	
Steering	:	Serviceable	Scrap Value (PARF/OMV)	:	
Undercarriage (Front)	:	Serviceable			
Undercarriage (Rear)	:	Serviceable			


TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
Front (Size)	:	70%	70%
MAKE	:		
Rear (Size)	:	70%	70%
MAKE	:		
SPARE (Size)	:		
MAKE	:		
Type of Road Wheels	:	Standard	


NOTE: The above percentages represent the estimated remaining life of the tyre threads
* Denotes damaged component/s

Direction of Impact (→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the rear o/s portion of the vehicle.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



 Damage Area/s

Damages sustained were the tailgate & its inner reinforcement- dented/bent/buckled/warped over an extensive area, tailgate hinge o/s- bent/misaligned, tailgate inner lock/striker- bent/twisted/disrupted, rear body panel - thrust inwards/buckled, rear bumper assembly, o/s rear side panel & its inner reinforcement dented/buckled/warped over an extensive area etc.

Note : Follow-up reinspection of damaged components & works-in-progress on 11 November 2019.

*Follow-up reinspection of vehicle on 24 November 2019 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.
(Note : Panel beater was on leave from 11 November 2019 to 15 November 2019.)*

ESTIMATE

The estimate submitted by **M/s AAK Logistics Services Pte Ltd** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs:

	Repairer's Estimate	Our Recommendation	
Spare Parts:	9105.65	4714.61	Estimated number of days for repairs: 7
Labour Charges:	1650.00	1000.00	
Paint Work	1500.00	1000.00	Number of photographs taken at time of state inspection: 44
Towing Charges			
Others	320.00	170.00	
TOTAL	12575.65	6884.61	

Remarks: The repairer has agreed to undertake the repairs on a contract lump sum of \$5,500.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.

APPRAISEMENT SCHEDULE

Registration No: GY 4460 P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$	Revised Amount \$
<u>PARTS REPLACEMENT- LIST ITEMS</u>					
1	1 pc	Tailgate	Dented/buckled/ warped	1673.50	1673.50
2	1 pc	Tailgate windscreen	Shattered	891.40	891.40
3	1 pc	Tailgate 'TOYOTA' motif	Essential	31.20	31.20
4	1 set	Tailgate third brake lamp assembly ✕	Serviceable	141.60	Rejected ✕
5	1 pc	Tailgate windscreen motor/wiper assembly ✕	Serviceable	412.40	Rejected ✕
6	1 pc	Tailgate windscreen nozzle ✕	Serviceable	21.10	Rejected ✕
7	1 pc	Tailgate windscreen weatherstrip	Torn	278.10	278.10
8	1 pc	Tailgate hinge o/s ✕	Bent/misaligned	65.10	Repair ✕
9	2 pcs	Tailgate damper @\$322.00 ✕	Serviceable	644.00	Rejected ✕
10	1 set	Tailgate rear garnish/handle	Distorted	195.80	195.80
11	1 pc	Tailgate side guide o/s	Clasped	21.40	21.40
12	1 pc	Tailgate stopper o/s	Wedged	18.40	18.40
13	1 pc	Tailgate inner lock	Bent/jammed	223.30	223.30
14	1 pc	Tailgate striker ✕	Bent	31.40	Repair R
15	1 pc	Tailgate draught weatherstrip	Essential	328.40	328.40
16	1 pc	Taillamp assembly o/s	Smashed	256.50	256.50
17	1 pc	Taillamp panel o/s	Smashed	321.80	321.80
18	1 pc	Rear end panel (outer) Repair	Buckled	621.90	621.90 R
19	1 pc	Rear bumper	Distorted	411.95	411.95
20	1 pc	Rear bumper reinforcement ✕	Bent	332.10	Repair R
21	1 pc	Rear bumper side retainer o/s ✕	Serviceable	23.90	Rejected ✕
22	1 pc	Rear side panel o/s	Buckled/warped	732.50	732.50
23	1 pc	Rear side inner panel o/s ✕	Buckled	419.80	Repair R
24	1 pc	Rear side panel inner board o/s ✕	Serviceable	218.60	Rejected ✕
			Sub - Total	8316.15	6006.15

APPRAISEMENT SCHEDULE

Registration No: GY 4460.P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	8316.15	6006.15
		<u>PARTS REPLACEMENT - LIST ITEMS</u> <u>(CONT'D)</u>			
25	1 pc	Rear side panel sliding door rail o/s	Intact	278.30	Rejected <i>XSL</i>
26	1 pc	Rear side panel sliding door rail end fixture o/s	Serviceable	51.20	Rejected <i>XSL</i>
			<i>5384.25</i>	8645.65	6006.15
			<i>25%</i>		1501.54
		Less : 25% by Pro Plus Automobile Engineers	<i>4038.18</i>	8645.65	4504.61
		<u>PARTS REPLACEMENT - SPECIAL</u> <u>NETT ITEMS</u>			
1	4 pcs	Terostat @\$80.00	Essential	320.00	120.00 <i>60</i>
2	1 set	Tailgate inner board clip/fastener	Essential	40.00	30.00 <i>150</i>
3	1 set	Rear bumper clip/fastener	Essential	50.00	30.00
4	1 set	Rear side panel inner board clip/fastener	Essential	50.00	30.00
			Sub - Total	9105.65	4714.61

APPRAISEMENT SCHEDULE

Registration No: GY 4460 P

Your Reference:

[illegible]


Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$5,500.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

ERROL TAN

B.A. Econ (Hons), UK

*Dip. Auto Engr. & Motor Trade Management .UK
Automobile Engineer & Licensed Appraiser*



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 19/19/19/VC06/022587

Your Ref : CS3/LPC19019520/R1cf3s2

13 December 2019

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF GY4460P

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of GY4460P
- b) GIA report GY4460P
- c) GIA report and photos of XE1865D

Kindly study the documents and let us have your report by 27 December 2019.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref : PP/ET/CT.4460.TP.11-19

25 November 2019

M/s Rhino Rental Pte Ltd
c/o 4 Penjuru Close
Singapore 608574

WITHOUT PREJUDICE

Dear Sirs,

**Re : Third Party Claim
Vehicle Registration No. GY 4460 P**

We refer to your instruction to appraise the above-mentioned vehicle on 5 November 2019.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs **AAK Logistics Services Pte Ltd** for **\$12,575.65** as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is **\$6,884.61**. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for **\$5,500.00 NETT** which, in our opinion is fair and reasonable.


The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of **7 (seven)** days, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,
PRO PLUS AUTOMOBILE ENGINEERS


Errol Tan
Licensed Appraiser & Automobile Engineer
Encls:



The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To: M/s Rhino Rental Pte Ltd
c/o 4 Penjuru Close
Singapore 608574

Insured	:	
Policy Number	:	
Claim Number	:	
Our Reference	:	PP/ET/CT.4460.TP.11-19
Own Damage/Sum Insured	:	
Excess	:	
Third Party/Insce Company	:	
Date	:	25 November 2019

Instructed By	:	Ms Lee Pei Juan
Date of Assignment	:	5 November 2019
Date of Accident	:	29 October 2019
Date of Inspection	:	6 November 2019
Name of Workshop	:	AAK Logistics Services Pte Ltd
Place of Inspection	:	4 Penjuru Close Singapore 608574

PARTICULARS OF DAMAGED VEHICLE

Registration Number	:	GY 4460 P	Odometer Reading	:	483 451 Km
Make/Model	:	Toyota Hiace 2.0	Radio/Cassette/CD	:	Fitted
Year of Manuf/Reg	:	2005	Air Conditioner	:	Fitted
Engine Number	:	2KD1242632	View Mirrors	:	Fitted -O/s & n/s
Chassis Frame Number	:	JTFHS0ZP300012688	Seat Belts	:	Fitted -Front only
Class/Type	:	Panel Van (Goods)	Other Assessories	:	
Colour	:	White	(Specify)	:	

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	:	Good	Any Apparent Engine	:	
Paintwork	:	Good	Modification/s	:	
Footbrakes	:	Serviceable	Market Value	:	-
Steering	:	Serviceable	Scrap Value (PARF/OMV)	:	-
Undercarriage (Front)	:	Serviceable			
Undercarriage (Rear)	:	Serviceable			

TYRE CONDITIONS ON VEHICLE

		NEAR SIDE 70%	OFF SIDE 70%
Front (Size)	:	195R14	
MAKE	:	Yokohama	
Rear (Size)	:	195R14	
MAKE	:	Yokohama	
SPARE (Size)	:	-	
MAKE	:	-	
Type of Road Wheels	:	Standard	

NOTE: The above percentages represent the estimated remaining life of the tyre threads


* Denotes damaged component/s

PRO PLUS AUTOMOBILE ENGINEERS

IMPACT OF VEHICLE

Direction of Impact (→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the rear o/s portion of the vehicle.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



 Damage Area/s

Damages sustained were the tailgate & its inner reinforcement- dented/bent/buckled/warped over an extensive area, tailgate hinge o/s- bent/misaligned, tailgate inner lock/striker- bent/twisted/disrupted, rear body panel - thrust inwards/buckled, rear bumper assembly, o/s rear side panel & its inner reinforcement dented/buckled/warped over an extensive area etc.

Note : Follow-up reinspection of damaged components & works-in-progress on 11 November 2019.

Follow-up reinspection of vehicle on 24 November 2019 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.

(Note : Panel beater was on leave from 11 November 2019 to 15 November 2019.)

ESTIMATE

The estimate submitted by **M/s AAK Logistics Services Pte Ltd** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts :	9105.65	4714.61	Estimated number of days for repairs: 7
Labour Charges :	1650.00	1000.00	
Paint Work :	1500.00	1000.00	Number of photographs taken at time of static inspection: 44
Towing Charges :			
Others :	320.00	170.00	
TOTAL	12575.65	6884.61	

Remarks: The repairer has agreed to undertake the repairs on a contract lump sum of \$5,500.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.

APPRAISEMENT SCHEDULE

Registration No: GY 4460 P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ c	Revised Amount \$ c
<u>PARTS REPLACEMENT- LIST ITEMS</u>					
1	1 pc	Tailgate	Dented/buckled/ warped	1673.50	1673.50
2	1 pc	Tailgate windscreen	Shattered	891.40	891.40
3	1 pc	Tailgate ' TOYOTA ' motif	Essential	31.20	31.20
4	1 set	Tailgate third brake lamp assembly	Serviceable	141.60	Rejected
5	1 pc	Tailgate windscreen motor/wiper assembly	Serviceable	412.40	Rejected
6	1 pc	Tailgate windscreen nozzle	Serviceable	21.10	Rejected
7	1 pc	Tailgate windscreen weatherstrip	Torn	278.10	278.10
8	1 pc	Tailgate hinge o/s	Bent/misaligned	65.10	Repair
9	2 pcs	Tailgate damper @\$322.00	Serviceable	644.00	Rejected
10	1 set	Tailgate rear garnish/handle	Distorted	195.80	195.80
11	1 pc	Tailgate side guide o/s	Clasped	21.40	21.40
12	1 pc	Tailgate stopper o/s	Wedged	18.40	18.40
13	1 pc	Tailgate inner lock	Bent/jammed	223.30	223.30
14	1 pc	Tailgate striker	Bent	31.40	Repair
15	1 pc	Tailgate draught weatherstrip	Essential	328.40	328.40
16	1 pc	Taillamp assembly o/s	Smashed	256.50	256.50
17	1 pc	Taillamp panel o/s	Smashed	321.80	321.80
18	1 pc	Rear end panel (outer)	Buckled	621.90	621.90
19	1 pc	Rear bumper	Distorted	411.95	411.95
20	1 pc	Rear bumper reinforcement	Bent	332.10	Repair
21	1 pc	Rear bumper side retainer o/s	Serviceable	23.90	Rejected
22	1 pc	Rear side panel o/s	Buckled/warped	732.50	732.50
23	1 pc	Rear side inner panel o/s	Buckled	419.80	Repair
24	1 pc	Rear side panel inner board o/s	Serviceable	218.60	Rejected
			Sub - Total	8316.15	6006.15

APPRAISEMENT SCHEDULE

Registration No: GY 4460 P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	8316.15	6006.15
		<u>PARTS REPLACEMENT- LIST ITEMS</u> <u>(CONT D)</u>			
25	1 pc	Rear side panel sliding door rail o/s	Intact	278.30	Rejected
26	1 pc	Rear side panel sliding door rail end fixture o/s	Serviceable	51.20	Rejected
				8645.65	6006.15
		Less : 25% by Pro Plus Automobile Engineers			1501.54
				8645.65	4504.61
		<u>PARTS REPLACEMENT- SPECIAL</u> <u>NETT ITEMS</u>			
1	4 pcs	Terostat @\$80.00	Essential	320.00	120.00
2	1 set	Tailgate inner board clip/fastener	Essential	40.00	30.00
3	1 set	Rear bumper clip/fastener	Essential	50.00	30.00
4	1 set	Rear side panel inner board clip/fastener	Essential	50.00	30.00
			Sub - Total	9105.65	4714.61

Registration No: GY 4460 P

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	9105.65	4714.61
		<u>LABOUR & MISC. CHARGES</u>			
1		To disconnect rear wire harness of electrical components to facilitate repairs, reconnect & check functions .		50.00	30.00
2		To dismantle/rebuild tailgate fittings/ancillary accessories etc to new tailgate.		150.00	60.00
3		To dismantle/renew tailgate windscreen to facilitate repairs including to conduct water leakages etc.		120.00	80.00
4		To dismantle/renew the rear accident damaged portions. To heat, cut/weld damaged body panels & components including to heat, knock-out, reshape, straighten, orientate, restore & align repairable constituents to symmetrical dimensions.		1650.00	1000.00
5		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.)))))		
6		To rustproofing & cavities preservation to the replaced and repaired panels.))	1500.00	1000.00
			Grand - Total	12575.65	6884.61

Pro Plus Automobile Engineers

ERROL TAN

B.A. Econ (Hons), UK

*Dip. Auto Engr. & Motor Trade Management, UK
Automobile Engineer & Licensed Appraiser*




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC19019520/R1tf3s2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 07-01-2020	
			Code : LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XE 1865D	Veh. Inspected	GY 4460P	
Policy No.	Z/19/VC06/105097	Coverage (\$)	0.00	
Claim No.	19/19/19/VC06/022587	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	24/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE MANUAL	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JTFHS02P300012688	Colour	WHITE	
Odometer	483457	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	GITI	6 mm	
L/H Front Tyre	195 R15C	GITI	6 mm	
R/H Rear Tyre	195 R15C	GITI	6 mm	
L/H Rear Tyre	195 R15C	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2019	Inspection Date	06/11/2019	
Survey held at	4 PENJURU CLOSE SINGAPORE 608574			
Repairer	AAK LOGISTICS SERVICES PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 4460P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED / BUCKLED / WARPED	1,673.50	1,673.50
1	TAILGATE WINDSCREEN	SHATTERED	891.40	891.40
1	TAILGATE 'TOYOTA' MOTIF	ESSENTIAL	31.20	31.20
1	SET TAILGATE THIRD BRAKE LAMP ASSEMBLY	SERVICEABLE	141.60	-
1	TAILGATE WINDSCREEN MOTOR / WIPER ASSEMBLY	SERVICEABLE	412.40	-
1	TAILGATE WINDSCREEN NOZZLE	SERVICEABLE	21.10	-
1	TAILGATE WINDSCREEN WEATHERSTRIP	TORN	278.10	278.10
1	TAILGATE HINGE O/S	TO REPAIR SEE LABOUR	65.10	-
2	TAILGATE DAMPER @ \$322.00	SERVICEABLE	644.00	-
1	SET TAILGATE REAR GARNISH / HANDLE	DISTORTED	195.80	195.80
1	TAILGATE SIDE GUIDE O/S	CLASPED	21.40	21.40
1	TAILGATE STOPPER O/S	WEDGED	18.40	18.40
1	TAILGATE INNER LOCK	BENT / JAMMED	223.30	223.30
1	TAILGATE STRIKER	TO REPAIR SEE LABOUR	31.40	-
1	TAILGATE DRAUGHT WEATHERSTRIP	ESSENTIAL	328.40	328.40
1	TAILLAMP ASSEMBLY O/S	SMASHED	256.50	256.50
1	TAILLAMP PANEL O/S	SMASHED	321.80	321.80
1	REAR END PANEL (OUTER)	TO REPAIR SEE LABOUR	621.90	-
1	REAR BUMPER	DISTORTED	411.95	411.95
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	332.10	-
1	REAR BUMPER SIDE RETAINER O/S	SERVICEABLE	23.90	-
1	REAR SIDE PANEL O/S	BUCKLED / WARPED	732.50	732.50
1	REAR SIDE INNER PANEL O/S	TO REPAIR SEE LABOUR	419.80	-
1	REAR SIDE PANEL INNER BOARD O/S	SERVICEABLE	218.60	-
1	REAR SIDE PANEL SLIDING DOOR RAIL O/S	SERVICEABLE	278.30	-
1	REAR SIDE PANEL SLIDING DOOR RAIL END FIXTURE O/S	SERVICEABLE	51.20	-
	LESS 25% DISCOUNT		-	-1,346.07
			8,645.65	4,038.18

Report Ref No. CS3/LPC19019520/R1tf3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
4	TEROSTAT @ \$80.00 (SN)	ESSENTIAL	320.00	60.00
1	SET TAILGATE INNER BOARD CLIP / FASTENER (SN)	ESSENTIAL	40.00	30.00
1	SET REAR BUMPER CLIP / FASTENER (SN)	ESSENTIAL	50.00	30.00
1	SET REAR SIDE PANEL INNER BOARD CLIP / FASTENER (SN)	ESSENTIAL	50.00	30.00
			460.00	150.00
	<u>LABOUR</u>			
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS.		50.00	30.00
	TO DISMANTLE / REBUILD TAILGATE FITTINGS / ANCILLARY ACCESSORIES ETC TO NEW TAILGATE.		150.00	60.00
	TO DISMANTLE / RENEW TAILGATE WINDSCREEN TO FACILITATE REPAIRS INCLUDING TO CONDUCT WATER LEAKAGES ETC.		120.00	80.00
	TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTIONS. TO HEAT, CUT / WELD DAMAGED BODY PANELS & COMPONENTS INCLUDING TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DIMENSIONS. INCLUSIVE OF THE REPAIR OF TAILGATE HINGE O/S, TAILGATE STRIKER, REAR END PANEL (OUTER), REAR BUMPER REINFORCEMENT AND REAR SIDE INNER PANEL O/S.		1,650.00	900.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		1,500.00	700.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			3,470.00	1,770.00
	GRAND TOTAL		12,575.65	5,958.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,750.00

Report Ref No. CS3/LPC19019520/R1tf3s2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.