

ASS. REC. BY:

REF: III

ASSIGNMENT

(2022)

From:

Date:

24/12/19

Veh No:

SJA 637P

Yr Regn:

27 Nov 2007

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJA 637P

Make:

Honda Civic 1.6 c.c 1595

at Workshop m/s

RICO GO

Colour

Blue

A/C: Insured / Std / NI / NA

of

8 Kaki Bukit Ave 4 #02-24 premier

Sp. Reading

167003

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

JHMFD 462085 200207

Policy No.

C/No:

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:


Before 12pm

Modi: Nil / S/Rim / STD / M/Rim or

Tyre Size:

F: 205/55 R16
R: 11

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NBX 6N

Bal. or Market Value:

\$ 20k

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

04

days

Res.: Yes or No

D.O.A.

D.O.I.

24-12-19

Lum Sum:

20

%

3 Val.: Yes or No

Survey held at

w/s

11AM

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COC: 12971

Net: 7000

L/S \$ 1850.00 (Rood \$

).

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$