

ASS. REC. NO.

REF:

CS INC 19022603 / Dyd3n2

Special Instructions:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Theresa Vimala

of

INC

Date/Time: 9:59am @ 24/12/11

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 7347T

Insured:

GZ 5718 K

at Workshop n/a

Soon Hock

Tel:

6542 5111

of

10 AMK Ind. Park 2A # 01-05/06

Policy No:

Claim No:

MT / 07 6745-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

20/12/2011

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment:

Date/Time:

10:21am @ 24/12/11

Person Contacted:

Lynn

Vehicle IN / OUT

Date/Time

Action/Instruction

13/11/11 ✓

SHC 73-17T - NA / FCS14010601 / 01

D.O.A. 4/6/2011

GZ 5718K - CS3 / SM019020003 / 03

D.O.A. 11/11/2011

ASSIGNED BY: Bryan

ASSIGNMENT

OE March 2025

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6
20

days

Res.: Yes or No

Est. Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 7347T

(Regn)

2017, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

c.c 1580

Colour:

Yellow

A/C: Insured / Std / Nil / NA

Sp.Rounding

492745

T/Radio: Insured / Std / Nil / NA

Eng/No:

G4LEGU329707

C/No:

KMHC851C VHU022840

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / B/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dakenti

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

20/12/2019

D.O.A.

24/12/2019

Survey held at

Chunni AMK

4.53pm

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front y N/S Body y N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NTUC G25718K

03/02/2020

find out 1/3 7300/- with 6 days 2 run (Red \$7053-48, 49%)

RECEIVED 05 FEB 2020

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

5/2/20 Typist

Report Format:

Comp. Sum. TP. 1/1

\$7300/-

Days Of Repair:

6

Resurvey No. of Trip:

3

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Work end (\$

Survey Fee:

Transportation:

\$ + RS. 01

Photos

Notes

10/11

250

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 24 December 2019 1:39 PM
To: Nivitha (LKK Auto); 'assignments'; 'SUR'
Subject: RE: TP CASES FARMED OUT ON 24/12/2019

Hi Nivitha

Attached are the name of OIC, etc..

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg

income
new different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 24 December 2019 11:49 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT ON 24/12/2019

Dear Sir/Mdm,

Thank you for the assignments.

Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]
Sent: Tuesday, 24 December 2019 9:59 AM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: TP CASES FARMED OUT ON 24/12/2019

Hi LKK, please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Huey huey	MT/1076636-002	24/12/2019	SLT1355Y	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		5lu868k	19/12	
2	serene	MT/1076807-002	24/12/2019	SLQ2790H	MASSIVE TRADING & AUTO	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569541	Anthony Cheong / 91082728		Gba4902a	21/12	

3	Jared	MT/1076881-001	24/12/2019	SMN1044P	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Liv Loi / 6481 1522	12:00-13:00	Gx3063p	20/12/2019	
4	Swee Kenig	MT/1076745-002	24/12/2019	SHC7347T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		Gx5718k	20/12/2019	65425119 or 6542 7162
5	airwan	MT/1076853-001	24/12/2019	SLL4883L	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTO CITY 4113	Cady Lee / 6266-6448 / 9692 4113		Xd4711a	13/12	
6	Jeff	MT/1076573-002	24/12/2019	SLM56205	MBM WHEELPOWER PTE LTD	160 SIN MING DRIVE #06-03/06, SIN MING AUTO CITY	Eryx Tan / 8138 7188		Slp2800b	20/12	
7	helena	MT/1076815-001	24/12/2019	SLH2188U	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		Shc5913r	20/12	agreeable with the appointment of Mr Lim - LKK

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

MCD819167812 / ComfortDelGro Engineering Pte Ltd - Loyalang
ENTRY DATE & TIME: 21/12/2019 10:48
SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/12/2019 10:49
Date Of Accident 20/12/2019 17:15
Exact Location Of Accident AIRPORT ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC7347T
Insured/Policyholder
Name Of Registered Owner CITYCAB PTE LTD
Co Reg No 1XXXXX839G
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
Model IONIQ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-18088937MFSH
Cover Note Number

Driver

Name of Driver LEE SOON HENG
NRIC No SXXXX510Z
Date Of Birth 18/03/1950
Occupation OUTDOOR
Date Of Driving Pass 28/05/1968
Driving Experience 51 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98581263
Fax Number
Contact Number
Email Address RAYMONDSHLEE@YAHOO.COM.SG

Address	BLK 100 LORONG 1 TOA PAYOH #11-275
Postcode	310100
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ5718K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUTHURAKKU SIVA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	FRT RIGHT

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839C


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21.12.2019
@09:30 hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - SHC 7347T
B - GZ 5718K



Along Airport Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20.12.2019 at about 17:15 hours I was travelling along Airport Road with One Female

Passenger onboard .

While travelling I was travelling straight , suddenly veh B (GZ 5718K) cut into my lane and
collided into my taxi A - Whole Left Portion .

As it took place too fast I could not take evasive action to prevent the accident .

No injury in this accident .

I have company video and photos at scene to support my claims .

Veh B (GZ 5718K) - Mr Muthurakku Siva

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21.12.2019
@09:30 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHC 7347 T
Technician:
Mileage: 492745
Time Printed 24.12.19 4:48 PM

HYUNDAI IONIQ

Front : Left

Actual	BEFORE	Specified Range
0°14'		-3°00' 3°00'
4°47'		-0°19' 5°41'
-1°00'		-1°30' 1°30'
16°29'		
16°43'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°54'		-3°00' 3°00'
4°58'		-0°19' 5°41'
0°35'		-1°30' 1°30'
13°49'		
12°54'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
1°08'		-3°00' 3°00'
-0°11'		-3°00' 3°00'
2°41'		-3°00' 3°00'
-0°26'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°47'		-3°30' 2°30'
-3°00'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-2°09'		-3°30' 2°30'
-0°17'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°39'		-3°00' 3°00'
-3°18'		-3°00' 3°00'
-1°22'		-3°00' 3°00'

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 7347T

DATE : 21.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

HTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>new</i>			\$ 459.40
	Rear Bumper Side Bracket (LH) <i>new</i>			\$ 33.10
	Rear Bumper Cover Clips <i>SVC</i>			\$ 22.00
	Rear Fender (LH) <i>Dented</i>			\$ 1,768.30
	Rear Fender Inner Lining (LH) <i>new</i>			\$ 73.60
	Rear Windscreen Moulding <i>new</i>			\$ 28.20
	Rear Door (LH) <i>Dented</i>			\$ 1,789.90
	Rear Door Protector (LH) <i>new</i>			\$ 116.20
	Front Door (LH) <i>Dented</i>			\$ 1,797.20
	Rear Tyre Rim (LH) <i>new</i>			\$ 1,124.20
	Rear Wheel Hub-Cap (LH) <i>2 distal</i>			\$ 134.10
	Rear Wheelbearing IN & Hub <i>2 Dist</i>			\$ 454.00
	Rear Trailing Arm (LH) <i>2 distal</i>			\$ 121.00
	Rear Assist (LH) <i>2 distal</i>			\$ 92.80
	Rear Shock Absorber (LH) <i>2 distal</i>			\$ 230.50
	Rear Shock Absorber Mounting (LH) <i>new</i>			\$ 61.40
	Rear Crossmember <i>new</i>			\$ 756.40
	Rear Upper Arm (LH) <i>2 distal</i>			\$ 112.20
	Rear Lower Arm (LH) <i>2 distal</i>			\$ 393.10
	Rear Knuckle Arm (LH) <i>2 distal</i>			\$ 386.90
	Front Fender (LH) <i>Dented</i>			\$ 490.70
	Front Fender Shield (LH) <i>dislodged</i>			\$ 114.70
	Emblem-Blue Drive (LH) <i>new</i>			\$ 26.60
	SUB TOTAL			\$ 10,586.50
	LESS 20%			\$ 2,117.30
	DISCOUNTED TOTAL			\$ 8,469.20
	Rear Bumper Advertisement Logo <i>new</i>			\$ 50.00
	Rear Bumper Rubber Mat <i>new</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>new</i>		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant <i>new</i>			\$ 46.00
	Rear Door Advertisement Logo (LH) <i>new</i>			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>new</i>			\$ 80.00
	Front Door Coloured Comfort Logo (LH) <i>new</i>			\$ 75.00
	Front Door Advertisement Logo (LH) <i>new</i>			\$ 100.00
	Rear Tyre (LH) <i>new</i>			\$ 216.00
	Front Fender Advertisement Logo (LH) <i>new</i>			\$ 100.00
				\$ 1,017.00

7819.20

6255.36

\$ 100.00

751.00

SHC 7347T

[illegible]

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7347T (Supplementary)

DATE : 26.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Wheel Hup-Cap (LH) <i>distorted</i>			\$ 134.10
	SUB TOTAL			\$ 134.10
	LESS 20%			\$ 26.82
	DISCOUNTED TOTAL			\$ 107.28
	<i>2 gm</i> <i>2 KE Auto</i>			
	<i>[Signature]</i>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022603/Dyd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 06-02-2020



ATTN: SWEE KENG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 5718K	Veh. Inspected	SHC 7347T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1076745-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	24/12/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHC851CVHU022840	Colour	YELLOW
Odometer	492745 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT, N/S REAR
PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/12/2019	Inspect Date / Time	24/12/2019 (04:53 PM)
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7347T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER SIDE BRACKET (LH)	NOT NECESSARY	33.10	-
10	REAR BUMPER COVER CLIPS	SERVICEABLE	22.00	-
1	REAR FENDER (LH)	DENTED	1,768.30	1,768.30
1	REAR FENDER INNER LINING (LH)	NOT NECESSARY	73.60	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	28.20	-
1	REAR DOOR (LH)	DENTED	1,789.90	1,789.90
1	REAR DOOR PROTECTOR (LH)	NOT NECESSARY	116.20	-
1	FRONT DOOR (LH)	DENTED	1,797.20	1,797.20
1	REAR TYRE RIM (LH)	NOT NECESSARY	1,124.20	-
1	REAR WHEEL HUP-CAP (LH)	DISTORTED	134.10	134.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	454.00	454.00
1	REAR TRAILING ARM (LH)	DISTORTED	121.00	121.00
1	REAR ASSIST (LH)	NOT NECESSARY	92.80	-
1	REAR SHOCK ABSORBER (LH)	DISTORTED	230.50	230.50
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	61.40	-
1	REAR CROSSMEMBER	NOT NECESSARY	756.40	-
1	REAR UPPER ARM (LH)	DISTORTED	112.20	112.20
1	REAR LOWER ARM (LH)	DISTORTED	393.10	393.10
1	REAR KNUCKLE ARM (LH)	DISTORTED	386.90	386.90
1	FRONT FENDER (LH)	DENTED	490.70	490.70
1	FRONT FENDER SHIELD (LH)	DISLODGE	114.70	114.70
1	EMBLEM-BLUE DRIVE (LH)	NECESSARY	26.60	26.60
1	FRONT WHEEL HUP-CAP (LH)(ADDITIONAL)	DISTORTED	134.10	134.10
	LESS 20% DISCOUNT		-2,144.12	-1,590.66
			8,576.48	6,362.64
SPECIAL NETT ITEMS				
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
2	REAR FENDER ADVERTISEMENT (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00

Report Ref No. CS/INC19022603/Dyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH)(SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT (LH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (LH)(SN)	NOT NECESSARY	216.00	-
1	FRONT FENDER ADVERTISEMENT (LH)(SN)	NECESSARY	100.00	100.00
			1,017.00	751.00
	LABOUR			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,200.00	700.00
	SPRAY PAINTING CHARGE.		1,250.00	800.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE).		480.00	150.00
	RE-SET REAR ABS SYSTEM).		200.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM).		400.00	-
			4,760.00	2,100.00
GRAND TOTAL			14,353.48	9,213.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)(CONFIRMED)				7,300.00

Report Ref No. CS/INC19022603/Dyd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.