

ASS. REC. BY:
Surveyor: Kenneth

REF: es/INC19022604/Kyd3nz Special Instruction:

ASSIGNMENT (Office)

From (Person): Theresa Vimala of INC Date/Time: 9:59am @ 24/12/19

Estimated Cost: _____ Bill to: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8MN1044P Insured: Gx3063P

at Workshop m/s: Optima Werkz Tel: 64811522

of 9A Seungam Ave North S

Policy No: _____ Claim No: MT/1076881-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/12/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 10:11am @ 24/12/19 Person Contacted: Jily Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Estimate <input checked="" type="checkbox"/>
	SMN1044P-X
	Gx3063P-X

ASS. REC. BY:

REF:

INC/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN1044P

Yr Regn:

07.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

Shuttle

c.c

1498

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

138.34

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

GP7

2004597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/12/19

D.O.A.

24/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

11/2

Kenneth confirmed deal by \$2,467.20 with Lily. (Red 590, 19%)

RECEIVED 12 FEB 2020

11/2/2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

250

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

2,467.20

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 24 December 2019 1:39 PM
To: Nivitha (LKK Auto); 'assignments'; 'SUR'
Subject: RE: TP CASES FARMED OUT ON 24/12/2019

Hi Nivitha

Attached are the name of OIC, etc..

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers

in with you

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 24 December 2019 11:49 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT ON 24/12/2019

Dear Sir/Mdm,

Thank you for the assignments.

Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]
Sent: Tuesday, 24 December 2019 9:59 AM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: TP CASES FARMED OUT ON 24/12/2019

Hi LKK, please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Huey huey	MT/1076636-002	24/12/2019	SLT1355Y	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		Slu868k	19/12	
2	serene	MT/1076807-002	24/12/2019	SLQ2790H	MASSIVE TRADING & AUTO	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569541	Anthony Cheong / 91082728		Gba4902s	21/12	

3	jared	MT/1076881-001	24/12/2019	SMN1044P	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Lily Loi / 6481 1522	12:00-13:00	Gx3063p	20/12/2019	
4	Swee keng	MT/1076745-002	24/12/2019	SHC7347T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		Gx5718k	20/12/2019	65425119 or 6542 7162
5	airwan	MT/1076853-001	24/12/2019	SLL4883L	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTOCITY	Cady Lee / 6266-6448 / 9692 4113		Xd4711a	13/12	
6	jeff	MT/1076573-002	24/12/2019	SLM5620S	MBM WHEELPOWER PTE LTD	160 SIN MING DRIVE #06-03/06, SIN MING AUTOCITY	Eryx Tan / 8138 7188		Sle2800b	20/12	
7	helena	MT/1076815-001	24/12/2019	SLH2188U	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		Shc6913r	20/12	agreeable with the appointment of Mr Lim - LKK

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

749B

Vehicle Details

Vehicle No.:

SMN1044P

Vehicle to be Exported:

Yes

Intended Deregistration Date:

20 Dec 2019

Vehicle Make:

HONDA

Vehicle Model:

SHUTTLE HYBRID 1.5 AUTO

Primary Colour:

Grey

Manufacturing Year:

2018

Engine No.:

LEB7105953

Chassis No.:

GP72004597

Maximum Power Output:

101.0 kW (135 bhp)

Open Market Value:

\$22,416.00

Original Registration Date:

25 Jul 2019

First Registration Date:

25 Jul 2019

Transfer Count:

0

Actual ARF Paid:

\$13,383.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Jul 2029

PARF Rebate Amount:

\$10,037.00

Intended COE Rebate Details

COE Expiry Date:

24 Jul 2029

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$34,000.00

COE Rebate Amount:

\$27,200.00

Total Rebate Amount:

\$37,237.00

The information contained herein is correct as at 20 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2019 16:47
Date Of Accident	20/12/2019 13:30
Exact Location Of Accident	JURONG POINT CAR PARK LEVEL B1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN1044P
Insured/Policyholder	
Name Of Registered Owner	TURBO SPRAY COAT SERVICES
Co Reg No	5XXXX749B
Email Address	PETERBACHA321@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-98463583

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID 1.5 A
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111178052
Cover Note Number	25/07/19 - 24/07/20

Driver

Name of Driver	BACHA S/O AMEER ALI
NRIC No	SXXXX713D
Date Of Birth	22/11/1961
Occupation	INDOOR
Date Of Driving Pass	23/07/1979
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98463583
Fax Number	
Contact Number	
Email Address	PETERBACHA321@GMAIL.COM

Address	BLK 662A JURONG WEST ST.64 #15-336
Postcode	641662
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX3063P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SIM GUAN TECK
NRIC/Passport Number	SXXXX187A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for compliance with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time: 20/12/2019
@ 4pm

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20/12/2019
@ 4pm

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/12/2019 at about 12:35 PM, I was parked my vehicle at Jurong Point Carpark (B1). When I return to my car (A) SMN1044P at about 2.10 PM, there was a man stand at behind of my vehicle. He then informed me that my vehicle (A) SMN1044P was hit by his vehicle (B) QX3063P while he make a reversing. I saw rear portion of my vehicle (A) SMN1044P was damage. I wish to lodge this report for insurance claim purpose.

I prefer to repair at Optima Workz Pte Ltd.

DOA: 20/12/19 @ 13:30 hrs

Vehicle No: SMN 1044P (Nuc Income Ins)


Type: Third Party Claim (By Optima Workz Pte Ltd)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GUARMC Sketch



Driver's Signature
(If driver is not the policyholder)
Date & Time: 20/12/2019 @ 4 PM

Reporting Centre Personnel's Signature
Name: (Blank)
NRIC/FIN No.:

Date: 21.12.2019
Vehicle No: SMN1044P
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72004597 - 2019
Reg.Year: 2019

Third Party Insurer: NTUC
Third Party Veh No: GX3063P
Date of Accident: 20.12.2019

*Not wither
Rear B4 paint 4 days
\$2467.20*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		\$967.90
2	REAR TAILGATE "HYBRID" EMBLEM	1		\$55.20
3	REAR TAILGATE "SHUTTLE" EMBLEM	1		\$45.60
4	REAR TAILGATE BACK UP LAMP RH	1		\$496.20
5	REAR TAILGATE INNER TRIM CLIPS	12	\$5.80	\$69.60
6	REAR WINDSCREEN RUBBER	1		\$112.00
7	REAR BUMPER			REPAIR
SUB TOTAL				\$1,746.50
LESS 20%				-\$349.30
PARTS TOTAL				\$1,397.20

P: \$1397.20

S/N: \$110

L: \$980

\$2487.20 4 days

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT GUM	1		\$80.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	\$30.00
S/N TOTAL				\$110.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC	\$500.00	350
LABOUR CHARGES TO REMOVE, REFIX & REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN RUBBER & ETC. TO EFFECT REPLACE AT REAR TAILGATE	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC	\$120.00	60
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE REAR BUMPER & ETC	\$600.00	400
LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC	\$80.00	50
LABOUR CHARGES TO DISCONNECT & RECONNECT, REMOVE & REINSTALLED REAR TAILGATE INNER WIRING & ELECTRICAL SYSTEMS & ETC	\$100.00	20

LABOUR TOTAL \$1,550.00

ONG TOTAL \$3,057.20

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Date: 21.12.2019
 Vehicle No: SMN1044P
 Model: HONDA SHUTTLE HYBRID 1.5
 Chassis: GP72004597 - 2019
 Reg.Year: 2019

Third Party Insurer: NTUC
 Third Party Veh No: GX3063P
 Date of Accident: 20.12.2019'

*Not authorized
 Repair by paint 4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE 1250	1		R1 \$967.90
2	REAR TAILGATE "HYBRID" EMBLEM	1		m \$55.20
3	REAR TAILGATE "SHUTTLE" EMBLEM	1		m \$45.60
4	REAR TAILGATE BACK UP LAMP RH 730	1		CN1 \$496.20
5	REAR TAILGATE INNER TRIM CLIPS	12	\$5.80	m \$69.60
6	REAR WINDSCREEN RUBBER	1		m \$112.00
7	REAR BUMPER			REPAIR
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and approved by third approval team.				
SUB TOTAL				\$1,746.50
LESS 20%				-\$349.30
PARTS TOTAL				\$1,397.20

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT GUM	1		\$80.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	\$30.00
S/N TOTAL				\$110.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC \$500.00 *350*

LABOUR CHARGES TO REMOVE, REFIX & REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN RUBBER & ETC. TO EFFECT REPLACE AT REAR TAILGATE \$150.00 *120*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC \$120.00 *60*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE REAR BUMPER & ETC \$600.00 *400*

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC \$80.00 *50*

LABOUR CHARGES TO DISCONNECT & RECONNECT, REMOVE & REINSTALLED REAR TAILGATE INNER WIRING & ELECTRICAL SYSTEMS & ETC \$100.00 *20*

LABOUR TOTAL \$1,550.00

ONG TOTAL \$3,057.20

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022604/Kyd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 12-02-2020



ATTN: JARED

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 3063P	Veh. Inspected	SMN 1044P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1076881-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	24/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP72004597	Colour	METALLIC GREY
Odometer	13834 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/12/2019	Inspect Date / Time	24/12/2019 (12:28 PM)
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 1044P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	967.90	967.90
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	55.20	55.20
1	REAR TAILGATE "SHUTTLE" EMBLEM	NECESSARY	45.60	45.60
1	REAR TAILGATE BACK UP LAMP RH	CRACKED	496.20	496.20
12	REAR TAILGATE INNER TRIM CLIPS @\$5.80	NECESSARY	69.60	69.60
1	REAR WINDSCREEN RUBBER	NECESSARY	112.00	112.00
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-349.30	-349.30
			1,397.20	1,397.20
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT GUM (SN)	NECESSARY	80.00	40.00
2	REAR WINDSCREEN STOPPER @\$15.00 (SN)	NECESSARY	30.00	30.00
			110.00	70.00
LABOUR				
	LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		500.00	350.00
	LABOUR CHARGES TO REMOVE,REFIX & REPLACE REAR WINDSCREEN GLASS,REAR WINDSCREEN SEALANT,REAR WINDSCREEN RUBBER & ETC.TO EFFECT REPLACE AT REAR TAILGATE.		150.00	120.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC.		120.00	60.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE REAR BUMPER & ETC.		600.00	400.00
	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC.		80.00	50.00
	LABOUR CHARGES TO DISCONNECT & RECONNECT,REMOVE & REINSTALLED REAR TAILGATE INNER WIRING & ELECTRICAL SYSTEMS & ETC.		100.00	20.00
			1,550.00	1,000.00

Report Ref No. CS/INC19022604/Kyd3n2



GRAND TOTAL		3,057.20	2,467.20
RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,467.20

Report Ref No. CS/INC19022604/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.