

ASS. REC. BY:

REF:

es/INC/19022605/ktd352

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Theresa Vimala of INCDate/Time: 9:50am 24/12/2019

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No: _____

SLQ 2790H

Insured: _____

GBA 4902S

at Workshop m/s _____

Massive Trading

Tel: _____

91082728

of _____

BLK 5038 # 01-405 Amk Ind. Park 2

Policy No: _____

Claim No: _____

MT/1076807-002

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A. _____

21/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:07am 24/12/19

Person Contacted: _____

AnthonyVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	<u>Estimate (✓)</u>
	<u>SLQ 2790H -X</u>
	<u>GBA 4902S -X</u>
	<u>lump sum \$3900/- (Red: 5630.27; 59%)</u>

ASS. REC. BY:

REF:

INL /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

Veh No:

SLQ 2790H Yr Regn: 07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A/A

c.c 1500

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

6760

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH104562835

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F:

F:

R:

215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/12/19

D.O.I.

24/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 06 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

☒

: Final Report

1) 6/1 Typist

Date/Time, File Return to?

Days Of Repair: 15

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

39001-

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 24 December 2019 1:39 PM
To: Nivitha (LKK Auto); 'assignments'; 'SUR'
Subject: RE: TP CASES FARMED OUT ON 24/12/2019

Hi Nivitha

Attached are the name of OIC, etc..

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 24 December 2019 11:49 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT ON 24/12/2019

Dear Sir/Mdm,

Thank you for the assignments.

Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]
Sent: Tuesday, 24 December 2019 9:59 AM

To: assignments<assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: TP CASES FARMED OUT ON 24/12/2019


Hi LKK, please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Huey huey	MT/1076636-002	24/12/2019	SLT1355Y	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		Slu868k	19/12	
2	serene	MT/1076807-002	24/12/2019	SLQ2790H	MASSIVE TRADING & AUTO	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569541	Anthony Cheong / 91082728		Gha4902s	21/12	

3	jared	MT/1076881-001	24/12/2019	SMN1044P	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Lily Loi / 6481 1522	12:00-13:00	Gx3063p	20/12/2019	
4	Swee keng	MT/1076745-002	24/12/2019	SHC7347T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		Gz5718k	20/12/2019	65425119 or 6542 7162
5	airwan	MT/1076853-001	24/12/2019	SLL4883L	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTOCITY	Cady Lee / 6266-6448 / 9692 4113		Xd4711a	13/12	
6	jeff	MT/1076573-002	24/12/2019	SLM5620S	MBM WHEELPOWER PTE LTD	160 SIN MING DRIVE #06-03/06, SIN MING AUTOCITY	Eryk Tan / 8138 7188		Slc2800b	20/12	
7	helena	MT/1076815-001	24/12/2019	SLH2188U	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		Shc6913r	20/12	agreeable with the appointment of Mr Lim - LKK

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg

income
INSURANCE COMPANY LIMITED




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 10:58
Date Of Accident	21/12/2019 20:15
Exact Location Of Accident	SENGKANG EAST AVE TURNING TO SENGKANG EAST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ2790H
Insured/Policyholder	
Name Of Registered Owner	LIM CHYE KOON
NRIC No	SXXXX180D
Email Address	SIMSHAREN@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96218878
Alternative Phone No	OTHERS-91287859

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA475884/1
Cover Note Number	03/07/2019 - 02/07/2021

Driver

Name of Driver	SIM CHWEE CHEOK
NRIC No	SXXXX721Z
Date Of Birth	29/11/1967
Occupation	INDOOR
Date Of Driving Pass	13/03/1989
Driving Experience	30 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91287859
Fax Number	
Contact Number	OTHERS-96218878

Address	293 PUNGGOL CENTRAL #15-441
Postcode	820293
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SIM HUAY GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO OWN WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA4902S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre/Insurer's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 21/12/2019 Time: 2015 Location: Sengkang E Ave, turning right to Sengkang E Rd
 My Vehicle A: S2Q2790H Vehicle B: G3A4902S Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/12/2019 @ ard 2015hrs, I was travelling along Sengkang E Ave going to turn right into Sengkang E Rd. While I was waiting for the right turn arrow to turn green, suddenly I felt a strong impact from the rear of my vehicle. I alighted from my vehicle and realised that veh B (G3A4902S) had collided into my vehicle rear portion.

Passenger: Mdm Sim Huey, IC 511144046

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Massive Trading 3 Auto

Email address: simsharen@yahoo.com

& myself: massive3@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Personnel's Signature
Name:
NRIC/FIN No.:



ANNUAL REPORT

To Whom It May Concern,

Accident involving my vehicle no. SLQ2790H on 21/12/19 (date) with
GBA4902J (other vehicle no) along Sengkang East Ave to East Rd

I, LIM CHYE KOON Nric No. S16091000

Owner of vehicle no. SLQ2790H am aware of the accident of my vehicle on
21/12/19 (Date) while car was driven by SIM CHWEI CHEONG

Nric No. S17957212. I hereby, authorise him / her to make the report.

X

Name

Date:

To fill in if there is a OD claim

I am aware of the circumstances and agreeable to claim my own insurance for the
above accident.

X

Name

Date:

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

NTUC Income
73 Bras Basah Road
#05-00 NTUC Trade Union House
Singapore 189556

Vehicle No : SLQ 2790 H
Make : Toyota Altis
Year : 2016

Not Authorise
11 Lmp @ 3900k
Running After Paint
5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid			<i>Bu</i>	\$683.10	✓
1 pc	Rear boot lid inner lock			<i>nd</i>	\$359.10	✓
1 pc	Rear boot lid inner lock sensor			<i>CM</i>	\$205.70	✓
1 pc	Rear boot lid emblem " Logo "			<i>nd</i>	\$65.70	✓
1 pc	Rear boot lid emblem " Corolla "			<i>nd</i>	\$75.10	✓
1 pc	Rear boot lid emblem " Altis "			<i>nd</i>	\$70.20	✓
1 pc	Rear boot rubber			<i>nd</i>	\$184.70	X
2 pcs	Rear boot lid lamp component	<i>cls</i>	\$446.70		\$893.40	✓
2 pcs	Rear fender inner trim		\$455.10		\$910.20	X
1 pc	Rear end panel			<i>nd</i>	\$537.10	✓
1 pc	Rear end panel inner garnish			<i>nd</i>	\$263.70	✓
2 pcs	Rear tail-lamp assy		\$450.10		\$900.20	✓
2 pcs	Rear tail-lamp panel		\$205.10		\$410.20	X
1 pc	Rear spare tyre cover board			<i>nd</i>	\$292.10	X
1 pc	Rear bumper			<i>Bu</i>	\$553.10	✓
1 pc	Rear bumper reinforcement			<i>nd</i>	\$339.60	✓
2 pcs	Rear bumper bracket		\$110.20		\$220.40	✓
2 pcs	Rear bumper side retainer		\$85.10		\$170.20	✓
2 pcs	Rear bumper reflector		\$88.35		\$176.70	X
1 set	Rear reverse sensor			<i>nd</i>	\$395.10	✓
1 pc	Rear exhaust silencer			<i>nd</i>	\$971.10	X
					\$8,673.70	4,639.6
				Less 25 %	\$2,168.43	1,159.9
					\$6,505.27	3,479.7

S Nett

1 pc Rear no plate
20 pcs Bumper clip

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

nd \$40.00 X
nd \$60.00 ✓
\$100.00 60.00

balance c/f \$6,605.27

SLQ 2790 H

balance b/f \$6,605.27

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

60d
\$1,200.00 7200

To putty & spray paint rear accident affected portion.

\$1,200.00 60d

Check/reconnect wiring.

\$45.00 20c

To spray anti rust on accident affected portion.

60d \$180.00 760.0

Remove/renew rear exhaust silencer

~ \$150.00 X

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 60d
Total \$9,530.27 1540.

Hi Kenneth,

Paint - 3,479.70
S Well - 60.00
Labour - 1,540.00

5,079.70

Lease

~~4,000.00~~
3900k

5 days

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

NTUC Income
73 Bras Basah Road
#05-00 NTUC Trade Union House
Singapore 189556

Vehicle No : SLQ 2790 H
Make : Toyota Altis
Year : 2016

Not Notarize
11 Day @ ?
Running After Paint
4-5 day

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid		<i>Bu</i> \$683.10 ✓
1 pc	Rear boot lid inner lock		<i>nu</i> \$359.10 ✓
1 pc	Rear boot lid inner lock sensor		\$205.70 ?
1 pc	Rear boot lid emblem " Logo "		<i>nu</i> \$65.70 ✓
1 pc	Rear boot lid emblem " Corolla "		<i>nu</i> \$75.10 ✓
1 pc	Rear boot lid emblem " Altis "		<i>nu</i> \$70.20 ✓
1 pc	Rear boot rubber		<i>nu</i> \$181.70 X
2 pcs	Rear boot lid lamp component	<i>cls</i> \$446.70	\$893.40 ✓
2 pcs	Rear fender inner trim	\$455.10	<i>nu</i> \$910.20 X
1 pc	Rear end panel		\$537.10 ?
1 pc	Rear end panel inner garnish		\$263.70 ?
2 pcs	Rear tail-lamp assy	<i>nu</i> \$450.10	\$900.20
2 pcs	Rear tail-lamp panel	\$205.10	<i>nu</i> \$410.20 X
1 pc	Rear spare tyre cover board		<i>nu</i> \$292.10 X
1 pc	Rear bumper		<i>Bu</i> \$553.10 ✓
1 pc	Rear bumper reinforcement		\$339.60 ?
2 pcs	Rear bumper bracket	<i>cls</i> \$110.20	\$220.40 ?
2 pcs	Rear bumper side retainer	\$85.10	\$170.20 ✓
2 pcs	Rear bumper reflector	\$88.35	<i>nu</i> \$176.70 X
1 set	Rear reverse sensor		<i>sch</i> \$395.10 ✓
1 pc	Rear exhaust silencer		<i>nu</i> \$971.10 X
			\$8,673.70
Less 25 %			\$2,168.43
			\$6,505.27

S Nett

1 pc Rear no plate
20 pcs Bumper clip

nu \$40.00 X
nu \$60.00 ✓
\$100.00

balance c/f \$6,605.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLQ 2790 H

balance b/f \$6,605.27

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 7

To putty & spray paint rear accident affected portion.

\$1,200.00 604

Check/reconnect wiring.

\$45.00 201

To spray anti rust on accident affected portion.

\$180.00 7

Remove/renew rear exhaust silencer

~ \$150.00 X

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 601

Total \$9,530.27



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022605/Ktd3s2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 09-01-2020



ATTN: SERENE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 4902S	Veh. Inspected	SLQ 2790H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1076807-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	24/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104562835	Colour	METALLIC BLACK
Odometer	67169 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	7 mm
L/H Front Tyre	215/45 R17	MICHELIN	7 mm
R/H Rear Tyre	215/45 R17	MICHELIN	7 mm
L/H Rear Tyre	215/45 R17	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/12/2019	Inspect Date / Time	24/12/2019 (01:15 PM)
Survey held at	BLK 5038 #01-405 AMK IND.PARK2		
Repairer	MASSIVE TRADING & AUTO		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2790H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BUCKLED	683.10	683.10
1	REAR BOOT LID INNER LOCK	DENTED	359.10	359.10
1	REAR BOOT LID INNER LOCK SENSOR	CRACKED	205.70	205.70
1	REAR BOOT LID EMBLEM "LOGO"	NECESSARY	65.70	65.70
1	REAR BOOT LID EMBLEM "COROLLA"	NECESSARY	75.10	75.10
1	REAR BOOT LID EMBLEM "ALTIS"	NECESSARY	70.20	70.20
1	REAR BOOT RUBBER	SERVICEABLE	181.70	-
2	REAR BOOT LID LAMP COMPONENT @ \$446.70	O/S CUT	893.40	446.70
2	REAR FENDER INNER TRIM @ \$455.10	SERVICEABLE	910.20	-
1	REAR END PANEL	BENT	537.10	537.10
1	REAR END PANEL INNER GARNISH	DENTED	263.70	263.70
2	REAR TAIL-LAMP ASSY @ \$450.10	N/S SERVICEABLE / O/S CUT	900.20	450.10
2	REAR TAIL-LAMP PANEL @ \$205.10	TO REPAIR SEE LABOUR	410.20	-
1	REAR SPARE TYRE COVER BOARD	SERVICEABLE	292.10	-
1	REAR BUMPER	BUCKLED	553.10	553.10
1	REAR BUMPER REINFORCEMENT	BENT	339.60	339.60
2	REAR BUMPER BRACKET @ \$110.20	O/S DISTORTED	220.40	110.20
2	REAR BUMPER SIDE RETAINER @ \$85.10	O/S DISTORTED	170.20	85.10
2	REAR BUMPER REFLECTOR @ \$88.35	SERVICEABLE	176.70	-
1	SET REAR REVERSE SENSOR	SCRATCHED	395.10	395.10
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	971.10	-
	LESS 25% DISCOUNT		-2,168.43	-1,159.90
			6,505.27	3,479.70
SPECIAL NETT ITEMS				
1	REAR NO PLATE (SN)	SERVICEABLE	40.00	-
20	BUMPER CLIP @ \$3.00 (SN)	NECESSARY	60.00	60.00
			100.00	60.00

Report Ref No. CS/INC19022605/Ktd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR TAIL-LAMP PANEL AND REAR EXHAUST SILENCER.		1,200.00	600.00
	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION.		1,200.00	600.00
	CHECK / RECONNECT WIRING.		45.00	20.00
	TO SPRAY ANTI RUST ON ACCIDENT PORTION.		180.00	60.00
	REMOVE / RENEW REAR EXHAUST SILENCER.	NOT NECESSARY	150.00	-
	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.		150.00	60.00
			2,925.00	1,340.00
	GRAND TOTAL		9,530.27	4,879.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,900.00

Report Ref No. CS/INC19022605/Ktd3s2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.