COMFORTDELGRO ENGINFERING

Our Ref :

Date: 23.12.2019

Time of Fax: (8(5)

emay Via Fax :

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Your Insured: SKR9591B

Date of Acc: 22 112 2019

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHC 1926 L

Loyang 59 Loyang Drive Singapore 508969 Fax no. 6546 8156

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng. Tel no. 62148355 or Hp no. 98240811

Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305

Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006

Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176

6214 8316 Larry Ng Tel:

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

L / Larry Ng

for Vice President **Crash Repairs & Claims Recovery**











COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC1926L DATE: 23. Dec. 2019

MAKE : TOYOTA
MODEL : PRIUS DOA: 22. Dec. 2019 AIG

MODEL	: PRIUS	DOA:	22. Dec. 2019	<u>AIG</u>
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 Front Bumper Cover			\$490.50
1	Front Bumper Clips		\$2.20	\$22.00
3	Front Bumper Side Retainer – RH			\$82.30
3	Front Bumper Bracket - RH			\$29.60
1	Support Front Bumper – RH			\$81.70
1	Headlamp – RH			\$3,455.00
	Headlamp Panel - RH			\$213.50
	Front Fender – RH			\$945.30
	Front Fender Hybrid Emblem – RH			\$86.50
	SUB TOTAL LESS 25% DISCOUNTED TOTAL			\$5,406.40 \$1,351.60 \$4,054.80
				\$-
	Labour Charge			
	Panel Beating			\$650.00
	Spray Painting Charge			\$500.00
	Wiring Charge			\$50.00
1	Tuff Kote			\$50.00
	TOTAL LABOUR			\$1,250.00
	ESTIMATE TOTAL		-	\$5,304.80
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.			
	ACCIDENT STATEMENT		
Date Of Report	23/12/2019 13:51		
Date Of Accident	22/12/2019 12:10		
Exact Location Of Accident	SENTOSA GATEWAY TWDS TELOK BLANGAH RD		
Country/State of Loss	SINGAPORE		
	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SHC1926L		
Insured/Policyholder			
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD		
Co Reg No	1XXXXX821R		
Email Address	FLEETSAFETY@CDGTAXI.COM.SG		
Mobile Phone No			
Alternative Phone No	OFFICE-65508768		
Vehicle Particulars			
Manufacturer	TOYOTA		
Model	PRIUS HYBRID 4G		
Exact Purpose for which vehicle was being used at time of accident			
Are you claiming under your own insurance policy for repair to your vehicle?	NO		
If No, Please state action to be taken	THIRD PARTY		
Vehicle Category	TAXI		
Insurance Company			
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD		
Гуре Of Coverage	THIRD PARTY FIRE AND/OR THEFT		
Fleet Policy	YES		
Policy Number	D-18088936MFSH		
Cover Note Number			

Driver

Name of Driver ALISAH VETHAMUTHU S/O JOSEPH

NRIC No SXXXX617B
Date Of Birth 03/08/1966
Occupation OUTDOOR
Date Of Driving Pass 13/11/2009

Driving Experience 10 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-91891704

Fax Number
Contact Number

EMail Address EVJ97@YAHOO.COM

BLK 558 ANG MO KIO AVENUE 10 Address

#03-1788

560558 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - TAXI DRIVER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions **CLEAR** DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

2

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR9591B

Vehicle Make/Model/Colour **MERCEDES**

Details Of Properties

PRIVATE CAR Vehicle Category TAN JOKE KUM

NRIC/Passport Number

Contact Number

Name of Driver

Address

Postcode

Insurance Company Name

LH FRONT Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved In this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMPORT TRAPETPOSITATEM PER LID

Policyholder's Signature Date & Time:

Dylver's Signature

(Indriver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

\$ - 7 \$ - 6

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about 1210 pm, I was alring along Sentosa Galoway towards
Teloke Blangah Rd. There were few stationary vehicles ahead of m
as it was red corrow. When the green arrow appeared, the vehicle
Started moving. When it was my turn to move I checked my
blind good for edgescone it was also for my la many
Storted accelerating. All of a sudden a mercentes bearing
reaction BSKR9591B hit WEN (A) Event Trust (Q).
registration BSKR9591B hiL VEH @ Pigut Trans @.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMPORT IPANCOUNCATION DYE LID

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.