

Surveyor:

REF: CSI/EQI19022624/E sd3s2

Special Instructions:

From (Person): Joel Goh of EQI Date/Time: 02/07/2019

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: City Adjusters & Investigators

Workshop:

OD/TP Re-inspection Evaluation

To Inspect Vehicle No: MDB 8193 Insured: SJT 9048 E

at Workshop m/s Pang car spray Tel: 71 Jalan Berkat 6, Taman Malim Jaya 75250, Malaysia

Policy No: Claim No: DMH001387-JG

Sum Insured: Excess:

Make of Veh: D.O.A. 02/09/18

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 12 days)

Date/Time: 31/12/19 Submit Final Fig RM18,494.40, 10 days (Red \$4557.60/ 20%; Original 12 days)

Date/Time	Action/Instruction
	MDB8193-X
	SJT9048E-X
28/12/19	Insurence does not have any details for the tp vehicle. Any queries refer to joel from eqi

RECEIVED 31 DEC 2019

URGENT

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :  
Salvage Value :  
Nett Value :

Inspected/  
Evaluated by:

Fee Charged:  
Basic & Add  
Transport  
Photos  
Others  
Total

Date:

150

1) Date/Time File Pass to

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

## Nivitha (LKK Auto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Monday, 23 December 2019 10:25 AM  
**To:** assignments  
**Cc:** Admin A  
**Subject:** RE: PAPER SURVEY FOR MDB8193 (DM19HO01387-JG)

Dear LKK

Any updates on this matter?

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
www.eqinsurance.com.sg

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti*

---

**From:** Joel Goh  
**Sent:** Tuesday, December 17, 2019 2:49 PM  
**To:** 'assignments'  
**Subject:** RE: PAPER SURVEY FOR MDB8193 (DM19HO01387-JG)  
**Importance:** High

Dear LKK

Please advise if this paper survey is completed.

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
www.eqinsurance.com.sg

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/06/2019 14:25
Date Of Accident	02/09/2018 18:00
Exact Location Of Accident	MALAYSIA NORTH-SOUTH HIGHWAY
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT9048E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RAMLI BIN MAHMOOD
NRIC No	S0073094G
Email Address	RAMLI49@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97101553
Alternative Phone No	OFFICE-97101553

### Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE 1.5M A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-006506
Cover Note Number	

### Driver

Name of Driver	RAMLI BIN MAHMOOD
NRIC No	S0073094G
Date Of Birth	16/04/1949
Occupation	INDOOR
Date Of Driving Pass	31/07/1978
Driving Experience	40 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97101553
Fax Number	
Contact Number	OFFICE-97101553
EMail Address	RAMLI49@HOTMAIL.COM

Address	BLK 637, PASIR RIS DRIVE 1 #02-574
Postcode	510637
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	MDB8193 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JAMEELA BTE S.HAMID GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG POLICE DIVISIONAL HQ ( 'J' DIVISION )
Police Station Address	ROAD: NO. 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7910000 - FAX NO: 68965649
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN. REMARKS: VEHICLE WAS ALREADY REPAIRED WHEN OWNER COME DOWN TO LODGE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	MDB8193
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

( ) Claim Own Damage ( ) Claim TP ( / ) Reporting Only ( ) Claim OD/TP at other workshop

Workshop Name: \_\_\_\_\_

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the said date, I was driving my car, a silver Honda Airwave, bearing plate number SJT 9048E along the Malaysian North-South Highway from Kuala Lumpur heading towards Malacca. The weather was clear after a heavy thunderstorm and the road condition was wet and slippery. I was travelling straight on the right most lane.

Around the KM 282.5 mark there had an accident between 2 cars. The car ahead of me, a black Honda, bearing plate number M088193, had applied the brake in order to avoid a collision with the car that was involved in the said accident. Seeing that the car ahead had applied its brake, I too applied my brake to avoid hitting him. Unfortunately, as the road was wet and slippery, my vehicle had slid ahead and hit the rear of the said black Honda. Even though I had ensured that I was following a safe distance and travelled at approx. 80 km/h, the car failed to stop in time.

My car suffered damages to the front bonnet and radiator, and the other car suffered damages to its rear bumper.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
 tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg  
 reg no. 1978-00490-N

**CERTIFICATE OF INSURANCE**

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF**PRIVATE CAR  
Comprehensive Classic****Certificate No. : DMPPHQ17-006506**

Classic Plan - EQ Authorised Workshop Only

Form: MX2

Excess:

Insured &amp; Named Driver S\$500.00 (Section 1 - Own Damage)

Unnamed Driver S\$1,000.00 (Section 1 - Own Damage)

YEIDR Additional S\$3,000.00

WindScreen S\$100.00

**1. Index Mark and Registration Number of Vehicles**

SJT9048E

**2. Name of Policyholder**

Ramli Bin Mahmood

**3. Effective Date of the Commencement of Insurance for the purpose of the Act**

08/12/2017

**4. Date of Expiry of Insurance**

07/12/2018

**5. Person or Classes of persons entitled to drive\***

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

**6. Limitation as to use\***

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover:

(a) use for hire or reward

(b) use for racing, pace-making, reliability trials or speed testing

(c) use for the carriage of goods (other than samples) in connection with any trade or business

(d) use for any purpose in connection with the Motor Trade

\*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase : Thong Lee Trading Pte Ltd

A000036/Star Capital Insurance Agency Pte Ltd

Date of Issue : 08/12/2017 09:54

Authorised Signatory  
EQ Insurance Company Limited

**Note**

Young, Elderly &/or Inexperience Driver (YEIDR) refers to any person authorized to drive who is below 26 years old or above 70 years old and/or the holder of a qualified driving licence of less than 2 years duration.





**SINGAPORE  
POLICE FORCE**



J/20190603/7046

1 of 2

**POLICE REPORT (NP299)**

Report No. J/20190603/7046

Police Station Of Origin  
Jurong Division HQ  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7910000

Date/Time Report Made 03/06/2019 22:23	Vide Report No.	Station Diary No.
Name Of Informant RAMLI BIN MAHMOOD	Address APT BLK 637 PASIR RIS DRIVE 1 #02-574 SINGAPORE 510637	
ID Type / ID No. NRIC NO / S0073094G	Contact No. Home/Office: Mobile: 97101553	
Nationality SINGAPORE CITIZEN	Email Address ramli49@hotmail.com	
Occupation Trainer and quality control	Sex Male	Age 70
Institution/School Name	Date of Birth 16/04/1949	Race Malay
Date/Time Of Incident 02/09/2018 18:00 - 02/09/2018 20:00	Location Of Incident JOHOR (MALAYSIA)	

**Brief details.**

On the said date, I was driving my car, a silver Honda Airwave, bearing plate number SJT9048E, along the Malaysian North-South Highway from Kuala Lumpur heading towards Melacca. The weather was clear after a heavy thunderstorm and the road condition was wet and slippery. I was traveling straight on the right-most lane.

Around the KM282 mark, there had occurred an accident between 2 cars. The car ahead of me, a black Honda, bearing plate number MDB8193, had applied the brakes in order to avoid collision with the car

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/06/2019 22:23
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



J/20190603/7046

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20190603/7046

that was involved in the said accident. Seeing that the car ahead had applied its brakes, I too applied my brakes to avoid hitting him. Unfortunately, as the road was wet, my vehicle had slid ahead and hit the said black Honda. Even though I had ensured that I was following a safe distance and travelled at approx. 80km/h, the car failed to stop in time.

My car suffered damages to the front bonnet and radiator, and the other car suffered damages to its rear bumper.

I am writing this report to serve as documentation for insurance claims.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/06/2019 22:23
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



**City Adjusters & Investigators Sdn. Bhd.** (Co.Reg.No.82961-H)

No. 65 (2nd Floor), Jalan USJ 21/10, Taman Seafield Jaya, 47630 Subang Jaya, Selangor Darul Ehsan.  
Tel: +603-8023 7166 Fax: +603-8023 0736  
SST NO:- 816-1809-32000715

**THIRD PARTY CLAIM VEHICLE ASSESSMENT SURVEY REPORT**

SIOU AH LEH

,None,None.

**HANDLING INSURER**

Handling Insurer : Not Applicable

Date Of Loss : 02/09/2018

Our File No :

Date :

C-TPD71610-LTK(CHF)4/2019

7/5/2019

Vehicle No :

Nature Of Claim :

SJT9048E

TP

Claim No :

N/A

**CLAIMANT INFORMATION**

Claimant : SIOU AH LEH

Address : ,None,None.

Insurance Co:

Policy No :

**VEHICLE IDENTIFICATION SUMMARY**

Reg No : MDB8193

Make &amp; Model : SUBARU - Forester 5 Dr. SUV 2.0 Lit 2.0i-P [4/2016 On ]

Reg. Date : 29/08/2018 [Manf. Year: 2018] /

Seating Cp : 5

Colour : Metallic Dark Blue

Engine : NOTSIGHTED

Body Type : 5 Dr SUV

Chassis No : PLPSJ5KC5JA837582

Market Value : 0.00

Odometer : 650 KM

Sum Insured : 0.00

AirCond : Yes

Wing Mirror :

Clock :

Radio :

Seat Belt :

Lamps :

Trailer :

Yes

Yes

Yes

Yes

Yes

No

**CONDITION OF VEHICLE & TYRE AT THE TIME OF SURVEY**

General Condition : Good

Steering :

Serviceable

Foot Brake :

Serviceable

Paint Work : Good

Hand Brake :

Serviceable

Engine Modification :

No

Pre-Accident Damage :

No

Front Tyre Size: 225/60R17

Front Left Side : Continental - 4mm

Front Right Side : Continental - 4mm

Rear Tyre Size : 225/60R17

Rear Left Side : Continental - 4mm

Rear Right Side : Continental - 4mm

**CLAIM SUMMARY**

Repairer's

Adjuster's

Difference

Diff %

Parts

0.00

19,182.00

0

0%

Miscellaneous Items

0.00

375.00

0

0%

Paintwork Material

0.00

350.00

0

0%

MET &amp; Panel Labour

0.00

2,040.00

0

0%

Paint Labour

0.00

1,105.00

0

0%

Towing

0.00

0.00

0

0%

Gross Total (RM)

0.00

23,052.00

0.00

0%

Net Amount (RM)

0.00

23,052.00

0.00

0%

Date Of Assignment:

07/09/2018

Est. Period Of Repair:

12 Days

Date Inspected:

07/09/2018

Present Location :

Recomm'd Reserve(RM):

23,052.00

Inspected At:

Peng Car Spray Workshop

71 Jalan Berkat 6 Taman Malim Jaya 75250 Melaka.

Adjuster : LOH THAI KHEONG (F)

Manager :LOH THAI KHEONG

Note: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to our best of our ability knowledge but an other liability under any circumstances is hereby expressly excluded.

# REFERENCE DETAILS

MRC Version :

MRCDBP28.1

TTS Code :

TC031

TPS Code :

SB009 ( SUBARU Forester 5 Dr, SUV 2.0 Lit 2.0i-P [4/2016 On] )

## PARTS

No.	Part No.	Part Description.	Qty	Src	Condition	Adj's Price	Disc(%)	Depr(%)	Nett
1	28111SG090	Wheel Rim Alloy ()	1	N	Chipped	1,200.00	0.00	0.00	1,200.00
2	52122FJ0315P	Boot Floor ()	1	F	Buckled	3,358.90	0.00	0.00	3,358.90
3	60809SG0509P	Tailgate ()	1	F	Buckled	4,264.60	0.00	0.00	4,264.60
4	91111SG590	Tailgate Finisher ()	1	F	Broken	853.00	0.00	0.00	853.00
5	63032SG300	Tailgate Lock ()	1	F	Jammed	296.00	0.00	0.00	296.00
6	63269SG031	Tailgate Support Strut LH ()	1	F	Bent	247.00	0.00	0.00	247.00
7	63269SG021	Tailgate Support Strut RH ()	1	F	Bent	247.00	0.00	0.00	247.00
8	57704SG012	Bumper Rear Cover ()	1	F	Deformed/ Broken	1,624.00	0.00	0.00	1,624.00
9	57711SG0219P	Bumper Rear Reinforcement ()	1	F	Buckled	1,545.00	0.00	0.00	1,545.00
10	57707SG070	Bumper Rear Retainer/Guide LH ()	1	F	Broken	112.40	0.00	0.00	112.40
11	57707SG060	Bumper Rear Retainer/Guide RH ()	1	F	Broken	112.40	0.00	0.00	112.40
12	52401SG0109P	Rear Panel ()	1	F	Buckled	1,887.00	0.00	0.00	1,887.00
13	94026SG000VH	Rear Panel Garnish ()	1	F	Broken	563.70	0.00	0.00	563.70
14	84281SC010	Bumper Reflector Rear LH ()	1	F	Cracked	142.00	0.00	0.00	142.00
15	84281SC000	Bumper Reflector Rear RH ()	1	F	Chipped	142.00	0.00	0.00	142.00
16	59122SG010	Quarter Panel Liner Rear LH ()	1	F	Broken	176.00	0.00	0.00	176.00
17	63232SG010	Windscreen Rear Weatherstrip ()	1	F	Necessary	84.00	0.00	0.00	84.00
18	84912SG210	Rear Lamp Body LH ()	1	F	Chipped	1,102.00	0.00	0.00	1,102.00
19	84912SG220	Rear Lamp Body RH ()	1	F	Chipped	1,102.00	0.00	0.00	1,102.00
<b>OTHERS</b>									
20	DETPARTCD	Quarter Panel Liner Clips LH	1	N	Necessary	30.00	0.00	0.00	30.00
21	DETPARTCD	Spare Wheel Retainer	1	F	Broken	93.00	0.00	0.00	93.00

F:Franchise, O:OEM, U:Used, N:Nett

Total Before Discount (RM) :

Total Parts (RM) :

17,223  
 Part Discard - 10%  
 parts - 15,500-70  
 misc - 645  
 L - 2200  
 18,345-70  
 10 days

19,182.00  
19,182.00

**MISCELLANEOUS**

No.	Part Description.	Qty	Src	Adj's Price	Nett
1	Paintwork Material			350.00	350.00
2	Windscreen Sealant Rear	1	Q	85.00	85.00
3	Underseal Materials	1	Q	40.00	40.00
4	Tail Lamp Sealant	2	Q	15.00	30.00
5	Road Wheel Alignment	1	Q	35.00	35.00
6	Road Wheel Balancing	1	Q	25.00	25.00
7	Road Test	1	Q	30.00	30.00
8	Other Items	1	Q	35.00	35.00
9	Floor Board Sealant	1	Q	60.00	60.00
10	Electrical (Check & Diagnose)	1	Q	35.00	35.00

**Total :-****725.00**

645

**LABOUR**

S.NO	Particular	Type	MET	Panel	Paint	Total
<b>01-New(TTS)</b>						
1	Boot Floor	New(TTS)	1.10	13.30	3.20	17.60
2	Rear Panel	New(TTS)	3.60	3.00	2.80	09.40
3	Tailgate	New(TTS)	3.10	0.40	5.20	08.70
4	Bumper Rear	New(TTS)	1.30	0.00	4.90	06.20
5	Bumper Rear	New(TTS)	0.30	0.00	0.00	00.30
6	Reinforcement Panel	New(TTS)	0.30	0.00	0.00	00.30
7	Lamp Assembly Rear LH (Its)	New(TTS)	0.30	0.00	0.00	00.30
7	Lamp Assembly Rear RH (Its)	New(TTS)	0.30	0.00	0.00	00.30
<b>02-OPINION</b>						
8	Tailgate Finisher	New	* 0.30	* 0.00	* 3.00	03.30
9	Quarter Panel Liner Rear LH	New	* 0.30	* 0.00	* 0.00	00.30
10	Quarter Panel Lower Extension LH	Repair	* 0.00	* 3.00	* 3.00	06.00
11	Fuel Tank R and R	R&R	* 3.20	* 0.00	* 0.00	03.20
12	Windscreen Rear	R&R	* 4.00	* 0.00	* 0.00	04.00
13	Suspension Rear R and R	R&R	* 4.20	* 0.00	* 0.00	04.20

**LABOUR - Summary**

	MET	Panel	Paint	Others	Total
Total Combined (TTS) (66%)	08.96	16.48	16.10		41.54
Total Overlap Hrs ( - )	01.01	00.00			1.01
Total Opinion Hrs (34%)	12.00	03.00	06.00		21.00

Total Hrs Without (Overlap)	20.00	19.50	22.10		61.60
-----------------------------	-------	-------	-------	--	-------

Job Allowance				00.50	0.50
CP				00.80	0.80

Labour Rate (In RM)	50.00	50.00	50.00	50.00	62.90
---------------------	-------	-------	-------	-------	-------

Labour Cost (Rate*Hrs) (In RM)	1,000.00 800	975.00 800	1,105.00 600	65.00	3,145.00
-----------------------------------	-----------------	---------------	-----------------	-------	----------

&lt;&lt; END OF ESTIMATE &gt;&gt;

230524



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. MDB 8193

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	WHEEL RIM ALLOY	SERVICEABLE	1,200.00	-
1	BOOT FLOOR	BUCKLED	3,358.90	3,358.90
1	TAILGATE	BUCKLED	4,264.60	4,264.60
1	TAILGATE FINISHER	BROKEN	853.00	853.00
1	TAILGATE LOCK	JAMMED	296.00	296.00
1	TAILGATE SUPPORT STRUT LH	SERVICEABLE	247.00	-
1	TAILGATE SUPPORT STRUT RH	SERVICEABLE	247.00	-
1	BUMPER REAR COVER	DEFORMED / BROKEN	1,624.00	1,624.00
1	BUMPER REAR REINFORCEMENT	BUCKLED	1,545.00	1,545.00
1	BUMPER REAR RETAINER / GUIDE LH	BROKEN	112.40	112.40
1	BUMPER REAR RETAINER / GUIDE RH	BROKEN	112.40	112.40
1	REAR PANEL	BUCKLED	1,887.00	1,887.00
1	REAR PANEL GARNISH	BROKEN	563.70	563.70
1	BUMPER REFLECTOR REAR LH	CRACKED	142.00	142.00
1	BUMPER REFLECTOR REAR RH	SERVICEABLE	142.00	-
1	QUARTER PANEL LINER REAR LH	BROKEN	176.00	176.00
1	WINDSCREEN REAR WEATHERSTRIP	NECESSARY	84.00	84.00
1	REAR LAMP BODY LH	CHIPPED	1,102.00	1,102.00
1	REAR LAMP BODY RH	CHIPPED	1,102.00	1,102.00
1	QUARTER PANEL LINER CLIPS LH	SERVICEABLE	30.00	-
1	SPARE WHEEL RETAINER	BROKEN	93.00	93.00
	LESS 10% DISCOUNT		-	-1,731.60
			19,182.00	15,584.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	WINDSCREEN SEALANT REAR (SN)	NECESSARY	85.00	85.00
2	TAIL LAMP SEALANT @ \$15.00 (SN)	NECESSARY	30.00	30.00
1	OTHER ITEMS (SN)	NECESSARY	35.00	35.00
1	FLOOR BOARD SEALANT (SN)	NECESSARY	60.00	60.00
			210.00	210.00

Report Ref No. CS1/EQ119022624/Esd3s2



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PAINTWORK MATERIAL		350.00	300.00
	UNDERSEAL MATERIALS		40.00	40.00
1	ROAD WHEEL ALIGNMENT		35.00	35.00
1	ROAD WHEEL BALANCING		25.00	25.00
1	ROAD TEST	NOT NECESSARY	30.00	-
	ELECTRICAL (CHECK & DIAGNOSE)		35.00	35.00
	LABOUR COST (RATE HRS): MET: 20HRS		1,000.00	800.00
	LABOUR COST (RATE HRS): PANEL: 19.50HRS		975.00	800.00
	LABOUR COST (RATE HRS): PAINT: 22.10		1,105.00	600.00
	OTHERS		65.00	65.00
			3,660.00	2,700.00
	<b>GRAND TOTAL</b>		<b>23,052.00</b>	<b>18,494.40</b>
	<b>RECOMMENDED COST OF REPAIRS (RINGGIT MALAYSIA)</b>			<b>18,494.40</b>

Report Ref No. CS1/EQ19022624/Esd3s2

**CHEN TSUE YEE**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.