

REG. BY: Ram

REF:

CC3/TMI19022628/Fqd30r

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SLR 2170S

Policy No.

MK000576

Claims No.

M1910001

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC7102H

Yr Regn: 14/07/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

C.C 1685

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

449897

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KmHLB41UMGU092328

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205 / 60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

2012/19

D.O.I.

24/12/19

Survey held at

comfortelgro (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHC7102H-CS/FCI15006083/K94392

DOA: 9/14/2015

SLR 2170S - X

TMI

LIS

26/12/19 @ 2.21pm revised to Telma Gomez via Messenger.

LIS: \$5600/- with 4 repair days (Red \$4032.90, 42%.)
Confirm on 7/1/2020 with change.

RECEIVED 07 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1) 02/1/2020 Trans

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Arid Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

290

11

261

Report Format:

MER TP

Lump Sum / L.P.R. / L.S.

5600

...CLAIM SUBFOLDER...(Pending for Approval)

CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'd	Status
Main	23 Dec 2019 17:51		23 Dec 2019 18:12 S\$9,512.90			Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	CCPL, Co. Reg. No.: 199502839G		
Main Claimant:	CCPL		
Vehicle Reg. No.:	SHC7102H	Date of Loss:	20/12/2019 02:00 - :59 [41 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SLR2170S	Policy No. (Claimant):	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang)	PROFILE	59 Loyang Drive, 508969 Loyang - Tel: 6214 8300
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Telma Gomez

Date: 26 Dec 2019

Preliminary Advice

Insured Vehicle No	: SLR2170S	Accident Date	: 20/12/2019
TP Vehicle No	: SHC7102H	Assignment Date	: 26/12/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 4.00
Date of Inspection	: 24/12/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,512.90
Revised Amount	:S\$	4,525.04
Check Items (Estimated)	:S\$	984.98
Total	:S\$	5,510.38

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2019 16:48
Date Of Accident	20/12/2019 02:20
Exact Location Of Accident	SCOTTS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC7102H
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	MOHAMMAD MAZIAN BIN MOHAMAD MATSON
NRIC No	SXXXX912E
Date Of Birth	11/03/1965
Occupation	OUTDOOR
Date Of Driving Pass	29/12/1989
Driving Experience	29 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94599366
Fax Number	
Contact Number	
Email Address	MOHDMAZIAN_1103@YAHOO.COM



Address

BLK 492C TAMPINES STREET 45
#02-284

Postcode

522492

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own
Vehicle-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)
involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by
ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] TAMPINES NORTH NPP

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20191220/2101

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR2170S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver UNKNOWN

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1



Name

MOHAMMAD MAZIAN BIN MOHAMAD MATSON

Approximate Age

Injuries Sustain

BACK AND NECK

Injured person in which vehicle?

SHC7102H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CITYCAR FTE LTD
CO. REG. NO. 199502830C

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report - 7/20191220/2101

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAD PTE LTD
CO. REG. NO. 19502833G

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

S. A. Mooris
CSO

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191220/2101

1 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191220/2101

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/12/2019 15:46	Vide Report No.:	Station Diary No.: 35
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MOHAMMAD MAZIAN BIN MOHAMED MATSOM			Address: APT BLK 492C TAMPINES STREET 45 #02-284 SINGAPORE 522492		
ID Type / ID No.: NRIC NO / S1711912E			Contact No.: Home/Office: Mobile: 94599366		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 11/03/1965	Type of Informant: Driver		
Race: Boyanese			Language:	Institution / School Name:	
Occupation: FIREMAN			Driving Licence Information: Class: 2B,2A,2,3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/12/2019 02:20	Type of Location: Straight Road
Location: Along Road 1 SCOTTS ROAD in front of Hyatt Hotel lamp post 22				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7102H	M/Taxi				Slightly Damaged	0
SLR2170S	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191220/2101

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

2 of 3

Report No. T/20191220/2101

CONTINUATION OF REPORT

Driver			
Name	MOHAMMAD MAZIAN BIN MOHAMED MATSOM	ID No.	S1711912E
Related Vehicle	SHC7102H (M/Taxi)	Contact No.	94599366
Hospital/Clinic	GLENEAGLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	20/12/2019	Date Discharge	NIL
No. of Days granted Medical Leave	14	Degree of Injury	Slight

Brief Details.

On 20/12/2019 @ 0220hrs, I was waiting to go to drive in to the Service Lobby of Hyatt Hotel along Scotts Road when another vehicle hit me from the rear.

I was given 14 days MC by Gleneagles Hospital for my back pain, and neck pain.



**SINGAPORE
POLICE FORCE**



T/20191220/2101

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

3 of 3

Report No. T/20191220/2101

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sr Staff Sgt MOHAMMAD ABDULGHANI BIN
MOHD ADNAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

20/12/2019 15:46

Classification Of Case:

Date/Time: 23.12.2019 14:42

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305369017

CUSTOMER

MS

CUSTOMER NO.

ADDRESS

(R)

(P)

CITYCAB PTE LTD

7010070

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65551188

(O)

COUNT CARD NO.

REGN NO.:

SHC7102H

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

20.12.2019 02:20

YR OF MANU

14.07.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU092328

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 20.12.2019

NATURE: 3P 20.12.2019

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Vehicle Identification Slip

Exit Pass

No.:

SHC7102H

CHIANG

Vehicle No.:

SHC7102H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/12/2019
Vehicle Reg. No.:	SHC7102H	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	14/07/2016
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU661310	Chassis No:	KMHLB41UMGU092328
Odometer:	449097 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	7,581.90
Miscellaneous Items	11.00
Labour	1,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,512.90
+ GST 7.00% (S\$)	665.90
Nett Amount (S\$)	10,178.80

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

9632890

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC7102H/23/12/2019 18:12**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID xxn <i>DD</i>	20.00	0.00	*2,174.90 FL
2	1		*BOOT LID LOCK UPPER <i>xxn</i>	20.00	0.00	*102.60 FL
3	1		*BOOT LID LOCK LOWER <i>xxn</i>	20.00	0.00	*31.70 FL
4	1		*BOOT LID H EMBLEM <i>nec</i>	20.00	0.00	*28.70 FL
5	1		*BOOT LID CRDI PLATE <i>nec</i>	20.00	0.00	*27.90 FL
6	2		*BOOT LID LAMP LH/RH <i>xxn</i>	20.00	0.00	*1,131.20 FL
7	1		*REAR BUMPER <i>cra</i>	20.00	0.00	*553.00 FL
8	1		*REAR BUMPER REINFORCEMENT <i>Buc</i>	20.00	0.00	*428.40 FL
9	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH <i>BT</i>	20.00	0.00	*160.60 FL
10	10		*REAR BUMPER CLIP 10PCS <i>nec</i>	20.00	0.00	*22.00 FL
11	1		*REAR BUMPER BRACKET <i>nec</i>	20.00	0.00	*35.60 FL
12	1		*REAR BUMPER SPONGE <i>Br</i>	20.00	0.00	*103.50 FL
13	1		*REAR BUMPER UNDER COVER <i>Br</i>	20.00	0.00	*228.00 FL
14	2		*TAIL LAMP LH/RH <i>xxn</i>	20.00	0.00	*1,395.60 FL
15	1		*REAR PANEL <i>Bu</i>	20.00	0.00	*526.70 FL
16	1		*REAR PANEL GRANISH <i>xxn</i>	20.00	0.00	*57.70 FL
17	1		*REAR PANEL LOWER PANEL <i>xxn</i>	20.00	0.00	*89.40 FL
18	1		*EXHAUST PIPE INSULATOR LH <i>nec</i>	20.00	0.00	*58.55 FL
19	1		*EXHAUST SILENCER LH <i>Br</i>	20.00	0.00	*967.70 FL
20	1		*EXHAUST PIPE CENTER <i>BT</i>	20.00	0.00	*709.00 FL
21	1		*BOOT LID COMFORT LOGO & TEL NO STICKER <i>nec</i>	0	0.00	*30.00 FS
22	1		*BOOT LID ADVERTISEMENT LOGO <i>nec</i>	0	0.00	*100.00 FS
23	1		*REAR BUMPER REVERSE SENSOR <i>scr</i>	0	0.00	*135.70 FS
24	1		*REAR BUMPER ADVERTISEMENT LOGO <i>nec</i>	0	0.00	*50.00 FS
25	2		*REAR FENDER ADVERTISEMENT LOGO LH/RH <i>nec</i>	0	0.00	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,348.45
- List Item Discount on L Items (\$\$)	1,766.55
Total Parts (\$\$)	7,581.90

ComfortDelGro Engineering Pte Ltd/SHC7102H/23/12/2019 18:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5863.95
4891.16
380
5071.16
108.56
128.48
3689.05
2951.24
380
5308.2

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	840.00 ✓
2	SPRAY PAINTING	New	750.00 \$60
3	WIRING	New	50.00 \$31
4	TIFF KOTE	New	50.00 ✓
5	REMOVE/REFIX REVERSE SENSOR	New	80.00 \$50
6	REMOVE/REFIX EXHAUST PIPE	New	150.00 \$101
Gross Labour Cost (S\$)			1,920.00

ComfortDelGro Engineering Pte Ltd/SHC7102H/23/12/2019 18:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

24/12/19.
Ram (LKK)
24/12/19 1220 hrs
Rancevnu@lkkauto.com
88622784P
4S (Approved)
AFT repair photo

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
LION CITY RENTALS PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MK000576	Date of Loss:	20/12/2019
Vehicle Reg. No.:	SHC7102H	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	14/07/2016
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU661310	Chassis No:	KMHLB41UMGU092328
Odometer:	449897 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	120.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	120.00
+ GST 7.00% (S\$)	8.40
Nett Amount (S\$)	128.40
+ Previous Estimates (S\$)	10,178.80
Claim Total (S\$)	10,307.20

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** **ComfortDelGro Engineering Pte Ltd/SHC7102H/03/01/2020 14:11****Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

There are no new parts selected.

ComfortDelGro Engineering Pte Ltd/SHC7102H/03/01/2020 14:11. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING FEES -KING DOLLY	New	80 120.00
Gross Labour Cost (\$\$)			120.00

ComfortDelGro Engineering Pte Ltd/SHC7102H/03/01/2020 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our Job Ref No : 305369017
Date : 03/01/20

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : RAM
: SHC7102H

Fax :
20/12/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: TOKIO MARINE SLR2170S
2. The finalized amount shall be:
- (a) Spare Parts after List discount SC
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$5,600.00

No Aft repair
photo

3. Estimated normal period for repairs: 4 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature :
Name : Ram
Date : 7/1/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:









































...CLAIM SUBFOLDER...(Pending for Survey Report)











































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2019 17:51	23 Dec 2019 18:12	26 Dec 2019 09:47	S\$5,600.00	S\$5,600.00		Pending for Survey Report
	Sendback Est	S\$9,512.90	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	03 Jan 2020 14:10	03 Jan 2020 14:11	03 Jan 2020 14:11			(Combined)	Combined with Main
		S\$120.00					Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K								
Main Claimant:	CCPL								
Vehicle Reg. No.:	SHC7102H	Date of Loss:	20/12/2019 02:00 - :59 [41 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1910001	Policy/Cover Note No.:	MK000576 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020						
Vehicle Reg. No. (Insured):	SLR2170S	Policy No. (Claimant):							
		Excess:	S\$1,600.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 07/01/2020]								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC7102H (M1910001)
[SLR2170S]
TP
CCPL
Dec 20 2019 2:00AM
[LION CITY RENTALS PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/12/19 18:12	Repairer Estimates	 Load HTM	<input type="checkbox"/>
2	03/01/20 14:11	Repairer Estimates Suppl. #1	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/19 14:21	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/01/20 10:55	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	07/01/20 10:55	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
33	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
38	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
65	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
66	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
67	07/01/20 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
68	07/01/20 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/01/20 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/01/20 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/01/20 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/01/20 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	07/01/20 10:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	07/01/20 10:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	07/01/20 10:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	07/01/20 10:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	23/12/19 18:15	E-filed GIA report	 Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	30/12/19 11:35	TP - SHC7102H COMPLETE SAS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/01/20 13:54	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19022628/FQD3E2

Date: 07/01/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000576
Claimant
Vehicle No : SHC7102H **Insured Vehicle No :** SLR2170S
Date of Loss: 20/12/2019 **Nature of Claim:** TP **Claim No:** M1910001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7102H**
 Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU661310
 Reg. Date: 14/07/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU092328
 Colour: Yellow Odometer: 449897 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,581.90	5,335.34	2,246.56	29.63
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,040.00	1,750.00	290.00	14.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,632.90	7,096.34	2,536.56	26.33
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	9,632.90	5,600.00	4,032.90	41.87
+ GST 7.00/7.00% (S\$)	674.30	392.00	282.30	41.87
Nett Amount (S\$)	10,307.20	5,992.00	4,315.20	41.87

INSPECTION

Date of Assignment: 26/12/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 24/12/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7102H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOT LID	Dented	2,174.90 FL	-	*2,174.90 FL
2	1		*BOOT LID LOCK UPPER	Not Necessary	102.60 FL	-	*- FL
3	1		*BOOT LID LOCK LOWER	Not Necessary	31.70 FL	-	*- FL
4	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	-	*28.70 FL
5	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	-	*27.90 FL
6	2		*BOOT LID LAMP LH/RH	Not Necessary	1,131.20 FL	-	*- FL
7	1		*REAR BUMPER	Cracked	553.00 FL	-	*553.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Buckled	428.40 FL	-	*428.40 FL
9	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Bent	160.60 FL	-	*160.60 FL
10	10		*REAR BUMPER CLIP 10PCS	Necessary	22.00 FL	-	*22.00 FL
11	1		*REAR BUMPER BRACKET	Necessary	35.60 FL	-	*35.60 FL
12	1		*REAR BUMPER SPONGE	Broken	103.50 FL	-	*103.50 FL
13	1		*REAR BUMPER UNDER COVER	Broken	228.00 FL	-	*228.00 FL
14	2		*TAIL LAMP LH/RH	Not Necessary	1,395.60 FL	-	*- FL
15	1		*REAR PANEL	Buckled	526.70 FL	-	*526.70 FL
16	1		*REAR PANEL GRANISH	Not Necessary	57.70 FL	-	*- FL
17	1		*REAR PANEL LOWER PANEL	Not Necessary	89.40 FL	-	*- FL
18	1		*EXHAUST PIPE INSULATOR LH	Necessary	58.55 FL	-	*58.55 FL
19	1		*EXHAUST SILENCER LH	Broken	967.70 FL	-	*967.70 FL
20	1		*EXHAUST PIPE CENTER	Bent	709.00 FL	-	*709.00 FL
21	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	-	*30.00 FS
22	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	-	*100.00 FS
23	1		*REAR BUMPER REVERSE SENSOR	Scratched	135.70 FS	-	*135.70 FS
24	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	-	*50.00 FS
25	2		*REAR FENDER ADVERTISEMENT LOGO LH/RH	Necessary	200.00 FS	-	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,348.45	6,540.25
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,766.55	1,204.91
Total Parts (\$\$)	7,581.90	5,335.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	840.00	840.00
2	SPRAY PAINTING	New	750.00	600.00
3	WIRING	New	50.00	30.00
4	TIFF KOTE	New	50.00	50.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
6	REMOVE/REFIX EXHAUST PIPE	New	150.00	100.00
Supplementary #1				
Labour Items				
7	TOWING FEES -KING DOLLY	New	120.00	80.00
Gross Labour Cost (S\$)			2,040.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >