

<<

Service Request Details

Claim

S0M02C7C

Reference

CS3/ASM19022670/T1vd3s2



Loss Date

December 21, 2019

Report Date

Jan 6, 2020 8:56:03 AM

Request Date

January 6, 2020

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle

SMM4109Y

Registration #

Make

TPVD

Model

TOYOTA

Service Address

Primary Contact/Insured

LIM HAN SENG

BLK 473A FERNVALE STREET, #20-19, 791473, Singapore

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

1

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type	Document SubType			
+ Upload Documents				
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	January 14, 2020
 LKKPreRepairInspection[4].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 14, 2020
 IA 7.1.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 7, 2020
 RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	January 7, 2020
 SURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	January 7, 2020
 SMJ2024L INS.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	January 6, 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP MY CAR-REPLY FROM TP.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	January 6, 2020
 SGX9071B TP.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	January 6, 2020
 TP MY CAR-PRI TP EMAIL WITH TP GIA SMM4109Y.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	January 6, 2020