



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19022676/R1ga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 09-03-2020



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FZ 2423S	Veh. Inspected	SLL 650T
Policy No.	AN3175757	Coverage (\$)	0.00
Claim No.	S9M02B5A	Excess (\$)	0.00
Assign From	KADRI MATEEN	Assign Date	26/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11208120	Colour	GREEN
Odometer	247832	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	LING LONG	6 mm
L/H Front Tyre	215/60 R16	LING LONG	6 mm
R/H Rear Tyre	215/60 R16	LING LONG	6 mm
L/H Rear Tyre	215/60 R16	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/12/2019	Inspection Date	26/12/2019
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------